Terraprobe

Consulting Geotechnical & Environmental Engineering
Construction Materials Inspection & Testing

PHASE ONE
ENVIRONMENTAL SITE ASSESSMENT
109 CARTWRIGHT AVENUE AND 130 BENTWORTH AVENUE
TORONTO, ONTARIO

Prepared for: **The Sterling Hall School**
99 Cartwright Avenue
Toronto, Ontario, M6A 1V4

Attention: Mr. Stephen Hardy

File No.: 02210387.000
January 12, 2023
©Terraprobe Inc.

Terraprobe Inc.

Greater Toronto
11 Indell Lane
Brampton, Ontario L6T 3Y3
(905) 796-2650 Fax: 796-2250

Hamilton – Niagara
903 Barton Street, Unit 22
Stoney Creek, Ontario L8E 5P5
(905) 643-7560 Fax: 643-7559

Central Ontario
220 Bayview Drive, Unit 25
Barrie, Ontario L4N 4Y8
(705) 739-8355 Fax: 739-8369

Northern Ontario
1012 Kelly Lake Rd., Unit 1
Sudbury, Ontario P3E 5P4
(705) 670-0460 Fax: 670-0558

www.terraprobe.ca

TABLE OF CONTENTS

SECTION PAGE

1.0 EXECUTIVE SUMMARY 1

2.0 INTRODUCTION 4
2.1 Phase One Property Information 4

3.0 SCOPE OF INVESTIGATION 5
3.1 Purpose of Investigation 5
3.2 Records Review 5
3.3 Interviews 6
3.4 Site Reconnaissance 6
3.5 Documentation and Evaluation of Information 7

4.0 RECORDS REVIEW 8
4.1 General 8
4.1.1 Phase One Study Area Determination 8
4.1.2 First Developed Use Determination 8
4.1.3 Fire Insurance Plans and Insurance Products 8
4.1.4 Chain of Title 10
4.1.5 City Directory Search 10
4.1.6 Environmental Reports 11
4.2 Environmental Source Information 11
4.2.1 ERIS 11
4.2.2 Other Source Information 14
4.3 Physical Setting Sources 15
4.3.1 Aerial Photographs and Historic Mapping 15
4.3.2 Topography, Hydrology, Geology 16
4.3.3 Fill Materials 16
4.3.4 Water Bodies, Wetlands and Areas of Natural Significance 16
4.3.5 Archaeological Resources or Areas of Archaeological Potential 17
4.3.6 Species at Risk 17
4.3.7 Well Records 17
4.4 Site Operating Records 18

5.0 INTERVIEWS 19

6.0 SITE RECONNAISSANCE 20
6.1 General Requirements 20
6.2 Specific Observations at Phase One Property 20
6.2.1 Building and Structure Descriptions 20
6.2.2 Designated Substances and Other Special Attention Items 20
6.2.3 Below Ground Structures 21
6.2.4 Above Ground Fuel Storage Tanks 21
6.3 Underground Fuel Storage Tanks 21
6.3.1 Exterior Site Conditions 21
6.4 Enhanced Investigation Property 22
6.5 Investigation of Phase One Study Area 23
6.6 Written Description of Investigation 23
6.7 Potentially Contaminating Activities 23

7.0 REVIEW AND EVALUATION OF INFORMATION 24
7.1 Current and Past Uses 24
7.2 Potentially Contaminating Activities 24
7.3 Areas of Potential Environmental Concern 27
7.4 Phase One Conceptual Site Model 28
7.5 Uncertainty or Absence of Information 28

8.0 CONCLUSIONS 30
8.1 Phase Two ESA Required Before Record of Site Condition 30
8.2 Record of Site Condition Based on Phase One ESA Alone 31
8.3 Signatures 31

9.0 REFERENCES 32

10.0 LIMITATIONS AND USE OF THE REPORT 33

FIGURES

Figure 1 – Phase One Property Location
Figure 2 – Phase One Property
Figure 3 – Phase One Study Area
Figure 4 – Adjacent Properties Land Uses
Figure 5 – PCA Locations
Figure 6 – APEC Locations

APPENDICES

Appendix A – Survey Plan
Appendix B – Table of Current and Past Land Uses
Appendix C – Opta Report
Appendix D – Chain of Title
Appendix E – City Directories
Appendix F – ERIS Report
Appendix G – Regulatory Responses
Appendix H – Aerial Photographs, Historic Maps
Appendix I – Topographic Map and Geological Mapping
Appendix J – Water Well Records
Appendix K – Site Photographs
Appendix L – APEC Table
Appendix M – Phase One Conceptual Site Model

1.0 EXECUTIVE SUMMARY

The Sterling Hall School retained Terraprobe Inc. (Terraprobe) to complete a Phase One Environmental Site Assessment (Phase One ESA) of the Phase One Property (Property) located at 109 Cartwright Avenue and 130 Bentworth Avenue in Toronto, Ontario.

The Property is located on the south side of Cartwright Avenue and north side of Bentworth Avenue, west of Paul David Street in Toronto, Ontario. The Property consists of two (2) adjacent properties on 0.56 hectares (1.4 acres) of land. The Property is currently occupied by a single-storey commercial building, driveway and parking lots. A concrete pad remains at 130 Bentworth Avenue, where a former building was located. The general land area is being used for staff parking by the adjacent Sterling Hall School.

In accordance with Ontario Regulation 153/04 (O. Reg. 153/04), the Property use is Community as defined by the Ministry of the Environment, Conservation and Parks (MECP). It is understood that the Property will potentially be developed for Residential use. Redeveloping the Property means the Property would be changing to a more sensitive land use. On this basis, a Record of Site Condition (RSC) would be a mandatory requirement under the O. Reg. 153/04, as amended.

The Property was developed for industrial and commercial use during the late 1950s to early 1960s. Prior to this time, the Property appeared as vacant, agricultural land.

Based on the records reviewed and a site inspection, the following Potentially Contaminating Activities (PCAs) were identified within the Phase One Property and Phase One Study Area (Study Area) and caused Areas of Potential Environmental Concern (APECs).

On-Site PCAs

- #28 – Gasoline and Associated Products Storage in Fixed Tanks
- NA[3] – De-icing Agents
- #30 – Importation of Fill Material of Unknown Quality
- #12 – Concrete, Cement and Lime Manufacturing
- #37 – Operation of Dry-Cleaning Equipment (where chemicals are used)
- #39 – Paints Manufacturing, Processing and Bulk Storage
- #55 – Transformer, Manufacturing, Processing and Use

Off-Site PCAs

- #28 – Gasoline and Associated Products Storage in Fixed Tanks
- NA[1] – Waste Generators

The Phase One ESA identified ten (10) APECs on the Property, caused by eight (8) on-site and off-site PCAs. In order to completely eliminate the potential for adverse environmental impact on the Phase One Property, the APECs would need to be investigated simultaneously for both soil and ground water.

The Phase One ESA identified the following Areas of Potential Environmental Concern (APECs) on the Property.

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Phase One Property	Potentially Contaminating Activity	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Ground-water, soil and/or sediment)
APEC 1	North side of 109 Cartwright Ave.	#NA1 – Waste Generator	Off-Site	Metals, HFM, PHCs, BTEX, VOCs	Ground Water
APEC 1A	North side of 109 Cartwright Ave.	#55 – Transformer, Manufacturing, Processing and Use	On-Site	PHCs, BTEX	Soil and Ground Water
APEC 2	East side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	On-Site	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 3	South side of 109 Cartwright Ave.	#12 – Concrete, Cement and Lime Manufacturing	On-Site	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 4	West side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	Metals, HFM, PHCs, BTEX	Ground Water
APEC 5	Northwest side of 130 Bentworth Ave.	#39 – Paints Manufacturing, Processing and Bulk Storage	On-Site	Metals, HFM, VOCs, PHCs	Soil and Ground Water
APEC 6	North side of 130 Bentworth Ave.	#NA[3] – De-icing Agents	On-Site	EC, SAR Na, Cl	Soils Ground Water

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Phase One Property	Potentially Contaminating Activity	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Ground-water, soil and/or sediment)
APEC 7	West central portion of 130 Bentworth Ave.	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	On-Site	VOCs, PHCs	Soil and Ground Water
APEC 8	East central portion of 130 Bentworth Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	On-Site	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 9	West side of 130 Bentworth Ave.	#NA1 – Waste Generator	Off-Site	Metals, HFM, PHCs, BTEX, VOCs	Ground Water
APEC 10	Entire Property	#30 – Importation of Fill Material of Unknown Quality	On-Site	Metals, HFM, PHCs, BTEX, VOCs, PAHs	Soils

2.0 INTRODUCTION

The Sterling Hall School retained Terraprobe Inc. (Terraprobe) to complete a Phase One Environmental Site Assessment (Phase One ESA) of the Phase One Property (Property) located at 109 Cartwright Avenue and 130 Bentworth Avenue in Toronto, Ontario.

The Property is located on the south side of Cartwright Avenue and north side of Bentworth Avenue, west of Paul David Street in Toronto, Ontario. The Property consists of two (2) adjacent properties on 0.56 hectares (1.4 acres) of land. The Property is currently occupied by a single-storey commercial building, driveway and parking lots. A concrete pad remains at 130 Bentworth Avenue, where a former building was located. The general land area is being used for staff parking by the adjacent Sterling Hall School.

In accordance with Ontario Regulation 153/04 (O. Reg. 153/04), the Property use is Commercial as defined by the Ministry of the Environment, Conservation and Parks (MECP). It is understood that the Property will be potentially developed for Institutional use. Redeveloping the Property means the Property would be changing to a more sensitive land use. On this basis, a Record of Site Condition (RSC) would be a mandatory requirement under the O. Reg. 153/04, as amended.

The general location of the Property is presented on Figure 1. The layout of the Property and notable features are presented in Figure 2. A plan of survey of the Phase One Property is provided in Appendix A.

2.1 Phase One Property Information

Available Property information is provided below:

Municipal Addresses	109 Cartwright Avenue and 130 Bentworth Avenue, Toronto
Legal Description	Lot 21, Plan 7165 and Lot 57, Plan 7165
PIN(s)	10236-0301 (LT) and 10236-0279 (LT)
Zoning	Not Available
Area	0.56 ha (1.4 ac)
Property Owner Information	The Sterling Hall School
Persons, other than Property Owner, who engaged the Qualified Person to conduct the Phase One ESA	The Sterling Hall School 99 Cartwright Avenue Toronto, Ontario, M6A 1V4 Mr. Stephen Hardy

3.0 SCOPE OF INVESTIGATION

3.1 Purpose of Investigation

The Phase One ESA was conducted to satisfy the intent of the requirements, methodology and practices for a Phase One ESA as described in O. Reg. 153/04, as amended. The objectives of the Phase One ESA were as follows, per O. Reg. 153/04:

- to develop a preliminary determination of the likelihood that one or more contaminants have affected any land or water on, in or under the Phase One Property;
- to determine the need for a Phase Two ESA;
- to provide a basis for carrying out any Phase Two ESA required; and,
- to provide adequate preliminary information about environmental conditions in the land or water on, in or under the Phase One Property for the conducting of a Risk Assessment following completion of a Phase Two ESA (if required).

The Phase One ESA involved the following principal tasks:

- a review of records and reports regarding historical and current use and activities for the Property and Study Area;
- interviews with available individuals having knowledge of current and/or past site activities;
- an inspection of the Property and observations of the Phase One Study Area (Study Area); and,
- evaluation of the information obtained and documentation of the results of the review.

Sampling and analysis of soil, ground water, or other materials (e.g., construction materials, air) was not conducted as part of Phase One ESA.

3.2 Records Review

The records review provides information on historical and current activities. The objectives of the records review were:

- to obtain and review records that relate to the current and past uses, site features and activities at the Property;
- to obtain and review records that relate to PCAs, water bodies, and areas of natural significance in the Phase One Study Area and the Property; and,
- based on the above, to provide an assessment of actual and/or potential contaminating activities and concerns with respect to the environmental condition of the Property.

The sources of information were reviewed included:

- archival information for the Property including aerial photographs, topographic maps, historical maps and drawing;
- property specific environmental reports and/or operating records (e.g., Certificates of Approval, waste generator registration, approvals, permits) provided to Terraprobe;

- geological and hydrogeological information in published government maps reports and/or databases;
- databases maintained by Risk Information Services (ERIS) containing environmentally related information from private, provincial, and federal sources;
- available fire insurance plans and insurance inspection reports;
- published Ontario Ministry of the Environment, Conservation and Parks (MECP) directories related to registered active and closed landfill sites;
- the Ontario Ministry of Natural Resources and Forestry (MNRF) Natural Heritage Information Centre database for information specific to natural areas, such as locations of environmentally sensitive areas;
- published information regarding Official Plans and zoning information for the area;
- sensitivity mapping by the local Conservation Authority; and,
- well head protection mapping by the local Conservation Authority/MECP.

3.3 Interviews

The objectives of the interview were to identify PCAs and/or potential contaminant pathways in, on or under the Property. Key personnel were interviewed, and asked questions related to specific site activities, such as:

- the nature of the operations;
- handling and storage of environmentally sensitive products and related wastes;
- environmental approvals and registrations;
- knowledge of previous reports related to the environmental condition of the Property;
- issues related to non-compliance, orders, or charges related to environmental conditions on the Property; and,
- construction or renovation work conducted on the Property.

3.4 Site Reconnaissance

The objectives of the site reconnaissance were:

- to identify Potentially Contaminating Activities (PCAs) on the Property based on observations of current and past uses;
- to identify PCAs in the Study Area based on observations of current and past uses; and
- to identify potential pathways for contamination migration at the Property and Study Area

The site reconnaissance included a review and evaluation of PCAs, including the following:

- activities and practices including site operations, processes and waste management currently carried out on the Property;
- evidence of past waste disposal, landfill or fill placement on the Property;
- the presence of hazardous or toxic chemicals, materials or processes on the Property;

- the presence of existing or former aboveground or underground fuel storage tanks on the Property;
- identification of heating and cooling systems on the Property;
- the presence of floor cracks, hydraulic hoists, elevators, sumps and drains, wells, pits and lagoons on the Property;
- identification of water supply source to the Property;
- the presence of various designated substances and building materials, including friable and non-friable asbestos, PCB-containing materials and electrical equipment, lead-based paint, mould, and chlorofluorocarbons (CFCs) in air-conditioning and refrigeration equipment on the Property, and,
- evidence of stained or odorous soils and stressed vegetation on the Property.

In addition, an inspection of adjacent properties and the properties located within the Phase One Study Area was completed. The inspection of off-site properties was completed to identify PCAs, which may cause an Area of Environmental Concern (APEC) to be identified for the Property. The inspection of off-site properties was limited to inspection from the Property boundaries and publicly accessible areas (roads, sidewalks, etc.).

3.5 Documentation and Evaluation of Information

The information obtained from the records review, interviews and site reconnaissance was described, documented and evaluated, as summarized below:

- documentation of information, as noted in subsequent sections of the report;
- description of past occupants and site uses;
- description of PCAs;
- description of APECs; and,
- completion of Conceptual Site Model

4.0 RECORDS REVIEW

4.1 General

4.1.1 Phase One Study Area Determination

As required under O. Reg. 153/04, the Phase One Study Area (Study Area) consisted of the area including the Property and any other properties that are located, wholly or partly, within 250 m from the nearest point on a boundary of the Property. Based on the historical development and land use on the Property and surrounding area, the Qualified Person determined that a 250 m radius around the Property was sufficient to identify PCAs that could potentially cause APECs on the Property. No additional properties outside the 250 m radius were included in the Study Area. The approximate limits of the Study Area are shown on Figure 3 (Phase One Study Area).

4.1.2 First Developed Use Determination

The determination of first developed use was based on the review of aerial photographs, historical mapping, and property ownership records. The details and evaluation of the above noted information sources are provided in subsequent sections of this report.

Based on the evaluated information:

- The Property passed from Crown ownership to private individuals in 1815 and 1838.
- The Property was likely first developed for industrial and commercial use during the late 1950s to early 1960s.

The table of Current and Past Land Uses of the Property is provided in Appendix B.

4.1.3 Fire Insurance Plans and Insurance Products

Opta Information Intelligence (Opta) is a private organization that provides risk information to insurers, private corporations, and risk managers. Opta was contracted thru ERIS to determine whether their records included any Fire Insurance Plans (FIPs) or Insurance Products for the Property. FIPs were available for the Property dated 1961. The FIPs were within the Pinchin ESA studies. Insurance Products obtained included a 1995 Multi risk report, 1998 Inspection Report, 1964 Site plan Report, 1983 Site plan Report, 1981 Inspection Report, 1969 Site plan Report, 1996 Inspection Report and 1981 Site plan Report.

According to the FIPs:

Date	Property	Study Area
1961 FIP	• The Property is developed with an Industrial building (Concrete Products Mfg.) at 109 Bentworth Avenue and Industrial building (Furniture Manufacturing) at 130 Cartwright Avenue.	*North:* • Primarily industrial. A fuel oil UST was located at 104 Cartwright Avenue. *South:* • Primarily industrial. A fuel oil UST was located at 135 Bentworth Avenue. *East:* • Primarily institutional. *West:* • Primarily industrial. A gasoline UST was located at 111 Cartwright Avenue. A gasoline UST was located at 113 Cartwright Avenue. A gasoline and fuel oil UST were located at 135 Bentworth Avenue.

According to the Insurance Products:

109 Cartwright Avenue

- The site building was constructed in 1960 with an addition built in 1969. Site building heating was natural gas fired.
- Furniture Guild (retail sales) occupied the site in 1981.

130 Bentworth Avenue

- The site building was constructed in 1960 with an addition built in 1976. Site building heating was natural gas fired.
- I Wagner Company (furniture mfg.) occupied the site in 1961. Graphic Imprint (printer) and Creative Arts (furniture mfg.) occupied the site in 1987, and 1990 respectively. Presidential Dry Cleaners along with Prime Printers occupied the site in 1998. Dry cleaning operations reportedly took place in the west-central portion of the site.
- From the various site plan reports: Flammable liquids storage was in a shed at the northwest corner of the site. A flammable liquids storage room was also located at the northeast corner of the building. A degreasing tank was located in the north area of the building.

The following PCAs were identified during review of the FIPs and Insurance Products.

- #12 – Concrete, Cement and Lime Manufacturing
- #28 – Gasoline and Associated Products Storage in Fixed Tanks
- #37 – Operation of Dry-Cleaning Equipment (where chemicals are used)

- #39 – Paints Manufacturing, Processing and Bulk Storage

A copy of the Opta report is provided in Appendix C.

4.1.4 Chain of Title

A Chain of Title for the Property dating back to Crown ownership was completed as part of the Phase One ESA. The information from the chain of title is summarized below:

- The Property passed from crown ownership to private individuals in 1818 and 1838.
- The Property was owned by private ownership until acquired by the current landowners i.e., 109 Cartwright Avenue Limited in 2007 and The Sterling Hall School in 2019 respectively.

The Chain of Title search results and parcel register are provided in Appendix D.

4.1.5 City Directory Search

ERIS was contracted to search City Directory information for the Property and select Properties within the Study Area. City Directories were available for the period 1950 to 2001.

A review of the City Directories indicated the following information pertaining to the Property:

109 Cartwright Avenue

- Artistic Pre-Cast Concrete (1950 to 1960).
- Saivo Tile Company (1965).
- Furniture Guild (1970).
- Lighting Originals Inc. (1995 to 2000).

130 Bentworth Avenue

- Wagner I. Co. Ltd. and Canada Chair Co. (1960 to 1981/82).
- Canada Chair Co. (circa 1985/86).
- Multi tenant (circa 1995, 2001). Notable entries included: Presidential Cleaners, K & B Supplies and Printing, Prime Printing.

The following PCAs were identified during review of the City Directories.

- #12 – Concrete, Cement and Lime Manufacturing
- #37 – Operation of Dry-Cleaning Equipment (where chemicals are used)
- #39 – Paints Manufacturing, Processing and Bulk Storage

City Directories are presented in Appendix D.

4.1.6 Environmental Reports

In 2006 and 2007, Pinchin Environmental Ltd. (Pinchin) completed a Phase I and II ESA for each of the 109 Cartwright Avenue and 130 Bentworth Avenue properties. Reports were only provided in Draft and incomplete (i.e., missing appendices, lab certificates, drawings etc.). As such, the Phase I and II ESA reports were not relied upon for the Phase One ESA study. The Pinchin reports were only reviewed to gain an understanding on site conditions in preparation of the Terraprobe Phase One and Two ESA proposal.

4.2 Environmental Source Information

4.2.1 ERIS

Environmental Risk Information Services Ltd. (ERIS) is an organization that maintains and searches various government and private databases for property-related environmental information. A search of the ERIS databases was requested for the Property and Study Area. There were eighteen (18) records found for the Property. There were four hundred and fifty-seven (457) records found for properties within the Phase One Study Area (250 m).

Property

- One (1) Dry Cleaning Facility
- Two (2) ERIS Historical Searches
- Fourteen (14) Ontario Regulation 347 Waste Generators Summary
- One (1) Scott's Manufacturing Directory

Study Area

- Four (4) Automobile Wrecking & Supplies
- Seven (7) Borehole
- Ten (10) Certificates of Approval
- Two (2) Delisted Fuel Tanks
- Two (2) Environmental Activity and Sector Registry
- Five (5) Environmental Registry
- Five (5) Environmental Compliance Approval
- Forty-three (43) ERIS Historical Searches
- Two (2) Fuel Storage Tank
- Four (4) Fuel Storage Tank - Historic
- Two hundred and one (201) Ontario Regulation 347 Waste Generators Summary
- One (1) National PCB Inventory
- Eight (8) National Pollutant Release Inventory
- Two (2) Pesticide Register
- Three (3) Private and Retail Fuel Storage Tanks
- One (1) Record of Site Condition

- Eighty-six (86) Scott's Manufacturing Directory
- Fifteen (15) Ontario Spills
- One (1) Waste Disposal Sites
- Fifty-five (55) Water Well Information System

On the basis of the above, the following have been identified as PCAs:

Location of PCA	PCA	Details
Phase One Property – 130 Bentworth Ave.	#NA1 – Waste Generator	2008737 Ontario Ltd, 10109734 Ontario Ltd., North Park Dry Cleaners and/or Presidential Dry Cleaners were listed as a waste generator between 1993 and 2015 for waste class 241.
137 Bentworth Ave. 27.7 m South	#NA1 – Waste Generator	Canada Cup, James River Canada, Georgia Pacific Canada and/or Fort James Canada Inc. were listed as a waste generator between 1986 and 1998 for waste class 252, 243 and 251.
113 Cartwright Ave. 30 m West	#28 – Gasoline and Associated Products Storage in Fixed Tanks #NA1 – Waste Generator #NA2 – Ontario Spills	A gasoline tank with a capacity of 1000 Litres was located onsite. Contaminated soils were reportedly encountered when removing the tank. 1262589 Ontario Ltd. and/or Dominion Roofing was listed as a hazardous waste generator between 1990 and 2021 for waste class 213, 252 and 251.
140 Bentworth Ave. 46.1 m West	#NA1 – Waste Generator #28 – Gasoline and Associated Products Storage in Fixed Tanks	North York City of Bentworth Yard was listed as a waste generator between 1993 and 2022 for waste class 213, 221 and 252. A gasoline tank with a capacity of 9000 Litres was located onsite.
123 Bentworth Ave. 67.1 m Southwest	#NA1 – Waste Generator	Georgia Pacific Canada and/or Kevric Ontario Real Estate Corp. were listed as a waste generator between 2007 and 2011 for waste class 112, 113, 148, 212, 214, 221, 243 and 252.
104 Cartwright Ave.	#NA1 – Waste Generator	Crisstar Cabinets was listed as a waste generator between 2010 and

Location of PCA	PCA	Details
83.8 m North		2021 for waste class 145, 211 and 252.
122 Cartwright Ave. 98.1 m Northwest	#NA1 – Waste Generator	Mr. T Shirt Inc. was listed as a waste generator between 1986 and 1998 for waste class 213.
142 Bentworth Ave. 100.7 m West	#27 – Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #49 – Salvage Yard, including Automobile Wrecking	I & D Autobody and Collision Centre Limited was located onsite in 2001. Canadian Iron Metal Inc. (scrap metal) was once located onsite.
92 Cartwright Ave. 108.8 m Northeast	#NA1 – Waste Generator	Maple Leaf Foods Inc. and/or Cappola Food Inc. were listed as a waste generator between 2007 and 2022 for waste class 145 and 252.
147 Bentworth Ave. 123.9 m Southwest	#NA1 – Waste Generator	Preston Metal and/or Aden Earthworks Inc. were listed as a waste generator between 1986 and 2022 for waste class 112, 212 and 253.
151 Bentworth Ave. 158.5 m West	#27 – Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Graf Auto Repair Limited was located onsite in 2012.
127 Cartwright Ave. 180.8 m West	#NA2 – Ontario Spills	In 1992, 350 Litres of diesel spilled to the road and sewers.
162 Bentworth Ave. 195.8 m West	#NA1 – Waste Generator	Eric Kingston Sales Ltd. was listed as a waste generator between 1986 and 1994 for waste class 213 and 252.
133 Cartwright Ave. 211.8 m West	#NA1 – Waste Generator #NA2 – Ontario Spills	Converters Inc. and Champion Investments were listed as a waste generator between 1986 and 1998 for waste class 145 and 213. In 1994, 240 Litres of transformer oil spilled to the ground from transformers.
161 Bridgeland Ave. 211.6 m North	#NA1 – Waste Generator	Browning Ferris and/or Wasteco were listed as a waste generator between 1986 and 2022 for waste class 213, 251 and 252.

Location of PCA	PCA	Details
124 Cartwright Ave. 246.7 m West	#NA1 – Waste Generator	Alternator Exchange Ltd. was listed as a waste generator between 1986 and 2006 for waste class 122, 213 and 241.

The ERIS Report is provided in Appendix E.

4.2.2 Other Source Information

Other environmental source information was searched as part of the Phase One ESA. The information that was searched includes:

- Freedom of Information (FOI) request to the MECP. The FOI request determines if information regarding orders, investigations or other information on file with respect to the Property.
- A review of the MECP databases for active and closed landfill sites and coal gasification plants.
- Technical Standards and Safety Authority (TSSA) was contacted in regard to records related to storage tanks for petroleum related products with respect to the Property
- The local Conservation Authority online regulation mapping database was reviewed to determine if the Property was considered regulated under the Conservation Authorities Act and other applicable Ontario Regulations.
- Municipal Zoning and Official Plan information was reviewed.

The information requests and responses are provided in Appendix F and are summarized below.

Information Request	Response
MECP FOI	A FOI request was sent to the MECP on December 12, 2023. A response from the MECP to the FOI request has not been received as of the date of this report.
MECP Databases	The Property is not located within 1 km of an open or closed landfill or within 1 km of a coal gasification plant.
TSSA	A request was sent to the TSSA on December 5, 2022. The TSSA responded the same day that they had no current records for fuel storage tanks at the Property.
Conservation Authority	Toronto Region Conservation Authority online database. The database indicated that the Property is not regulated by the Conservation Authority.
Zoning	Not Available

4.3 Physical Setting Sources

4.3.1 Aerial Photographs and Historic Mapping

Aerial photographs, satellite imagery and historic maps were reviewed. Aerial photographs, satellite images and historic maps were selected based on available dates and scale in order to provide as much information as reasonably practical regarding the development of the Property and Study Area from first developed land use until the present development of the Property. The state of development of the Property and Study Area is summarized below:

Date	Source	Property	Study Area
1946	National Archives	Property appears as undeveloped, agricultural land.	North: Undeveloped, agricultural South: Undeveloped, agricultural East: Undeveloped, agricultural West: Undeveloped, agricultural
1950	National Archives	Property appears as undeveloped, agricultural land.	North: Undeveloped, agricultural South: Undeveloped, agricultural East: Undeveloped, agricultural with an inferred rural residence West: Undeveloped, agricultural
1965	National Archives	Property appears developed with two industrial and/or commercial buildings	North: Industrial/commercial South: Industrial/commercial East: Institutional West: Industrial/commercial
1970	National Archives	No significant changes.	North: No significant changes South: No significant changes East: No significant changes West: No significant changes
1982	National Archives	No significant changes.	North: No significant changes South: No significant changes East: No significant changes West: No significant changes
2019	Google Earth	The building located at 130 Bentworth Ave. has been demolished, with only the concrete floor slab remaining.	North: No significant changes South: No significant changes East: No significant changes West: No significant changes

No PCAs were identified during review of aerial photographs.

Aerial photographs and historic maps are provided in Appendix H.

4.3.2 Topography, Hydrology, Geology

The 1982 Ontario Base Map provides topographic information for the Property, and the geological mapping produced by the Ontario Geological Survey provides information on the surficial and bedrock geology in the area of the Property.

Topography	The elevation at the Property is approximately 183 metres above mean sea level.
Hydrogeology	The nearest water body Maple Leaf Creek located approximately 500 m west of the Property. The approximate depth to ground water, based on wells located within the Study Area ranges from 6 to 7 metres below ground surface. Ground water is interpreted to flow towards the southwest based on topography and the nearest water body.
Geology (overburden)	Based on published geological information, the near surface soil at and in the vicinity of the Property consists of stone poor, sandy silt to silt sand – textured till.
Geology (bedrock)	The bedrock underlying the Property is the Georgian Bay Formation which is comprised of shale with limestone interbeds.
Geology (depth to bedrock)	Based upon a borehole drilled within the Study Area, the depth to bedrock is greater than 50 metres below ground surface.

Topographic and geological mapping is provided in Appendix I.

4.3.3 Fill Materials

Based on findings from a concurrent geotechnical investigation, fill material was encountered at several boreholes drilled at 109 Cartwright Avenue and 130 Bentworth Avenue. This is associated with PCA#30 – Importation of Fill Material of Unknown Quality, as per O. Reg. 153/04.

4.3.4 Water Bodies, Wetlands and Areas of Natural Significance

Mapping from the MNRF was reviewed to determine if water bodies were present on the Property and within the Study Area. The MNRF National Heritage Information Centre database for listings of Areas of Natural or Scientific Interest (ANSIs) was reviewed. The information is summarized below.

Water Bodies (Property)	• There are no waterbodies located on the Property.
Water Bodies (Study Area)	• No waterbodies are located within the Study Area.

Wetland (Property)	Provincially Significant • No Provincially Significant wetlands are present on the Property. Non-Provincially Significant • No Non-Provincially Significant wetlands are present on the Property. Unevaluated • No Unevaluated wetlands are present on the Property.
Wetland (Study Area)	Provincially Significant • No Provincially Significant wetlands are present in the Study Area. Non-Provincially Significant • No Non-Provincially Significant wetlands are present in the Study Area Unevaluated • No Unevaluated wetlands are present in the Study Area.
ANSIs (Property)	Provincially Significant Life Science ANSI • No Life Science or Erath Science ANSIs were identified on the Property. Provincially Significant Earth Science ANSI • No Life Science or Earth Science ANSIs were identified on the Property.
ANSIs (Study Area)	Provincially Significant Life Science ANSI • No Life Science ANSIs were identified in the Study Area. Provincially Significant Earth Science ANSI • No Earth Science ANSIs were identified in the Study Area.

4.3.5 Archaeological Resources or Areas of Archaeological Potential

No additional archaeological evaluation of the Property was conducted as part of the Phase One ESA.

4.3.6 Species at Risk

No science-based assessment of potential species at risk or species habitat was conducted as part of the Phase One ESA.

4.3.7 Well Records

The MECP well records database was searched through ERIS and through the MECP online Water Well Database for records located on the Property and in the Study Area (within 250 m). A copy of the Well

Records is provided in Appendix J and are summarized below.

Water Wells (Property)	• No domestic wells were listed for the Property. • No other wells on the Property were listed through the MECP online well record database.
Water Wells (Study Area)	• No domestic water wells were located within the Study Area • Fifty-Five (55) properties with test holes/monitoring wells etc. were identified by ERIS in the Study Area.
Stratigraphy	Based upon boreholes drilled within the Study Area, the stratigraphy in the area of the Property is as follows: • Brown silty clay till over grey clayey silt till.
Depth to Water Table	Based on monitoring wells installed within the Study Area, the depth to ground water is approximately 6 to 7 m below ground surface.
Depth to Bedrock	Based on boreholes drilled within the Study Area, the depth to bedrock is greater than 50 metres below ground surface.

4.4 Site Operating Records

No site operating records were provided for review.

5.0 INTERVIEWS

On December 9, 2022, Mr. Stephen Hardy was sent a Site Questionnaire. A response has not been received to date. Tenants were also interviewed by Terraprobe on the day of the Site Reconnaissance.

6.0 SITE RECONNAISSANCE

6.1 General Requirements

Date of Investigation	December 9, 2022
Time of Investigation	9:00 am
Weather Conditions	5°C, Sunny
Duration of Investigation	Approximately 2.0 hours
Was the Facility Operating? (only for enhanced investigation)	Not Applicable
Person Conducting Investigation and Qualifications	David Mably
Person supervising Investigation and Qualifications	David Mably

6.2 Specific Observations at Phase One Property

The site reconnaissance included a walking tour of the Property, as well as compiling written and photographic records. Site features are presented on Figure 2, and site photographs are presented in Appendix K.

6.2.1 Building and Structure Descriptions

The Property is currently occupied by a single-storey building, driveway and parking lots. A concrete pad for a former building remains at 130 Bentworth Avenue. A detached shed is also located on the Property.

6.2.2 Designated Substances and Other Special Attention Items

The inspection was carried out in accessible areas and included an assessment of the potential presence of the following materials:

- Designated substances (i.e., acrylonitrile, asbestos, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, lead, mercury, silica, vinyl chloride).
- Polychlorinated biphenyls (PCBs).
- Ozone depleting substances.
- Urea-formaldehyde foam insulation (UFFI).
- Special attention items (i.e., mould, radioactive materials).

The presence of these materials is summarized below.

Asbestos	Asbestos containing materials may be present in the buildings in vinyl floor tiles. The condition of the materials appeared satisfactory.
Lead	No materials containing lead were observed during the site inspection.
Mercury	No materials containing mercury were observed during the site inspection.
Other Designated Substances	None of the other designated substances identified above were observed during the site inspection.
PCBs	No PCB-containing materials were observed during the site inspection.
Ozone Depleting Substances	No ozone depleting substances were observed during the site inspection. Roof top HVAC units were inaccessible.
UFFI	No suspected UFFI products were observed during the site inspection.
Mould	No mould was observed during the site inspection. However, water damage through ceiling tiles was observed in the warehouse at 109 Cartwright Avenue.
Radioactive Materials	No manmade sources of radiation were observed during the site inspection.
Herbicides and Pesticides	No herbicides or pesticides were noted during the site inspection

6.2.3 Below Ground Structures

No below ground structures were observed on the Property.

6.2.4 Above Ground Fuel Storage Tanks

No above ground fuel storage tanks were observed on the Property.

6.3 Underground Fuel Storage Tanks

Abandoned fuel oil supply and return piping was observed exterior to the building at 109 Cartwright Avenue, where a suspected buried fuel oil tank remains. No other evidence of USTs was observed on the Property.

6.3.1 Exterior Site Conditions

At the time of the Site Reconnaissance, the Property consisted of one (1) commercial building, paved parking lots and landscaping.

The following table provides additional details on the conditions observed on the Property.

Water Sources	The building at 109 Cartwright Avenue is connected to the municipal water system. Properties within the Study Area appeared to be serviced with municipal water.
Underground Utilities and Services	The inspection of the Property indicated the following information related to utility services: • Water enters from the north side of the Property. • Natural gas enters from the north side of the Property. • Hydro is underground from the northwest corner of the Property.
Current and Former Wells	No monitoring wells were observed on the Property during the site inspection.
Sewage Works	The Property is connected to municipal sewage system.
Railways	No railways were observed on or adjacent to the Property.
Stained and Odorous Soils	No evidence of stained or odorous soils were observed during the site inspection.
Stressed Vegetation	No evidence of stressed vegetation was observed during the site inspection.
Fill Materials	No evidence of fill materials was observed during the site inspection.
Watercourses, Ditches or Standing Water	No watercourses, ditches or standing water were observed during the site inspection.
Air Emissions	No air emission sources were observed on the Property.
Roads, Parking Facilities, and Right-of-Ways	Access to the Property is via a driveway off Cartwright Avenue and Bentworth Avenue.
Waste Handling	Private and municipal waste storage bins were located on the Property.

6.4 Enhanced Investigation Property

The current and historical activities on the Property at 130 Bentworth Avenue qualify the site as an Enhanced Investigation Property. However, no historical records other than those reported via ERIS were available for our review.

6.5 Investigation of Phase One Study Area

At the time of the site inspection, the Property uses were noted on the properties within the Study Area and immediately adjacent to the Property as summarized below.

Direction	Property Uses
North	Commercial/Industrial
East	Institutional
South	Commercial/Industrial
West	Commercial/Industrial

6.6 Written Description of Investigation

The site reconnaissance included a walking tour of the Property conducted on December 9, 2022, by David Mably, P. Eng. The tour consisted of an inspection of the Property and all building and structures (if present). Written and photographic records regarding the condition of the Property were compiled.

6.7 Potentially Contaminating Activities

The following Potentially Contaminating Activities (PCAs) were observed during the site inspection.

- Suspect fuel oil UST located at east side of 109 Cartwright Avenue.
- De-icing agents used in parking lots to control ice accumulation.

7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Current and Past Uses

Current and past uses of the Property were determined from historical aerial photographs, chain of title documents, city directories and the ERIS database. The current and past uses of the site are provided in Appendix B, in a form approved by the MECP under O.Reg. 153/04.

7.2 Potentially Contaminating Activities

The Phase One ESA identified the following Potentially Contaminating Activities (PCAs) on the Property and within the Study Area. The locations of the PCAs are illustrated in Figure 5.

Location of PCA	PCA	Potential APEC (Yes/No)	Justification
109 Cartwright Ave. Phase One Property	#55 – Transformer, Manufacturing, Processing and Use	APEC 1 (Yes)	PCA results in an APEC on the Property.
109 Cartwright Ave. Phase One Property	#28 – Gasoline and Associated Products Storage in Fixed Tanks	APEC 2 (Yes)	PCA results in an APEC on the Property.
109 Cartwright Ave. Phase One Property	#12 – Concrete, Cement and Lime Manufacturing	APEC 3 (Yes)	PCA results in an APEC on the Property.
111 Cartwright Ave. Directly West	#28 – Gasoline and Associated Products Storage in Fixed Tanks	APEC 4 (Yes)	Based on the nature of the PCA and distance away, the PCA results in an APEC on the Property.
104 Cartwright Ave. 83.8 m North	#NA1 – Waste Generator	APEC 1A (Yes)	Based on the nature of the PCA and inferred upgradient location, the PCA results in an APEC on the Property.
130 Bentworth Ave. Phase One Property	#39 – Paints Manufacturing, Processing and Bulk Storage	APEC 5 (Yes)	PCA results in an APEC on the Property.
130 Bentworth Ave. Phase One Property	#NA[3] – De-icing Agents	APEC 6 (Yes)	PCA results in an APEC on the Property.

Location of PCA	PCA	Potential APEC (Yes/No)	Justification
130 Bentworth Ave. Phase One Property	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	APEC 7 (Yes)	PCA results in an APEC on the Property.
130 Bentworth Ave. Phase One Property	#28 – Gasoline and Associated Products Storage in Fixed Tanks	APEC 8 (Yes)	PCA results in an APEC on the Property.
140 Bentworth Ave. Directly West	#28 – Gasoline and Associated Products Storage in Fixed Tanks	APEC 9 (Yes)	PCA results in an APEC on the Property.
109 Cartwright Ave. and 130 Bentworth Ave. Phase One Property	#30 – Importation of Fill Material of Unknown Quality	APEC 10 (Yes)	PCA results in an APEC on the Property.
137 Bentworth Ave. 27.7 m South	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
113 Cartwright Ave. 30 m West	#28 – Gasoline and Associated Products Storage in Fixed Tanks #NA1 – Waste Generator #NA2 – Ontario Spills	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
140 Bentworth Ave. 46.1 m West	#NA1 – Waste Generator #28 – Gasoline and Associated Products Storage in Fixed Tanks	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.

Location of PCA	PCA	Potential APEC (Yes/No)	Justification
123 Bentworth Ave. 67.1 m Southwest	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
122 Cartwright Ave. 98.1 m Northwest	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
142 Bentworth Ave. 100.7 m West	#27 – Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles #49 – Salvage Yard, including Automobile Wrecking	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
92 Cartwright Ave. 108.8 m Northeast	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
147 Bentworth Ave. 123.9 m Southwest	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
151 Bentworth Ave. 158.5 m West	#27 – Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.

Location of PCA	PCA	Potential APEC (Yes/No)	Justification
127 Cartwright Ave. 180.8 m West	#NA2 – Ontario Spills	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
162 Bentworth Ave. 195.8 m West	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
133 Cartwright Ave. 211.8 m West	#NA1 – Waste Generator #NA2 – Ontario Spills	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.
161 Bridgeland Ave. 211.6 m North	#NA1 – Waste Generator	No	Based on the distance away, soil and/or ground water impacts, if present, are not likely to affect the Property. The QP does not believe this PCA will cause an APEC on the Property.

7.3 Areas of Potential Environmental Concern

The PCAs identified in Section 7.2 were evaluated for their potential to create an Area of Potential Environmental Concern (APEC) on the Phase One Property through consideration of:

- the type of PCA;
- the potential magnitude of the PCA (e.g., small-scale waste generation versus significant commercial activity);
- the Potential Contaminants of Concern (PCoCs) associated with the PCA;
- the nature of those PCoCs in terms of their mobility in soil, ground water, and sediment as applicable;
- the anticipated direction of ground water flow;
- the anticipated hydraulic conductivity of saturated media;
- the distance between the PCA and the Property.

The analysis and rationale used to determine that a particular PCA may not create an APEC on the Property is provided in Section 7.2. The APECs identified are presented in a form approved by the Director in Appendix L.

The physical area of each APEC is illustrated on Figure 6. Please note that the area illustrated does not necessarily represent the complete potential area of impact, but represents the most likely potential area of impact, and thus represents the area that would first require intrusive investigation in a Phase Two ESA should a Phase Two ESA be conducted.

7.4 Phase One Conceptual Site Model

The Phase One Conceptual Site Model is presented in Appendix M and includes Figures 1 through Figure 6.

7.5 Uncertainty or Absence of Information

A discussion and description of how any uncertainties or absence of information may affect the conclusion as to the presence of any APEC or the validity of the Phase One CSM is provided in the table below.

Component	Uncertainty of Absence of Information	Effect on Phase One CSM
Fire Insurance Plans	Fire Insurance Plans, if available, which include the Phase One Property, were obtained as part of the investigation. As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM
Chain of Title	Chain of Title dating back to Crown ownership was reviewed as part of the investigation. As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM
Environmental Reports	All previous environmental reports provided to Terraprobe were reviewed. As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM
Environmental Source Information	Environmental Source Information was searched through a combination of Environmental Risk Information Services (ERIS) and Freedom of Information requests (FOI). As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM

Component	Uncertainty of Absence of Information	Effect on Phase One CSM
Aerial Photographs	Aerial Photographs were obtained from a combination of federal, provincial, municipal and private sources. The series of air photos selected represent the development of the Phase One Property and Phase One Study Area. As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM
Topography, Hydrology and Geology	The Topography, Hydrology and Geology were evaluated through available resources from the MNRF and published Water Well Records. As such, there exists no known void or absence of information for this component	No anticipated effect upon the Phase One CSM
Water Bodies and Areas and Natural Significance	Water Bodies and Areas and Natural Significance were evaluated through available resources from the MNRF, local conservation authorities and the MECP. As such, there exists no known void or absence of information for this component	No anticipated effect upon the Phase One CSM
Well Records	Well Records were provided through the summary provided by Environmental Risk Information Services (ERIS) as well as the MECP Water Well Information System (WWIS) database. As such, there exists no known void or absence of information for this component	No anticipated effect upon the Phase One CSM
Site Reconnaissance	Unrestricted access to the Property was provided. As such, there exists no known void or absence of information for this component.	No anticipated effect upon the Phase One CSM
Interviews	Interviews with persons knowledgeable regarding the current and historic environmental condition of the Phase One Property were conducted. As such, there exists no known void or absence of information for this component	No anticipated effect upon the Phase One CSM

Based upon the information obtained, as noted above, it is the belief of the QP_{ESA} that there are no significant uncertainties or absence of information that would affect the conclusion as to the presence of an APEC or the validity of the Phase One Conceptual Site Model.

8.0 CONCLUSIONS

8.1 Phase Two ESA Required Before Record of Site Condition

The Sterling Hall School retained Terraprobe Inc. (Terraprobe) to complete a Phase One Environmental Site Assessment (Phase One ESA) of the Phase One Property (Property) located at 109 Cartwright Avenue and 130 Bentworth Avenue in Toronto, Ontario.

The Property is located on the south side of Cartwright Avenue and north side of Bentworth Avenue, west of Paul David Street in Toronto, Ontario. The Property consists of two (2) adjacent properties on 0.56 hectares (1.4 acres) of land. The Property is currently occupied by a single-storey commercial building, driveway and parking lots. A concrete pad remains at 130 Bentworth Avenue, where a former building was located. The general land area is being used for staff parking by the adjacent Sterling Hall School.

In accordance with Ontario Regulation 153/04 (O. Reg. 153/04), the Property use is Community as defined by the Ministry of the Environment, Conservation and Parks (MECP). It is understood that the Property will potentially be developed for Residential use. Redeveloping the Property means the Property would be changing to a more sensitive land use. On this basis, a Record of Site Condition (RSC) would be a mandatory requirement under the O. Reg. 153/04, as amended.

The Property was developed for industrial and commercial use during the late 1950s to early 1960s. Prior to this time, the Property appeared as vacant, agricultural land.

Based on the records reviewed and a site inspection, the following Potentially Contaminating Activities (PCAs) were identified within the Phase One Property and Phase One Study Area (Study Area) and caused Areas of Potential Environmental Concern (APECs).

On-Site PCAs

- #28 – Gasoline and Associated Products Storage in Fixed Tanks
- NA[3] – De-icing Agents
- #30 – Importation of Fill Material of Unknown Quality
- #12 – Concrete, Cement and Lime Manufacturing
- #37 – Operation of Dry-Cleaning Equipment (where chemicals are used)
- #39 – Paints Manufacturing, Processing and Bulk Storage
- #55 – Transformer, Manufacturing, Processing and Use

Off-Site PCAs

- #28 – Gasoline and Associated Products Storage in Fixed Tanks
- NA[1] – Waste Generators

The Phase One ESA identified ten (10) APECs on the Property, caused by eight (8) on-site and off-site PCAs. In order to completely eliminate the potential for adverse environmental impact on the Phase One Property, the APECs would need to be investigated simultaneously for both soil and ground water.

8.2 Record of Site Condition Based on Phase One ESA Alone

A Record of Site Condition (RSC) could not be obtained solely on the basis of a Phase One ESA. A Phase Two ESA would be required prior to submitting an RSC.

8.3 Signatures

The Phase One Environmental Site Assessment has been completed under the direction and supervision of R. Baker Wohayeb, M.A.Sc., P. Eng., M. Eng. The findings and conclusions presented in this report have been determined on the basis of the information that was obtained and reviewed, and on an assessment of the existing conditions on the Phase One Property and properties within the Phase One Study Area.

The Phase One Environmental Site Assessment was completed in general accordance with the requirements of Ontario Regulation 153/04 (Records of Site Condition–Part XV.1 of the Environmental Protection Act). The objectives and requirements set out in that Ontario Regulation 153/04, for a Phase One Environmental Site Assessment, were met in carrying out this environmental site assessment and preparation of the report.

Yours truly,

Terraprobe Inc.







David Mably, P. Eng.
Senior Environmental Engineer

R. Baker Wohayeb, M.A.Sc., M. Eng., P. Eng.
Director, Environment

9.0 REFERENCES

1. Barnett, P.J., Cowan, W.R. and Henry, A.P.; *Quaternary Geology of Ontario, Southern Sheet;* Ontario Geological Survey; Map 2556, 1991
2. Ontario Geological Survey; *Bedrock Geology of Ontario, Southern Sheet;* Map 2544; 1991
3. Ontario Ministry of the Environment and Climate Change, January 1993. *Ontario Inventory of PCB Storage Sites*. ISBN 0-7778-0836-6.
4. Ontario Ministry of the Environment and Climate Change, June 1991. *Waste Disposal Site Inventory*. ISBN 0-7729-8409-3.
5. The Ontario Geological Survey. 2003. *Surficial Geology of Southern Ontario*.
6. MNRFF Natural Heritage Mapping website: http://www.gisapplication.lrc.gov.on.ca/mamnh/Index.html?site=MNR_NHLUPS_NaturalHeritage&viewer=NaturalHeritage&locale=en-US

10.0 LIMITATIONS AND USE OF THE REPORT

This report was prepared for the exclusive use of The Sterling Hall School and is intended to provide an assessment of the environmental condition on the Phase One Property located at located at 109 Cartwright Avenue and 130 Bentworth Avenue, Toronto, Ontario.

Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. Terraprobe Inc. accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report, including consequential financial effects on transactions or property values, or requirements for follow-up actions and costs.

The assessment should not be considered a comprehensive audit that eliminates all risks of encountering environmental problems. The information presented in this report is based on information collected during the completion of the Phase One Environmental Site Assessment by Terraprobe Inc. It was based on the conditions on the Phase One Property at the time of the site inspection supplemented by a review of historical information to assess the environmental conditions regarding the Phase One Property, as reported herein.

Sampling and analysis of soil, ground water or any other material was not carried out as part of this assessment. Consequently, the presence and/or extent of any adverse environmental impact cannot be verified. The potential for environmental liability and/or environmental impact is an opinion that has been arrived at within the scope of this assessment.


In assessing the environmental conditions/history of the Phase One Property, Terraprobe Inc. has relied in good faith on information provided by others, as noted in this report, and has assumed that the information provided by those individuals is factual and accurate. Terraprobe Inc. accepts no responsibility for any deficiency, misstatement or inaccuracy in this report resulting from the information provided by those individuals.

There is no warranty expressed or implied by this report regarding the environmental status of the Phase One Property. Professional judgement was exercised in gathering and analysing information collected by our staff, as well as that submitted by others. The conclusions presented are the product of professional care and competence and cannot be construed as an absolute guarantee.

In the event that during future work new information regarding the environmental condition of the Phase One Property is encountered, or in the event that the outstanding responses from the regulatory agencies indicate outstanding issues on file with respect to the Phase One Property, Terraprobe Inc. should be notified in order that we may re-evaluate the findings of this assessment and provide amendments, as required.

FIGURES

TERRAPROBE INC.





Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:

Legend:

Phase One Property Boundary


Project Title:
Phase One Environmental Site Assessment

Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario

Figure Title:
Phase One Property Location

Designed By: OE	***File No.:*** 02210387.000.300
Drawn By: AA	***Scale:*** As Shown
Reviewed By: DM	***Figure No.:*** 1
Date: January 2023	

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02210387.000.300 Phase One.dwg, aalashaab, , DWG To PDF.pc3



Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:

Legend:

	Phase One Property Boundary
T	Transformer
	Suspect Fuel/Oil UST
	Former Fuel Oil and/or Gasoline UST
FL	Former Flammable Storage Room
DT	Former Degreasing Tank
CP	Former Concrete Products Manufacturing
SP	Former Spray Painting
WW	Former Wood Working
DC	Former Dry Cleaning


Project Title:
Phase One Environmental Site Assessment

Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario

Figure Title:
Phase One Property
Historical Site Features

Designed By: OE	***File No.:*** 02210387.000.300
Drawn By: AA	***Scale:*** As Shown
Reviewed By: DM	***Figure No.:*** 2
Date: January 2023	

Y:\Shared\CAT\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02210387.000.300 Phase One.dwg, aalashaab, , DWG To PDF.pc3



Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:

Legend:

- Phase One Property Boundary
- Phase One Study Area, 250m


Project Title:
Phase One Environmental Site Assessment

Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario

Figure Title:
Phase One Study Area

Designed By: OE	***File No.:*** 02210387.000.300
Drawn By: AA	***Scale:*** As Shown
Reviewed By: DM	***Figure No.:*** 3
Date: January 2023	

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A_Dwgs_Logs\AutoCAD\02210387.000.300 Phase One.dwg, aalakhaab, _DWG To PDF.pc3



Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:

Legend:

- Phase One Property Boundary
- Phase One Study Area, 250m
- Residential Property Use
- Community Property Use (Roads)
- Industrial/Commercial Property Use
- ParkProperty Use
- Institutional Property Use

Project Title:
Phase One Environmental Site Assessment

Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario

Figure Title:
Adjacent Property Uses

Designed By: OE	***File No.:*** 02210387.000.300
Drawn By: AA	***Scale:*** As Shown
Reviewed By: DM	***Figure No.:*** 4
Date: January 2023	

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A_Dwgs_Logs\AutoCAD\02210387.000.300 Phase One.dwg, aalakhaab, _DWG To PDF.pc3



Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:

PCA - Potentially Contaminating Activity

Red PCA Causing APEC

Green PCA Not Causing APEC

Legend:

	Phase One Property Boundary
	Phase One Study Area, 250m
	Suspect Fuel/Oil UST
	Former Fuel Oil and/or Gasoline UST
#12	Concrete, Cement and Lime Manufacturing
#27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles
#28	Gasoline and Associated Products Storage in Fixed Tanks
#30	Importation of Fill Material of Unknown Quality
#37	Operation of Dry Cleaning Equipment (where chemicals are used)
#39	Paints Manufacturing, Processing and Bulk Storage
#49	Salvage Yard, including automobile wrecking
#55	Transformer Manufacturing, Processing and Use
NA^1	Waste Generator
NA^2	Ontario Spill
NA^3	De-Icing Activities


Project Title:
Phase One Environmental Site Assessment


Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario


Figure Title:
PCA Locations


Designed By: OE	*File No.:* 02210387.000.300
Drawn By: AA	*Scale:* As Shown
Reviewed By: DM	*Figure No.:* 5
Date: January 2023	


Y:\Shared\CAD\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A_Dwgs_Logs\AutoCAD\02210387.000.300 Phase One.dwg, aallashaab, _DWG To PDF.pc3
























Terraprobe Inc.
Consulting Geotechnical & Environmental Engineering
Construction Materials, Inspection & Testing
11 Indell Lane - Brampton Ontario L6T 3Y3 (905) 796-2650

Reference:
Toronto Maps v2

Notes:
APEC - Area of Potential Environmental Concern

Legend:

- Phase One Property Boundary
- APEC 1,1A - PCA #55, NA[1]
- APEC 2 - PCA #28
- APEC 3 - PCA #12
- APEC 4 - PCA #28
- APEC 5 - PCA #39
- APEC 6 - PCA NA[3]
- APEC 7 - PCA #37
- APEC 8 - PCA #28
- APEC 9 - PCA #28
- APEC 10 - PCA #30

Project Title:
Phase One Environmental Site Assessment

Site Location:
109 Cartwright Avenue and 130 Bentworth Avenue
Toronto, Ontario


Figure Title:
APEC Locations


Designed By: OE	***File No.:*** 02210387.000.300
Drawn By: AA	***Scale:*** As Shown
Reviewed By: DM	***Figure No.:*** 6
Date: January 2023	


Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A. Dwgs, Logs\AutoCAD\02210387.000.300 Phase One.dwg, aalashaab... DWG To PDF.pc3

APPENDIX A

TERRAPROBE INC.




See Detail B
See Detail A
See Detail C
CARTWRIGHT AVENUE
(By Registered Plan 7164)
PIN 10236-0302 (LT)
BENTWORTH AVENUE
(By Registered Plan 7165)
PIN 10236-0277 (LT)
LOT 23
PIN 10236-0299 (LT)
LOT 22
PIN 10236-0300 (LT)
LOT 21
PIN 10236-0301 (LT)
LOT 20
LOT 19
LOT 18
LOT 56
PIN 10236-0280 (LT)
LOT 57
PIN 10236-0279 (LT)
LOT 58
LOT 59
LOT 60
PIN 10236-0278
REGISTERED PLAN 7165
Municipal Number 111
1 Story Building
Municipal Number 109
1 Story Building
Municipal Number 121
1 Story Building
Municipal Number 99
Sterling Hall Boy's School
1 Story Brick Building
Sterling Hall Boy's
School New Addition
Municipal Number 137
1 Story Building
SHED
TRAILER
CONCRETE AREA
Asphalt Speed Bumps
Parking
LAMP POLE
LIGHT POLE
Concrete Curb
Concrete Sidewalk
ASPHALT
CONCRETE WALK
BACK OF CURB
GUTTER
CURB CUT
C/L Of Road
STEPS
RAMP
Detail A
Not To Scale
Detail B
Not To Scale
Detail B
Not To Scale
N72°35'20"E (P2&Meos)
N72°25'20"W (P3&Meos)
N72°25'40"W (P4&Meos)
N72°23'40"W (P1&Meos)
22.86 (P4&Set)
45.72 (P4&Meos)
137.11 (Meos) 137.16 (P2)
177.41 (P3&Meos)
177.39 (P4)
88.74 (P4 Prop&Meos)
88.72
30.33(P2&Meos)
24.39 (P4&Meos)
26.16 (P3&Meos)
182.85 (P3&Meos)
411.96 (P3&Meos)
SIB (P2)
IB
IP
CB
MH
HP
SIGN
CLF
POST
CONC
TRE(D)=0.30
TRE(D)=0.20
TRE(D)=4.00
TRE(D)=0.40
TRE(D)=0.60
TRE(D)=0.80
TRE(D)=1.00
TRE(D)=1.20
TRE(D)=1.40
TRE(D)=1.60
TRE(D)=1.80
TRE(D)=2.00
TRE(D)=2.20
TRE(D)=2.40
TRE(D)=2.60
TRE(D)=2.80
TRE(D)=3.00
TRE(D)=3.20
TRE(D)=3.40
TRE(D)=3.60
TRE(D)=3.80
TRE(D)=4.00
TRE(D)=4.20
TRE(D)=4.40
TRE(D)=4.60
TRE(D)=4.80
TRE(D)=5.00
TRE(D)=5.20
TRE(D)=5.40
TRE(D)=5.60
TRE(D)=5.80
TRE(D)=6.00
TRE(D)=6.20
TRE(D)=6.40
TRE(D)=6.60
TRE(D)=6.80
TRE(D)=7.00
TRE(D)=7.20
TRE(D)=7.40
TRE(D)=7.60
TRE(D)=7.80
TRE(D)=8.00
TRE(D)=8.20



SKETCH SHOWING TOPOGRAPHIC FEATURES

LOTS 18 TO 21 AND 57 TO 60 REGISTERED PLAN 7165

CITY OF TORONTO

(FORMERLEY CITY OF NORTH YORK)

SCALE 1 : 300

5 0 5 10 20 metres

J.D. BARNES LIMITED

METRIC DISTANCES AND/OR COORDINATES SHOWN ON THIS PLAN ARE IN METRES AND CAN BE CONVERTED TO FEET BY DIVIDING BY 0.3048.

CAUTION

TOPOGRAPICAL INFORMATION ON THIS SKETCH HAS BEEN COMPILED FROM THREE PREVIOUS TOPOGRAPHICAL SURVEYS COMPLETED BY J.D. BARNES DATED: FEBRUARY 2005, OCTOBER 2014 & OCTOBER 2018

PREVIOUS SURVEYS WERE NOT FIELD VERIFIED, AND MAY NOT REPRESENT CURRENT SITE CONDITIONS. SITE CONDITIONS SHOULD BE VERIFIED WITH A CURRENT SURVEY, PRIOR TO RELYING ON THIS SURVEY FOR ANY PURPOSES.

NOTES

DISTANCES SHOWN ON THIS PLAN ARE GROUND AND CAN BE CONVERTED TO GRID BY MULTIPLYING BY THE COMBINED SCALE FACTOR 0.999889

ELEVATIONS

ELEVATIONS SHOWN ON THIS PLAN ARE RELATED TO GEODETIC DATUM AND ARE DERIVED FROM THE CITY OF TORONTO (NORTH YORK) BENCH MARK NY 18019 HAVING A PUBLISHED ELEVATION OF 184.299 METRES.

LEGEND

□	DENOTES SURVEY MONUMENT SET
■	DENOTES SURVEY MONUMENT FOUND
□ ✳	DENOTES UNABLE TO SET SURVEY MONUMENT DUE TO SITE CONDITIONS
SIB	DENOTES STANDARD IRON BAR
SSIB	DENOTES SHORT STANDARD IRON BAR
IB	DENOTES IRON BAR
CC	DENOTES CUT CROSS
CA	DENOTES CUT ARROW
CP	DENOTES CONCRETE PIN WITH OLS IDENTIFICATION WASHER
Wit	DENOTES WITNESS
NI	DENOTES NOT IDENTIFIED
Prop	DENOTES PROPORTION
M	DENOTES METER
P1	DENOTES PLAN OF SURVEY W.S. GIBSON & SONS, SEPT 27, 1969
P2	DENOTES PLAN BA-511
P3	DENOTES PLAN BA-515
P4	DENOTES PLAN 7165
□ CB	DENOTES SINGLE CATCHBASIN
G METER	DENOTES GAS METER
GV	DENOTES GAS VALVE
STM MH	DENOTES STORM MANHOLE
H	DENOTES FIRE HYDRANT
WV	DENOTES WATER VALVE
BOL	DENOTES BOLLARD
HP	DENOTES HYDRO POLE
TP	DENOTES TELEPHONE POLE
FP	DENOTES STEEL FENCE POST
CLF	DENOTES CHAIN LINK FENCE
AE	DENOTES EDGE OF ASPHALT
HT	DENOTES HYDRO TRANSFORMER
HTC	DENOTES HYDRO TRANSFORMER CONNECTION
183.00	DENOTES CURRENT J.D. BARNES TOPOGRAPHIC SURVEY DATA
183.48	DENOTES J.D. BARNES TOPOGRAPHIC SURVEY DATED OCTOBER 21st 2014
183.45	DENOTES J.D. BARNES TOPOGRAPHIC SURVEY DATED FEBRUARY 10, 2005

SURVEYOR'S CERTIFICATE

I CERTIFY THAT:

THE SURVEY WAS COMPLETED ON 28th OF SEPTEMBER 2018.

DATE

GREGORY MCDONALD
ONTARIO LAND SURVEYOR

J.D.BARNES LIMITED
LAND INFORMATION SPECIALISTS
SURVEYING MAPPING GIS
140 RENFREW DRIVE, SUITE 100, MARKHAM, ON L3R 6B3
T: (905) 477-3600 F: (905) 477-3882 www.jdbarnes.com

DRAWN BY:	CHECKED BY:	REFERENCE NO.:
SSM	GM	14-15-010-02

FILE: G:\Surveys\14-15-010(Sterling Hall)\02 (add parcel TARPD)\dwg\14-15-010-02-A.dgn

PLOTTED: 10/30/2018

APPENDIX B

TERRAPROBE INC.




TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY
(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)

Project # 2210387
Address 109 Cartwright Ave., Toronto
Description Lot 21, Plan 7165
Pin 10236-0301 (LT)

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
2007 to Present	109 Cartwright Avenue Limited	Inferred Commercial Use	Commercial	Current use today from Site Visit
1976 to 2007	Dufferin Ranee Investments Limited	Inferred Commerical use		City directories indicate commerical tenants
1969 to 1976	Gordon Saltzman and Samuel Silverstein			
1962 to 1969	Dufferin Ranee Investments Limited	Inferred Industrial use	Industrial	City directories indicate industrial tenant
1954 to 1962	James Primavera	Inferred Agricultural or Other		1961 FIP depicts industrial building
1943 to 1954	Eleanor J. Murphy		Agricultural or Other	Aerial photographs depict vacant, agricultural land
1943 to 1943	Benjamin Cooper			Chain of Title
1936 to 1943	Thomas A. Russell			
1936 to 1936	Willam Henry Clarke			
1935 to 1936	Park Home Site Company Limited			
1904 to 1935	William Henry Clarke			
1856 to 1904	William Clarke			
1856 to 1856	Thomas Goulding Jr.			
1836 to 1856	Thomas Goulding Sr.			
Before 1838	Crown Land			

Notes:

SI is satellite imagery

AP is aerial photograph

CD is city directory

FIP is fire insurance plan

HM is Historic Map

OBM is Ontario Base Map

For each owner, specify one of the following types of Property Use (as defined in O.Reg. 153/04) that applies:

Agriculture or Other, Commercial, Community, Industrial, Institutional, Parkland, Residential

TABLE OF CURRENT AND PAST USES OF THE PHASE ONE PROPERTY
(Refer to clause 16(2)(b), Schedule D, O. Reg. 153/04)


Project # 2210387
Address 130 Bentworth Ave., Toronto
Description Lot 57, Plan 7165
Pin 10236-0279 (LT)


Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
2019 to Present	The Sterling Hall School	Vacant, Commerical lot	Commercial	Current use today from Site Visit
2006 to 2019	130 Bentworth Avenue Limited	Inferred Commerical use		City directories indicate commerical tenants
2005 to 2006	Israel Wagner			
1957 to 2005	Issac Wagner, Gertrude Wagner and Yechezkel Wagner	Inferred Industrial use	Industrial	1961 FIP depicts industrial building
1952 to 1957	De Carlo Brothers Limited	Inferred Agricultural or Other	Agricultural or Other	Aerial photographs depict vacant, agricultural land
1947 to 1952	Winifred E. Newnham			Chain of Title
1944 to 1947	Henry J. Ponsfield			
1943 to 1944	Benjamin Cooper			
1936 to 1943	Thomas A. Russell			
1904 to 1935	William Henry Clarke			
1850 to 1904	William Clarke			
1815 to 1850	Robert Clarke			
Before 1815	Crown Land			

Notes:
SI is satellite imagery
AP is aerial photograph
CD is city directory
FIP is fire insurance plan
HM is Historic Map
OBM is Ontario Base Map
For each owner, specify one of the following types of Property Use (as defined in O.Reg. 153/04) that applies:
Agriculture or Other, Commercial, Community, Industrial, Institutional, Parkland, Residential

APPENDIX C

TERRAPROBE INC.





opta
INFORMATION INTELLIGENCE

enviroscan





An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

Midori

Site Address:

130 Bentworth Ave. & 109 Cartwright Ave., North York, ON

Project No:

22113000820

Opta Order ID:

120581

Requested By:

Eleanor Goolab
ERIS

Date Completed:


12/9/2022 5:48:13 PM

ENVIROSCAN Report

Search Area: 130 Bentworth Ave. & 109 Cartwright Ave., North York, ON

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Opta Historical Environmental Services Enviroscan™ Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

Report Index

Page **Report Title**

5 (1995) Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7 Reference No: 10118574 (distance = 80 metres*)
17 (1998) Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7 Reference No: 10118574 (distance = 80 metres*)
39 (1964) Siteplan Report - 1964 I. WAGNER CO. LTD. 130 Bentworth Avenue North York Township ON M6A1P7 (distance = 0 metres*)
41 (1983) Siteplan Report - 1983 I. WAGNER CO. LTD. 130 Bentworth Avenue North York ON M6A1P7 (distance = 0 metres*)
43 Siteplan Report - 19?? 130 Bentworth Avenue North York ON M6A1P7 (distance = 0 metres*)
45 (1981) Inspection Report - 1981 FURNITURE GUILD 109 Cartwright Avenue North York ON M6A1V4 (distance = 0 metres*)
54 (1969) Siteplan Report - 1969 FURNITURE GUILD 109 Cartwright Avenue Borough of North York (Toronto) ON M6A1V4 (distance = 0 metres*)
56 (1996) Inspection Report - 1996 DUFFERIN-RONCE INVESTMENTS LTD 109 Cartwright Avenue Toronto ON M6R1V4 (distance = 0 metres*)
66 (1981) Siteplan Report - 1981 FURNITURE GUILD 109 Cartwright Avenue North York ON M6R1V4 (distance = 0 metres*)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10118574

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

Ontario Branch
Confidential Report

MULTIRISK SURVEY

Insured:	GRAPHIC IMPRINT
Location Surveyed:	130 BENTWORTH AV NORTH YORK, ONTARIO M6A 1P7
Person Contacted:	Mr. Silvestein
Telephone Number:	( ) -
Policy Number:	CMC0220670
AIS Reference:	10118574
Surveyed by:	Ravi Khanna
Date of Survey:	1995.11.27

Committed to Service Excellence

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10118574

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

NOTE: The sole purpose of this report is to provide insurance pricing and underwriting information about the particular insured and location named. Only the person requesting this survey will receive a copy of the report, and IAO asks that it be kept strictly confidential. This report does not guarantee compliance with any standards or with any federal, provincial or municipal codes, ordinances or regulations. Tests of fire and other protection equipment have not been conducted or witnessed during this survey.

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from a survey of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications, referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the services being provided.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

1995

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

M U L T I R I S K - F I R E, L I A B I L I T Y A N D
B A S I C C R I M E

OCCUPANCY:

The insured is a tenant at this location. They have been in operation since 1987 and at this location for 8 year(s). They occupy 130 sq. m and are not the major occupant, having 1 employee. The premises are in good condition. The insured is interested in loss prevention, however there have been losses during the last 3 years.

* Loss History

Magnesium dust created by a table saw used for cutting magnesium dies used in embossing ignited causing fire and approximately $2,000 damage. Insured now keeps a pail of water nearby and has also reduced this operation.

* Occupancy Description (Insured / major tenant if insured is non-occupant)

Printer. Insured uses an offset printing press, hot foil stamping and embossing machines. Premises are well setup. A single saw is used for cutting magnesium embossing dies to size. Waste rags are disposed off in open metal pails. (Rec. Made). One 20l can of Varn Wash V133 (F.P 108 deg F) is stored in original metal container.

* Other Classes of Occupants

Plumber, wine storage warehouse, woodworker and drycleaner.

* Undersirable Features

1. Non standard disposal of waste rags.

It is recommended that this location be resurveyed in 1 year(s).

BUILDING:

* Built - 1960 (est.) Height: Storey(s) (excluding basement) - 1 and 2
* Addition(s) - 1976
* There are no renovations.
* Building condition - Good

* Area: Ground Floor - 1907 sq. m Total (including basement) - 2474 sq. m

---

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

1995

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

BASIC CONSTRUCTION:

* Walls - 80% Masonry - Concrete blocks
  20% Wood Frame - Wood frame metal clad

* Floors - (excluding basement) 80% Concrete; 20% Wood joist

* Roof - 80% - Wood joist
  - Surface material(s) - Tar and gravel
  - Roof replaced, unable to determine when.
  - 20% - Steel deck
  - Surface material(s) - Tar and gravel
  - Roof replaced, unable to determine when.

INTERIOR FINISH:

* Walls - 80% non-combustible
  - 20% open

* Ceilings - 50% non-combustible
  - 50% open

BASEMENTS: None

VERTICAL OPENINGS:

* Stairs - Non-fire rated enclosure

MEZZANINE: None

OUTBUILDINGS: None

HEATING:

* Hot Water/Steam - 80% - Natural gas
  - Original installation.
  - Installation appears safe

* Forced Warm Air - 20% - Natural gas
  - Original installation.
  - Installation appears safe

* Heating appliances - All enclosed in a separate room
* Combustible materials - Not stored in this room at time of survey

* Fuel Tanks/Supply:
  - Supply - UG Natural Gas Connection

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

---

* Chimneys:
  - Masonry - Standard
  - ULC Factory Built - Standard

ELECTRICAL:

* Condition - Good and appeared safe at the time of the survey.
* Wiring - Conduit, BX
* Overcurrent protection - Circuit Breakers, Ordinary Fuses.
* Electrical system - Original installation.

PLUMBING:

* Condition - Good at the time of the survey.
* Piping is Copper
* Plumbing - Original installation.

EXPOSURES: (within 15m of the risk):

* LEFT: TO TENANT
  Construction - Masonry.
  Occupancy - Woodworker.
  Distance - 0 m Height - 2 storeys
  Protection - Automatic Sprinklers Grading - Severe

* REAR: TO TENANT
  Construction - Masonry.
  Occupancy - Dry cleaner.
  Distance - 0 m Height - 1 storeys
  Protection - Automatic Sprinklers Grading - Moderate

* FRONT: OPEN

* RIGHT: OPEN

MUNICIPAL PROTECTION:

* The FUS Public Fire Protection Classification is 2
* Responding (career) fire department North York
* Distance from risk Less than 2.5 km
* Access via Paved roads. Year-round.

* The building itself is easily accesible to the fire department.
* Two hydrants within 155m (standard)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

PRIVATE PROTECTION at this location includes the following:

* Standard extinguishers; Automatic sprinkler (The sprinkler system was neither tested nor evaluated during this survey, a sprinkler survey is available upon request)

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

M U L T I R I S K - L I A B I L I T Y

OCCUPANCY - GENERAL INFORMATION

* Neighbourhood is predominantly industrial
* Insured - tenant Area occupied - 180 sq. m
* % accessible to the public could not be determined
* Gross revenue - could not be determined at the time of the survey

---

PREMISES information at the time of this survey

* The following appeared to be SATISFACTORY:

  Stairs, ramps, handrails; Floor surfaces & coverings; Wall & ceilings; Inerior Lighting; Exterior Lighting; Emergency Lighting; Interior Housekeeping; Exterior Housekeeping; Washrooms; Sidewalks, Yards & Parking Lots; Snow & ice removal; Signs & Awnings; Fire exits

* Elevating devices in operation - none

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

1995

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

M U L T I R I S K - B A S I C C R I M E

NEIGHBOURHOOD:

* Predominantly industrial
* Stable
* Best described as having a low crime rate

BUSINESS:

* Description - Custom printer
* Hours of Operation - 9:00am-5:00pm Mon-Fri
* Typical Stock - Paper, inks.
* Smash and Grab exposure is low
* There is no safe on the premises

GENERAL PROTECTION at the time of this survey:

* The following appeared to be SATISFACTORY:

  Exterior Lighting, Interior Lighting, Roof Accessability, Target stock protection, Police Patrols

* Security Alarm System - None

PHYSICAL PROTECTION (TENANT or OWNER/OCCUPANT):

* The exterior locks at this location are deadbolt, spring
* The windows are barred

This report section is designed to provide basic crime information only. More detailed crime information can be obtained by ordering an Expanded Crime Supplement.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

1995

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

M U L T I R I S K - S P R A Y A P P L I C A T I O N S

OCCUPANCY:

Principal occupancy at this location is Woodworker

* Product(s) Applied: - Paint
* Applied in: - Booth
* Construction: - Prefabricated
* Floor Construction: - Concrete
* Spray area: - Standard
* Frequency of use: - Moderate
* Work done: - Only in intended area

EQUIPMENT:

* Compressed air spray gun

VENTILATION:

* Ventilation - suitable for this installation
* Filtering system - Dry filter
* Filtering system - Well maintained.
* Ventilation motor - Non-sparking and labelled
* Exhaust duct - Suitable

ELECTRICAL:

* Electrical equipment located inside the spray area - None
* Electrical equipment located outside the spray area - Non-Standard
* Lighting fixtures are labelled
* At time of survey, lighting fixtures appeared to be in good repair
* Lighting deficiencies - None

DRYER INSTALLATION:

* No dryers were found

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

HAZARDS:

* Storage of flammable and combustible liquid is non-standard

* Flammable and combustible liquids storage
  - In the open
  - Outside spray area
* Labelled safety cans not used
* Handling - Unsafe

* Quantity in spray area - 0 litres.
* Quantity outside spray area - 400 litres.

* As a result of survey, the following were found to be satisfactory:

  Storage of dirty rags in safety containers; Restriction of smoking; Posting of no smoking signs; Heating equipment a sufficient distance from spray area; Spray area is not highly congested

* As a result of survey the following were found needing attention, please refer to the remarks and recommendations for further details:

* Maintenance - Good

PROTECTION:

* Portable fire extinguishers - Suitable
  - Well located
* Automatic fixed extinguishing system - None
* Automatic sprinklers - In the booth or room

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

1995

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

GRAPHIC IMPRINT
130 AV BENTWORTH; NORTH YORK, ONTARIO

M U L T I R I S K
R E M A R K S / R E C O M M E N D A T I O N S

REMARKS:

* Fire, Liability & Basic Crime - Premises are located east of Dufferin Street and south of Hwy 401 in Downsview. There are several tenants in this building and insured is located at one of the rear units. Most tenants areas are separated by gypsum board partition walls and a common hallway extends from the front of the building to the rear separating tenants on both sides. Insured was cooperative and appeared interested in loss control.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Multirisk Report - 1995 GRAPHIC IMPRINT 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

RECOMMENDATIONS:

* 95-1 Fire, Liability & Basic Crime - All rags soaked with oil or flammable liquids should be kept in ULC or equivalent labelled safety containers.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



enviroscan
OPTA INFORMATION INTELLIGENCE

1998

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574FF>

AIS Reference: 10118574 LETTER OF RECOMMENDATION Page 1

CRRS
INSURERS' ADVISORY ORGANIZATION INC.
Ontario

CONFIDENTIAL

ADDRESS OF RISK:

130 BENTWORTH AV

TORONTO, ON
M6A 1P7

NAME OF BUILDING OWNER:
I. Wagner Co. Ltd.

MAILING ADDRESS:

130 BENTWORTH AV

TORONTO, ON
M6A 1P7

CONTACT(S):
Erin Brown, Manager

AIS REFERENCE: 10118574

IAO FILE NO.: SR06055

SURVEY DATE: 1998-Nov-25

SPRINKLERED RISK: Yes

NO. OF FIRE DIVISIONS: 1

RISK SURVEYED BY:
Ronald W. Roy

(905) 263-4553

SURVEY-FIRE AND EXTENDED COVERAGE INSURANCE

The survey of the above property was made on behalf of participating insurance companies. The information gathered on this survey is used by these insurers to aid in deciding whether to underwrite the risk, and if so, at what cost.

The following comments were developed from this survey, and are based on conditions, practices observed, other pertinent data supplied by management personnel at the risk, and information secured at the time of the survey.

Please note that the following recommendations have been made with the intention of pointing out those areas in which remedial action could have the beneficial effect of making your premises safer.

PLEASE NOTE THAT RECOMMENDATIONS HIGHLIGHTED WITH '***', THREE ASTERISKS ARE OF PARTICULAR IMPORTANCE, AND THEIR EARLY IMPLEMENTATION IS ENCOURAGED.

Thank you for your co-operation during this visit, and please do not hesitate to get in touch with us if we can be of any further assistance.

_____

Ronald W. Roy,
Representative

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

REMARKS

[ENTIRE SURVEY]
(98/11) This is the first survey by this organization since November 27,1995.

(98/11) There was no one available to test the sprinkler system at the time of survey . The system was inspected however and was found in order with the control valve in the open position . The system has been converted to a dry pipe system .

(98/11) There have been tenant changes . Recommendations to previous tenants have been deleted .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

RECOMMENDATIONS

[ENTIRE SURVEY]
** (98/11)-98 The missing fire department pumper caps should be replaced as soon as possible .

** (98/11)-98 The dry pipe sprinkler valve(s) , as well as associated equipment such as quick opening devices , should be trip tested regularly in accordance with NFPA Standard No . 13A "Inspection Testing and Maintenance of Sprinkler Systems , and the local Fire Code .

[PROMPT COURIER INC.]
** (98/11)-98 Distribution of ULC labelled extinguishers should be on a basis of one "2A" rated unit for each 278.7 sq m (3,000 sq ft) or on each floor of each building, to protect both combustibles and combustible building structures; supplemented by Class "B,C" rated units where oil or electrical fire hazards may exist in accordance with NFPA Standard No. 10, "Portable Fire Extinguishers". In this case, no extinguisher should be provided.

[COZY COMFORT PLUS]
** (98/11)-98 Standard automatic sprinkler protection should be extended to protect the (20'x20') office area .

[HANCOCK CREATIONS]
** (98/11)-98 All flammable liquids should be stored in a ULC labelled metal cabinet which should be equipped and constructed in accordance with NFPA Standard No. 30, "Flammable and Combustible Liquids Code".

NOTE: Not more than three (3) such cabinets should be located in a single fire area unless provided with a separation of at least 30.5 m (100 ft).

** (98/11)-98 A well designed dust collection system exhausting to an outdoor ground level cyclone and bin of non-combustible construction should be installed on all dust producing equipment in accordance with NFPA Standard No. 664, "Fires and Explosions in Wood Processing and Woodworking Facilities".

** (98/11)-98 A safe designated area for smoking should be established and be provided with an adequate supply of safety ash receptacles and fixed lighters.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

AIS Reference: 10118574 LETTER OF RECOMMENDATION Page 4

** (98/11)-98 Standard automatic sprinkler protection should be provided throughout the spray booth and its associated exhaust plenum and ductwork with sprinklers under the control of a separate easily accessible ULC labelled OS&Y indicating valve.

NOTE:
1. Sprinklers should be installed on an Extra Hazard occupancy spacing of 8.361 sq m (90 sq ft).

2. Sprinklers temperature rated for 91.74 Deg C (165 Deg F).

3. All sprinklers should be automatic operating including duct sprinklers. Dry pendent sprinklers can be used for protection in ducts if they are subject to freezing.

4. Protection should be provided by a wet-type sprinkler system as the operation of a dry pipe system is considered too slow for this application.

5. Sprinklers protecting spray areas should be protected against overspray residue with thin plastic or paper bag coverings to ensure quick operation.

[N.M.GRAFSTEIN SACRAMENTAL]
** (98/11)-98 Standard automatic sprinkler protection should be extended to protect the (15'x30') metal cooler .

c

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

AIS Ref No.: 10118574

1998

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

CRRS
INSURERS' ADVISORY ORGANIZATION INC.
Ontario

CONFIDENTIAL

ADDRESS OF RISK:
130 BENTWORTH AV

TORONTO, ON
M6A 1P7

NAME OF BUILDING OWNER:
I. Wagner Co. Ltd.

MAILING ADDRESS:
130 BENTWORTH AV

TORONTO, ON
M6A 1P7

CONTACT(S):
Erin Brown, Manager

AIS REFERENCE: 10118574

IAO FILE NO.: SR06055

SURVEY DATE: 1998-Nov-25

SPRINKLERED RISK: Yes

NO. OF FIRE DIVISIONS: 1

RISK SURVEYED BY:
Ronald W. Roy

(905) 263-4553

SURVEY-FIRE AND EXTENDED COVERAGE INSURANCE

The survey of the above property was made on behalf of participating insurance companies. The information gathered on this survey is used by these insurers to aid in deciding whether to underwrite the risk, and if so, at what cost.

The following comments were developed from this survey, and are based on conditions, practices observed, other pertinent data supplied by management personnel at the risk, and information secured at the time of the survey.

Please note that the following recommendations have been made with the intention of pointing out those areas in which remedial action could have the beneficial effect of making your premises safer.

PLEASE NOTE THAT RECOMMENDATIONS HIGHLIGHTED WITH '***', THREE ASTERISKS ARE OF PARTICULAR IMPORTANCE, AND THEIR EARLY IMPLEMENTATION IS ENCOURAGED.

Thank you for your co-operation during this visit, and please do not hesitate to get in touch with us if we can be of any further assistance.

Ronald W. Roy,
Representative

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- OVERVIEW ---

This is a one and part two storey concrete block /class 2 metal deck (20%) and wood joist (80%) multiple tenant industrial building with concrete on grade floors and wood joist second floor built in 1960 (est.) with a major addition in 1976 and in good repair.The building is in one fire division.

Building heat is provided by well arranged natural gas fired roof mounted , combination heating /air conditioning units, and a safely arranged natural gas fired hot water boiler in a shut off room .

Electrical equipment is standard for occupancy.Wiring is in rigid conduit, and BX cable protected by circuit breaker panels.

External building exposures are moderate from a masonry industrial building located 33.55 m (110 ft) west . There are no other exposures within 45.75 m (150 ft) .

This is a multiple tenant building consisting of tenant offices on the second floor , a woodworker , storage of grape juice , job printer , a dry cleaner and foil stamping on the first floor .

Standard automatic dry pipe sprinkler protection has been provided with local alarms only .

There is a standard water supply consisting of a single 152.4 mm (6 in) underground connection to a 304.8 mm (12 in) street main at a static pressure of 448.5 kPa (65 psi) .

There is a nonstandard distribution of ULC labelled fire extinguishers.

Hydrant protection is standard from public hydrants.

The area is served by the career Toronto Fire Department

Access to the property is good.

The FUS grading for this area is 03

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

REMARKS

[ENTIRE SURVEY]
(98/11) This is the first survey by this organization since November 27,1995.

(98/11) There was no one available to test the sprinkler system at the time of survey . The system was inspected however and was found in order with the control valve in the open position . The system has been converted to a dry pipe system .

(98/11) There have been tenant changes . Recommendations to previous tenants have been deleted .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

RECOMMENDATIONS

[ENTIRE SURVEY]
** (98/11)-98 The missing fire department pumper caps should be replaced as soon as possible .

** (98/11)-98 The dry pipe sprinkler valve(s) , as well as associated equipment such as quick opening devices , should be trip tested regularly in accordance with NFPA Standard No . 13A "Inspection Testing and Maintenance of Sprinkler Systems , and the local Fire Code .

[PROMPT COURIER INC.]
** (98/11)-98 Distribution of ULC labelled extinguishers should be on a basis of one "2A" rated unit for each 278.7 sq m (3,000 sq ft) or on each floor of each building, to protect both combustibles and combustible building structures; supplemented by Class "B,C" rated units where oil or electrical fire hazards may exist in accordance with NFPA Standard No. 10, "Portable Fire Extinguishers". In this case, no extinguisher should be provided.

[COZY COMFORT PLUS]
** (98/11)-98 Standard automatic sprinkler protection should be extended to protect the (20'x20') office area .

[HANCOCK CREATIONS]
** (98/11)-98 All flammable liquids should be stored in a ULC labelled metal cabinet which should be equipped and constructed in accordance with NFPA Standard No. 30, "Flammable and Combustible Liquids Code".

NOTE: Not more than three (3) such cabinets should be located in a single fire area unless provided with a separation of at least 30.5 m (100 ft).

** (98/11)-98 A well designed dust collection system exhausting to an outdoor ground level cyclone and bin of non-combustible construction should be installed on all dust producing equipment in accordance with NFPA Standard No. 664, "Fires and Explosions in Wood Processing and Woodworking Facilities".

** (98/11)-98 A safe designated area for smoking should be established and be provided with an adequate supply of safety ash receptacles and fixed lighters.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

AIS Ref No.: 10118574

AIS Reference: 10118574 Sprinkler Report Page 5

** (98/11)-98 Standard automatic sprinkler protection should be provided throughout the spray booth and its associated exhaust plenum and ductwork with sprinklers under the control of a separate easily accessible ULC labelled OS&Y indicating valve.

NOTE:
1. Sprinklers should be installed on an Extra Hazard occupancy spacing of 8.361 sq m (90 sq ft).

2. Sprinklers temperature rated for 91.74 Deg C (165 Deg F).

3. All sprinklers should be automatic operating including duct sprinklers. Dry pendent sprinklers can be used for protection in ducts if they are subject to freezing.

4. Protection should be provided by a wet-type sprinkler system as the operation of a dry pipe system is considered too slow for this application.

5. Sprinklers protecting spray areas should be protected against overspray residue with thin plastic or paper bag coverings to ensure quick operation.

[N.M.GRAFSTEIN SACRAMENTAL]
** (98/11)-98 Standard automatic sprinkler protection should be extended to protect the (15'x30') metal cooler .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- OVERVIEW OF FIRE DIVISION ---

FIRE DIVISION: 1 - Entire building

IBC Ind Code: 3991
Construction: 4 Masonry

Single fire division

--- OCCUPANTS IN FIRE DIVISION ---

1. Good Housekeeping with standard supply of portable fire extinguishers is to be assumed for all occupants unless otherwise stated.

2. If the Fire Division is sprinklered, then the overall grading of sprinklers and water supplies to all occupants is equal to that of the Fire Division grading, unless otherwise stated.

[1] OCCUPANT 1 - Prompt Courier Inc., unit 200
IBC Ind Code: - [6610] Office Tenants - N.O.C.
AREA: 56 sq.m.

The insured operates a communications office for voice contact with independent broker courier services . The insured indicates to field services where to pick up and deliver letters or parcels . Operations appear well arranged with good housekeeping . The insured may occasionally store some customer's goods in the warehouse area of another tenant on the first floor . There was no fire extinguisher available at the time of survey (rec. made) .

[2] OCCUPANT 2 - Tenant offices, second floor
IBC Ind Code: - [6610] Office Tenants - N.O.C.
AREA: 557 sq.m.

Approximately 12 separate tenant offices appear well arranged . Several were locked at the time of survey .

[3] OCCUPANT 3 - Cozy Comfort Plus, First floor
IBC Ind Code: - [5151] Furniture, Antiques
AREA: 223 sq.m.

Small office area and warehouse for storage of furniture . Stock appears well arranged in cartons on pallets up to a height of 1.83 m (6 ft) . There is an unsprinklered (20 x 20) office (rec. made) . No unusual features .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



1998

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

[4] OCCUPANT 4 - The Golden Imprint, First floor (rear)
IBC Ind Code: - [2750] Commercial Printing, Publishing, Electro-typing
AREA: 130 sq.m.

Job printer using several offset presses with foil stamping and embossing . A small amount of blanket wash is safely stored in the open . Soiled rags are stored in a metal container with a lid . Customers paper goods are safely stored in the open on pallets .

[5] OCCUPANT 5 - Hancock Creations, first floor (rear)
IBC Ind Code: - [2490] Wood Product N.O.C.
AREA: 306 sq.m.

Woodworker manufacturing display cabinets . There are less than 5 major pieces of machinery connected occasionally to a portable dust collector . Housekeeping is poor and there is evidence of extensive smoking (rec. made) . Paint spraying is carried out in a partially sprinklered standard metal spray booth (rec. made) . Approximately 380 L (100 US gal) of paint and stain is unsafely stored in the open (rec. made).

[6] OCCUPANT 6 - N.M.Grafstein Sacramental, first floor
IBC Ind Code: - [5061] Non-Alcoholic Beverages
AREA: 446 sq.m.

Wholesale storage and distribution of sacramental grape juice in cartons on pallets on the floor up to 1.83 m (6 ft) high over an area of (30'x60') . There is an unsprinklered metal lined cooler (15'x30') (rec. made) .Operation appears well arranged with good housekeeping .

[7] OCCUPANT 7 - Presidential Dry Cleaners, first floor
IBC Ind Code: - [7220] Laundries, Drycleaners, Dyers - Other Than Self
AREA: 237 sq.m.

Dry cleaning operations appear well arranged using one dry cleaning machine and several steam presses and irons .There is one Fulton high pressure steam boiler safely arranged in a shut off concrete block room with the opening protected by an unlabelled metal door . Clothes are safely hung on steel rails .

[8] OCCUPANT 8 - Prime Printing, first floor
IBC Ind Code: - [2750] Commercial Printing, Publishing, Electro-typing
AREA: 460 sq.m.

Appears to be a job printer . Access was denied at the time of survey .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- CONSTRUCTION ---

Year Originally Built: 1960
Year of Most Recent Additions: 1976

HEIGHT: 2 Story(ies) (6.1 m. : 20.0 ft.)

none

STATE OF REPAIR:

fair

WALLS:

Masonry
80% Concrete Block (305 mm)

Combustible
20% WFMC Wood Frame/Metal Clad

Types of Walls
100% Independent, Bearing

FLOORS:

Masonry & Fire-Res.
80% Concrete on Grade

Combustible
20% Wood Joist

ROOF:

Non-Combustible
20% Class II Steel Deck

Combustible
80% Wood Joist

Surface
100% Approved

AREA:

Grade - 1,907 sq.m. (20527.4 sq. ft)
Total - 2,474 sq.m. (26630.8 sq. ft)

Seperation Walls: The building is separated by an 203.2 mm (8 in) concrete block wall with unprotected and/or poorly protected openings.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

VERTICAL OPENINGS:

none

Elevators:

none

COMBUSTIBLE INTERIOR CONSTRUCTION:

None

COMBUSTIBLE CONCEALED SPACES:

None

INTERIOR FINISH - Walls:

None

INTERIOR FINISH - Ceilings:

None

COMBUSTIBLE EXTERIOR ATTACHMENTS:

None

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- FIRE HAZARDS ---

COMMON HAZARDS

Heating:

Building heat is safely arranged from natural gas fired hot water boiler located in a separate shut off room and roof mounted , combination heating / air conditioning units.

- 80% Central Heat Boiler
- 20% Central Heat Warm Air Gas

Heating Appliance Installation:

- 0% Replaced, 0, No Deficiencies Noted

Fuel Supply:

- UG Natural Gas Connection
- None

Chimneys & Flues:

Material:	Unlabelled Prefabricated
Condition:	Good
Installation Type:	Standard

Air Conditioning:

Central - approximately 20% of the total building area is air conditioned .

- 20% Central

Electrical:

Safe. Electrical equipment is standard for occupancy.All visible wiring appears to be in good condition.

Wiring:	Conduit, BX
Protection:	Circuit Breakers
Condition:	Good

Plumbing:

Type:	Copper
Condition:	Good

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

SPECIAL HAZARDS:

Unsafe - see occupants

HIGH PILING:

none

HAZARDOUS MATERIAL:

Unsafe - see occupants

HOUSEKEEPING:

Fair to good . See occupants .

EXPOSURES:

West: moderate from a one storey , masonry industrial building located 33.55 m (110 ft) 15.25 m (50 ft) away .
There are no external exposures within 45.75 m (150 ft) east north and south of the risk .

PROCESS DESCRIPTION:

-See Overview of Fire Division.

ACTIVITY:

8 hrs/day , 5 days/wk.

SMOKING RESTRICTED:

Yes . Restricted in the tenant areas .

AUTOMATED EQUIPMENT:

Stand alone personal computers.Further information is available upon request.

NUMBER OF PRODUCTION WORKERS:

See occupants

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- PROTECTION ---

MUNICIPAL PROTECTION:

FUS Classification:	02
Responding Fire Department:	Toronto
Type of Fire Department:	Career
Distance to Fire Hall:	< 2.5 km
Public Hydrants:	Standard
Accesibility:	Good
Congested Area:	No

INTERNAL PROTECTION:

Extinguishers:	Non-Standard

Fire extinguishers were overdue for servicing in some tenant areas .

Standpipe & Hose:	None
Watchman Service:	None
Fire Detection Alarm System:	None

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

1998

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- SPRINKLERED PROTECTION ---

PERCENT SPRINKLERED (excl. concealed spaces):

98% sprinklered

TYPE OF SPRINKLER SYSTEM: 100% - dry pipe

SPRINKLER PROTECTION:

Sprinkler Installation Date: 80% - 1960 ; 20% - 1976

Protection Against Freezing:

Adequate

Additional Sprinkler Protection Required:

Minor unsprinklered areas . See occupants .

Equipment Standard:

yes

Alarms:

The sprinkler system could not be tested at the time of survey and could only be viewed from a distance . It appears that the alarms are local only .

Primary Water Supplies:

Standard single water supply consisting of a 152.4 mm (6 in) connection to a 304.8 mm (12 in) street main fed two ways .Static pressure 448.5 kPa (65 psi) .There was no one available to make a 50.8 mm (2 in) drain test at this survey .

Secondary Water Supplies:

No - not required

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

SPRINKLER PROTECTION DETAILS:

The sprinkler system is installed based on an ordinary hazard pipe schedule , with 12.077 m2 (130 sq ft) spacing using 12.7 mm (.5 in) orifice 73.948 Deg C (165 Deg F) sprinklers which is adequate for the ordinary hazard Group 2 occupancy .

The required water supply for this system is 5700 L/min (1500 US gpm) (37 psi) at the base of the sprinkler riser , including a hose allowance of 1330 L/min (350 US gpm) .

A flow test taken in 1986 at Dufferin Street and Samor Rd.indicates a volume of 8846.4 L/min (2328 US gpm) is available at a pressure of 462.3 kPa (67 psi) with a static pressure of 517.5 kPa (75 psi) . Therefore a standard water supply is available .

Overall Sprinkler Grading:

Fire Division [1]: 83.79 = 98.0 (EF) * 95.0/100 (RF) * 90.0/100 (AT)

EF - Unsprinklered areas
RF - Missing fire department pumper caps
AT - No recent dry pipe valve test

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

OPTA INFORMATION INTELLIGENCE

1998

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- BUSINESS INTERRUPTION ---

This is a multiple tenant building . No unusual features .

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

N
W E
S

ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- ADDITIONAL PERILS ---

WINDSTORM: No unusual features

LIGHTNING FEATURES: No unusual features

EXPLOSION:

SPRINKLER LEAKAGE:

Stock Skidded or Shelved: yes

Stock Susceptible to Large Water Damage: Moderate

Floors Drained: no

SMOKE DAMAGE SUSCEPTIBILITY:

moderate

RIOT, VANDALISM, MALICIOUS ACTS:

Access Restricted: NO

Guard Supervised: NO

Yards Fenced: Partial

Yards Lit: yes

Remote from Populated Areas: no

COLLAPSE: No apparent hazard

FLOOD: No history of flooding in this area .

No apparent hazard

EARTHQUAKE ZONE: 0

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

IMPACT HAZARDS:

By Aircraft:	no
By Road Vehicles:	Unlikely but possible from trucks moving in shipping areas
By Trains:	no
By Floating Vessels:	no

--- CRIME ---

The building is located in a built up industrial area with good exterior lighting .There is no evidence of vandalism in the area and none reported at the risk.Physical protection is provided by single cylinder dead bolts and slide bolts.

Security systems have been provided in some tenant areas.

This section provides basic crime information only. For more detailed information, a comprehensive crime survey may be ordered.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



ENVIROSCAN Report

Inspection Report - 1998 I. Wagner Co. Ltd. 130 BENTWORTH AV TORONTO ON M6A 1P7
Reference No: 10118574

Requested by:
Eleanor Goolab
Date Completed: 12/09/2022 17:48:13

enviroscan
OPTA INFORMATION INTELLIGENCE

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.

--- MANAGEMENT - LOSS PREVENTION PROGRAMMES ---

Basic Fire Protection:	Control Required & Exercised
Self-Inspection:	Control Required & Exercised
Fire Protection Equipment:	Control Required & Exercised
Pre-Emergency Planning:	Control Required & Exercised
Plant Security:	Control Not Required
Private Fire Brigade:	Control Not Required
Smoking Regulations:	Control Required & Exercised
Welding, Cutting and Griding:	Control Required & Exercised
Impariment Notification:	Control Required & Exercised
Preventative Maintenance:	Control Required & Exercised

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.




Siteplan Report - 1964 I. WAGNER CO. LTD. 130 Bentworth Avenue North York Township ON M6A1P7


This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.




REVISED	
DATE	BY


SERIAL NO. 6055





SECTION A—A





SECTION B—B

FILE NO. 6055

I. WAGNER CO. LTD.

NORTH YORK TWP, ONTARIO

SCALE 1" = 50' DATE NOV. 1964 INSP. K. R. R.

CANADIAN UNDERWRITERS' ASSOCIATION
PROVINCE OF ONTARIO BRANCH
PROPERTY DEPARTMENT
SPECIAL RISKS DIVISION
TORONTO, CANADA

PLAN REFERENCE SHEET NO. 1747 BLOCK NO. 174701


Jerome

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Siteplan Report - 1983 I. WAGNER CO. LTD. 130 Bentworth Avenue North York ON M6A1P7


This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.





ELEV. A-A





ELEV. B-B

10118574

FILE NO. SR 6055

I. WAGNER CO. LTD.

130 BENTWORTH AVE.

NORTH YORK, ONTARIO

Sheet: 1747 Block: T74701 Scale: 1" = 50' 1:600

INSURERS' ADVISORY ORGANIZATION

ONTARIO

Date: NOV. 1983 Field Rep.: R. K.


This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Siteplan Report - 19?? 130 Bentworth Avenue North York ON M6A1P7


This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.



SECTION A—A



Inspection Report - 1981 FURNITURE GUILD 109 Cartwright Avenue North York ON M6A1V4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

A11

INSURERS' ADVISORY ORGANIZATION
TORONTO

CONFIDENTIAL

For Use of Members Only
Not For General Distribution

INSPECTION REPORT

File No. SR 7506 (16)

Plan Attached

SPECIAL RISKS DIVISION

SPRINKLER PROTECTION IN SERVICE

NAME OF RISK: Furniture Guild,

LOCATION: 109 Cartwright Avenue, North York, Ontario.

SURVEYED BY: M.A. Pearl DATE: January 20, 1981

OCCUPANCY

1. (a) Showroom for retail furniture sales.

CONSTRUCTION

2. (a) FIRE DIVISIONS: Single Fire Division

(b) BUILT IN: 1960 Additions: 1969

Repair: Good

(c) HEIGHT: 1 Sto.(s) 3.7m, 4.9m (12', 16')

(d) WALLS: (i) Construction: Concrete block

(ii) Type: independent, bearing, non bearing, party. (Other)

(e) FLOORS: Concrete

(f) ROOF: (i) Construction: 52% Class II metal deck on exposed steel; 48% wood joist

(ii) Roof Surface: Non-combustible (Other)

(g) SUPPORTING STEEL: Adequately protected by sprinklers only.

(h) TOTAL GRADE FLOOR AREA: No information available

Total area: 930 sq. m (10,000 sq. ft.)

Separation Walls: No information available

(i) VERTICAL OPENINGS: None
Elevators: None Number of elevators: Freight or passenger

(j) INTERIOR FINISH:

Exterior Walls: No information available

Interior Walls: 76% plasterboard sheathed; 24% open.

Ceilings: 80% non-combustible mineral tile; 20% open.

(k) (i) COMBUSTIBLE CONCEALED SPACES: Minor. 29.3m x 15.3m (96' x 50') by 0.6m (2') deep sprinklered space over the front section of the showroom.

Roof: % Ceiling: %

(ii) NON-COMBUSTIBLE CONCEALED SPACES: Minor. 15.3m x 19.5m (50' x 64') by 1.5m (5') deep unsprinklered space over the rear section of the showroom.

(l) No information available

(m) SMOKE AND HEAT VENTING: Adequate

HAZARDS

3. (a) COMMON HAZARDS:

(i) Heating: The building is heated by three forced air, natural gas-fired ceiling units, venting to type "B" gas vents.

Chimneys and Flues: No information available

(ii) Air Conditioning: None Type Central, Window % Air Conditioned.

(iii) Electrical: Safe Unsafe Circuit breakers Fuses used Wiring installed not updated in Last 30 Years Transformers PCB filled: No. (Other)

(b) SPECIAL HAZARDS: None

(c) RADIOACTIVE MATERIALS: None

(d) HIGH PILING: None

(e) HOUSEKEEPING: Safe

(f) HAZARDOUS MATERIAL: None

(g) EXPOSURES:

		Protection Required	Protection Provided
North	Light	No	No
South	Light	No	No
East	None	No	No
West	Light	No	No

(h) ACTIVITY: Moderate Hrs/Day 9 Days/Wk 6

Number of Production Workers: No information available

(i) MAINTENANCE WELDING: No

(j) SMOKING RESTRICTED: No. Not restricted (considered a minor deficiency).

(k) ELECTRONIC Data Processing Equipment: No

(l) PROCESS DESCRIPTION:

The building is occupied as a showroom and warehouse for retail sales of furniture. No repairs are done on the premises. Furniture in the 12.2m x 15.3m (40' x 50') storage area is skidded and piled 2.4m to 3.1m (8' to 10') high.

PROTECTION

4. (a) SPRINKLER PROTECTION:
OVERALL GRADING OF SPRINKLERS AND WATER SUPPLIES:

(i) Area Sprinklered (excluding concealed spaces): 99%
100% Wet. A 15.3m x 19.5m (50' x 64') by 1.5m (5') deep non-combustible blind space over the rear section of the building is not provided with sprinkler protection (sprinklers are not considered necessary in this area).

(ii) Date of Sprinklers: 100%: 1969

(iii) Protection Against Freezing: No
Sections shut off in winter: No information available
Sections on cold weather system: No information available
Sections subject to freezing
Not adequately protected: No information available

(iv) (a) Additional Sprinklers Required: No

(b) Unsprinklered Areas Not Requiring Sprinklers:
No information available

(v) Sprinkler Equipment Standard: Yes

(vi) Alarms: Inside electric bell and outside water gong only (Recommendation made).

(vii) Water Supplies:

(a) Grading: Standard

(b) Primary: Municipal - Standard

(c) Secondary: Provided - None Required - No

(d) Standard Single Supply: No information available

(viii) Additional system details from a 150mm (6") connection to a 300mm (12") circulating street main. Static pressure 448.5 kPa (65 p.s.i.), residual pressure 414 kPa (60 p.s.i.) with a 50mm (2") drain fully open. This Ordinary Hazard Group 2 occupancy requires a minimum supply of 3230 L/min (850 U.S. g.p.m.) at 262.2 kPa (38 p.s.i.) at grade level.

A flow test done at Bridgeland near Caledonia in 1975 gave the following results:

Static Pressure - 379.5 kPa (55 p.s.i.).

Flow		Residual Pressure
2443.4 L/min (643 U.S. g.p.m.)	at	345 kPa (50 p.s.i.)
4567.6 L/min (1202 U.S. g.p.m.)	at	310.5 kPa (45 p.s.i.)
2840 L/min (1800 U.S. g.p.m.)	at	276 kPa (40 p.s.i.)

Fire Department Pumper Connection: Yes

4. (b) OTHER PROTECTION

(i) Extinguishers: Standard

(ii) Standpipes and Hose: None

(iii) Watchman Service: None

(iv) Special Equipment and Apparatus: None

4. (c) OUTSIDE PROTECTION

(i) Hydrants: Public: Standard

Private: None

Flushed: No information available

(ii) Fire Dept. Public: Paid Distance to Fire Hall 2.4 km (1 1/2 miles)

Private: No

F.U.S. Classification of Municipality: No information available

(iii) Accessibility:

To Property: Good

Into Building: Good

EXTENDED COVERAGE

5. (a) WINDSTORM - Unusual Hazards: No

(b) LIGHTNING: Unusual Features: No

(c) EXPLOSION: Unusual Features: No

(d) SPRINKLER LEAKAGE: Stock Skidded or Shelved: Yes

Stock Susceptible to Large Water Damage:
No information available

Floors Drained: No

(e) RIOT, VANDALISM, MALICIOUS ACTS:
Access restricted: No
Guard Supervised: No
Yards Fenced: No information available
Yards Lit: Yes
Remote from populated areas: No

(f) EARTHQUAKE - Zone: No information available

(g) IMPACT HAZARDS - by aircraft: No information available

- by road vehicles: No information available

- by trains: No information available

- by floating vessels: No information available

(h) FLOOD HAZARDS: No information available

(i) SMOKE - Susceptibility of Stock to Smoke Damage: No information available

(j) COLLAPSE - Susceptibility to Collapse: No information available

6. BUSINESS INTERRUPTION

(a) Seasonal: No

(b) Operation: 9 Hrs/Day 6 Days/Wk.

(c) Interdependency: No

(d) Raw Materials Mainly: Domestic

Stock on hand for: 6-8 weeks

Stock Replacement Time: 2-4 weeks

(e) Computerized Programming: No

(f) Single Train Production:

(g) Vital Machinery Custom Made:

Replacement Time:

(h) Private Power Generation: No

Alternative Power Source: No

(i) Production Dependent on Pollution Control Equipment: No information available

(j) Other Important Features: No

BUSINESS INTERRUPTION DETAILS:

No unusual features.

7.

UNDESIRABLE FEATURES

Prominent: Local alarms only.

Other: None apparent.

8.

MANAGEMENT - LOSS PREVENTION PROGRAMMES

	CONTROL REQUIRED:		CONTROL EXERCISED:
(a) Basic Fire Protection:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(b) Self-inspection:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(c) Maintenance of Fire Protection Equipment:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(d) Pre-emergency Planning:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(e) Plant Security:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(f) Private Fire Brigade:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(g) Smoking Regulations:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(h) Welding, Cutting & Grinding:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)

	CONTROL REQUIRED:		CONTROL EXERCISED:
(i) Impairment Notification:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)
(j) Preventive Maintenance:	Yes,	No,	Satisfactory, Unsatisfactory, (Other)

Comments: No information available

9. TENANTS: None.


MD/mg/03/02/81


Siteplan Report - 1969 FURNITURE GUILD 109 Cartwright Avenue Borough of North York (Toronto) ON M6A1V4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



REVISED	
DATE	BY





FILE NO. 7506

FURNITURE GUILD

BOROUGH OF NORTH YORK (TORONTO) ONTARIO

SCALE 1" = 50' DATE OCTOBER 1969 FIELD REP P.K.B.B.

CANADIAN UNDERWRITERS' ASSOCIATION
PROVINCE OF ONTARIO BRANCH
PROPERTY DEPARTMENT
SPECIAL RISKS DIVISION
TORONTO

PLAN REFERENCE SHEET NO. 1747 BLOCK NO. 17474701

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

Inspection Report - 1996 DUFFERIN-RONCE INVESTMENTS LTD 109 Cartwright Avenue Toronto ON M6R1V4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

CONFIDENTIAL

LOSS CONTROL ENGINEERING DEPARTMENT

Ontario

INSURED:	Dufferin-Ronce Investments Ltd	06 November 2008
	109 Cartwright Avenue Toronto, Ontario M6R 1V4	File No. SR07506 Reference 011951
MAILING ADDRESS:	109 Cartwright Avenue Toronto, Ontario M6R 1V4	
CONTACT:	Mr Gordon Saltzman, Owner	

SURVEY-FIRE AND EXTENDED COVERAGE INSURANCE

The survey of the above property on December 13 1996 was made on behalf of participating insurance companies. The information gathered on this survey is used by these insurers to aid in deciding whether to underwrite the risk, and if so, at what cost.

The following comments were developed from this survey, and are based on conditions, practices observed, other pertinent data supplied by management personnel at the risk, and information secured at the time of survey.

Please note that the following recommendations have been made with the intention of pointing out those areas in which remedial action could have the beneficial effect of making your premises safer.

RECOMMENDATIONS IN CAPITAL LETTERS ARE OF PARTICULAR IMPORTANCE, AND THEIR EARLY IMPLEMENTATION IS ENCOURAGED.

Thank you for your co-operation during this visit, and please do not hesitate to get in touch with us if we can be of any further assistance.

Representative: Ravi Khanna

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the service being provided.

REMARKS:

1. This is an update of the previous survey of the premises done by this Organization in January, 1981.

2. The sprinkler system was satisfactorily tested at the time of this visit.

3. The entire building is now occupied by "Liquidation World" for retail sales of housewares.

RECOMMENDATIONS:

73-1 SINCE A FIRE OR AN IMPAIRMENT TO THE SPRINKLER EQUIPMENT MAY GO UNNOTICED FOR A LONG TIME WHEN THE PREMISES ARE UNATTENDED, CONSIDERATION SHOULD BE GIVEN TO INSTALLING AN UNDERWRITERS LABORATORIES OF CANADA LISTED SUPERVISORY SERVICE AND MONITORY EQUIPMENT ON YOUR SPRINKLER VALVES, WITH A CONNECTION TO A CENTRAL STATION OFF-PREMISES. THIS WOULD ALERT YOUR FIRE DEPARTMENT AUTOMATICALLY IN CASE OF FIRE. THIS FACILITY WHICH IS AVAILABLE FROM VARIOUS SERVICE COMPANIES MAY ADVANTAGEOUSLY AFFECT YOUR INSURANCE RATE AND YOUR AGENT OR BROKER COULD PROVIDE SPECIFIC DETAILS.

INSURERS' ADVISORY ORGANIZATION
Ontario

CONFIDENTIAL

INSPECTION REPORT

File No. 07506
Reference: 011951

Not on Plan

NAME OF RISK: Dufferin-Ronce Investments Ltd

LOCATION: 109 Cartwright Avenue
Toronto, Ontario
M6R 1V4

SURVEYED BY: Ravi Khanna

SURVEY DATE: December 13 1996

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from an inspection of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the service being provided.

GENERAL COMMENTS

OCCUPANCY: Retail housewares liquidator.

CONSTRUCTION

FIRE DIVISIONS: Single fire division.

BUILT IN: 1960

Additions: 1969

Repair: Good

HEIGHT: 1 Sto. = 3.66 m, 4.88 m (12', 16')

Basement: None

WALLS: Construction: 100%: 25.4 cm (10") concrete block.

Type of Walls: Independent, bearing

FLOORS: Concrete on grade.

ROOF: 52% Class II metal deck on exposed steel; 48% wood joist.

AREA:

Grade: 929 m2 (10000 sq ft)

Total: 929 m2 (10000 sq ft)

Separation Walls: None

VERTICAL OPENINGS: None

Elevators: None

INTERIOR FINISH - Walls: 76% plasterboard sheathed; 24% open

INTERIOR FINISH - Ceilings: 80% non-combustible mineral tile; 20% open

COMBUSTIBLE CONCEALED SPACES: Minor. 29.28 m x 15.25 m (96' x 50') by .61 m (2') deep sprinklered space over the front section of the showroom.

HAZARDS

COMMON HAZARD:

Heating: The building is heated by forced air, natural gas-fired ceiling units and roof top combination heating and air-conditioning units.

Chimmeys and Flues: Standard

Air-Conditioning: Central - 80% air-conditioned.

Electrical: Safe. Circuit breakers and fuses used. Wiring installed in 1960 and 1969 and updated in recent years.

SPECIAL HAZARDS: None

RADIOACTIVE MATERIAL: None

HIGH PILING: None

HOUSEKEEPING: Safe

HAZARDOUS MATERIAL: None

EXPOSURES:

North Protection Required: N Protection Provided: N

Open to Cartwright Avenue.

South — Protection Required: N Protection Provided: N

Moderate by a one and two storey sprinklered, building detached by 18.3 m (60') of masonry construction which is occupied as a multi-tenant industrial building.

East — Protection Required: N Protection Provided: N

Open to park.

West — Protection Required: N Protection Provided: N

Moderate by a one storey adjacent, sprinklered building detached by 7.625 m (25') of non-combustible construction and occupied by a commercial tenant.

ACTIVITY: Moderate 10 hrs/day, 7 days/wk.

Number of Production Workers: None

SMOKING RESTRICTED: No, not restricted (considered a minor deficiency).

ELECTRONIC DATA PROCESSING: No

PROCESS DESCRIPTION: Entire building is occupied as a retail store for sales of housewares and some toys. These are mostly ends of line and clearance/liquidation merchandise. All stock is well arranged. An electric operated forklift truck is provided in the rear storage area.

PROTECTION

OVERALL GRADING: 100 (EF) x 95/100 (RF) x 100/100 (AT) = 95

(RF) - No spare sprinkler cabinet and wrench.

Area Sprinklered (excluding concealed spaces): 100% Sprinklered - 100% Wet

Sprinkler Installation Date: 100%: 1969

Protection Against Freezing: Adequate

Sprinkler Protection Required: No

Equipment Standard: Yes

Alarms: Inside electric bell and outside water gong only (Recommendation made).

Primary Water Supplies: Municipal - Standard

Secondary Water Supplies: Standard single supply from a 152.4 mm (6") connection to a 304.8 mm (12") circulating street main. Static pressure 448.5 kPa (65 psi), residual pressure 414 kPa (60 psi) with a 50.8 mm (2")

---

drain fully open. This Ordinary Hazard Group 2 occupancy requires a minimum supply of 3230 L/min (850 US gpm) at 262.2 kPa (38 psi) at grade level.

A flow test done in the vicinity in 1975 gave the following results:

Flow	Residual Pressure
8276.4 L/min (2178 US gpm)	at 393.3 kPa (57 psi)
4693 L/min (1235 US gpm)	at 414 kPa (60 psi).

Fire Department Pumper Connection: Yes.

OTHER PROTECTION:

Extinguishers: Standard

Standpipe and Hose: None

Watchman Service: None

Special Equipment: None

OUTSIDE PROTECTION:

Public Hydrants: Standard

Public Fire Department: Paid.
Distance to Fire Hall: 2.42 km (1 1/2 miles)

F.U.S. Municipality Classificaiton: 2

Accessibility: To Property - Good

Into Building - Good

EXTENDED COVERAGE

WINDSTORM - No

LIGHTNING (FEATURES) - No

EXPLOSION - No

SPRINKLER LEAKAGE - Stock Skidded or Shelved: No
Stock Susceptible to Large Water Damage: No
Floors Drained: No

RIOT, VANDALISM, MALICIOUS ACTS

Access Restricted: A monitored burglar alarm system is provided for the premises.

_____

Guard Supervised: No

Yards Fenced: In part.

Yards Lit: Yes

Remote from Populated Areas: No

EARTHQUAKE - Zone: 0

IMPACT HAZARDS:

By Aircraft: No

By Road Vehicles: Possible due to vehicles entering property or backing into loading bay doors.

By Trains: No

By Floating Vessels: No

SMOKE DAMAGE - Susceptibility of stock to smoke damage: Moderate to severe.

BUSINESS INTERRUPTION

Seasonal: No

Operational: 10 hrs/day, 7 days/wk

Interdependency: No

Raw Materials: Domestic. Tenant purchases ends of line or clearance supplies from wholesalers or manufacturers.

Stock On Hand: Six to eight weeks.

Stock Replacement Time: Varied

Computer Programming: No

Single Train Production: No

Vital Machinery Custom Made: N/A

Replacement Time: No

Private Power Generation: No

Alternate Power Generation: No

ADDITIONAL BUSINESS INTERRUPTION DETAILS:

No

UNDESIRABLE FEATURES

PROMINENT:

Local alarms only.

OTHER:

None apparent.

MANAGEMENT - LOSS PREVENTION PROGRAMMES

TENANTS

1. Asterisk (*) denotes change of occupancy since last survey.

2. Good housekeeping with a standard supply of portable extinguishers, unless otherwise stated.

3. If the building is sprinklered, then the overall grading of sprinklers and water supplies to all tenants is equal to that of the building grading, unless otherwise stated.

* LIQUIDATION WORLD (IBC Code: 5990)
  Occupies the entire building for retail sales of housewares. See "Process Description".

Siteplan Report - 1981 FURNITURE GUILD 109 Cartwright Avenue North York ON M6R1V4

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the full Terms and Conditions at the front of this document.



FILE NO. 7506

CARTWRIGHT AVE.

1000' TO 12" x 36" IN CALEDONIA ROAD
(305M TO 300MM & 900MM)


12" AT 70 P.S.I
(300MM AT 483 KPa)


85'
(25.9m)


500' TO 6" AT PAUL DAVID ST.
(152.5M TO 150MM)

109

6" (150MM)







School Playground

NOTE: BLDG IS HEATED BY THREE NATURAL GAS FIRED ROOF MOUNTED FURNACES.


1011953

FILE NO. SR 7506
FURNITURE GUILD.
109 CARTWRIGHT AVENUE
NORTH YORK, ONTARIO.
Sheet: 1747 Block: 2401 Scale: 1" = 50'
2.54CM = 1.55M.
INSURERS' ADVISORY ORGANIZATION
ONTARIO
Date: JAN 20, 1981 Field Rep.: M.A.P.

This document is owned by Opta Information Intelligence Inc. and is subject to copyright protection. Please see the purchase order relating to the release of this document for complete terms and conditions.

APPENDIX D

TERRAPROBE INC.



CHAIN OF TITLE REPORT

Project #: 2210387
Address: 109 Cartwright Avenue, Toronto
Legal Description: Lot 21 Plan 7165

Searched at: Toronto
LRO #: 80

PIN #: 10236-0301 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent (N1/2 - 100 Acres)	30 04 1838	Crown	**Thomas GOULDING, Sr.**
64719	Deed	07 11 1856	Thomas Goulding, Sr.	Thomas GOULDING, Jr.
64720	Deed	07 11 1856	Thomas Goulding, Jr.	William CLARKE
51090	Deed	14 07 1904	William Clarke - Estate	William Henry CLARKE
20600	Deed	11 12 1935	William Henry Clarke	Park Home Site Company Limited
21189	Deed	16 05 1936	Park Home Site Company Limited	William Henry CLARKE
21389	Deed	25 06 1936	William Henry Clarke	Thomas A. RUSSELL
38450	Deed	27 08 1943	Thomas A. Russell - Estate	Benjamin COOPER
38148	Deed	24 11 1943	Benjamin Cooper	Eleanor J. MURPHY

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: 2210387
Address: 109 Cartwright Avenue, Toronto
Legal Description: Lot 21 Plan 7165

Searched at: Toronto
LRO #: 80

PIN #: 10236-0301 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
170088	Deed	15 04 1954	Eleanor J. Murphy	James PRIMAVERA
388004	Deed	31 07 1962	James Primavera	Dufferin-Ranee Investments Limited
569589	Deed	18 12 1969	Dufferin-Ranee Investments Limited	Gordon SALTZMAN & Samuel SILVERSTEIN
NY586453	Deed	11 12 1976	Gordon Saltzman & Samuel Silverstein	Dufferin-Ranee Investments Limited
AT1545025	Deed **(Present Owner)**	17 08 2007	Dufferin-Ranee Investments Limited	**109 Cartwright Avenue Limited**

CHAIN OF TITLE REPORT

Project #: 2210387
Address: 130 Bentworth Avenue, Toronto
Legal Description: Lot 57 Plan 7165

Searched at: Toronto
LRQ #: 80

PIN #: 10236-0279 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent (S1/2 - 100 Acres)	03 11 1815	Crown	**Robert CLARKE**
37399	Deed	28 01 1850	Robert Clarke	William CLARKE
51090	Deed	14 07 1904	William Clarke - Estate	William Henry CLARKE
20600	Deed	11 12 1935	William Henry Clarke	Park Home Site Company Limited
21189	Deed	16 05 1936	Park Home Site Company Limited	William Henry CLARKE
21389	Deed	25 06 1936	William Henry Clarke	Thomas A. RUSSELL
38450	Deed	27 08 1943	Thomas A. Russell - Estate	Benjamin COOPER
40374	Deed	01 06 1944	Benjamin Cooper	Henry J. PONSFIELD
55568	Deed	02 06 1947	Henry J. Ponsfield	Winifred E. NEWNHAM

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: 2210387
Address: 130 Bentworth Avenue, Toronto
Legal Description: Lot 57 Plan 7165


Searched at: Toronto
LRO #: 80

PIN #: 10236-0279 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
130273	Deed	16 05 1952	Winifred E. Newnham	De Carlo Brothers Limited
YR268927	Deed	14 11 1957	De Carlo Brothers Limited	Isac WAGNER, Yechezkel WAGNER & Gertrude WAGNER
AT883499	Deed	08 08 2005	Isac Wagner & Gertrude Wagner - Estate	Israel WAGNER
AT1152082	Lease	31 05 2006	Israel Wagner & Yechezkel Wagner	2008737 Ontario Limited (Lessee)
AT1164573	Deed	12 06 2006	Israel Wagner & Yechezkel Wagner	130 Bentworth Avenue Limited
AT5148240	Deed (Present Owner)	30 05 2019	130 Bentworth Avenue Limited	**The Sterling Hall School**

APPENDIX E

TERRAPROBE INC.



ENVIRONMENTAL RISK INFORMATION SERVICES

CITY DIRECTORY

Project Property: *130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario*

Report Type: *City Directory*

Order No: *22113000820*

Information Source: *Polk's Toronto North York On., Criss Cross Directory (TRL)*

Date Completed: *January 5, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

City Directory Information Source
Polk's Toronto North York On., Criss Cross Directory (TRL)

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 2001	
Site Listing:	130 Bentworth Avenue -Adapt-Able Design -Armstrong Baum Plumbing & Heating -Canada Chair Co -Cozy Comfort Plus -Eurotech Imports -The Golden Imprint -Presidential Cleaners Plant -Prime Printing -Prompt Couriers INC -Residential (1 Tenant) 109 Cartwright Avenue -Lighting Originals INC
Adjacent Properties:	
Bentworth Avenue (85-165)	87-CS Azzueri Soccer Club

	89-Metrowide Wholesale Co 130-Bentworth Avenue -Adapt-Able Design -Armstrong Baum Plumbing & Heating -Canada Chair Co -Cozy Comfort Plus -Eurotech Imports -The Golden Imprint -Presidential Cleaners Plant -Prime Printing -Prompt Couriers INC -Residential (1 Tenant) 137-Fort James Canada -Harmon Associates 139-Ontario Acoustic Supply INC 141-AJ Stone Co LTD 142-Canadian Iron Metal INC -I&D Autobody & Collision Center LTD 144-Renata Sales INC 146-Grieco Frank & Peter Contracting LTD 147-Prestige Motors 150-Adventist Counselling Center -Dominion Auto Stereo -Seventh-Day Adventist Churches 151-Graf Auto Center LTD 154-Seventh Day Adventist Churches 155-Aleph Plastics LTD

	-Britstone Textile Import LTD -Regal Hosiery LTD 157-Crown Canadian Linen -Mantex Jobbers LTD 162-Seventh Day Adventist Churches -Toronto Central Seventh Day Adventist Church 164-Eastern Textiles LTD
Cartwright Avenue (60-130)	-All Residential 92-Cappola Foods 99-Sterling Hall School of Toronto 102-Graham Brothers Radiators LTD 106-D'Otters INC 109-Lighting Originals INC 111-MCU Automotive 113-Dominion Roofing -The Roof Tune Up 117-NYCYO 120-Italdoor & Woodworking 121-Universal Lamp-Landscape -Universal Lamp MFG 122-Lamintech -Picture Picture 124-Alternator Exchange Co LTD -Art Venture MFG -That Lighting Place -The Original by Jiame Mejia

	125-Panet Electric Lighting Center 126-Chair King INC -Janos 127-Benix & Co 128-Rainbow Gifts 129-Big Screen TV Systems -Carjeanne Investments -Giant Screen TV Systems -Zaldiam & Co 130-Drapery King
Bridgeland Avenue (153-245 Odd)	153-Alliance Stone LTD -Bargains Group LTD -Bezic Developments LTD -Boys of Europe -Canada Cleaning Supplies -Circuit Breaker -City Lift Truck SVC LTD -Cobrin's LTD -Contact Innovations INC -Custom Tailor House -Fab-Ind LTD -The Futon Factory -Glen Orchard Homes -Henry Choice Jeans -Jeff Green Investments -Lynco Aluminum Centers LTD

	-RB INC -Rainbow Aluminum & Vinyl Products LTD -Sanitary Maintenance -Satellite Drive -Solids & Colours LTD -Squeeggesnet -Steam Sauna -Triangle LTD -Unitool INC -Video 99 161-Wasteco -Residential (1 Tenant) 185-Food King Co -Shrimp Delux -Trans-World Distributors LTD 195-Hedonics Retail LTD -Isherwood Enterprises LTD -Tanmer Construction LTD 201-Art Craft LTD -Newhouse Capital Corp -Yetnikoff Trudeau Levi Cooper & McGraw INC -Zeifman & Assoc -Residential (5 Tenants) 223-Cedar Forming LTD -Garney & Co -Greenwall Forming LTD 225-Bridgeland MT Restaurant

	227-PMG Planning Consultants -Valufax Real Estate Appraisers LTD -Residential (1 Tenant) 229-Classica Imports -Surka Fred & Assoc 241-All Repairs -Jermark Plumbing & Mechanical SVC LTD -Scarborough Metal -Residential (2 Tenants) 245-Geovin Furniture INC
Dufflaw Road (65-80)	75-CPI Corporate Promotions INC -Lithco Graphics LTD 80-Aziz J&A LTD -Dophes LTD -Gillett Cleaning Products -ISA Intl
Orfus Road (65-130)	65-Canadian Goaltending Academy -Canadian Hockey Academy -Rinx -Whirly Ball 66-McCaul Importers LTD -R&E Sales LTD 71-Stitches Mega Store -Stitched Mega Warehouse 76-Bingo Press & Specialty

	80-Swenson Canada INC -Wahl Mfg Co 88-Canadian Ellite Fashions -Chef Revival -Kinetic Gymnastics & Fitness INC 90-BEnix & Co 92-Harvey's Building Supplies INC -Harvey's Hardware 95-B&C Marvellous Maxx 98-Barnes & Castle Seattle Coffee Co 100-Galleryof Shoes 103-Bikini Bay Clothing Co -Dworkin Distributors LTD -Express Flower Wholesale -Fancy Diamond Jewellery LTD -Home Matters Furnishings INC -Windsor Bridal 107-International Boys 109-Inleather 110-Pamensy Canada LTD 111-Chester LTD -International Clothiers 112-Barber & Beauty Shop Installations -Barber & Beauty Supply LTD -Barber's Supply -Barber Shop Installations -Toronto Barber & Beauty Supply LTD

	115-Pritchard Paper Products -Threads On Threads 116-Intl Shoes Factory Outlet -Lynn Fashions 121-Sirens Fashion Outlet 130-Choice Canadian Imports -Ontario Korean Businessmen's Association -Sincere Trading of KBA Co-Op LTD -SM Footwear LTD
Paul David Street (All)	-All Residential

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1995	
Site Listing:	130 Bentworth Avenue -Armstrong Baum Plumbing -Canadian Chair Co -Calvin Marketing INC -Golden Imprint -KB Supplies & Printing -Presidential Cleaners -Versatile Management -Office

	-Office -Adapt-Able Design INC -Bergman Trading -Prompt Couriers INC 109 Cartwright Avenue -World of Lights
Adjacent Properties:	
Bentworth Avenue (85-165)	130-Armstrong Baum Plumbing -Canadian Chair Co -Calvin Marketing INC -Golden Imprint -KB Supplies & Printing -Presidential Cleaners -Versatile Management -Office -Office -Adapt-Able Design INC -Bergman Trading -Prompt Couriers INC 137-Canada Cup INC 139-Ontario Acoustic Supply INC 141-AJ Stone Co LTD 142-Graf Auto Center 144-Body Tech

	147-Advantage Distributing LTD 150-Candore Fashions 151-Unitool INC 153-Residential (1 Tenant) 155-Britstone Textile & Aleph Plaster -Toby Britstone Occupational 156-975435 Ontario LTD 157-Green Jay Sales INC -Mantex Jobbers LTD -New Look Fashions 162-Kingston Sales LTD 164-Eastern Textiles LTD
Cartwright Avenue (60-130)	-All Residential 92-Cappola Bros Whole Meat LTD -Cappola Food INC 99-Sterling Hall School of Toronto 102-Graham Brothers Radiators LTD 104-RB Right Bounce Sport INC 106-Selected Mode 109-World of Lights 111-MCU Rustproofing 113-Aba Sign & Frame CTR -Dominion Sheet Metal & Roofing 117Kiddie Proofers 120-Caneurop MFG LTD 121-Cartwrights Famous Universal

	122-Liquidation World 124-Alternator Exchange Co LTD -Cartwright Dist. Co -Palazzo Furniture & Upholstery -That Lighiting Place -World of Picture Frames 125-Panet Electric Lighting Center 126-Design Plumbing & Renovation -Lingerie Lines 127-Benix & Co -Home Picture
Bridgeland Avenue (153-245 Odd)	153-Bright Electric LTD -Canada Base Co -City Lift SVC LTD -Classic Heating & Air Cond -Dollco Printing -Galaxy Bakery -Hogarth Printing Co LTD -Jaggs Fashions LTD -Lynco Aluminum CTR LTD -Reba Equipment Enterprises LTD -Video 99 -Residential (1 Tenant) 161-Wasteco 185-Excel Plastics -Tamko INC

	195-ABCO Appliance Repair -Astral Towing & Storage LTD -Hedonics Warehouse Outlet -Saturn Construction 201-Andrade Consulting Group -Angel Dance Wear INC -Coast to Coast Trading -Curtis Property MGMT LTD -Falcon INTL Microage -NRYK Investments -Realtel Network -Seaboard Importing Co -Toronto Telecom -Variations -100 Reitter MGMT Corp 223-Cedar Forming LTD -Garney & Co -Greenwall Forming LTD 225-Bridgeland Restaurant 227-Kose Group 229-Classica Imports 241-All Repairs -Georgia Equipment -Jermack Plumbing & Mechanical -Residential (3 Tenants) 245-Cooper Bros Upholstery Co LTD

Dufflaw Road (65-80)	75-Jaytex of Canada -Reena Fashions 80-Hadar Fashions -J&A Aziz LTD
Orfus Road (65-130)	65-Lithco Graphics 66-McCaul Importers LTD -R&E Sales LTD 67-Dream Shoppe Lingerie 76-Bazaar & Novelty Co 80-Swenson Canada INC -Wahl Mfg Co 88-California Shoe Co -Emerson Summers Co LTD 95-Décor -Hughes Containers LTD 98-Harvey's Building Supplies 100-David Charles Super Shoe Warehouse 103-Edward Dworkin Dist. -Fancy Diamond Jewellery LTD -Heritage Fine Clothing 107-Kids World Warehouse 109-Inleather 110-Fendy Fashions -VJ Pamensky Canada INC -WEG Electric Motors 111-Ad Plus International Clothiers

	112-Beauty & Barber Shop Installations -Toronto Barber & Beauty Supply 115-Canadian Elite Fashions -Pritchard Paper Products -Simply Coats LTD 116-Anna Liza Lingerie -Lynn Fashions 120-Louis Interiors INC 130-Holiday Sportswear Mfg LTD -Sincere Trading Co KBA Co-Op
Paul David Street (All)	-All Residential

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1990	
Site Listing:	130 Bentworth Avenue -Armstrong Baum Plumbing 109 Cartwright Avenue -No Return
Adjacent Properties:	

Bentworth Avenue (85-165)	130-Armstrong Baum Plumbing 137-Canada Cup INC 139-Ontario Acoustic Supply INC 140-Department of Parks & Recreation 142-Graf Auto Center 150-152-Candore Fashions 151-Bailey Metal & Roofing Products -Maintenance Construction Products INC 154-Ontario Metal Spinning 155-Britstone Textile Imports LTD 157-Green Jay Sales INC 162-Kingston Sales LTD 164-Eastern Textiles LTD
Cartwright Avenue (60-130)	-All Residential 99-Reena Foundation 102-Graham Brothers Radiators LTD 104-106-RB Right Bounce Sport INC 113-Dominion Sheet Metal 117-Universal Lamp MFG 120-Caneurop MFG LTD 121-Universal Lamp MFG 124-Foreign Greeting Card Co -World of Picture Frames LTD -Cartwright Dist. Co 125-Panet Electric Lighting Center 126-Globecraft Dist.

	129-General Products
Bridgeland Avenue (153-245 Odd)	153-Delta Equities & Development Corp -Bezic Developments LTD -Chelsea Metal INC -Bright Electric LTD -Shell X Courier SVC -Compsec -Galaxy Bakery LTD -Fraser & Co LTD -DS Fraser & Co -Reba Equipment Enterprises LTD -Diamond Yarn -Stirling Importers -Hogarth Printing Co LTD -Unicare Medical Products -Relaxe Upholstery -Lynco Aluminum Center LTD 181-National Rubber Co 185-American Louver of Can 201-Level Operations Springboard -Seaboard Importing Co -Microage Computers -Rentsch & Assoc LTD 223-Greenwall Forming LTD 225-Bridgeland Restaurant 229-Fabirx

	241-Silverstone -Garny & Co LTD 245-Cooper Bros Upholstery Co LTD -Broadloom Mills
Dufflaw Road (65-80)	67-Heritage Lighitng Co 75-Jaytex of Canada -American Pant INTL
Orfus Road (65-130)	65-Rothmans of Pall Mall Canada LTD 66-Window Magic 67-Rothmans of Pall Mall Canada LTD 71-Scot Mechanical INC 76-Costi-I IAS Rehab Center 80-Wahl Co -Swenson & Son LTD 88-Emerson Summers Co LTD 92-Harvey's Building Supplies INC 95-Hughes Containers LTD 98-Bellevue Home Entertainment -Residential (1 Tenant) 100-Dophes LTD -Gillett Cleaning Products -X-Press Canada 103-Herhoge Clothing 107-Rose Textile Children's Wear 110-Utaco Agencies

	-WEG Electric Motors 111-International Clothiers 112-Toronto Barber & Beauty Supply 115-Factory Sports INC -New Season Garment Co -Pritchard Paper Products -Robes Royal 120-Louis Interiors INC 121-Merto Toronto Housing authority 130-Sincere Trading Co KBA Co-Op
Paul David Street (All)	-All Residential 45-Alpine Construction Co

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1985-1986	
Site Listing:	130 Bentworth Avenue -Canada Chair Co 109 Cartwright Avenue -Living Lighting
Adjacent Properties:	

Bentworth Avenue (85-165)	87-Central Slipper Co 130-Canada Chair Co 137-Canada Cup INC 139-Ontario Acoustic & Drywall INC 140-Department of Parks & Recreation 141-Canadian Custom Packaging LTD 142-Graf Auto Center 150-Candor Fashions 151-Bailey Metal Products -Bailey-Hunt LTD -Preston Metal & Roofing Products -Mantane Construction Products 152-Arrow Footwear LTD 154-Ontario Metal Spinning -Della Machine & Tool Co 155-Regina Quilting 156-Wilson Carpet SVC LTD 162-Kingston Sales LTD
Cartwright Avenue (60-130)	-All Residential 92-Cappola Bros Wholesale Meats 94-Greenwall Forming LTD 99-Reena Foundation 102-Graham Brothers Radiators LTD 104-106-McCaul Importers 109-Living Lighting

	111-Litefrom Lighting & MFG 113-Regal Greeting Cards 117-Piccione Machine Tool & Gear MFG LTD 120-Caneurop MFG Co LTD 121-Universal Lamp Co 122-Colonial Packaging Co 124-Sunrise Restaurant -Foreign Greeting Cards -Rife News Co -Wooltex INC -Alternator Exchange LTD -World of Picture Frames -Babos Dist Co LTD -Globecraft Dist Co LTD -Philatec Supply Co -Philasteel Furniture Products -Can-Am Air Leakage Control Systems Corp -G&P Foreign Cars SVC & Body Work 125-Panet Electric Lighting Center 127-Unitrade Assoc 129-Villaneuve LTD
Bridgeland Avenue (153-245 Odd)	153-Delta Equities & Development Corp -Claritch Contracting LTD -McCutcheon LTD -Comspec Communications INC -DS Fraser & Co LTD

	-TNT Appliances -Maitel Communications -Reba Equipment Enterprises -Diamond Yarn -Sterling Importers of Sundries -Hogarth Printing Co LTD -Heritage Upholstery -Tri-Lite LTD -Techaire Systems INC 161-Browning Farris INC 181-National Rubber Co 185-Bernard Taub & Assoc 201-Level Plastics Plus -Arodal SVC Ontario -Janitorial SVC & Supplies 223-Glengarry Transport LTD -Quinte Transport LTD 225-Bridgeland Restaurant 227-CR Systems -Woodard & Co LTD -Jeffcoat Controls 229-Tem-Pro Systems INC 241-B-Jay Auto SVC -Grant's Sign Erection and SVC LTD -Garney & Co 243-Cooper Bros Upholstery Co LTD 245-Broadloom Mills

Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD
Orfus Road (65-130)	65-Rothmans of Pall Mall Canada LTD 66-Window Magic 67-Rothmans of Pall Mall Canada LTD 71-Rothmans of Pall Mall Canada LTD 76-Costi-I IAS Rehab Center 80-Riling-Wahl Co -Swenson & Son LTD 88-Emerson Summers Co LTD 92-Harvey's Building Supplies INC 95-Hughes Containers LTD 98-HR Fabrics 100-Aziz J&A LTD 107-Vatco Agencies 109-Northcotte Silk INC 111-Heritage Clothing 115-Duras Co -Prime Time Video -Bronsport LTD 121-Ontario Housing Corp -Tenant & Inquiry Bd 130-Wayfoong Holding INC
Paul David Street (All)	-All Residential 45-Alpine Construction Co

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1980	
Site Listing:	130 Bentworth Avenue -Wagner I Co LTD -Canada Chairs 109 Cartwright Avenue -Furniture Guild Home Beautifiers LTD
Adjacent Properties:	
Bentworth Avenue (85-165)	89-Central Slipper Co 105-Hughes Containers LTD 130-Wagner I Co LTD -Canada Chairs 137-Canada Cup INC 139-Ontario Acoustic Drywall INC 140-Department of Parks & Recreation 141-Canadian Custom Packaging LTD 142-Graf Auto Center -Nu-Style Woodworks 144-Metropolitan Sheet Metal LTD 150-Nicolas MFC Co

	-Film Trex of Canada INC 151-Bailey Metal Products -Bailey-Hunt LTD -Preston Metal & Roofing Products -Mantane Construction Products 152-Arrow Footwear LTD 155-Regina Quilting 156-Office Stationers -Wilson Carpet SVC LTD 162-Kingston Sales LTD 164-Eastern Textiles
Cartwright Avenue (60-130)	-All Residential 92-Cappola Bros Wholesale Meats 94-Greenwall Forming LTD 99-Cartwright Public School 102-Graham Brothers Radiators LTD -Tucker's Auto SVC 104-106-McCaul Importers 109-Furniture Guild Home Beautifiers LTD 111-Litefrom Lighting & MFG 113- Dominion Sheet Metal & Roofing Works -Sheers Co -Drapery World 117-Piccione Machine Tool & Gear MFG LTD 120-Caneurop MFG Co LTD 121-Universal Lamp Co

	122-Colonial Packaging Co 124-Sunrise Restaurant -Foreign Greeting Cards -Rife News Co -Canadian Jeerle -Toronto Colour SVC -Fired Sales Co LTD -World of Picture Frames -North Western Sheet Metal Works LTD -Globecraft -Tri-Lite Industries LTD -Farrell Enterprises LTD -Vulcan Waterproofing 125-Panet Electric Lighting Center 127-Philatech Supply Co 129-Villaneuve LTD
Bridgeland Avenue (153-245 Odd)	153-Delta Equities & Development Corp -McCutcheon LTD -Comspec Communications INC -Unitrade Assoc -Griffin Sheet Metals -DS Fraser & Co LTD -Unitrade Assoc -JE McCutcheon LTD -Chelsea Girl -Stirling Importers

	-Hogarth Printing Co -Heritage Upholstery -Jardi Sportswear -Techaire Systems LTD 161-Browning Farris INC 183-Cardinal Products 185-Riviera Slacks 195-Superior Crane & Hoist Rental -Sylcroft Importing Tools LTD 223-Glengarry Transport LTD 225-Bridgeland Restaurant 227-ME Electronics -Woodard and Co 229-Tem-Pro Systems INC -JC Footwear 241-Worth More Furniture Warehouse -B-Jay Auto SVC -Unirail Iron Co -Grant's Sign Erections and Serv LTD 243-245-Toronto Bedding Co
Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD 80-Huston Co
Orfus Road (65-130)	65-Rothmans of Pall Mall Canada LTD 66-Metro Wall Coverings Co LTD 67-Rothmans of Pall Mall Canada LTD

	71-Rothmans of Pall Mall Canada LTD 76-Costi-I IAS Rehab Center 80-Riling-Wahl Co -Swenson & Son LTD 88-Emerson Summers Co LTD 92-96-Harvey's Building Supplies INC 98-HR Fabrics 100-Aziz J&A LTD 103-Bedford Bedding & Upholstery Co 106-Living Room by Diamond Bros LTD 109-Northcotte Silk INC 110-Towers Department Store 111-ALbini Showrooms LTD 115-David Barry Co 121-Ontario Housing Corp -Tenant & Inquiry Bd
Paul David Street (All)	-All Residential 45-Alpine Construction Co

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1976	
Site Listing:	130 Bentworth Avenue

	-Wagner I Co LTD 109 Cartwright Avenue -Furniture Guild Home Beautifiers LTD
Adjacent Properties:	
Bentworth Avenue (85-165)	85-Price Tri-Tile LTD -Tri-Tile LTD 87-89-Central Slipper & Shoe Co 105-Hughes Containers LTD 123-Frolic Toys 130-Wagner I Co LTD 137-Canada Cup INC 140-Department of Parks & Recreation 142-Lawrence & Newell LTD -Nu-Style Woodworks LTD 144-Metropolitan Sheet Metal LTD 147-DNA Associates 150-Kingston Sales LTD 151-Bailey Metal Products -Bailey-Hunt LTD -Preston Metal & Roofing Products 152-CB Wrought Iron Mfg Co LTD 155-Warehouse of Fellows Smyth Fisher LTD 156- Canada Hardware Co LTD 164-Eastern Textiles

Cartwright Avenue (60-130)	-All Residential 92-Cappola Bros LTD 99-Cartwright Public School 102-Graham Brothers Radiators LTD -Tucker's Auto SVC 104-106-McCaul Importers 109-Furniture Guild Home Beautifiers LTD 111-Litefrom Lighting & MFG 113- Dominion Sheet Metal & Roofing Works -United Drapery 117-Piccione Machine Tool & Gear MFG LTD 120-Caneurop MFG Co LTD 121-Universal Lamp Mfg Co 122-Maher Shoes 124-Sunrise Restaurant -Stationary INTL -Rifco Greeting Cards -Rife News Co -Mark-James Of Canada -J&I Distributors Co LTD 125-Panet Electric Lighting Center 126-World of Pictures 127-Kidde Walter & Co 128-Diplomat Carpet 129-Trans Northern Pipeline -Conditioning Contractors

Bridgeland Avenue (153-245 Odd)	153-Techaire Systems INC -Delta Equities & Development Corp LTD -McCutcheon LTD 161-Bulklift Systems LTD -Timeco Mining & Industrial Equipment LTD 183-Cardinal Products 185-Zenith Electric Supply LTD 195-Superior Crane & Hoist Rental 201-Raylena Construction Co LTD 223-Glengarry Transport LTD 225-Bridgeland Restaurant 227-K&S Products -Kert Herbert Agencies 229-Tem-Pro Systems INC -Cool Air Systems LTD 241-Two Thousand One Interiors LTD -Hi Fi Headquarters 243-245-Toronto Bedding Co
Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD
Orfus Road (65-130)	66-Metro Wall Coverings Co LTD 76-Costi-I IAS Rehab Center 80-Riling-Wahl Co -Swenson & Son LTD 88-Emerson Summers Co LTD

	92-Haldane Electric Supply LTD -Electric Super Mart 95-American Louver of Can LTD 100-Aziz J&A LTD 106-Living Room by Diamond Bros LTD 107-Heughs Canada LTD 109-C Northcotte Silk INC 110-Towers Department Store 111-Albini Showrooms LTD 121-Ontario Housing Corp
Paul David Street (All)	-All Residential 45-Alpine Construction Co -Alpine Sewer & Watermains

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1970	
Site Listing:	130 Bentworth Avenue -Wagner I Co LTD 109 Cartwright Avenue -Furniture Guild

Adjacent Properties:	
Bentworth Avenue (85-165)	130-Wagner I Co 140-Nu-Style Woodworks LTD -Lawrence & Newell 144-Metropolitan Sheet Metal 150-Kingston Sales LTD -Cond-Air LTD 152-Bailey Metal Products LTD 154-CB Wrought Iron Mfg Co -Walker Gault Metal Co LTD -Walker Marketing of Canada LTD -Knoll Intl Canada LTD 156-Rotary Club of Fairbank -Walker Marketing of Canada -Knoll Intl Canada LTD 162-Knoll Intl Canada LTD 164-Eastern Textiles 85-Tilrite LTD -Tri-Tile LTD 87-Federal Carpet Co of Can 89-Central Slipper & Shoe Co 105-Hugh Containers LTD 123-Rotor Electric Co LTD -Torcan Products 135-Ebco Design & Mfg LTD

	-Art Bookbinding & Novelty -Art Die-Cutting Co 137-Corvend LTD -Canada Cup 147-Miller Herman of Canada LTD 151-Bailey Metal Products -Bailey-Hunt LTD -Preston Metal & Roofing Products LTD 155-Calvert-Dale Estates LTD 157-National Home Products -Empire Carbide Engineering LTD -Weld-O-Stud Canada LTD -Elmco Products LTD
Cartwright Avenue (60-130)	-All Residential 90-Frankland Haulage LTD -Stewart TV Toronto LTD 92-Cappola Bros Radiator Repair 102-Graham Bros Radiator Repair -Tucker's Auto SVC 104-106-Toronto Kitchen Equipment Co LTD 120-Caneurop Mfg Co LTD 122-McGregor LTD 124-Canada Sand Papers LTD -Fried Sales Hardware -Rife News Magazines & Greeting Cards -McDermott Metal Products LTD

	-Sunrise Restaurant -Rifco Greeting Cards -J&I Distributors Greeting Cards & Sundries -Mark James Canada LTD -Cdn Jerlee LTD -Peerless Plating Rack Co LTD -King Koil Sleep Products 128-Diplomat Carpet -Bon-Rand Electronics Dist. 130-Fairlady Fashion Wigs 99-Cartwright Avenue Pub Sch 109-Furniture Guild 111-Siemens Medical Can LTD 113-Dominion Sheet Metal & Roofing Works 115-Smith CJ Refrigeration Co LTD 117-Piccione Machine Tool & Gear Mfg 119-United Pumps of Canada LTD -Engco LTD -Dewrance of Canada 121-123-Savon Fabrics Co 125-Marks Sales Co LTD 127-Kidde & Co of Can LTD 129-Trans-Northern Pipe Lines Co -Ironside & Assoc -Cartwright Constn LTD

Bridgeland Avenue (153-245 Odd)	153-Ricci-Graham Industries LTD 161-Consolidated Glass Industries 185-Zenith Electric Supply LTD 195-A&D Transport LTD 201-Raylena Construction Co LTD -Superior Crane & Hoist Rental LTD 223-Glengarry Transport LTD -Tennant Transport 225-Bridgeland Restaurant 227-Sherwood LTD -Stylecraft Decorative Hardware LTD 229-Cool-Air Systems LTD -Downtown Electric 245-Toronto Bedding Co LTD
Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD 50-80-Huston Co LTD -Wilkinson Sword LTD -Onkyo of Canada LTD
Orfus Road (65-130)	66-Zentronics LTD 76-Graham Automotive Mfg LTD 80-Swenson & Son LTD -Wahl MFG Co -Riling-Wahl Co 88-Summers-Emerson CO LTD

	-Apex Knitting CO LTD 92-94-Lanzarotta Wholesale Grocers 98-Haldene Elec Sup LTD 100-Aziz J&A LTD 106-Living Room by Diamond Bros 110-Allied Towers Merchants LTD -Law Office -Alberts Hdw Co LTD -Castle Toys LTD -Donny Children's Wear -Drew Apparel -Jet Photo Equipment -Knox Furn Co LTD -Lake Shore Discount -Midland Jewellers LTD -Richie Snackbar LTD -Sherman Discount Records LTD 103-Hickeson & Co 107-Van Heughen Can LTD 109-Northcott C Silk CO LTD 111-Ward Carpet Cleaners 113-Ont Housing Corp -Central Maintenance Dept
Paul David Street (All)	-All Residential 45-Alpine Sewer & Watermains

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1966	
Site Listing:	130 Bentworth Avenue -Wagner I Co LTD -Miller Naismith LTD -MN Automation LTD 109 Cartwright Avenue -Furniture Guild
Adjacent Properties:	
Bentworth Avenue (85-165)	130-Wagner I Co -Miller Naismith LTD -MN Automation LTD 140-North York Park Dept 142-Cadn Adhesives LTD -Lawrence & Newell LTD 144-Metropolitan Sheet Metal 146-Centri-Cast LTD 150-Jacobson Leif LTD 152-Air Comfort Engineering Co 154-CB Wrought Iron Mfg Co

	-Walker Gault Metal Co LTD 156-Galt Metal Metal Industries -Lewis Showcases LTD -Arrow Furniture Co -Rehabilitation Industries INC -Walker Marketing of Canada 162-Knoll Intl Canada LTD 164-Poole Co LTD -Stafford Co LTD 85-Tilrite LTD -Tri-Tile LTD 87-Federal Carpet Co of Can -Hindustan Carpet Co 89-Central Slipper & Shoe Co 135-Ebco Design & Mfg LTD -Art Bookbinding & Novelty 137-Corvend LTD 147-Ontario Metal Specialties Co LTD 151-Bailey Metal Products -Bailey-Hunt LTD -Preston Metal & Roofing Products LTD 155-Calvert-Dale Estates LTD 157-National Home Products -Empire Carbide Engineering LTD -Weld-O-Stud Canada LTD -Rank Taylor Hobson LTD

Cartwright Avenue (60-130)	-All Residential 90-Disher-Farrand LTD 102-Graham Bros Radiator Repair -Tucker's Auto SVC 104-Toronto Kitchen Equipment Co LTD 106-Medical Electric Co LTD -Consolidated X-Ray Supplies Co LTD 120-Caneurop Mfg Co LTD 122-Parker Bros Games LTS -Canadian Folding Cartons -Rite-Way Dept Store -Parker Fisher Sales LTD 124-Canada Sand Papers LTD -Erlich LTD -Feller & Kates Real Estate LTD -McDermott Metal Products LTD -Regency Plastics Co LTD -Jerod Holdings -Momar LTD -Sunrose Plastics Restaurant -Ontario Plastic Bag Co -Doruve Aluminum Industries LTD 99-Cartwright Avenue Pub Sch 109-Furniture Guild 111-Siemens Medical Can LTD

	113-Dominion Sheet Metal & Roofing Works 115-Smith CJ Refrigeration Co LTD 117-Piccione Machine Tool & Gear Mfg 119-United Pumps of Canada LTD -Engco LTD -Dewrance of Canada 121-123-Savon Fabrics Co 125-Marks Sales Co LTD 127-Kidde & Co of Can LTD 129-Trans-Northern Pipe Lines Co -Ironside & Assoc -Cartwright Constn LTD
Bridgeland Avenue (153-245 Odd)	153-Compresses Air Equipment LTD 161-Consolidated Glass Industries 171-Dominion Dairies LTD 185-Zenith Electric Supply LTD 195-Chrysler Air-Temp LTD 201-Frankland Haulage -Superior Crane & Hoist Rental LTD 223-Bridgeland Terminals LTD 225-Bridgeland Drive-In Restaurant 227-Sherwood LTD -Stylecraft Decorative Hardware LTD 229-Cool-Air Systems LTD -Authorized Radio & TV SVC 245-Toronto Bedding Co LTD

Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD
Orfus Road (65-130)	66-Zentronics LTD 76-Graham Automotive Mfg LTD 80-Swenson & Son LTD -Wahl MFG Co -Riling-Wahl Co 88-Summers-Emerson CO LTD -Apex Knitting CO LTD 92-Rockower of Canada LTD 94-Lanzarotta Wholesale Grocers 98-Rothmans of Pall Mall Can LTD 106-Living Room by Diamond Bros 110-Allied Towers Merchants LTD -Jet Photo Equipment 103-Queen City Bedding Co LTD -Iseda Therapeadic Sleep Products
Paul David Street (All)	-All Residential

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1959	

Site Listing:	130 Bentworth Avenue -Oxford Furniture MFG Co 109 Cartwright Avenue -Artistic Pre-Cast Concrete Co
Adjacent Properties:	
Bentworth Avenue (85-165)	130-Oxford Furniture MFG Co 140-North York Park Dept 142-Streamline Metalcraft Co LTD 144-Lombard Heating LTD 146-Centri-Cast LTD 150-Bawden Roy LTD -Chibau Securities LTD -National Engineering & Supply Co 152-Jacobsen Leif Custom Furniture 154-Tasco Television & Appliance SVC 164-Poole Co LTD 147-Senco Sales LTD 151-Bailey Metal Products
Cartwright Avenue (60-130)	-All Residential 90-Fisher-Farrand LTD 92-International Quality Control Corp

	-X-ray and Radiography 102-Graham Bros Radiator Repair -McLean Auto Repair 104-Cameron Starcraft Industries LTD 106-Collini T Co LTD 99-Cartwright Avenue Pub Sch 109-Artistic Pre-Cast Concrete Co 113-Caltraco Metals LTD 115-Dominion Sheet Metal Works LTD 117-A-1 Engineering 125-Marks BL Co LTD 127-Kidde & Co of Can LTD 129-Trans-Northern Pipe Lines Co -Ironside & Assoc -Cartwright Constn LTD
Bridgeland Avenue (153-245 Odd)	153-Compresses Air Equipment LTD 161-Consolidated Glass Industries 171-Dominion Dairies LTD 185-Zenith Electric Supply LTD 195-Therm-O-Rite Products LTD -Douglas Engineering Co LTD -Marks Exporters LTD 201-Disero & Son LTD 223-Bridgeland Terminals LTD 225-Bridgeland Drive-In Restaurant

	229-Hostess Food Products LTD 241-Dufferin Steel Co lTD -Bulk Lift Systems LTD -Timeco Toronto Industrial & Mining Equipment LTD -Personal Cheque Printers
Dufflaw Road (65-80)	75-Rothmans of Pall Mall Canada LTD
Orfus Road (65-130)	66-Wholesale Radio & Electronics LTD 80-Swenson & Son LTD -Wahl MFG Co -Riling-Wahl Co 88-Summers-Emerson CO LTD -Apex Knitting CO LTD 103-Queen City Bedding Co LTD
Paul David Street (All)	-All Residential

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1955	
Site Listing:	130 Bentworth Avenue -Street Not Listed

	109 Cartwright Avenue -Street Not Listed
Adjacent Properties:	
Bentworth Avenue (85-165)	-Street Not Listed
Cartwright Avenue (60-130)	-Street Not Listed
Bridgeland Avenue (153-245 Odd)	-Street Not Listed
Dufflaw Road (65-80)	-Street Not Listed
Orfus Road (65-130)	-Street Not Listed
Paul David Street (All)	-Street Not Listed

PROJECT NUMBER: 22113000820	
Site Address:	130 Bentworth Avenue & 109 Cartwright Avenue, North York, Ontario
Year: 1950	
Site Listing:	130 Bentworth Avenue -Street Not Listed


	109 Cartwright Avenue -Street Not Listed
Adjacent Properties:	
Bentworth Avenue (85-165)	-Street Not Listed
Cartwright Avenue (60-130)	-Street Not Listed
Bridgeland Avenue (153-245 Odd)	-Street Not Listed
Dufflaw Road (65-80)	-Street Not Listed
Orfus Road (65-130)	-Street Not Listed
Paul David Street (All)	-Street Not Listed

-All listings for businesses were listed as they are in the city directory.

-Listings that are residential are listed as “residential” with the number of tenants. The name of the residential tenant is not listed in the above city directory.

APPENDIX F

TERRAPROBE INC.



DATABASE REPORT

Project Property:	*2210387* *130 Bentworth Ave & 109 Cartwright Avenu* *North York ON M6A 1V4*
Project No:	
Report Type:	*RSC Report (Urban)*
Order No:	*22113000820*
Requested by:	*Terraprobe Ltd.*
Date Completed:	*December 7, 2022*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary By Data Source.....45
Map.....90
Aerial.....91
Topographic Map.....92
Detail Report.....93
Unplottable Summary.....415
Unplottable Report.....416
Appendix: Database Descriptions.....422
Definitions.....431

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*2210387* *130 Bentworth Ave & 109 Cartwright Avenu North York ON M6A 1V4*
Project No:	

Order Information:

Order No:	*22113000820*
Date Requested:	*November 30, 2022*
Requested by:	*Terraprobe Ltd.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

Aerial Photographs	*Aerials - National Collection*
City Directory Search	*CD - Subject Site plus 250m Radius*
ERIS Xplorer	*ERIS Xplorer*
Insurance Products	*Fire Insurance Maps/Inspection Reports/Site Plans*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	4	4
BORE	Borehole	Y	0	7	7
CA	Certificates of Approval	Y	0	10	10
CDRY	Dry Cleaning Facilities	Y	1	0	1
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	2	2
EASR	Environmental Activity and Sector Registry	Y	0	2	2
EBR	Environmental Registry	Y	0	5	5
ECA	Environmental Compliance Approval	Y	0	5	5
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	2	43	45
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	2	2
FSTH	Fuel Storage Tank - Historic	Y	0	4	4
GEN	Ontario Regulation 347 Waste Generators Summary	Y	14	201	215
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	1	1
NPRI	National Pollutant Release Inventory	Y	0	8	8
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	2	2
PINC	Pipeline Incidents	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	3	3
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	1	1
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	1	86	87
SPL	Ontario Spills	Y	0	15	15
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	1	1
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	55	55
	Total:		18	457	475

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	S/0.0	0.41	93
1	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	S/0.0	0.41	93
1	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	S/0.0	0.41	93
2	SCT	The Golden Imprint Inc.	130 Bentworth Ave North York ON M6A 1P7	S/0.0	0.41	94
2	GEN	1019734 ONTARIO LTD.	130 BENTWORTH AVENUE TORONTO ON M6A 1P7	S/0.0	0.41	94
2	GEN	PRESIDENTIAL DRY CLEANERS	130 BENTWORTH AVENUE TORONTO ON M6A 1P7	S/0.0	0.41	94
2	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	S/0.0	0.41	95
2	GEN	ARMSTRONG BAUM PLUMBING & HEATING REG'D STYLE NAME	130 BENTWORTH AVE TORONTO ON M6A 1P7	S/0.0	0.41	95

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
2	EHS		130 Bentworth Avenue Toronto ON M6A 1P7	S/0.0	0.41	95
2	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	S/0.0	0.41	96
2	GEN	658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON	S/0.0	0.41	96
2	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	S/0.0	0.41	96
2	GEN	658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON M6A1P7	S/0.0	0.41	97
2	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	S/0.0	0.41	97
2	GEN	2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	S/0.0	0.41	97
2	GEN	658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON M6A1P7	S/0.0	0.41	98
2	CDRY	North Park Dry Cleaners	130 Bentworth Ave. Toronto ON M6A1P7	S/0.0	0.41	98
3	EHS		109 Cartwright Avenue Toronto ON M6A 1V4	NNW/0.0	-1.31	99

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
4	WWIS		111 CARTWRIGHT AVE. TORONTO ON ***Well ID:*** 7332346	NW/6.1	-0.55	99
5	WWIS		109 CARTWRIGHT AVE TORONTO ON ***Well ID:*** 7048099	NW/9.0	-0.53	102
6	EHS		111 Cartwright Avenue North York ON M6A 1V4	NW/11.2	-0.72	104
7	SCT	CLASSIC MANTEL INDUSTRIES LTD.	111 Cartwright Ave Toronto ON M6A 1V4	NW/11.5	-1.33	105
7	SCT	Classic Mantel Industries Ltd.	111 Cartwright Ave North York ON M6A 1V4	NW/11.5	-1.33	105
8	WWIS		105-123 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 6929659	SSE/13.8	0.41	105
9	WWIS		111 CARTWRIGHT AVE. Toronto ON ***Well ID:*** 7332345	NW/15.9	-1.56	108
10	WWIS		111 CARTWRIGHT AVE. Toronto ON ***Well ID:*** 7332344	NW/21.3	-1.04	111
11	CA	CANADA CUP INC.	137 BENTWORTH AVE. TORONTO CITY ON M6A 1P6	S/27.7	0.46	114
11	SCT	JAMES RIVER CANADA INC.	137 BENTWORTH AVE NORTH YORK ON M6A 1P6	S/27.7	0.46	114
11	SCT	FORT JAMES CANADA INC.	137 Bentworth Ave North York ON M6A 1P6	S/27.7	0.46	114
11	CA		137 Bentworth Avenue Toronto ON M6A 1P6	S/27.7	0.46	114

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	EBR	Fort James Canada Inc.	137 Bentworth Avenue Toronto Ontario Toronto ON	S/27.7	0.46	115
11	SCT	Georgia-Pacific Canada Inc.	137 Bentworth Ave North York ON M6A 1P6	S/27.7	0.46	115
11	GEN	CANADA CUP INC.	137 BENTWORTH AVE. TORONTO ON M6A 1P6	S/27.7	0.46	116
11	GEN	CANADA CUP (SEE & USE ON1947701) 08-289	137 BENTWORTH AVE. TORONTO ON M6A 1P6	S/27.7	0.46	116
11	GEN	CANADA CUP INC. 08-289	137 BENTWORTH AVE. TORONTO ON M6A 1P6	S/27.7	0.46	116
11	GEN	JAMES RIVER CANADA INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	S/27.7	0.46	117
11	GEN	FORT JAMES CANADA INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	S/27.7	0.46	117
11	GEN	GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	S/27.7	0.46	118
11	EHS		137 Bentworth Avenue North York ON M6A 1P6	S/27.7	0.46	118
11	EHS		137 Bentworth Ave Toronto ON M6A 1P6	S/27.7	0.46	118
11	EBR	Fort James Canada Inc.	137 Bentworth Avenue Toronto Ontario Toronto ON	S/27.7	0.46	118
11	SCT	The Morris Group/Marketing	137 Bentworth Ave Toronto ON M6A 1P6	S/27.7	0.46	119

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	CA	Georgia-Pacific Canada, Consumer Products, Inc.	137 Bentworth Avenue Toronto ON M6A 1P6	S/27.7	0.46	119
11	ECA	Georgia-Pacific Canada, Consumer Products, Inc.	137 Bentworth Avenue Toronto ON L6X 1A9	S/27.7	0.46	119
11	ECA	Fort James Canada Inc.	137 Bentworth Avenue Toronto ON L6X 1A9	S/27.7	0.46	120
12	EHS		105-123 Bentworth Avenue Toronto ON M6A 1P6	SE/33.8	1.44	120
13	GEN	University of Toronto	U of T CDE - Shaw 105 Bentworth Ave. Unit 1 North York ON M6A 1P6	ESE/36.7	1.44	120
14	GEN	Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	NW/37.0	-2.08	121
15	WWIS		102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281892	N/37.6	-0.63	121
16	FST	DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AVE NORTH YORK M6A 1V4 ON CA ON	WNW/40.1	-1.58	124
16	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	125
16	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	125
16	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	126
16	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	126
16	GEN	Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	126

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	GEN	Dominion Sheet Metal and Roofing Works.	113 Cartwright Ave Toronto ON M6Z1V4	WNW/40.1	-1.58	127
16	GEN	Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	127
17	GEN	DOMINION SHEET METAL & ROOFING WKS	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	WNW/40.1	-1.58	128
17	GEN	DOMINION SHEET METAL & ROOFING WKS12-523	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	WNW/40.1	-1.58	128
17	GEN	DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	WNW/40.1	-1.58	128
17	GEN	1262589 Ontario Ltd.	113 CARTWRIGHT AVENUE NORTH YORK ON	WNW/40.1	-1.58	129
17	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	129
17	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	130
17	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	130
17	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	WNW/40.1	-1.58	131
17	GEN	1262589 Ontario Ltd.	113 Cartwright Avenue North York ON	WNW/40.1	-1.58	131
18	SPL	PETRO-CANADA	113 CARTWRIGHT AV SERVICE STATION TORONTO CITY ON M6A 1V4	WNW/41.3	-1.51	132
18	PRT	DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	WNW/41.3	-1.51	132

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
18	FSTH	DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	WNW/41.3	-1.51	132
18	FSTH	DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	WNW/41.3	-1.51	132
19	WWIS		102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281833	N/45.0	-0.56	133
20	PRT	CITY OF NORTH YORK PUBLIC WORKS DEPT	140 BENTWORTH AV NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	136
20	GEN	NORTH YORK, CITY OF	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	136
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	137
20	FSTH	CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES	140 BENTWORTH AVE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	137
20	FSTH	CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES	140 BENTWORTH AVE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	137
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	138
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	138
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	138
20	FST	CITY OF TORONTO	140 BENTWORTH AVE NORTH YORK M6A 1P7 ON CA ON	WSW/46.1	-0.53	139

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	139
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON	WSW/46.1	-0.53	140
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	140
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	141
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	141
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	141
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	142
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	142
20	GEN	CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	WSW/46.1	-0.53	143
21	WWIS		102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281891	N/49.6	-0.53	143
22	SCT	Georgia-Pacific Canada Inc.	123 Bentworth Ave North York ON M6A 1P6	SE/67.1	0.96	147
22	GEN	GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	SE/67.1	0.96	147

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	SCT	Georgia-Pacific Canada Inc.	123 Bentworth Ave North York ON M6A 1P6	SE/67.1	0.96	148
22	GEN	GEORGIA-PACIFIC CANADA, CONSUMER PRODUCTS, ULC	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	SE/67.1	0.96	148
22	CA	Georgia-Pacific Canada, Consumer Products, Inc.	123 Bentworth Avenue Toronto ON M6A 1P6	SE/67.1	0.96	149
22	NPRI	Georgia-Pacific Canada Consumer Products LP	123 Bentworth Avenue Toronto ON M6A 1P6	SE/67.1	0.96	149
22	NPRI	GEORGIA-PACIFIC CANADA LP	123 Bentworth Avenue Toronto ON M6A1P6	SE/67.1	0.96	150
22	GEN	GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	SE/67.1	0.96	150
22	GEN	GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	SE/67.1	0.96	151
22	GEN	Kevric Ontario Real Estate Corp.	123 Bentworth Ave. Toronto ON M6A 1P6	SE/67.1	0.96	152
22	GEN	Kevric Ontario Real Estate Corp.	123 Bentworth Ave. Toronto ON M6A 1P6	SE/67.1	0.96	152
22	NPRI	GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 Bentworth Avenue Toronto ON M6A1P6	SE/67.1	0.96	152
22	NPRI	GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 Bentworth Avenue Toronto ON M6A1P6	SE/67.1	0.96	155
22	ECA	Georgia-Pacific Canada, Consumer Products, Inc.	123 Bentworth Avenue Toronto ON L6X 1A9	SE/67.1	0.96	156
22	NPRI	GEORGIA-PACIFIC CANADA LP	123 BENTWORTH AVENUE NOT AVAILABLE TORONTO ON M6A1P6	SE/67.1	0.96	156

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	NPRI	GEORGIA-PACIFIC CANADA LP	123 BENTWORTH AVENUE NOT AVAILABLE TORONTO ON M6A1P6	SE/67.1	0.96	157
22	GEN	Shaw Dental Laboratory, Inc.	105 -123 Bentworth Avenue, Unit 1 North York ON M6A1P6	SE/67.1	0.96	157
22	GEN	Shaw Dental Laboratory, Inc.	105 -123 Bentworth Avenue, Unit 1 North York ON M6A1P6	SE/67.1	0.96	158
23	SPL	TORONTO HYDRO	117 CARTWRIGHT AVE. TRANSFORMER TORONTO CITY ON M6A 1V4	W/67.3	-1.55	158
24	SCT	Ontario Acoustic Supply Inc.	139 Bentworth Ave North York ON M6A 1P6	SSW/67.9	-0.27	159
25	SCT	ITALDOOR & WOODWORKING LTD.	120 CARTWRIGHT AVE TORONTO ON M6A 1V2	NW/70.0	-2.55	159
25	SCT	Italdoor & Woodworking Ltd.	120 Cartwright Ave North York ON M6A 1V2	NW/70.0	-2.55	159
25	EHS		120 Cartwright Avenue Toronto ON M6A 1V2	NW/70.0	-2.55	160
25	EHS		120 Cartwright Avenue Toronto ON	NW/70.0	-2.55	160
25	EHS		120 Cartwright Ave Toronto ON	NW/70.0	-2.55	160
25	GEN	Toronto Transit Commission	120 Cartwright Ave Toronto ON M6A 1V2	NW/70.0	-2.55	160
26	WWIS		185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159338	WNW/73.5	-2.11	161
27	SCT	SELECTED MODE INC.	106 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	NNW/74.8	-1.52	164

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	WWIS		185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159339	W/74.9	-1.77	165
29	EHS		99 Cartwright Avenue Toronto ON	NE/79.8	1.44	168
30	WWIS		ON ***Well ID:*** 7161397	SSE/82.9	0.46	168
31	SCT	MEGA UNIFORMS LTD	104 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	N/83.8	-1.31	169
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	170
31	GEN	crisstar cabinets inc	104 Carwright Ave. North York ON	N/83.8	-1.31	170
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	171
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	171
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON	N/83.8	-1.31	172
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	172
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	172
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	173
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	173

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	174
31	GEN	Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	N/83.8	-1.31	174
32	WWIS		123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191977	SSE/86.8	0.49	174
33	WWIS		123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191975	SSE/87.8	0.28	178
34	GEN	105 Bentworth Inc	105 Bentworth Ave North York ON M6A 1P6	ESE/89.6	1.44	182
34	EHS		105 Bentworth Avenue North York ON M6A 1P6	ESE/89.6	1.44	182
34	EHS		105 Bentworth Avenue North York ON M6A 1P6	ESE/89.6	1.44	182
35	SCT	UNIVERSAL CHINA LAMP & GLASS	121 CARTWRIGHT AVE TORONTO ON M6A 1V4	W/90.0	-2.55	182
35	SCT	Universal China Lamp & Glass Co. Ltd. - Universal Lamp Manufacturing Division	121 Cartwright Ave Toronto ON M6A 1V4	W/90.0	-2.55	183
35	SCT	Universal Lamp	121 Cartwright Ave Toronto ON M6A 1V4	W/90.0	-2.55	184
36	SCT	Superb Fashions Ltd.	89 Bentworth Ave Unit 4 Toronto ON M6A 1P6	ESE/91.3	1.44	185
36	SCT	Russo Apparel Mfg. Inc.	89 Bentworth Ave Unit 3 North York ON M6A 1P6	ESE/91.3	1.44	185
36	SCT	XS: Clothing Co. Inc.	89 Bentworth Ave Unit 2 North York ON M6A 1P6	ESE/91.3	1.44	185

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
36	SCT	Empire Uniforms	89 Bentworth Ave Unit 3 Toronto ON M6A 1P6	ESE/91.3	1.44	186
36	SCT	Adele Wechsler Designs Limited	89 Bentworth Ave Unit 3 North York ON M6A 1P6	ESE/91.3	1.44	186
37	WWIS		123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191976	SSE/94.0	0.39	186
38	SCT	PICTURE PICTURE	122 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	NW/98.1	-3.56	190
38	SCT	Picture Picture Co.	122 Cartwright Ave North York ON M6A 1V2	NW/98.1	-3.56	190
38	SCT	Lamintech Corp. Ltd	122 Cartwright Ave North York ON M6A 1V2	NW/98.1	-3.56	191
38	GEN	MR. T-SHIRT INC.	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	NW/98.1	-3.56	191
38	GEN	MR. T-SHIRT INC.	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	NW/98.1	-3.56	191
38	GEN	MR. T-SHIRT INC. (OUT OF BUSINESS)	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	NW/98.1	-3.56	192
38	GEN	MR. T-SHIRT INC. (OUT OF BUSINESS)27-183	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	NW/98.1	-3.56	192
38	SCT	Picture Picture Co. Ltd.	122 Cartwright Ave Toronto ON M6A 1V2	NW/98.1	-3.56	192
38	SCT	Lamintech Corp. Ltd.	122 Cartwright Ave North York ON M6A 1V2	NW/98.1	-3.56	192
38	SCT	Lamin Tech	122A Cartwright Ave Toronto ON M6A 1V2	NW/98.1	-3.56	193

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	WWIS		ON **Well ID:** 7161057	SE/99.4	0.65	193
40	CA	I&D AUTOBODY & COLLISION CENTRE LTD.	142 BENTWORTH AVENUE TORONTO CITY ON M6A 1P7	WSW/100.7	-1.51	194
40	AUWR	CANADIAN IRON METAL INC	142 BENTWORTH AVE NORTH YORK ON M6A 1P7	WSW/100.7	-1.51	194
40	EBR	I & D Autobody and Collision Centre Limited	142 Bentworth Avenue Toronto ON	WSW/100.7	-1.51	194
41	WWIS		102 CARTRIGHT AVE Toronto ON **Well ID:** 7281890	N/108.0	-0.59	195
42	SCT	CAPPOLA FOOD INC.	92 CARTWRIGHT AVE TORONTO ON M6A 1V2	NNE/108.8	0.63	198
42	GEN	Cappola Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	198
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	199
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	199
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	199
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	200
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON	NNE/108.8	0.63	200
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	200

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	201
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	201
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	202
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	202
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	203
42	GEN	Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	NNE/108.8	0.63	203
43	WWIS		102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281889	N/109.2	-0.50	203
44	WWIS		99 CARTWRIGHT AVE Toronto ON ***Well ID:*** 7222994	ENE/121.3	2.44	207
45	EHS		85 Bentworth Avenue North York ON M6A 1P6	ESE/121.6	1.44	210
46	GEN	PRESTON METAL & ROOFING PRODUCTS	147 BENTWORTH AVENUE TORONTO ON M6A 1P6	SW/123.9	-0.68	210
46	GEN	PRESTON METAL (OUT OF BUSINESS) 31-244	147 BENTWORTH AVENUE TORONTO ON M6A 1P6	SW/123.9	-0.68	210
47	GEN	Aden Earthworks Inc.	147A Bentworth Ave Toronto ON M6A 1P6	SW/124.0	-0.68	211
47	GEN	Brea Water Technologies	147 Bentworth Ave Toronto ON M6A 1P6	SW/124.0	-0.68	211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
47	GEN	Aden Earthworks Inc.	147A Bentworth Ave Toronto ON M6A 1P6	SW/124.0	-0.68	211
48	EBR	1014177 Ontario Ltd.	147 Bentworth Avenue Toronto CITY OF TORONTO ON	SW/125.2	-0.72	212
48	CA	1014177 Ontario Ltd.	147 Bentworth Ave Toronto ON	SW/125.2	-0.72	212
48	EHS		147 Bentworth Ave Toronto ON	SW/125.2	-0.72	213
48	ECA	1014177 Ontario Ltd.	147 Bentworth Ave Toronto ON M6A 1P6	SW/125.2	-0.72	213
48	EHS		147 Bentworth Avenue North York ON M6A 1P6	SW/125.2	-0.72	213
48	EHS		147 Bentworth Avenue North York ON M6A 1P6	SW/125.2	-0.72	213
49	WWIS		185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159337	NW/128.5	-3.56	213
50	SPL	TRANSPORT TRUCK	127 CARTWRIGHT AVE. MOTOR VEHICLE (OPERATING FLUID) TORONTO CITY ON M6A 1V4	W/129.2	-2.56	217
50	SCT	BENIX & CO	127 CARTWRIGHT AVE TORONTO ON M6A 1V4	W/129.2	-2.56	217
51	WWIS		185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159336	NW/134.6	-3.56	218
52	GEN	EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	WSW/134.7	-1.36	221

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	GEN	EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	WSW/134.7	-1.36	221
52	GEN	EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	WSW/134.7	-1.36	222
52	GEN	EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	WSW/134.7	-1.36	222
53	WWIS		ON ***Well ID:*** 7232232	E/141.2	2.44	223
54	CA	NORTH YORK CITY	MCADAM AVE./PAUL DAVID ST. NORTH YORK CITY ON	E/142.3	2.44	224
55	WWIS		ON ***Well ID:*** 7218673	E/142.8	2.44	224
56	WWIS		161 BRIDGELAND TORONTO ON ***Well ID:*** 7154036	N/153.2	-0.60	225
57	SCT	SWENSON CANADA INC.	80 ORFUS RD NORTH YORK ON M6A 1M1	SSE/153.8	-0.62	227
57	SCT	SWENSON CANADA LIMITED INC.	80 ORFUS RD NORTH YORK ON M6A 1M1	SSE/153.8	-0.62	228
57	SCT	Wahl Canada Inc.	80 Orfus Rd North York ON M6A 1M1	SSE/153.8	-0.62	228
58	SCT	COLLEZIONI DONNA	150 BENTWORTH AVE TORONTO ON M6A 1P7	WSW/157.5	-1.62	228
59	SCT	ZALDIAM & CO	129 CARTWRIGHT AVE NORTH YORK ON M6A 1V4	W/157.9	-2.56	229
59	SCT	ZALDIAM & CO	129 Cartwright Ave Toronto ON M6A 1V4	W/157.9	-2.56	229

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
59	SCT	Trippers Inc.	129 Cartwright Ave North York ON M6A 1V4	W/157.9	-2.56	229
60	CA	GRANT AUTO REPAIR LIMITED	151-153 BENTWORTH AVE.,LOT 66 NORTH YORK CITY ON M6A 1P6	SW/158.5	-1.55	229
60	CA	GRAF AUTO REPAIR LIMITED	151-153 BENTWORTH AVE., LOT 66 NORTH YORK CITY ON M6A 1P6	SW/158.5	-1.55	230
60	EASR	GRAF AUTO REPAIR LIMITED	151 BENTWORTH AVE NORTH YORK ON M6A 1P6	SW/158.5	-1.55	230
61	SCT	SM FOOTWEAR LTD.	130 ORFUS RD NORTH YORK ON M6A 1L9	SSW/160.5	-1.58	230
61	EHS		130 Orfus Road Toronto ON M6A 1L9	SSW/160.5	-1.58	231
62	WWIS		106-110 ORFUS RD NORTH YORK ON ***Well ID:*** 6929661	SSW/165.3	-1.49	231
63	WWIS		161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154035	N/168.7	0.49	233
64	EHS		100 Orfus Rd Toronto ON M6A1L9	S/174.0	-1.73	236
65	WWIS		161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154054	N/179.3	-0.61	237
66	GEN	SWENSON CANADA INC	80 ORFUS ROAD TORONTO ON M6A 1M1	SSE/187.0	-0.59	239
66	GEN	SWENSON CANADA INC 36-270	80 ORFUS ROAD TORONTO ON M6A 1M1	SSE/187.0	-0.59	240
66	GEN	SWENSON CANADA INC.	80 ORFUS ROAD TORONTO ON M6A 1M1	SSE/187.0	-0.59	240

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
66	GEN	SWENSON CANADA INC.	80 ORFUS ROAD TORONTO ON M6A 1M1	SSE/187.0	-0.59	241
67	SCT	EMERSON SUMMERS CO. LTD.	88 ORFUS RD UNIT 2 NORTH YORK ON M6A 1L9	SSE/187.0	-0.67	241
68	WWIS		157 Bentworth Ave, York Toronto ON ***Well ID:*** 7048137	SW/194.0	-1.50	242
69	EHS		155-157 Bentworth Ave. Toronto ON M6A 1P6	WSW/194.5	-1.58	245
70	PES	HARVEY'S BUILDING SUPPLIES (1987) LTD.	96 ORFUS ROAD TORONTO ON M6A 1L9	SSE/195.6	-1.58	245
70	PES	HARVEY'S BUILDING SUPPLIES (1987) LTD.	96 ORFUS ROAD TORONTO ON M6A 1L9	SSE/195.6	-1.58	245
71	GEN	ERIC KINGSTON SALES LTD.	162 BENTWORTH AVE. TORONTO ON M6A 1P7	WSW/195.8	-1.53	246
71	GEN	ERIC KINGSTON SALES LTD.	162 BENTWORTH AVE. TORONTO ON M6A 1P7	WSW/195.8	-1.53	246
71	GEN	ERIC KINGSTON (OUT OF BUSINESS) 14-247	162 BENTWORTH AVE. TORONTO ON M6A 1P7	WSW/195.8	-1.53	247
71	GEN	ERIC KINGSTON SALES LTD. 14-247	162 BENTWORTH AVE. TORONTO ON M6A 1P7	WSW/195.8	-1.53	247
72	SCT	BAZAAR & NOVELTY CO.	76 ORFUS RD NORTH YORK ON M6A 1L9	SE/197.7	-0.31	247
72	SCT	BAZAAR NOVELTY	76 ORFUS RD NORTH YORK ON M6A 1L9	SE/197.7	-0.31	248
73	WWIS		161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154034	N/197.7	0.46	248

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	SCT	BRITSTONE TEXTILE IMPORT	155 BENTWORTH AVE TORONTO ON M6A 1P6	SW/200.2	-1.52	251
74	SCT	Canada Glass & Mirror Co.	155 Bentworth Ave Toronto ON M6A 1P6	SW/200.2	-1.52	251
75	SPL	NORTH YORK HYDRO	133 CARTWRIGHT TORONTO CITY ON M6A 1V4	W/211.8	-3.56	252
75	GEN	ICI CONVERTERS INK 21-545	133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE BRAMPTON ON M6A 1V4	W/211.8	-3.56	252
75	GEN	ICI CONVERTERS INK(OUT OF BUS)	133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE BRAMPTON ON M6A 1V4	W/211.8	-3.56	253
75	GEN	CONVERTERS INK	133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	W/211.8	-3.56	253
75	GEN	CONVERTERS INC.(OUT OF BUS) 11-026	133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	W/211.8	-3.56	253
75	GEN	CONVERTERS INK LTD. (OUT OF BUSINESS)	133 CARTWRIGHT AVENUE TORONTO ON M6A 1V4	W/211.8	-3.56	254
75	GEN	CHAMPION INVESTMENTS LTD. 07-538	133 CARTWRIGHT AVE., NORTH YORK C/O BOX 47 SUITE 2600, 20 QUEEN ST. W. TORONTO ON M6A 1V4	W/211.8	-3.56	254
76	SPL	UNKNOWN	ORFUS RD/DUFFLAW RD & OUTFALL H275 IN RUSTIC PARK. TORONTO CITY ON	SSE/212.7	-1.27	254
77	SCT	GREEN JAY SALES INC.	157 BENTWORTH AVE TORONTO ON M6A 1P6	SW/214.3	-1.55	255
77	SCT	MANTEX JOBBERS LTD.	157 Bentworth Ave Unit 1 North York ON M6A 1P6	SW/214.3	-1.55	255
77	SCT	Minuteman Press	157 Bentworth Ave Toronto ON M6A 1P6	SW/214.3	-1.55	256

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
77	SCT	Dunmet Products (1998) Ltd.	157 Bentworth Ave North York ON M6A 1P6	SW/214.3	-1.55	256
77	GEN	The Promise Holdings Inc.	157 Bentworth Avenue Toronto ON M6A 1P6	SW/214.3	-1.55	256
77	GEN	Dunmet Products Ltd	157 Bentworth Ave North York ON M6A 1P6	SW/214.3	-1.55	256
77	GEN	Dunmet Products (2014) Limited	157 Bentworth avenue Toronto ON M6A1P6	SW/214.3	-1.55	257
78	WWIS		130 BRIDGELAND ROAD Toronto ON ***Well ID:*** 7179517	NNE/219.9	1.37	257
79	SPL	G.A. FOSS TRANSPORT LTD.	161 BRIDGELAND AVE. TANK TRUCK (CARGO) TORONTO CITY ON	N/221.6	0.55	260
79	GEN	BROWNING-FERRIS INDUSTRIES LTD.	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	N/221.6	0.55	261
79	GEN	BROWNING-FERRIS INDUSTRIES LTD.	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	N/221.6	0.55	261
79	GEN	BROWNING-FERRIS INDUSTRIES LTD. 06-111	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	N/221.6	0.55	262
79	GEN	BROWNING-FERRIS INDUSTRIES LIMITED	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	N/221.6	0.55	262
79	GEN	WASTECO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	263
79	GEN	WASTECO, A DIVISION OF	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	263
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON	N/221.6	0.55	263

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
79	EHS		161 Bridgeland Avenue Toronto ON	N/221.6	0.55	264
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	264
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	265
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	265
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	265
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON	N/221.6	0.55	266
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	266
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	267
79	GEN	SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	267
79	GEN	SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	268
79	GEN	WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	N/221.6	0.55	268
79	GEN	SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	268
79	GEN	WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	N/221.6	0.55	269

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
79	GEN	WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	N/221.6	0.55	269
79	GEN	SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	270
79	EHS		161 Bridgeland Avenue North York ON M6A 1Z1	N/221.6	0.55	270
79	GEN	SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	N/221.6	0.55	270
79	GEN	WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	N/221.6	0.55	271
79	EHS		161 Bridgeland Avenue North York ON M6A 1Z1	N/221.6	0.55	271
80	SCT	Drummer's East Agency Ltd.	66 Orfus Rd North York ON M6A 1L9	SE/222.0	0.10	271
81	SCT	GENERAL TRANSFORMERS LTD.	185 BRIDGELAND AVE TORONTO ON M6A 1Y7	NNW/224.4	-1.50	272
81	SPL		185 Bridgeland Ave<UNOFFICIAL> Toronto ON M6A 1Y7	NNW/224.4	-1.50	272
81	SPL	Faylaura Investments Inc.	185 Bridgeland Ave Toronto ON M6A 1Y7	NNW/224.4	-1.50	272
81	EHS		185 Bridgeland Avenue Toronto ON M6A 1Y7	NNW/224.4	-1.50	273
81	SPL		Property west of 185 Bridgeland Avenue Toronto ON	NNW/224.4	-1.50	273
82	SCT	AMERICAN LOUVER OF CANADA LTD.	185 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	NNW/224.7	-1.50	274

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
82	SCT	Silkscape Designs Inc.	185 Bridgeland Ave Unit 1 North York ON M6A 1Y7	NNW/224.7	-1.50	274
83	SCT	Lorellana Couture Inc.	164A Bentworth Ave Toronto ON M6A 1P7	WSW/231.1	-2.56	274
84	EHS		164 Bentworth Ave Toronto ON M6A1P7	WSW/231.2	-2.56	274
85	WWIS		278 BRIDGELAND AVE TORONTO ON ***Well ID:*** 6930320	N/231.4	1.13	274
86	SPL		223 Bridgeland Avenue, North York Toronto ON	NW/232.9	-2.56	278
87	WWIS		ON ***Well ID:*** 7192516	WSW/239.5	-2.56	278
87	WWIS		ON ***Well ID:*** 7231719	WSW/239.5	-2.56	279
88	WWIS		245 BRIDGELAND AVE Toronto ON ***Well ID:*** 7286369	WNW/242.4	-3.35	280
89	GEN	1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	SE/242.6	-0.59	284
89	GEN	1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	SE/242.6	-0.59	284
89	GEN	1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	SE/242.6	-0.59	284
90	SCT	HUGHES CONTAINERS LIMITED	95 ORFUS RD TORONTO ON M6A 1M4	S/244.2	-2.56	285
91	WWIS		1277 Caledonia rd Toronto ON	W/244.7	-3.56	285

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7365139			
92	EHS		135 Cartwright Avenue North York ON M6A 1V4	W/246.2	-3.56	288
93	SCT	Alternator Exchange Co. Ltd.	124A Cartwright Ave North York ON M6A 1V2	WNW/246.7	-3.56	288
93	SCT	ALTERNATOR EXCHANGE CO. LTD.	124 A CARTWRIGHT AVE TORONTO ON M6A 1V2	WNW/246.7	-3.56	288
93	SCT	Arte Unico Inc.	124 Cartwright Ave Toronto ON M6A 1V2	WNW/246.7	-3.56	289
93	GEN	ALTERNATOR EXCHANGE LTD.	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	WNW/246.7	-3.56	289
93	GEN	ALTERNATOR EXCHANGE COMPANY LTD.	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	WNW/246.7	-3.56	290
93	GEN	ALTERNATOR EXCHANGE COMPANY LTD. 02-029	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	WNW/246.7	-3.56	290
93	GEN	ALTERNATOR EXCHANGE COMPANY LIMITED	124A CARTWRIGHT AVENUE TORONTO ON M6A 1V2	WNW/246.7	-3.56	290
93	GEN	ALTERNATOR EXCHANGE COMPANY LIMITED	124 A Cartwright Ave., Toronto ON M6A 1V2	WNW/246.7	-3.56	291
93	SCT	Arte Unico Inc.	124 Cartwright Ave North York ON M6A 1V2	WNW/246.7	-3.56	291
94	SCT	ARBOR STORE INTERIORS INC.	52 ORFUS RD NORTH YORK ON M6A 1L6	ESE/254.6	-0.58	292
94	SCT	UNIVERSAL SHOWCASE LTD.	52 Orfus Rd North York ON M6A 1L6	ESE/254.6	-0.58	292
94	EHS		52 Orfus Road Toronto ON	ESE/254.6	-0.58	292

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
95	WWIS		ON ***Well ID:*** 7374604	NW/254.9	-1.54	292
96	GEN	SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	WSW/255.0	-2.56	293
96	EHS		166 Bentworth Avenue Toronto ON M6A 1P7	WSW/255.0	-2.56	294
96	GEN	SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	WSW/255.0	-2.56	294
96	GEN	SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	WSW/255.0	-2.56	294
96	GEN	SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	WSW/255.0	-2.56	295
97	EHS		167 Bentworth Avenue North York ON M6A 1P6	SW/257.7	-2.56	295
98	BORE		ON	W/261.4	-3.56	295
99	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181106	WSW/261.6	-2.56	297
100	SCT	CALEDONIA MARBLE COMPANY LTD.	167 BENTWORTH AVE NORTH YORK ON M6A 1P6	SW/264.2	-2.56	300
100	SCT	CALEDONIA MARBLE COMPANY LTD	167 BENTWORTH AVE NORTH YORK ON M6A 1P6	SW/264.2	-2.56	300
100	SCT	Caledonia Marble Company Ltd.	167 Bentworth Ave Toronto ON M6A 1P6	SW/264.2	-2.56	301
101	WWIS		102 -123 BENTOWORTH AVE. NORTH YORK ON	ENE/265.5	3.92	301

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7149492			
102	GEN	SUPERIOR CRANE LIMITED	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNW/266.2	-1.59	304
102	GEN	SUPERIOR OUT OF BUSINESS	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNW/266.2	-1.59	304
102	GEN	SUPERIOR OUT OF BUSINESS 34-130	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNW/266.2	-1.59	305
102	GEN	FER-PAL CONSTRUCTION LTD.	195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	NNW/266.2	-1.59	305
102	GEN	FER-(OUT OF BUS)	195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	NNW/266.2	-1.59	305
102	GEN	H & E Copy Services Inc.	195 Bridgeland Ave. Toronto ON M6A 1Y7	NNW/266.2	-1.59	306
102	GEN	Curtis Properties (195 Bridgeland) Inc.	195 Bridgeland Ave Toronto ON M6A 1Y7	NNW/266.2	-1.59	306
102	SPL	Shefa<UNOFFICIAL>	195 Bridgeland Avenue Toronto ON	NNW/266.2	-1.59	307
102	EHS		195 Bridgeland Avenue North York ON M6A 1Z4	NNW/266.2	-1.59	307
102	WDS	Gus Kastanis	195 Bridgeland toronto ON M6A 1Y7	NNW/266.2	-1.59	307
103	SCT	ATTARDO CO. LTD.	1259 CALEDONIA RD TORONTO ON M6A 2X6	W/267.2	-3.53	308
103	BORE		ON	W/267.2	-3.53	308

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
103	SCT	Yongetex Limited	1259 Caledonia Rd North York ON M6A 2X6	W/267.2	-3.53	310
103	EHS		1259 Caledonia Road Toronto ON M6A 2X6	W/267.2	-3.53	310
104	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7180722	W/267.4	-2.87	310
105	WWIS		112-120 ORFUS RD NORTH YORK ON ***Well ID:*** 6929662	SW/267.8	-2.56	314
106	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181269	WSW/268.9	-2.67	316
107	BORE		ON	WNW/269.3	-3.56	320
108	WWIS		1289 CALEDONIA RD NORTH YORK ON ***Well ID:*** 7167693	WNW/270.1	-2.55	321
109	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7180725	WSW/270.4	-2.56	325
110	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181104	WSW/271.2	-2.67	328
111	GEN	BASF CANADA INC.	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	W/271.3	-3.56	331
111	GEN	BASF (OUT OF BUS)	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	W/271.3	-3.56	331
111	GEN	BASF CANADA INC. (OUT OF BUSINESS)	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	W/271.3	-3.56	332

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
111	SPL		1277 Caledonia Rd Toronto ON	W/271.3	-3.56	332
111	GEN	732090 Ontario LTD	1277 Caledonia Road Toronto ON M6A2X7	W/271.3	-3.56	333
111	EHS		1277 Caledonia Rd North York ON M6A 1V2	W/271.3	-3.56	333
111	EHS		1277 Caledonia Rd North York ON M6A 1V2	W/271.3	-3.56	333
112	WWIS		167 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 7316357	WSW/272.6	-2.56	333
113	WWIS		102 -123 BENTWORTH AVE. NORTH YORK ON ***Well ID:*** 7149493	ENE/274.3	3.36	336
114	SCT	FANCY DIAMOND JEWELLERY LTD.	103 ORFUS RD NORTH YORK ON M6A 1M4	S/274.4	-3.25	340
114	SCT	EDWARD DWORKIN DISTRIBUTORS	103 ORFUS RD TORONTO ON M6A 1M4	S/274.4	-3.25	340
114	GEN	Beebed Realty	103 Orphus Rd. Toronto ON	S/274.4	-3.25	340
115	SCT	TORONTO BARBER & BEAUTY SUPPLY	112 ORFUS RD TORONTO ON M6A 1L9	SSW/275.2	-3.45	341
116	WWIS		167 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 7316356	SW/275.4	-2.56	341
117	WWIS		1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181105	WSW/276.2	-2.87	344
118	EHS		1277 Caledonia Road North York ON M6A 1V2	W/276.4	-3.56	347

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
118	EHS		1277 Caledonia Road North York ON M6A 1V2	W/276.4	-3.56	348
119	GEN	CALEDONIA MARBLE COMPANY LTD.	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	WSW/277.4	-2.56	348
119	GEN	CALEDONIA (OUT OF BUS) 07-054	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	WSW/277.4	-2.56	348
119	GEN	CALEDONIA MARBLE CO. (OUT OF BUSINESS)	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	WSW/277.4	-2.56	348
119	EHS		176 Bentworth Avenue North York ON M6A 1P7	WSW/277.4	-2.56	349
120	WWIS		80 DUFFLAW Toronto ON ***Well ID:*** 7173825	S/278.0	-2.56	349
121	GEN	CALEDONIA MARBLE COMPANY LTD.	167 BENTWORTH AVENUE TORONTO ON M6A 1P6	SW/278.8	-2.56	352
121	GEN	Caledonia Marble Co Ltd	167 Bentworth Ave. Toronto ON M6A 1P7	SW/278.8	-2.56	353
121	GEN	Caledonia Marble Co Ltd	167 Bentworth Ave. Toronto ON M6A 1P7	SW/278.8	-2.56	353
122	BORE		ON	ESE/280.0	-0.53	354
123	SCT	Simcoe Fluid Power Inc.	61 McAdam Ave Toronto ON M6A 1S6	E/280.4	3.28	355
123	EASR	ALESSANDRO GERALDO, DEBORA CANTANHEDE	61 McAdam AV Toronto ON M6A 1S6	E/280.4	3.28	355
124	NPCB	CURTIS PROPERTIES	SUITE 101; 201 BRIDEGLAND AVE. SUITE 101; 201 BRIDGELAND AVE. TORONTO ON M6A 1Y7	NW/282.9	-1.58	356

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
124	SCT	ANGEL DANCE WEAR INC	201 BRIDGELAND AVE UNIT 3 TORONTO ON M6A 1Y7	NW/282.9	-1.58	356
124	GEN	Zeifmans LLP	201 Bridgeland Ave Toronto ON M6A 1Y7	NW/282.9	-1.58	356
125	SCT	LOUIS INTERIORS INC	120 ORFUS RD TORONTO ON M6A 1L9	SW/285.2	-3.37	356
126	SCT	Galaxy Silk Screening Design	1245 Caledonia Rd Toronto ON M6A 2X6	WSW/285.8	-2.56	357
126	GEN	GALAXY SILK SCREENING INC.	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	WSW/285.8	-2.56	357
126	GEN	Finer Fabrics Ltd	1245 Caledonia Rd Toronto ON M6A 2X6	WSW/285.8	-2.56	357
126	GEN	GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	WSW/285.8	-2.56	358
126	GEN	GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	WSW/285.8	-2.56	358
126	GEN	GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	WSW/285.8	-2.56	358
127	WWIS		1277 Caledonia rd Toronto ON ***Well ID:*** 7365301	W/286.3	-3.56	359
128	EHS		185 Bridgeland Avenue North York ON M6A 2V1	NNW/286.3	-0.49	362
129	WWIS		ON ***Well ID:*** 7343059	WSW/286.7	-2.56	362
130	EHS		Dufflaw Rd Orfus Rd Toronto ON	SSE/286.7	-2.56	363

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	GEN	ULTRAMAR CANADA LTD.	171 BENTWORTH AVENUE CARDLOCK SITE 00235 TORONTO ON M6A 1P6	WSW/287.1	-2.56	363
131	GEN	ULTRAMAR CANADA LTD.	ULTRAMAR CARDLOCK - SITE 00235 171 BENTWORTH AVENUE TORONTO ON M6A 1P6	WSW/287.1	-2.56	364
131	DTNK	ULTRAMAR CANADA INC	171 BENTWORTH AV TORONTO ON	WSW/287.1	-2.56	364
132	WWIS		245 BROADLAND AVE Toronto ON ***Well ID:*** 7191352	WNW/288.5	-2.53	365
133	SCT	PREMIER KNITWEAR INC.	1283 CALEDONIA RD TORONTO ON M6A 2X7	WNW/289.2	-3.56	368
133	SCT	Louis Interiors Inc.	1283 Caledonia Rd Toronto ON M6A 2X7	WNW/289.2	-3.56	368
133	GEN	MERIT AUTOMOTIVE PRODUCTS LTD.	1283 CALEDONIA ROAD NORTH YORK ON M6A 2X7	WNW/289.2	-3.56	368
133	GEN	MERIT AUTOMOTIVE PRODUCTS LTD. 26-162	1283 CALEDONIA ROAD NORTH YORK ON M6A 2X7	WNW/289.2	-3.56	369
134	GEN	658457 Ontario Inc.	153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6	NNE/290.2	1.59	369
134	GEN	658457 Ontario Inc.	153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6	NNE/290.2	1.59	369
135	SCT	GALAXY BAKERY	153 BRIDGELAND AVE UNIT 5 TORONTO ON M6A 2Y6	NNE/290.3	1.59	370
135	SCT	HOGARTH PRINTING COMPANY LIMIT	153 BRIDGELAND AVE UNIT 14 TORONTO ON M6A 2Y6	NNE/290.3	1.59	370
135	SCT	STEAM SAUNA	153 Bridgeland Ave Unit 13 Toronto ON M6A 2Y6	NNE/290.3	1.59	370

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
135	SCT	UNITOOL Inc.	153 Bridgeland Ave Unit 12 North York ON M6A 2Y6	NNE/290.3	1.59	370
135	GEN	D.S. FRASER EQUIPMENT INC.	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	NNE/290.3	1.59	371
135	GEN	D.S. FRASER EQUIPMENT INC. 48-039	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	NNE/290.3	1.59	371
135	GEN	D.S. (OUT OF BUS)	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	NNE/290.3	1.59	372
135	GEN	BEAUTIFUL SOUTH INC.	153 BRIDGELAND AVENUE, UNIT 4 TORONTO ON M6A 2Y6	NNE/290.3	1.59	372
135	SCT	Steam Sauna Inc.	153 Bridgeland Ave Unit 13 Toronto ON M6A 2Y6	NNE/290.3	1.59	372
135	SCT	Rainbow Aluminum/Vinyl Prods	153 Bridgeland Ave Unit 15 North York ON M6A 2Y6	NNE/290.3	1.59	373
136	EHS		227 Bridgeland Avenue North York ON M6A 1Z4	NW/291.0	-2.14	373
137	RSC		1215 Caledonia Road Toronto ON M6A 2X3	WSW/291.4	-2.56	373
138	WWIS		1289 CALEDONIA RD NORTH YORK ON ***Well ID:*** 7167692	WNW/291.6	-2.59	374
139	SPL		1285 Caledonia Rd Toronto ON	WNW/291.8	-2.50	377
139	SPL	City of Toronto	1285 Caledonia Rd. Toronto ON	WNW/291.8	-2.50	377
140	PRT	FRANK & WILLIES SERVICE CENTRE LTD	141 CARTWRIGHT AV TORONTO ON M6A1V4	W/291.8	-4.08	378

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
141	GEN	S & F DEMELIS CONSTRUCTION LTD.	141 CARTWRIGHT AVENUE TORONTO ON M6A 1V4	W/291.8	-4.08	378
141	SPL	City of Toronto	141 Cartwright Ave<UNOFFICIAL> Toronto ON M6A 1V4	W/291.8	-4.08	378
141	DTNK	FRANK & WILLIES SERVICE CENTRE LTD	141 CARTWRIGHT AV TORONTO ON M6A 1V4	W/291.8	-4.08	379
142	BORE		ON	ESE/292.3	0.06	379
143	WWIS		1277 Caledonia rd Toronto ON ***Well ID:*** 7365303	W/294.1	-3.56	381
144	BORE		ON	W/294.6	-3.40	384
145	WWIS		1277 Caledonia rd Toronto ON ***Well ID:*** 7365302	W/294.9	-3.71	385
146	SCT	DUNMET PRODUCTS (1988) LTD.	178 BENTWORTH AVE NORTH YORK ON M6A 1P7	WSW/295.0	-2.56	388
146	SCT	Dunmet Products (1998) Ltd.	178 Bentworth Ave North York ON M6A 1P7	WSW/295.0	-2.56	388
146	EHS		178-180 Bentworth Avenue Toronto ON M6A 1P7	WSW/295.0	-2.56	389
146	EHS		178-180 Bentworth Avenue Toronto ON M6A 1P7	WSW/295.0	-2.56	389
147	GEN	ROTHMANS OF PALL MALL CANADA LTD	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	SE/295.0	-1.59	389
147	GEN	ROTHMANS BENSON & HEDGES INC.	BENSON & HEDGES 67-75 DUFFLAW ROAD	SE/295.0	-1.59	390

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			TORONTO ON M6A 2W4			
147	GEN	ROTHMANS (OUT OF BUSINESS)	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	SE/295.0	-1.59	390
147	GEN	ROTHMANS (OUT OF BUSINESS) 33-040	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	SE/295.0	-1.59	390
147	GEN	ROTHMANS BENSON & HEDGES(OUT OF BUS.)	67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	SE/295.0	-1.59	391
148	EHS		225 Bridgeland Ave Toronto ON M6A 1Y7	NW/295.6	-1.95	391
149	GEN	TORONTO DISTRICT SCHOOL BOARD	YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD TORONTO ON M6A 1L6	ESE/296.0	-0.24	391
149	GEN	TORONTO DISTRICT SCHOOL BOARD	YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD TORONTO ON M6A 1L6	ESE/296.0	-0.24	392
150	BORE		ON	W/296.3	-3.56	393
151	EHS		67 & 75 Dufflaw Rd & 65 Orfus Rd_Toronto (ERIS) North York ON M6A 1L7	SE/297.3	-1.59	394
152	WWIS		245 BRIDGELAND AVE Toronto ON ***Well ID:*** 7286370	WNW/298.4	-2.63	394
153	SCT	Geovin Furniture Inc.	245 Bridgeland Ave North York ON M6A 1Y7	WNW/298.9	-2.65	398
153	EBR	Geovin Furniture Inc.	245 Bridgeland Avenue Toronto M6A 1Y7 CITY OF TORONTO ON	WNW/298.9	-2.65	398
153	CA	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	398

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
153	GEN	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	399
153	EHS		245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	399
153	GEN	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	399
153	GEN	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	399
153	GEN	245 Bridgeland Avenue Ltd	245 Bridgeland Avenue Toronto ON	WNW/298.9	-2.65	400
153	GEN	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	400
153	ECA	Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	WNW/298.9	-2.65	400
154	EHS		245 Bridgeland Avenue Toronto ON	WNW/299.0	-2.65	401
155	SCT	DOLDAN FASHIONS MFG CO LTD	1287 CALEDONIA RD NORTH YORK ON M6A 2X7	WNW/299.5	-2.53	401
155	SCT	DOLDAN FASHIONS	1287 CALEDONIA RD NORTH YORK ON M6A 2X7	WNW/299.5	-2.53	401
155	SCT	DOLDAN FASHIONS MFG. CO. LTD.	1287 Caledonia Rd North York ON M6A 2X7	WNW/299.5	-2.53	401
155	SCT	Doldan Fashions Manufacturing Co. Ltd.	1287 Caledonia Rd North York ON M6A 2X7	WNW/299.5	-2.53	402
156	AUWR	SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	NW/299.9	-2.14	402

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
156	AUWR	SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A1Y7	NW/299.9	-2.14	402
156	GEN	Dax Automotive and Collision	241 Bridgeland Ave 241 Bridgeland Ave North York ON M6A 1Y7	NW/299.9	-2.14	402
156	AUWR	SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A1Y7	NW/299.9	-2.14	403
157	SCT	Giffin Sheet Metals Limited	133 Bridgeland Ave North York ON M6A 1Y7	NNE/299.9	2.97	403
157	GEN	GIFFIN SHEET METALS LIMITED	LOT 1, CONC. 5, VAUGHAN TWP. 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNE/299.9	2.97	403
157	GEN	GIFFIN SHEET METALS LIMITED	133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNE/299.9	2.97	404
157	GEN	GIFFIN SHEET METALS LIMITED 18-256	LOT 1, CONC. 5, VAUGHAN TWP. 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNE/299.9	2.97	404
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	NNE/299.9	2.97	405
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	NNE/299.9	2.97	405
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	NNE/299.9	2.97	406
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	NNE/299.9	2.97	406
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	NNE/299.9	2.97	406

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON	NNE/299.9	2.97	407
157	NPRI	GIFFIN SHEET METALS LTD.	133 BRIDGELAND AVENUE NOT AVAILABLE TORONTO ON M6A 1Y7	NNE/299.9	2.97	407
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	409
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	409
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	410
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	410
157	NPRI	Giffin Sheet Metals Ltd.	133 BRIDGELAND AVENUE NOT AVAILABLE TORONTO ON M6A 1Y7	NNE/299.9	2.97	411
157	EHS		133 Bridgeland Avenue North York ON M6A 1Z4	NNE/299.9	2.97	412
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	412
157	GEN	GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	NNE/299.9	2.97	413
157	GEN	OXFORD PROPERTIES GROUP	115-133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	NNE/299.9	2.97	414

Executive Summary: Summary By Data Source

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-May 31, 2022 has found that there are 4 AUWR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADIAN IRON METAL INC	142 BENTWORTH AVE NORTH YORK ON M6A 1P7	100.7	40
SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	299.9	156
SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A1Y7	299.9	156
SCARBOROUGH METALS	241 BRIDGELAND AVE NORTH YORK ON M6A1Y7	299.9	156

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 7 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	261.4	98
	ON	267.2	103
	ON	269.3	107
	ON	280.0	122

Site	Address	Distance (m)	Map Key
	ON	292.3	142
	ON	294.6	144
	ON	296.3	150

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 10 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADA CUP INC.	137 BENTWORTH AVE. TORONTO CITY ON M6A 1P6	27.7	11
	137 Bentworth Avenue Toronto ON M6A 1P6	27.7	11
Georgia-Pacific Canada, Consumer Products, Inc.	137 Bentworth Avenue Toronto ON M6A 1P6	27.7	11
Georgia-Pacific Canada, Consumer Products, Inc.	123 Bentworth Avenue Toronto ON M6A 1P6	67.1	22
I&D AUTOBODY & COLLISION CENTRE LTD.	142 BENTWORTH AVENUE TORONTO CITY ON M6A 1P7	100.7	40
1014177 Ontario Ltd.	147 Bentworth Ave Toronto ON	125.2	48

Site	Address	Distance (m)	Map Key
NORTH YORK CITY	MCADAM AVE./PAUL DAVID ST. NORTH YORK CITY ON	142.3	54
GRAF AUTO REPAIR LIMITED	151-153 BENTWORTH AVE., LOT 66 NORTH YORK CITY ON M6A 1P6	158.5	60
GRANT AUTO REPAIR LIMITED	151-153 BENTWORTH AVE.,LOT 66 NORTH YORK CITY ON M6A 1P6	158.5	60
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153

CDRY - Dry Cleaning Facilities

A search of the CDRY database, dated Jan 2004-Dec 2020 has found that there are 1 CDRY site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
North Park Dry Cleaners	130 Bentworth Ave. Toronto ON M6A1P7	0.0	2

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Feb 28, 2022 has found that there are 2 DTNK site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ULTRAMAR CANADA INC	171 BENTWORTH AV TORONTO ON	287.1	131
FRANK & WILLIES SERVICE CENTRE LTD	141 CARTWRIGHT AV TORONTO ON M6A 1V4	291.8	141

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011- Sep 30, 2022 has found that there are 2 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GRAF AUTO REPAIR LIMITED	151 BENTWORTH AVE NORTH YORK ON M6A 1P6	158.5	60
ALESSANDRO GERALDO, DEBORA CANTANHEDE	61 McAdam AV Toronto ON M6A 1S6	280.4	123

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Oct 31, 2022 has found that there are 5 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Fort James Canada Inc.	137 Bentworth Avenue Toronto Ontario Toronto ON	27.7	11
Fort James Canada Inc.	137 Bentworth Avenue Toronto Ontario Toronto ON	27.7	11
I & D Autobody and Collision Centre Limited	142 Bentworth Avenue Toronto ON	100.7	40
1014177 Ontario Ltd.	147 Bentworth Avenue Toronto CITY OF TORONTO ON	125.2	48
Geovin Furniture Inc.	245 Bridgeland Avenue Toronto M6A 1Y7 CITY OF TORONTO ON	298.9	153

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Sep 30, 2022 has found that there are 5 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Georgia-Pacific Canada, Consumer Products, Inc.	137 Bentworth Avenue Toronto ON L6X 1A9	27.7	11

Site	Address	Distance (m)	Map Key
Fort James Canada Inc.	137 Bentworth Avenue Toronto ON L6X 1A9	27.7	11
Georgia-Pacific Canada, Consumer Products, Inc.	123 Bentworth Avenue Toronto ON L6X 1A9	67.1	22
1014177 Ontario Ltd.	147 Bentworth Ave Toronto ON M6A 1P6	125.2	48
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Jul 31, 2022 has found that there are 45 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	130 Bentworth Avenue Toronto ON M6A 1P7	0.0	2
	109 Cartwright Avenue Toronto ON M6A 1V4	0.0	3
	111 Cartwright Avenue North York ON M6A 1V4	11.2	6
	137 Bentworth Ave Toronto ON M6A 1P6	27.7	11
	137 Bentworth Avenue North York ON M6A 1P6	27.7	11

Site	Address	Distance (m)	Map Key
	105-123 Bentworth Avenue Toronto ON M6A 1P6	33.8	12
	120 Cartwright Ave Toronto ON	70.0	25
	120 Cartwright Avenue Toronto ON	70.0	25
	120 Cartwright Avenue Toronto ON M6A 1V2	70.0	25
	99 Cartwright Avenue Toronto ON	79.8	29
	105 Bentworth Avenue North York ON M6A 1P6	89.6	34
	105 Bentworth Avenue North York ON M6A 1P6	89.6	34
	85 Bentworth Avenue North York ON M6A 1P6	121.6	45
	147 Bentworth Ave Toronto ON	125.2	48
	147 Bentworth Avenue North York ON M6A 1P6	125.2	48
	147 Bentworth Avenue North York ON M6A 1P6	125.2	48
	130 Orfus Road Toronto ON M6A 1L9	160.5	61

Site	Address	Distance (m)	Map Key
	100 Orfus Rd Toronto ON M6A1L9	174.0	64
	155-157 Bentworth Ave. Toronto ON M6A 1P6	194.5	69
	161 Bridgeland Avenue Toronto ON	221.6	79
	161 Bridgeland Avenue North York ON M6A 1Z1	221.6	79
	161 Bridgeland Avenue North York ON M6A 1Z1	221.6	79
	185 Bridgeland Avenue Toronto ON M6A 1Y7	224.4	81
	164 Bentworth Ave Toronto ON M6A1P7	231.2	84
	135 Cartwright Avenue North York ON M6A 1V4	246.2	92
	52 Orfus Road Toronto ON	254.6	94
	166 Bentworth Avenue Toronto ON M6A 1P7	255.0	96
	167 Bentworth Avenue North York ON M6A 1P6	257.7	97

Site	Address	Distance (m)	Map Key
	195 Bridgeland Avenue North York ON M6A 1Z4	266.2	102
	1259 Caledonia Road Toronto ON M6A 2X6	267.2	103
	1277 Caledonia Rd North York ON M6A 1V2	271.3	111
	1277 Caledonia Rd North York ON M6A 1V2	271.3	111
	1277 Caledonia Road North York ON M6A 1V2	276.4	118
	1277 Caledonia Road North York ON M6A 1V2	276.4	118
	176 Bentworth Avenue North York ON M6A 1P7	277.4	119
	185 Bridgeland Avenue North York ON M6A 2V1	286.3	128
	Dufflaw Rd Orfus Rd Toronto ON	286.7	130
	227 Bridgeland Avenue North York ON M6A 1Z4	291.0	136
	178-180 Bentworth Avenue Toronto ON M6A 1P7	295.0	146
	178-180 Bentworth Avenue Toronto ON M6A 1P7	295.0	146

Site	Address	Distance (m)	Map Key
	225 Bridgeland Ave Toronto ON M6A 1Y7	295.6	148
	67 & 75 Dufflaw Rd & 65 Orfus Rd_Toronto (ERIS) North York ON M6A 1L7	297.3	151
	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153
	245 Bridgeland Avenue Toronto ON	299.0	154
	133 Bridgeland Avenue North York ON M6A 1Z4	299.9	157

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2022 has found that there are 2 FST site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AVE NORTH YORK M6A 1V4 ON CA ON	40.1	16
CITY OF TORONTO	140 BENTWORTH AVE NORTH YORK M6A 1P7 ON CA ON	46.1	20

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 4 FSTH site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	41.3	18

Site	Address	Distance (m)	Map Key
DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	41.3	18
CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES	140 BENTWORTH AVE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES	140 BENTWORTH AVE NORTH YORK ON M6A 1P7	46.1	20

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 215 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	0.0	1
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	0.0	1
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	0.0	1
1019734 ONTARIO LTD.	130 BENTWORTH AVENUE TORONTO ON M6A 1P7	0.0	2
PRESIDENTIAL DRY CLEANERS	130 BENTWORTH AVENUE TORONTO ON M6A 1P7	0.0	2
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	0.0	2

Site	Address	Distance (m)	Map Key
ARMSTRONG BAUM PLUMBING & HEATING REG'D STYLE NAME	130 BENTWORTH AVE TORONTO ON M6A 1P7	0.0	2
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	0.0	2
658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON	0.0	2
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON	0.0	2
658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON M6A1P7	0.0	2
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	0.0	2
2008737 ONTARIO LTD	130 BENTWORTH AVE. TORONTO ON M6A 1P7	0.0	2
658457 ONTARIO INC.	130 BENTWORTH AVENUE TORONTO ON M6A1P7	0.0	2
CANADA CUP INC.	137 BENTWORTH AVE. TORONTO ON M6A 1P6	27.7	11
CANADA CUP (SEE & USE ON1947701) 08-289	137 BENTWORTH AVE. TORONTO ON M6A 1P6	27.7	11
CANADA CUP INC. 08-289	137 BENTWORTH AVE. TORONTO ON M6A 1P6	27.7	11
JAMES RIVER CANADA INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	27.7	11

Site	Address	Distance (m)	Map Key
FORT JAMES CANADA INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	27.7	11
GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.	137 BENTWORTH AVENUE TORONTO ON M6A 1P6	27.7	11
University of Toronto	U of T CDE - Shaw 105 Bentworth Ave. Unit 1 North York ON M6A 1P6	36.7	13
Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	37.0	14
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	16
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	16
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	16
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	16
Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	40.1	16
Dominion Sheet Metal and Roofing Works.	113 Cartwright Ave Toronto ON M6Z1V4	40.1	16
Dominion Roofing	113 Cartwright Avenue North York ON M6A 1V4	40.1	16

Site	Address	Distance (m)	Map Key
DOMINION SHEET METAL & ROOFING WKS	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	40.1	17
DOMINION SHEET METAL & ROOFING WKS12-523	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	40.1	17
DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	40.1	17
1262589 Ontario Ltd.	113 CARTWRIGHT AVENUE NORTH YORK ON	40.1	17
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	17
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	17
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	17
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON M6A 1V4	40.1	17
1262589 Ontario Ltd.	113 Cartwright Avenue North York ON	40.1	17
NORTH YORK, CITY OF	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20

Site	Address	Distance (m)	Map Key
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20
CITY OF TORONTO	BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	46.1	20

Site	Address	Distance (m)	Map Key
GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	67.1	22
GEORGIA-PACIFIC CANADA, CONSUMER PRODUCTS, ULC	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	67.1	22
GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	67.1	22
GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 BENTWORTH AVENUE TORONTO ON M6A 1P6	67.1	22
Kevric Ontario Real Estate Corp.	123 Bentworth Ave. Toronto ON M6A 1P6	67.1	22
Kevric Ontario Real Estate Corp.	123 Bentworth Ave. Toronto ON M6A 1P6	67.1	22
Shaw Dental Laboratory, Inc.	105 -123 Bentworth Avenue, Unit 1 North York ON M6A1P6	67.1	22
Shaw Dental Laboratory, Inc.	105 -123 Bentworth Avenue, Unit 1 North York ON M6A1P6	67.1	22
Toronto Transit Commission	120 Cartwright Ave Toronto ON M6A 1V2	70.0	25
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
crisstar cabinets inc	104 Carwright Ave. North York ON	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31

Site	Address	Distance (m)	Map Key
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
Crisstar Cabinets Inc	104 Cartwright Ave. North York ON M6A 1V2	83.8	31
105 Bentworth Inc	105 Bentworth Ave North York ON M6A 1P6	89.6	34
MR. T-SHIRT INC.	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	98.1	38
MR. T-SHIRT INC.	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	98.1	38

Site	Address	Distance (m)	Map Key
MR. T-SHIRT INC. (OUT OF BUSINESS)	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	98.1	38
MR. T-SHIRT INC. (OUT OF BUSINESS)27-183	122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	98.1	38
Cappola Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42

Site	Address	Distance (m)	Map Key
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
Maple Leaf Food Inc.	92 Cartwright Ave. Toronto ON M6A 1V2	108.8	42
PRESTON METAL & ROOFING PRODUCTS	147 BENTWORTH AVENUE TORONTO ON M6A 1P6	123.9	46
PRESTON METAL (OUT OF BUSINESS) 31-244	147 BENTWORTH AVENUE TORONTO ON M6A 1P6	123.9	46
Aden Earthworks Inc.	147A Bentworth Ave Toronto ON M6A 1P6	124.0	47
Brea Water Technologies	147 Bentworth Ave Toronto ON M6A 1P6	124.0	47
Aden Earthworks Inc.	147A Bentworth Ave Toronto ON M6A 1P6	124.0	47
EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	134.7	52
EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	134.7	52
EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	134.7	52

Site	Address	Distance (m)	Map Key
EXPRESS ROADSIDE RECOVERY INC	144 Bentworth Ave Toronto ON M6A 1P7	134.7	52
SWENSON CANADA INC	80 ORFUS ROAD TORONTO ON M6A 1M1	187.0	66
SWENSON CANADA INC 36-270	80 ORFUS ROAD TORONTO ON M6A 1M1	187.0	66
SWENSON CANADA INC.	80 ORFUS ROAD TORONTO ON M6A 1M1	187.0	66
SWENSON CANADA INC.	80 ORFUS ROAD TORONTO ON M6A 1M1	187.0	66
ERIC KINGSTON SALES LTD.	162 BENTWORTH AVE. TORONTO ON M6A 1P7	195.8	71
ERIC KINGSTON SALES LTD.	162 BENTWORTH AVE. TORONTO ON M6A 1P7	195.8	71
ERIC KINGSTON (OUT OF BUSINESS) 14-247	162 BENTWORTH AVE. TORONTO ON M6A 1P7	195.8	71
ERIC KINGSTON SALES LTD. 14-247	162 BENTWORTH AVE. TORONTO ON M6A 1P7	195.8	71
ICI CONVERTERS INK 21-545	133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE BRAMPTON ON M6A 1V4	211.8	75
ICI CONVERTERS INK(OUT OF BUS)	133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE BRAMPTON ON M6A 1V4	211.8	75
CONVERTERS INK	133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	211.8	75

Site	Address	Distance (m)	Map Key
CONVERTERS INC.(OUT OF BUS) 11-026	133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	211.8	75
CONVERTERS INK LTD. (OUT OF BUSINESS)	133 CARTWRIGHT AVENUE TORONTO ON M6A 1V4	211.8	75
CHAMPION INVESTMENTS LTD. 07-538	133 CARTWRIGHT AVE., NORTH YORK C/O BOX 47 SUITE 2600, 20 QUEEN ST. W. TORONTO ON M6A 1V4	211.8	75
The Promise Holdings Inc.	157 Bentworth Avenue Toronto ON M6A 1P6	214.3	77
Dunmet Products Ltd	157 Bentworth Ave North York ON M6A 1P6	214.3	77
Dunmet Products (2014) Limited	157 Bentworth avenue Toronto ON M6A1P6	214.3	77
BROWNING-FERRIS INDUSTRIES LTD.	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	221.6	79
BROWNING-FERRIS INDUSTRIES LTD.	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	221.6	79
BROWNING-FERRIS INDUSTRIES LTD. 06-111	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	221.6	79
BROWNING-FERRIS INDUSTRIES LIMITED	161 BRIDGELAND AVENUE TORONTO ON M6A 1Z1	221.6	79
WASTECO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79

Site	Address	Distance (m)	Map Key
WASTECO, A DIVISION OF	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	221.6	79

Site	Address	Distance (m)	Map Key
SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	221.6	79
WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
SOUTHERN SANITATION WASTECO - TORONTO	161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	221.6	79
WASTECO	161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	221.6	79
1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	242.6	89
1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	242.6	89
1056934 Ontario Limited	65 Orfus Rd. Toronto ON M6A 1L7	242.6	89
ALTERNATOR EXCHANGE LTD.	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	246.7	93
ALTERNATOR EXCHANGE COMPANY LTD.	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	246.7	93

Site	Address	Distance (m)	Map Key
ALTERNATOR EXCHANGE COMPANY LTD. 02-029	124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	246.7	93
ALTERNATOR EXCHANGE COMPANY LIMITED	124A CARTWRIGHT AVENUE TORONTO ON M6A 1V2	246.7	93
ALTERNATOR EXCHANGE COMPANY LIMITED	124 A Cartwright Ave., Toronto ON M6A 1V2	246.7	93
SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	255.0	96
SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	255.0	96
SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	255.0	96
SCM Special Construction Machines	166 Bentworth Avenue Toronto ON M6A 1P7	255.0	96
SUPERIOR CRANE LIMITED	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	266.2	102
SUPERIOR OUT OF BUSINESS	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	266.2	102
SUPERIOR OUT OF BUSINESS 34-130	195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	266.2	102
FER-PAL CONSTRUCTION LTD.	195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	266.2	102
FER-(OUT OF BUS)	195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	266.2	102

Site	Address	Distance (m)	Map Key
H & E Copy Services Inc.	195 Bridgeland Ave. Toronto ON M6A 1Y7	266.2	102
Curtis Properties (195 Bridgeland) Inc.	195 Bridgeland Ave Toronto ON M6A 1Y7	266.2	102
BASF CANADA INC.	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	271.3	111
BASF (OUT OF BUS)	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	271.3	111
BASF CANADA INC. (OUT OF BUSINESS)	AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7	271.3	111
732090 Ontario LTD	1277 Caledonia Road Toronto ON M6A2X7	271.3	111
Beebed Realty	103 Orphus Rd. Toronto ON	274.4	114
CALEDONIA MARBLE COMPANY LTD.	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	277.4	119
CALEDONIA (OUT OF BUS) 07-054	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	277.4	119
CALEDONIA MARBLE CO. (OUT OF BUSINESS)	176 BENTWORTH AVENUE TORONTO ON M6A 1P7	277.4	119
CALEDONIA MARBLE COMPANY LTD.	167 BENTWORTH AVENUE TORONTO ON M6A 1P6	278.8	121

Site	Address	Distance (m)	Map Key
Caledonia Marble Co Ltd	167 Bentworth Ave. Toronto ON M6A 1P7	278.8	121
Caledonia Marble Co Ltd	167 Bentworth Ave. Toronto ON M6A 1P7	278.8	121
Zeifmans LLP	201 Bridgeland Ave Toronto ON M6A 1Y7	282.9	124
GALAXY SILK SCREENING INC.	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	285.8	126
Finer Fabrics Ltd	1245 Caledonia Rd Toronto ON M6A 2X6	285.8	126
GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	285.8	126
GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	285.8	126
GREEN GALAXY COMPANIES	1245 CALEDONIA ROAD TORONTO ON M6A 2X6	285.8	126
ULTRAMAR CANADA LTD.	171 BENTWORTH AVENUE CARDLOCK SITE 00235 TORONTO ON M6A 1P6	287.1	131
ULTRAMAR CANADA LTD.	ULTRAMAR CARDLOCK - SITE 00235 171 BENTWORTH AVENUE TORONTO ON M6A 1P6	287.1	131
MERIT AUTOMOTIVE PRODUCTS LTD.	1283 CALEDONIA ROAD NORTH YORK ON M6A 2X7	289.2	133
MERIT AUTOMOTIVE PRODUCTS LTD. 26-162	1283 CALEDONIA ROAD NORTH YORK ON M6A 2X7	289.2	133

Site	Address	Distance (m)	Map Key
658457 Ontario Inc.	153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6	290.2	134
658457 Ontario Inc.	153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6	290.2	134
D.S. FRASER EQUIPMENT INC.	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	290.3	135
D.S. FRASER EQUIPMENT INC. 48-039	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	290.3	135
D.S. (OUT OF BUS)	153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	290.3	135
BEAUTIFUL SOUTH INC.	153 BRIDGELAND AVENUE, UNIT 4 TORONTO ON M6A 2Y6	290.3	135
S & F DEMELIS CONSTRUCTION LTD.	141 CARTWRIGHT AVENUE TORONTO ON M6A 1V4	291.8	141
ROTHMANS OF PALL MALL CANADA LTD	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	295.0	147
ROTHMANS BENSON & HEDGES INC.	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	295.0	147
ROTHMANS (OUT OF BUSINESS)	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	295.0	147
ROTHMANS (OUT OF BUSINESS) 33-040	BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	295.0	147

Site	Address	Distance (m)	Map Key
ROTHMANS BENSON & HEDGES (OUT OF BUS.)	67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	295.0	147
TORONTO DISTRICT SCHOOL BOARD	YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD TORONTO ON M6A 1L6	296.0	149
TORONTO DISTRICT SCHOOL BOARD	YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD TORONTO ON M6A 1L6	296.0	149
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153
245 Bridgeland Avenue Ltd	245 Bridgeland Avenue Toronto ON	298.9	153
Geovin Furniture Inc.	245 Bridgeland Ave Toronto ON M6A 1Y7	298.9	153
Dax Automotive and Collision	241 Bridgeland Ave 241 Bridgeland Ave North York ON M6A 1Y7	299.9	156
GIFFIN SHEET METALS LIMITED	LOT 1, CONC. 5, VAUGHAN TWP. 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED 18-256	LOT 1, CONC. 5, VAUGHAN TWP. 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	299.9	157

Site	Address	Distance (m)	Map Key
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A-1Y7	299.9	157
OXFORD PROPERTIES GROUP	115-133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	299.9	157

Site	Address	Distance (m)	Map Key
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LIMITED	133 Bridgeland Avenue Toronto ON M6A 1Y7	299.9	157

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 1 NPCB site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CURTIS PROPERTIES	SUITE 101; 201 BRIDEGLAND AVE. SUITE 101; 201 BRIDGELAND AVE. TORONTO ON M6A 1Y7	282.9	124

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 8 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Georgia-Pacific Canada Consumer Products LP	123 Bentworth Avenue Toronto ON M6A 1P6	67.1	22
GEORGIA-PACIFIC CANADA LP	123 Bentworth Avenue Toronto ON M6A1P6	67.1	22
GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 Bentworth Avenue Toronto ON M6A1P6	67.1	22
GEORGIA-PACIFIC CANADA LP	123 BENTWORTH AVENUE NOT AVAILABLE TORONTO ON M6A1P6	67.1	22
GEORGIA-PACIFIC CANADA LP	123 BENTWORTH AVENUE NOT AVAILABLE TORONTO ON M6A1P6	67.1	22

Site	Address	Distance (m)	Map Key
GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP	123 Bentworth Avenue Toronto ON M6A1P6	67.1	22
Giffin Sheet Metals Ltd.	133 BRIDGELAND AVENUE NOT AVAILABLE TORONTO ON M6A 1Y7	299.9	157
GIFFIN SHEET METALS LTD.	133 BRIDGELAND AVENUE NOT AVAILABLE TORONTO ON M6A 1Y7	299.9	157

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Sep 30, 2022 has found that there are 2 PES site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HARVEY'S BUILDING SUPPLIES (1987) LTD.	96 ORFUS ROAD TORONTO ON M6A 1L9	195.6	70
HARVEY'S BUILDING SUPPLIES (1987) LTD.	96 ORFUS ROAD TORONTO ON M6A 1L9	195.6	70

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 3 PRT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
DOMINION SHEET METAL & ROOFING WORKS	113 CARTWRIGHT AV TORONTO ON M6A 1V4	41.3	18
CITY OF NORTH YORK PUBLIC WORKS DEPT	140 BENTWORTH AV NORTH YORK ON M6A 1P7	46.1	20
FRANK & WILLIES SERVICE CENTRE LTD	141 CARTWRIGHT AV TORONTO ON M6A1V4	291.8	140

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Oct 2022 has found that there are 1 RSC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	1215 Caledonia Road Toronto ON M6A 2X3	291.4	137

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 87 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
The Golden Imprint Inc.	130 Bentworth Ave North York ON M6A 1P7	0.0	2
CLASSIC MANTEL INDUSTRIES LTD.	111 Cartwright Ave Toronto ON M6A 1V4	11.5	7
Classic Mantel Industries Ltd.	111 Cartwright Ave North York ON M6A 1V4	11.5	7
JAMES RIVER CANADA INC.	137 BENTWORTH AVE NORTH YORK ON M6A 1P6	27.7	11
FORT JAMES CANADA INC.	137 Bentworth Ave North York ON M6A 1P6	27.7	11
Georgia-Pacific Canada Inc.	137 Bentworth Ave North York ON M6A 1P6	27.7	11
The Morris Group/Marketing	137 Bentworth Ave Toronto ON M6A 1P6	27.7	11
Georgia-Pacific Canada Inc.	123 Bentworth Ave North York ON M6A 1P6	67.1	22

Site	Address	Distance (m)	Map Key
Georgia-Pacific Canada Inc.	123 Bentworth Ave North York ON M6A 1P6	67.1	22
Ontario Acoustic Supply Inc.	139 Bentworth Ave North York ON M6A 1P6	67.9	24
ITALDOOR & WOODWORKING LTD.	120 CARTWRIGHT AVE TORONTO ON M6A 1V2	70.0	25
Italdoor & Woodworking Ltd.	120 Cartwright Ave North York ON M6A 1V2	70.0	25
SELECTED MODE INC.	106 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	74.8	27
MEGA UNIFORMS LTD	104 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	83.8	31
UNIVERSAL CHINA LAMP & GLASS	121 CARTWRIGHT AVE TORONTO ON M6A 1V4	90.0	35
Universal China Lamp & Glass Co. Ltd. - Universal Lamp Manufacturing Division	121 Cartwright Ave Toronto ON M6A 1V4	90.0	35
Universal Lamp	121 Cartwright Ave Toronto ON M6A 1V4	90.0	35
Superb Fashions Ltd.	89 Bentworth Ave Unit 4 Toronto ON M6A 1P6	91.3	36
Russo Apparel Mfg. Inc.	89 Bentworth Ave Unit 3 North York ON M6A 1P6	91.3	36

Site	Address	Distance (m)	Map Key
XS: Clothing Co. Inc.	89 Bentworth Ave Unit 2 North York ON M6A 1P6	91.3	36
Empire Uniforms	89 Bentworth Ave Unit 3 Toronto ON M6A 1P6	91.3	36
Adele Wechsler Designs Limited	89 Bentworth Ave Unit 3 North York ON M6A 1P6	91.3	36
Lamintech Corp. Ltd.	122 Cartwright Ave North York ON M6A 1V2	98.1	38
Lamin Tech	122A Cartwright Ave Toronto ON M6A 1V2	98.1	38
PICTURE PICTURE	122 CARTWRIGHT AVE NORTH YORK ON M6A 1V2	98.1	38
Picture Picture Co.	122 Cartwright Ave North York ON M6A 1V2	98.1	38
Lamintech Corp. Ltd	122 Cartwright Ave North York ON M6A 1V2	98.1	38
Picture Picture Co. Ltd.	122 Cartwright Ave Toronto ON M6A 1V2	98.1	38
CAPPOLA FOOD INC.	92 CARTWRIGHT AVE TORONTO ON M6A 1V2	108.8	42
BENIX & CO	127 CARTWRIGHT AVE TORONTO ON M6A 1V4	129.2	50
SWENSON CANADA INC.	80 ORFUS RD NORTH YORK ON M6A 1M1	153.8	57

Site	Address	Distance (m)	Map Key
SWENSON CANADA LIMITED INC.	80 ORFUS RD NORTH YORK ON M6A 1M1	153.8	57
Wahl Canada Inc.	80 Orfus Rd North York ON M6A 1M1	153.8	57
COLLEZIONI DONNA	150 BENTWORTH AVE TORONTO ON M6A 1P7	157.5	58
ZALDIAM & CO	129 CARTWRIGHT AVE NORTH YORK ON M6A 1V4	157.9	59
ZALDIAM & CO	129 Cartwright Ave Toronto ON M6A 1V4	157.9	59
Trippers Inc.	129 Cartwright Ave North York ON M6A 1V4	157.9	59
SM FOOTWEAR LTD.	130 ORFUS RD NORTH YORK ON M6A 1L9	160.5	61
EMERSON SUMMERS CO. LTD.	88 ORFUS RD UNIT 2 NORTH YORK ON M6A 1L9	187.0	67
BAZAAR & NOVELTY CO.	76 ORFUS RD NORTH YORK ON M6A 1L9	197.7	72
BAZAAR NOVELTY	76 ORFUS RD NORTH YORK ON M6A 1L9	197.7	72
BRITSTONE TEXTILE IMPORT	155 BENTWORTH AVE TORONTO ON M6A 1P6	200.2	74

Site	Address	Distance (m)	Map Key
Canada Glass & Mirror Co.	155 Bentworth Ave Toronto ON M6A 1P6	200.2	74
GREEN JAY SALES INC.	157 BENTWORTH AVE TORONTO ON M6A 1P6	214.3	77
MANTEX JOBBERS LTD.	157 Bentworth Ave Unit 1 North York ON M6A 1P6	214.3	77
Minuteman Press	157 Bentworth Ave Toronto ON M6A 1P6	214.3	77
Dunmet Products (1998) Ltd.	157 Bentworth Ave North York ON M6A 1P6	214.3	77
Drummer's East Agency Ltd.	66 Orfus Rd North York ON M6A 1L9	222.0	80
GENERAL TRANSFORMERS LTD.	185 BRIDGELAND AVE TORONTO ON M6A 1Y7	224.4	81
AMERICAN LOUVER OF CANADA LTD.	185 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	224.7	82
Silkscape Designs Inc.	185 Bridgeland Ave Unit 1 North York ON M6A 1Y7	224.7	82
Lorellana Couture Inc.	164A Bentworth Ave Toronto ON M6A 1P7	231.1	83
HUGHES CONTAINERS LIMITED	95 ORFUS RD TORONTO ON M6A 1M4	244.2	90
Alternator Exchange Co. Ltd.	124A Cartwright Ave North York ON M6A 1V2	246.7	93

Site	Address	Distance (m)	Map Key
ALTERNATOR EXCHANGE CO. LTD.	124 A CARTWRIGHT AVE TORONTO ON M6A 1V2	246.7	93
Arte Unico Inc.	124 Cartwright Ave Toronto ON M6A 1V2	246.7	93
Arte Unico Inc.	124 Cartwright Ave North York ON M6A 1V2	246.7	93
ARBOR STORE INTERIORS INC.	52 ORFUS RD NORTH YORK ON M6A 1L6	254.6	94
UNIVERSAL SHOWCASE LTD.	52 Orfus Rd North York ON M6A 1L6	254.6	94
CALEDONIA MARBLE COMPANY LTD.	167 BENTWORTH AVE NORTH YORK ON M6A 1P6	264.2	100
CALEDONIA MARBLE COMPANY LTD	167 BENTWORTH AVE NORTH YORK ON M6A 1P6	264.2	100
Caledonia Marble Company Ltd.	167 Bentworth Ave Toronto ON M6A 1P6	264.2	100
ATTARDO CO. LTD.	1259 CALEDONIA RD TORONTO ON M6A 2X6	267.2	103
Yongetex Limited	1259 Caledonia Rd North York ON M6A 2X6	267.2	103
FANCY DIAMOND JEWELLERY LTD.	103 ORFUS RD NORTH YORK ON M6A 1M4	274.4	114

Site	Address	Distance (m)	Map Key
EDWARD DWORKIN DISTRIBUTORS	103 ORFUS RD TORONTO ON M6A 1M4	274.4	114
TORONTO BARBER & BEAUTY SUPPLY	112 ORFUS RD TORONTO ON M6A 1L9	275.2	115
Simcoe Fluid Power Inc.	61 McAdam Ave Toronto ON M6A 1S6	280.4	123
ANGEL DANCE WEAR INC	201 BRIDGELAND AVE UNIT 3 TORONTO ON M6A 1Y7	282.9	124
LOUIS INTERIORS INC	120 ORFUS RD TORONTO ON M6A 1L9	285.2	125
Galaxy Silk Screening Design	1245 Caledonia Rd Toronto ON M6A 2X6	285.8	126
PREMIER KNITWEAR INC.	1283 CALEDONIA RD TORONTO ON M6A 2X7	289.2	133
Louis Interiors Inc.	1283 Caledonia Rd Toronto ON M6A 2X7	289.2	133
GALAXY BAKERY	153 BRIDGELAND AVE UNIT 5 TORONTO ON M6A 2Y6	290.3	135
HOGARTH PRINTING COMPANY LIMIT	153 BRIDGELAND AVE UNIT 14 TORONTO ON M6A 2Y6	290.3	135
STEAM SAUNA	153 Bridgeland Ave Unit 13 Toronto ON M6A 2Y6	290.3	135
UNITOOL Inc.	153 Bridgeland Ave Unit 12 North York ON M6A 2Y6	290.3	135

Site	Address	Distance (m)	Map Key
Steam Sauna Inc.	153 Bridgeland Ave Unit 13 Toronto ON M6A 2Y6	290.3	135
Rainbow Aluminum/Vinyl Prods	153 Bridgeland Ave Unit 15 North York ON M6A 2Y6	290.3	135
DUNMET PRODUCTS (1988) LTD.	178 BENTWORTH AVE NORTH YORK ON M6A 1P7	295.0	146
Dunmet Products (1998) Ltd.	178 Bentworth Ave North York ON M6A 1P7	295.0	146
Geovin Furniture Inc.	245 Bridgeland Ave North York ON M6A 1Y7	298.9	153
DOLDAN FASHIONS MFG CO LTD	1287 CALEDONIA RD NORTH YORK ON M6A 2X7	299.5	155
DOLDAN FASHIONS	1287 CALEDONIA RD NORTH YORK ON M6A 2X7	299.5	155
DOLDAN FASHIONS MFG. CO. LTD.	1287 Caledonia Rd North York ON M6A 2X7	299.5	155
Doldan Fashions Manufacturing Co. Ltd.	1287 Caledonia Rd North York ON M6A 2X7	299.5	155
Giffin Sheet Metals Limited	133 Bridgeland Ave North York ON M6A 1Y7	299.9	157

SPL - Ontario Spills

A search of the SPL database, dated 1988-Sep 2020; Dec 2020-Mar 2021 has found that there are 15 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PETRO-CANADA	113 CARTWRIGHT AV SERVICE STATION TORONTO CITY ON M6A 1V4	41.3	18
TORONTO HYDRO	117 CARTWRIGHT AVE. TRANSFORMER TORONTO CITY ON M6A 1V4	67.3	23
TRANSPORT TRUCK	127 CARTWRIGHT AVE. MOTOR VEHICLE (OPERATING FLUID) TORONTO CITY ON M6A 1V4	129.2	50
NORTH YORK HYDRO	133 CARTWRIGHT TORONTO CITY ON M6A 1V4	211.8	75
UNKNOWN	ORFUS RD/DUFFLAW RD & OUTFALL H275 IN RUSTIC PARK. TORONTO CITY ON	212.7	76
G.A. FOSS TRANSPORT LTD.	161 BRIDGELAND AVE. TANK TRUCK (CARGO) TORONTO CITY ON	221.6	79
	185 Bridgeland Ave<UNOFFICIAL> Toronto ON M6A 1Y7	224.4	81
Faylaura Investments Inc.	185 Bridgeland Ave Toronto ON M6A 1Y7	224.4	81
	Property west of 185 Bridgeland Avenue Toronto ON	224.4	81
	223 Bridgeland Avenue, North York Toronto ON	232.9	86
Shefa<UNOFFICIAL>	195 Bridgeland Avenue Toronto ON	266.2	102

Site	Address	Distance (m)	Map Key
	1277 Caledonia Rd Toronto ON	271.3	111
	1285 Caledonia Rd Toronto ON	291.8	139
City of Toronto	1285 Caledonia Rd. Toronto ON	291.8	139
City of Toronto	141 Cartwright Ave<UNOFFICIAL> Toronto ON M6A 1V4	291.8	141

WDS - Waste Disposal Sites - MOE CA Inventory

A search of the WDS database, dated Oct 2011- Sep 30, 2022 has found that there are 1 WDS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Gus Kastanis	195 Bridgeland toronto ON M6A 1Y7	266.2	102

WWIS - Water Well Information System

A search of the WWIS database, dated Jun 30 2022 has found that there are 55 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	111 CARTWRIGHT AVE. TORONTO ON ***Well ID:*** 7332346	6.1	4
	109 CARTWRIGHT AVE TORONTO ON ***Well ID:*** 7048099	9.0	5
	105-123 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 6929659	13.8	8


Site	Address	Distance (m)	Map Key
	111 CARTWRIGHT AVE. Toronto ON ***Well ID:*** 7332345	15.9	9
	111 CARTWRIGHT AVE. Toronto ON ***Well ID:*** 7332344	21.3	10
	102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281892	37.6	15
	102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281833	45.0	19
	102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281891	49.6	21
	185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159338	73.5	26
	185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159339	74.9	28
	ON ***Well ID:*** 7161397	82.9	30
	123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191977	86.8	32
	123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191975	87.8	33
	123 BENTWORTH AVE TORONTO ON ***Well ID:*** 7191976	94.0	37
	ON	99.4	39

Site	Address	Distance (m)	Map Key
	Well ID: 7161057		
	102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281890	108.0	41
	102 CARTRIGHT AVE Toronto ON ***Well ID:*** 7281889	109.2	43
	99 CARTWRIGHT AVE Toronto ON ***Well ID:*** 7222994	121.3	44
	185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159337	128.5	49
	185 BRIDGELAND AVE Toronto ON ***Well ID:*** 7159336	134.6	51
	ON ***Well ID:*** 7232232	141.2	53
	ON ***Well ID:*** 7218673	142.8	55
	161 BRIDGELAND TORONTO ON ***Well ID:*** 7154036	153.2	56
	106-110 ORFUS RD NORTH YORK ON ***Well ID:*** 6929661	165.3	62
	161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154035	168.7	63
	161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154054	179.3	65

Site	Address	Distance (m)	Map Key
	157 Bentworth Ave, York Toronto ON ***Well ID:*** 7048137	194.0	68
	161 BRIDGELAND RD. TORONTO ON ***Well ID:*** 7154034	197.7	73
	130 BRIDGELAND ROAD Toronto ON ***Well ID:*** 7179517	219.9	78
	278 BRIDGELAND AVE TORONTO ON ***Well ID:*** 6930320	231.4	85
	ON ***Well ID:*** 7192516	239.5	87
	ON ***Well ID:*** 7231719	239.5	87
	245 BRIDGELAND AVE Toronto ON ***Well ID:*** 7286369	242.4	88
	1277 Caledonia rd Toronto ON ***Well ID:*** 7365139	244.7	91
	ON ***Well ID:*** 7374604	254.9	95
	1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181106	261.6	99
	102 -123 BENTOWORTH AVE. NORTH YORK ON ***Well ID:*** 7149492	265.5	101
	1245 CALEDONIA RD Toronto ON	267.4	104

Site	Address	Distance (m)	Map Key
	Well ID: 7180722		
	112-120 ORFUS RD NORTH YORK ON ***Well ID:*** 6929662	267.8	105
	1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181269	268.9	106
	1289 CALEDONIA RD NORTH YORK ON ***Well ID:*** 7167693	270.1	108
	1245 CALEDONIA RD Toronto ON ***Well ID:*** 7180725	270.4	109
	1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181104	271.2	110
	167 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 7316357	272.6	112
	102 -123 BENTWORTH AVE. NORTH YORK ON ***Well ID:*** 7149493	274.3	113
	167 BENTWORTH AVE NORTH YORK ON ***Well ID:*** 7316356	275.4	116
	1245 CALEDONIA RD Toronto ON ***Well ID:*** 7181105	276.2	117
	80 DUFFLAW Toronto ON ***Well ID:*** 7173825	278.0	120
	1277 Caledonia rd Toronto ON ***Well ID:*** 7365301	286.3	127

Site	Address	Distance (m)	Map Key
	ON ***Well ID:*** 7343059	286.7	129
	245 BROADLAND AVE Toronto ON ***Well ID:*** 7191352	288.5	132
	1289 CALEDONIA RD NORTH YORK ON ***Well ID:*** 7167692	291.6	138
	1277 Caledonia rd Toronto ON ***Well ID:*** 7365303	294.1	143
	1277 Caledonia rd Toronto ON ***Well ID:*** 7365302	294.9	145
	245 BRIDGELAND AVE Toronto ON ***Well ID:*** 7286370	298.4	152



Map: 0.3 Kilometer Radius

Order Number: 22113000820

Address: 130 Bentworth Ave & 109 Cartwright Avenu, North York, ON

ERIS


- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

79°28'30"W

43°43'30"N



43°43'30"N

Aerial


Year: 2021

Order Number: 22113000820

Address: 130 Bentworth Ave & 109 Cartwright Avenu, North York, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Order Number: 22113000820

Address: 130 Bentworth Ave & 109 Cartwright Avenu, ON

Source: ESRI World Topographic Map

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 3	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON	GEN

Generator No: ON3169469
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	2 of 3	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON	GEN

Generator No: ON3169469
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	3 of 3	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON	GEN

Generator No: ON3169469
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2011
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 14	S/0.0	183.8 / 0.41	***The Golden Imprint Inc.*** ***130 Bentworth Ave*** ***North York ON M6A 1P7***	SCT

Established: 1987
Plant Size (ft²):
Employment: 3

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: All Other Services Related to Advertising
SIC/NAICS Code: 541899

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	2 of 14	S/0.0	183.8 / 0.41	***1019734 ONTARIO LTD.*** ***130 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P7***	GEN

Generator No: ON1749900
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	3 of 14	S/0.0	183.8 / 0.41	***PRESIDENTIAL DRY CLEANERS*** ***130 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P7***	GEN

Generator No: ON1749900
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

2	4 of 14	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON M6A 1P7	GEN

Generator No: ON3169469
SIC Code: 812320
SIC Description: Dry Cleaning & Laundry Serv. (exc. Coin-Op.)
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

2	5 of 14	S/0.0	183.8 / 0.41	ARMSTRONG BAUM PLUMBING & HEATING REG'D STYLE NAME 130 BENTWORTH AVE TORONTO ON M6A 1P7	GEN

Generator No: ON7402218
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

2	6 of 14	S/0.0	183.8 / 0.41	130 Bentworth Avenue Toronto ON M6A 1P7	EHS

Order No: 20051216013
Status: C
Report Type: Custom Report
Nearest Intersection:
Municipality: Toronto
Client Prov/State: ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	12/29/2005	**Search Radius (km):**	0.25
Date Received:	12/16/2005	**X:**	-79.464336
Previous Site Name:		**Y:**	43.720644
Lot/Building Size:			
Additional Info Ordered:			

---

2 **7 of 14** **S/0.0** **183.8 / 0.41** **2008737 ONTARIO LTD**
130 BENTWORTH AVE.
TORONTO ON M6A 1P7 **GEN**

Generator No:	ON3169469
SIC Code:	812320
SIC Description:	Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

---

2 **8 of 14** **S/0.0** **183.8 / 0.41** **658457 ONTARIO INC.**
130 BENTWORTH AVENUE
TORONTO ON **GEN**

Generator No:	ON4446196
SIC Code:	323119
SIC Description:	OTHER PRINTING
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

---

2 **9 of 14** **S/0.0** **183.8 / 0.41** **2008737 ONTARIO LTD**
130 BENTWORTH AVE.
TORONTO ON **GEN**

Generator No:	ON3169469
SIC Code:	812320
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years:	2013
PO Box No:	
Country:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	10 of 14	S/0.0	183.8 / 0.41	658457 ONTARIO INC. 130 BENTWORTH AVENUE TORONTO ON M6A1P7	GEN

Generator No: ON4446196
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	11 of 14	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON M6A 1P7	GEN

Generator No: ON3169469
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	12 of 14	S/0.0	183.8 / 0.41	2008737 ONTARIO LTD 130 BENTWORTH AVE. TORONTO ON M6A 1P7	GEN

Generator No: ON3169469

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

2	*13 of 14*	*S/0.0*	*183.8 / 0.41*	***658457 ONTARIO INC.*** ***130 BENTWORTH AVENUE*** ***TORONTO ON M6A1P7***	***GEN***

Generator No: ON4446196
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

2	*14 of 14*	*S/0.0*	*183.8 / 0.41*	***North Park Dry Cleaners*** ***130 Bentworth Ave.*** ***Toronto ON M6A1P7***	***CDRY***

Legal Name of Company:
Region:

Waste Quantity by Year

Reporting Year: 2015
Quantity of PERC (kg): -
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 25
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2013
Quantity of PERC (kg): 121.32

Total Waste Water (kg):	0
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	-
Total Mix (kg):	100
Total Mix (L):	-
Request for Confidentiality:	No
Reason for Confidentiality:	

Reporting Year:	2012
Quantity of PERC (kg):	-
Total Waste Water (kg):	0
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	-
Total Mix (kg):	-
Total Mix (L):	114
Request for Confidentiality:	No
Reason for Confidentiality:	

Reporting Year:	2011
Quantity of PERC (kg):	-
Total Waste Water (kg):	0
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	-
Total Mix (kg):	-
Total Mix (L):	205
Request for Confidentiality:	No
Reason for Confidentiality:	

---

3 | **1 of 1** | **NNW/0.0** | **182.1 / -1.31** | **109 Cartwright Avenue**
Toronto ON M6A 1V4 | **EHS**

Order No:	20070611014	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Custom Report	**Client Prov/State:**	
Report Date:	6/20/2007	**Search Radius (km):**	0.25
Date Received:	6/11/2007	**X:**	-79.465005
Previous Site Name:		**Y:**	43.722183
Lot/Building Size:			
Additional Info Ordered:			

---

4 | **1 of 1** | **NW/6.1** | **182.9 / -0.55** | **111 CARTWRIGHT AVE.**
TORONTO ON | **WWIS**

Well ID:	7332346	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02-May-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z310708	**Contractor:**	7644
Tag:	A265262	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	

Clear/Cloudy: ***UTM Reliability:***
Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7332346.pdf

Additional Detail(s) (Map)

Well Completed Date: 2019/04/03
Year Completed: 2019
Depth (m): 6.096
Latitude: 43.7215713942095
Longitude: -79.4649999885726
Path: 733\7332346.pdf

Bore Hole Information

Bore Hole ID: 1007428100 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 623642.00
Code OB Desc: ***North83:*** 4842094.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 03-Apr-2019 00:00:00 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007919116
Layer: 2
Color: 2
General Color: GREY
Mat1: 34
Most Common Material: TILL
Mat2:
Mat2 Desc:
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 15.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007919115
Layer: 1
Color: 6
General Color: BROWN
Mat1: 34
Most Common Material: TILL
Mat2: 28
Mat2 Desc: SAND

Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007919124
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007919125
Layer: 2
Plug From: 1.0
Plug To: 8.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007919126
Layer: 3
Plug From: 8.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007919123
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007919114
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007919119
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1007919120
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.375

Water Details

Water ID:	1007919118
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007919117
Diameter:	4.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1007428100	***Tag No:***	A265262
Depth M:	6.096	***Contractor:***	7644
Year Completed:	2019	***Path:***	733\7332346.pdf
Well Completed Dt:	2019/04/03	***Latitude:***	43.7215713942095
Audit No:	Z310708	***Longitude:***	-79.4649999885726

---

5 ***1 of 1*** ***NW/9.0*** ***182.9 / -0.53*** ***109 CARTWRIGHT AVE TORONTO ON*** ***WWIS***

Well ID:	7048099	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	10-Aug-2007 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z74086	***Contractor:***	7241
Tag:	A056663	***Form Version:***	3
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7048099.pdf

Additional Detail(s) (Map)

Well Completed Date: 2007/07/26
Year Completed: 2007
Depth (m): 5.79
Latitude: 43.7215175566316
Longitude: -79.4650137781706
Path: 704\7048099.pdf

Bore Hole Information

Bore Hole ID: 23048099
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 26-Jul-2007 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623641.00
North83: 4842088.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 30248099
Layer: 2
Color: 2
General Color: GREY
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 05
Mat3 Desc: CLAY
Formation Top Depth: 4.269999980926514
Formation End Depth: 5.789999961853027
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 30148099
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 4.269999980926514

Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44003477
Layer: 1
Plug From: 2.740000009536743
Plug To: 0.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 25948099
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 29048099
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 42148099
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.740000009536743
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 43148099
Layer: 1
Slot: 10
Screen Top Depth: 2.740000009536743
Screen End Depth: 5.789999961853027
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Links

Bore Hole ID: 23048099
Depth M: 5.79
Year Completed: 2007
Well Completed Dt: 2007/07/26
Audit No: Z74086
Tag No: A056663
Contractor: 7241
Path: 704\7048099.pdf
Latitude: 43.7215175566316
Longitude: -79.4650137781706

6	1 of 1	NW/11.2	182.7 / -0.72	111 Cartwright Avenue North York ON M6A 1V4	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No: 20190206154
Status: C
Report Type: Standard Report
Report Date: 11-FEB-19
Date Received: 06-FEB-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.465103
Y: 43.721658

---

7 | **1 of 2** | **NW/11.5** | **182.1 / -1.33** | **CLASSIC MANTEL INDUSTRIES LTD.**
111 Cartwright Ave
Toronto ON M6A 1V4 | **SCT**

Established: 1948
Plant Size (ft²): 5000
Employment: 9

--Details--
Description: Other Millwork
SIC/NAICS Code: 321919

---

7 | **2 of 2** | **NW/11.5** | **182.1 / -1.33** | **Classic Mantel Industries Ltd.**
111 Cartwright Ave
North York ON M6A 1V4 | **SCT**

Established: 01-JUN-48
Plant Size (ft²): 8000
Employment:

--Details--
Description: Other Millwork
SIC/NAICS Code: 321919

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

---

8 | **1 of 1** | **SSE/13.8** | **183.8 / 0.41** | **105-123 BENTWORTH AVE**
NORTH YORK ON | **WWIS**

Well ID: 6929659
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z40260
Tag: A036870
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06-Dec-2005 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/692\6929659.pdf

Additional Detail(s) (Map)

Well Completed Date: 2005/11/07
Year Completed: 2005
Depth (m): 6.1
Latitude: 43.7204209675846
Longitude: -79.464483128625
Path: 692\6929659.pdf

Bore Hole Information

Bore Hole ID: 11328628
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 07-Nov-2005 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623686.00
North83: 4841967.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933039900
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 4.800000190734863
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933039898
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:

Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933039899
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 4.800000190734863
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933282715
Layer: 1
Plug From: 0.0
Plug To: 2.700000047683716
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 966929659
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11343483
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930873641
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933415887
Layer: 1

Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Hole Diameter

Hole ID:	11549744
Diameter:	15.0
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11328628	**Tag No:**	A036870
Depth M:	6.1	**Contractor:**	6607
Year Completed:	2005	**Path:**	692\6929659.pdf
Well Completed Dt:	2005/11/07	**Latitude:**	43.7204209675846
Audit No:	Z40260	**Longitude:**	-79.464483128625

---

9 ***1 of 1*** ***NW/15.9*** ***181.8 / -1.56*** ***111 CARTWRIGHT AVE. Toronto ON*** ***WWIS***

Well ID:	7332345	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02-May-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z310709	**Contractor:**	7644
Tag:	A260396	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7332345.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/04/03
Year Completed:	2019
Depth (m):	6.096
Latitude:	43.7220802680177
Longitude:	-79.4653470235267
Path:	733\7332345.pdf

Bore Hole Information

Bore Hole ID:	1007428097	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623613.00
Code OB Desc:		**North83:**	4842150.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03-Apr-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007919103
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	34
Most Common Material:	TILL
Mat2:	
Mat2 Desc:	
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	0.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919113
Layer:	3
Plug From:	8.0
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919111
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919112
Layer:	2
Plug From:	1.0
Plug To:	8.0
Plug Depth UOM:	ft

Method of Construction & Well

Use

Method Construction ID:	1007919110
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007919102
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007919106
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007919107
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.375

Water Details

Water ID:	1007919105
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007919104
Diameter:	4.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1007428097	***Tag No:***	A260396
Depth M:	6.096	***Contractor:***	7644
Year Completed:	2019	***Path:***	733\7332345.pdf

Well Completed Dt:	2019/04/03	**Latitude:**	43.7220802680177
Audit No:	Z310709	**Longitude:**	-79.4653470235267

10 **1 of 1** **NW/21.3** **182.4 / -1.04** **111 CARTWRIGHT AVE. Toronto ON** **WWIS**

Well ID:	7332344	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02-May-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z310707	**Contractor:**	7644
Tag:	A265263	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7332344.pdf

Additional Detail(s) (Map)

Well Completed Date:	2019/04/03
Year Completed:	2019
Depth (m):	6.096
Latitude:	43.7216283989223
Longitude:	-79.4652219983127
Path:	733\7332344.pdf

Bore Hole Information

Bore Hole ID:	1007428094	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623624.00
Code OB Desc:		**North83:**	4842100.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03-Apr-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007919090
Layer:	1

Color:	6
General Color:	BROWN
Mat1:	34
Most Common Material:	TILL
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007919091
Layer:	2
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	28
Mat2 Desc:	SAND
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	15.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919099
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919100
Layer:	2
Plug From:	1.0
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007919101
Layer:	3
Plug From:	8.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007919098
Method Construction Code:	6
Method Construction:	Boring

Other Method Construction:

Pipe Information

Pipe ID: 1007919089
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007919094
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007919095
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 1
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.375

Water Details

Water ID: 1007919093
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1007919092
Diameter: 4.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1007428094
Depth M: 6.096
Year Completed: 2019
Well Completed Dt: 2019/04/03
Audit No: Z310707
Tag No: A265263
Contractor: 7644
Path: 733\7332344.pdf
Latitude: 43.7216283989223
Longitude: -79.4652219983127

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	1 of 19	S/27.7	183.9 / 0.46	CANADA CUP INC. 137 BENTWORTH AVE. TORONTO CITY ON M6A 1P6	CA

Certificate #: 8-3074-87-
Application Year: 87
Issue Date: 8/12/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: TWO GAS-FIRED BOILERS
Contaminants: Nitrogen Oxides, Sulphur Dioxide
Emission Control: No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	2 of 19	S/27.7	183.9 / 0.46	JAMES RIVER CANADA INC. 137 BENTWORTH AVE NORTH YORK ON M6A 1P6	SCT

Established: 1963
Plant Size (ft²): 100000
Employment: 400

--Details--
Description: PLASTICS PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3089

Description: PLASTICS FOAM PRODUCTS
SIC/NAICS Code: 3086

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	3 of 19	S/27.7	183.9 / 0.46	FORT JAMES CANADA INC. 137 Bentworth Ave North York ON M6A 1P6	SCT

Established: 1963
Plant Size (ft²): 100000
Employment: 400

--Details--
Description: Polystyrene Foam Product Manufacturing
SIC/NAICS Code: 326140

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	4 of 19	S/27.7	183.9 / 0.46	137 Bentworth Avenue Toronto ON M6A 1P6	CA

Certificate #: 3056-52XKAL
Application Year: 01
Issue Date: 9/27/01
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Fort James Canada Inc.
Client Address: 228 Queen Street West

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client City: Brampton
Client Postal Code: L6X 1A9
Project Description: This application is for a plant-wide certificate of approval including emissions from natural gas heating, plastic extrusion operations and material handling. A full range of plastic products ranging from cutlery to cups produced primarily from polystyrene and polyethylene are manufactured at this facility and emissions occur from the following five (5) processes: -volatile organic emissions from the melting and extruding of polystyrene and polyethylene; -emissions from space and water heating using natural gas; -dust emissions from the grinding of scrap and waste polystyrene and polyethylene; -dust emissions from the pneumatic conveying and filling system; and -volatile organic emissions from the cleaning liquids used to clean extruder dies.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	5 of 19	S/27.7	183.9 / 0.46	Fort James Canada Inc. 137 Bentworth Avenue Toronto Ontario Toronto ON	EBR

EBR Registry No: IA01E0705
Ministry Ref No: 2056-4WYRJ2
Notice Type: Instrument Decision
Notice Stage:
Notice Date: October 03, 2001
Proposal Date: May 23, 2001
Year: 2001
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Fort James Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 228 Queen Street, Brampton Ontario, L6X 1A9
Comment Period:
URL:

Site Location Details:

137 Bentworth Avenue Toronto Ontario Toronto

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	6 of 19	S/27.7	183.9 / 0.46	Georgia-Pacific Canada Inc. 137 Bentworth Ave North York ON M6A 1P6	SCT

Established: 1963
Plant Size (ft²): 100000
Employment: 400

--Details--
Description: Corrugated and Solid Fibre Box Manufacturing
SIC/NAICS Code: 322211

Description: Other Paperboard Container Manufacturing
SIC/NAICS Code: 322219

Description: All Other Converted Paper Product Manufacturing
SIC/NAICS Code: 322299

Description: Polystyrene Foam Product Manufacturing
SIC/NAICS Code: 326140

Description: Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code: 326150

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

---

11 **7 of 19** **S/27.7** **183.9 / 0.46** **CANADA CUP INC.**
137 BENTWORTH AVE.
TORONTO ON M6A 1P6 **GEN**

Generator No: ON0387402
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

11 **8 of 19** **S/27.7** **183.9 / 0.46** **CANADA CUP (SEE & USE ON1947701) 08-289**
137 BENTWORTH AVE.
TORONTO ON M6A 1P6 **GEN**

Generator No: ON0387402
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 92,93,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

11 **9 of 19** **S/27.7** **183.9 / 0.46** **CANADA CUP INC. 08-289**
137 BENTWORTH AVE.
TORONTO ON M6A 1P6 **GEN**

Generator No: ON0387402
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

11	*10 of 19*	*S/27.7*	*183.9 / 0.46*	***JAMES RIVER CANADA INC.*** ***137 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P6***	***GEN***

Generator No: ON1947701
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

11	*11 of 19*	*S/27.7*	*183.9 / 0.46*	***FORT JAMES CANADA INC.*** ***137 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P6***	***GEN***

Generator No: ON1947701
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			

11	12 of 19	S/27.7	183.9 / 0.46	**GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.** **137 BENTWORTH AVENUE** **TORONTO ON M6A 1P6**	GEN

Generator No: ON1947701
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

11	13 of 19	S/27.7	183.9 / 0.46	**137 Bentworth Avenue** **North York ON M6A 1P6**	EHS

Order No: 20050812015
Status: C
Report Type: Complete Report
Report Date: 8/18/2005
Date Received: 8/12/2005
Previous Site Name:
Lot/Building Size: building approx. 20,000
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.464776
Y: 43.720168

11	14 of 19	S/27.7	183.9 / 0.46	**137 Bentworth Ave** **Toronto ON M6A 1P6**	EHS

Order No: 20050928031
Status: C
Report Type: Complete Report
Report Date: 10/6/2005
Date Received: 9/28/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.4647
Y: 43.720002

11	15 of 19	S/27.7	183.9 / 0.46	**Fort James Canada Inc.** **137 Bentworth Avenue Toronto Ontario Toronto ON**	EBR

EBR Registry No: IA04E0900
Ministry Ref No: 6688-5ZXL5S
Notice Type: Instrument Decision

Decision Posted:
Exception Posted:
Section:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Notice Stage: **Act 1:**
Notice Date: May 23, 2006 **Act 2:**
Proposal Date: June 15, 2004 **Site Location Map:**
Year: 2004
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Fort James Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 228 Queen Street West, Brampton Ontario, L6X 1A9
Comment Period:
URL:

Site Location Details:

137 Bentworth Avenue Toronto Ontario Toronto

11	16 of 19	S/27.7	183.9 / 0.46	**The Morris Group/Marketing** **137 Bentworth Ave** **Toronto ON M6A 1P6**	SCT

Established: 01-AUG-29
Plant Size (ft²):
Employment:

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Other Printing
SIC/NAICS Code: 323119

Description: Digital Printing
SIC/NAICS Code: 323115

11	17 of 19	S/27.7	183.9 / 0.46	**Georgia-Pacific Canada, Consumer Products, Inc.** **137 Bentworth Avenue** **Toronto ON M6A 1P6**	CA

Certificate #: 8793-5WKM5Q
Application Year: 2004
Issue Date: 2/28/2004
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

11	18 of 19	S/27.7	183.9 / 0.46	**Georgia-Pacific Canada, Consumer Products, Inc.**	ECA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				137 Bentworth Avenue **Toronto ON L6X 1A9**	

Approval No:	8793-5WKM5Q	**MOE District:**	Metro Toronto
Approval Date:	2004-02-28	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.465904
Record Type:	ECA	**Latitude:**	43.720222
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Georgia-Pacific Canada, Consumer Products, Inc.
Address: 137 Bentworth Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3128-5SBQFZ-14.pdf
PDF Site Location:

11	**19 of 19**	**S/27.7**	**183.9 / 0.46**	**Fort James Canada Inc.** **137 Bentworth Avenue** **Toronto ON L6X 1A9**	**ECA**

Approval No:	3056-52XKAL	**MOE District:**	Metro Toronto
Approval Date:	2001-09-27	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.465904
Record Type:	ECA	**Latitude:**	43.720222
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Fort James Canada Inc.
Address: 137 Bentworth Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2056-4WYRJ2-14.pdf
PDF Site Location:

12	**1 of 1**	**SE/33.8**	**184.8 / 1.44**	**105-123 Bentworth Avenue** **Toronto ON M6A 1P6**	**EHS**

Order No:	20100824024	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	9/2/2010	**Search Radius (km):**	0.25
Date Received:	8/24/2010	**X:**	-79.463772
Previous Site Name:		**Y:**	43.720544
Lot/Building Size:			

Additional Info Ordered: Fire Insur. Maps and/or Site Plans

13	**1 of 1**	**ESE/36.7**	**184.8 / 1.44**	**University of Toronto** **U of T CDE - Shaw 105 Bentworth Ave. Unit 1** **North York ON M6A 1P6**	**GEN**

Generator No: ON6333540
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

14 | ***1 of 1*** | ***NW/37.0*** | ***181.3 / -2.08*** | ***Dominion Roofing, 113 Cartwright Avenue, North York ON M6A 1V4*** | ***GEN***

Generator No: ON1373800
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

---

15 | ***1 of 1*** | ***N/37.6*** | ***182.8 / -0.63*** | ***102 CARTRIGHT AVE, Toronto ON*** | ***WWIS***

Well ID:	7281892	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Test Hole	***Data Entry Status:***	
Use 2nd:	Monitoring	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	24-Feb-2017 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z251094	***Contractor:***	7241
Tag:	A217290	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/02/01

Year Completed: 2017
Depth (m): 4.572
Latitude: 43.7225563039638
Longitude: -79.4645899726886
Path:

Bore Hole Information

Bore Hole ID: 1006358240
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01-Feb-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623673.00
North83: 4842204.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006603944
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 3.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006603945
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 10.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1006603943
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603953
Layer:	1
Plug From:	15.0
Plug To:	4.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603954
Layer:	2
Plug From:	4.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603955
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006603952
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006603942
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006603948
Layer:	1
Material:	5

Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	5.0
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006603949
Layer:	1
Slot:	.10
Screen Top Depth:	5.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Water Details

Water ID:	1006603947
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006603946
Diameter:	2.25
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006358240	**Tag No:**	A217290
Depth M:	4.572	**Contractor:**	7241
Year Completed:	2017	**Path:**	728\7281892.pdf
Well Completed Dt:	2017/02/01	**Latitude:**	43.7225563039638
Audit No:	Z251094	**Longitude:**	-79.4645899726886

---

16 | ***1 of 8*** | ***WNW/40.1*** | ***181.8 / -1.58*** | ***DOMINION SHEET METAL & ROOFING WORKS*** | ***FST***

113 CARTWRIGHT AVE NORTH YORK M6A 1V4
ON CA
ON

Instance No:	11009438	**Manufacturer:**	
Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:	FS Liquid Fuel Tank	**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Single Wall UST	**Fuel Type2:**	NULL
Install Date:	11/28/1990	**Fuel Type3:**	NULL
Install Year:	1990	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	

Capacity: 10000
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: Fuels Safety Private Fuel Outlet - Self Serve
Facility Location:
Device Installed Location: 113 CARTWRIGHT AVE NORTH YORK M6A 1V4 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: DOMINION SHEET METAL & ROOFING WORKS
Item: FS LIQUID FUEL TANK

---

16 | ***2 of 8*** | ***WNW/40.1*** | ***181.8 / -1.58*** | ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON M6A 1V4 | ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description: ROOFING AND RELATED WORK
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Sefora Montanari
Choice of Contact: CO_ADMIN
Phone No Admin: 416-789-0601 Ext.228
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

16 | ***3 of 8*** | ***WNW/40.1*** | ***181.8 / -1.58*** | ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON M6A 1V4 | ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description: ROOFING AND RELATED WORK
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Sefora Montanari
Choice of Contact: CO_ADMIN
Phone No Admin: 416-789-0601 Ext.228
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

16 | **4 of 8** | **WNW/40.1** | **181.8 / -1.58** | **1262589 Ontario Ltd.**
113 Cartwright Avenue
North York ON M6A 1V4 | **GEN**

Generator No: ON1373800
SIC Code: 232330
SIC Description: ROOFING AND RELATED WORK
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Azril Rom
Choice of Contact: CO_ADMIN
Phone No Admin: 416-789-0601 Ext.229
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

16 | **5 of 8** | **WNW/40.1** | **181.8 / -1.58** | **1262589 Ontario Ltd.**
113 Cartwright Avenue
North York ON M6A 1V4 | **GEN**

Generator No: ON1373800
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

16 | **6 of 8** | **WNW/40.1** | **181.8 / -1.58** | **Dominion Roofing**
113 Cartwright Avenue
North York ON M6A 1V4 | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON1373800
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

16	7 of 8	WNW/40.1	181.8 / -1.58	**Dominion Sheet Metal and Roofing Works.** **113 Cartwright Ave** **Toronto ON M6Z1V4**	GEN

Generator No: ON6383945
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

16	8 of 8	WNW/40.1	181.8 / -1.58	**Dominion Roofing** **113 Cartwright Avenue** **North York ON M6A 1V4**	GEN

Generator No: ON1373800
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	1 of 9	WNW/40.1	181.8 / -1.58	DOMINION SHEET METAL & ROOFING WKS 113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	GEN

Generator No: ON1373800
SIC Code: 4236
SIC Description: SHEET METAL & ROOF.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 9	WNW/40.1	181.8 / -1.58	DOMINION SHEET METAL & ROOFING WKS12-523 113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	GEN

Generator No: ON1373800
SIC Code: 4236
SIC Description: SHEET METAL & ROOF.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	3 of 9	WNW/40.1	181.8 / -1.58	DOMINION SHEET METAL & ROOFING WORKS 113 CARTWRIGHT AVENUE NORTH YORK ON M6A 1V4	GEN

Generator No: ON1373800
SIC Code: 4236
SIC Description: SHEET METAL & ROOF.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

17	4 of 9	WNW/40.1	181.8 / -1.58	1262589 Ontario Ltd. 113 CARTWRIGHT AVENUE NORTH YORK ON	GEN

Generator No: ON1373800
SIC Code: 232330
SIC Description: Roofing and Related Work
Approval Years: 03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

17	5 of 9	WNW/40.1	181.8 / -1.58	1262589 Ontario Ltd. 113 Cartwright Avenue North York ON M6A 1V4	GEN

Generator No: ON1373800
SIC Code: 232330
SIC Description:
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

17 ***6 of 9*** ***WNW/40.1*** ***181.8 / -1.58*** ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON M6A 1V4 ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description:
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

17 ***7 of 9*** ***WNW/40.1*** ***181.8 / -1.58*** ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON M6A 1V4 ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

17 | ***8 of 9*** | ***WNW/40.1*** | ***181.8 / -1.58*** | ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON M6A 1V4 | ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description:
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

17 | ***9 of 9*** | ***WNW/40.1*** | ***181.8 / -1.58*** | ***1262589 Ontario Ltd.***
113 Cartwright Avenue
North York ON | ***GEN***

Generator No: ON1373800
SIC Code: 232330
SIC Description: ROOFING AND RELATED WORK
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	1 of 4	WNW/41.3	181.9 / -1.51	PETRO-CANADA 113 CARTWRIGHT AV SERVICE STATION TORONTO CITY ON M6A 1V4	SPL

Ref No:	40969	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	9/17/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNDERGROUND TANK LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/18/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	CORROSION	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: PETROCAN - CONTAMINATED SOIL ENCOUNTERED WHILE REMOVING INGROUND TANK.
Contaminant Qty:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	2 of 4	WNW/41.3	181.9 / -1.51	DOMINION SHEET METAL & ROOFING WORKS 113 CARTWRIGHT AV TORONTO ON M6A 1V4	PRT

Location ID:	15211
Type:	private
Expiry Date:	
Capacity (L):	10000.00
Licence #:	0001044122

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	3 of 4	WNW/41.3	181.9 / -1.51	DOMINION SHEET METAL & ROOFING WORKS 113 CARTWRIGHT AV TORONTO ON M6A 1V4	FSTH

License Issue Date:	12/10/1990
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Private Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1990
Corrosion Protection:	
Capacity:	10000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	4 of 4	WNW/41.3	181.9 / -1.51	DOMINION SHEET METAL & ROOFING WORKS 113 CARTWRIGHT AV TORONTO ON M6A 1V4	FSTH

License Issue Date: 12/10/1990
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 10000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

19 | **1 of 1** | **N/45.0** | **182.8 / -0.56** | **102 CARTRIGHT AVE Toronto ON** | **WWIS**

Well ID: 7281833
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z245481
Tag: A185472
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 24-Feb-2017 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/02/01
Year Completed: 2017
Depth (m): 4.2672
Latitude: 43.7226838146037
Longitude: -79.4646984501115
Path:

Bore Hole Information

Bore Hole ID: 1006358570
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01-Feb-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:

Elevation:
Elevrc:
Zone: 17
East83: 623664.00
North83: 4842218.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006601998
Layer: 3
Color: 2
General Color: GREY
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 14.0
Formation End Depth:
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006601997
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 11
Mat3 Desc: GRAVEL
Formation Top Depth: 2.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006601996
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3: 60
Mat3 Desc: CEMENTED
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006602006
Layer: 1

Plug From: 14.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006602007
Layer: 2
Plug From: 3.0
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006602008
Layer: 3
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006602005
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1006601995
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006602001
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.0
Casing Diameter: 1.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006602002
Layer: 1
Slot: .10
Screen Top Depth: 4.0
Screen End Depth: 14.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.25

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID:	1006602000
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006601999
Diameter:	2.25
Depth From:	0.0
Depth To:	14.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1006358570	***Tag No:***	A185472
Depth M:	4.2672	***Contractor:***	7241
Year Completed:	2017	***Path:***	728\7281833.pdf
Well Completed Dt:	2017/02/01	***Latitude:***	43.7226838146037
Audit No:	Z245481	***Longitude:***	-79.4646984501115

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	1 of 18	WSW/46.1	182.9 / -0.53	CITY OF NORTH YORK PUBLIC WORKS DEPT 140 BENTWORTH AV NORTH YORK ON M6A 1P7	PRT

Location ID:	15189
Type:	private
Expiry Date:	
Capacity (L):	9000.00
Licence #:	0001052804

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	2 of 18	WSW/46.1	182.9 / -0.53	NORTH YORK, CITY OF BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	GEN

Generator No:	ON0132013
SIC Code:	8364
SIC Description:	REC./CULTURE ADMIN.
Approval Years:	93,94,95,96,97,98,99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	3 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	GEN

Generator No: ON0132013
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	4 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES 140 BENTWORTH AVE NORTH YORK ON M6A 1P7	FSTH

License Issue Date: 6/2/1994
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 9000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	5 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO, REVENUE SERVICES, FINANCIAL SERVICES 140 BENTWORTH AVE NORTH YORK ON M6A 1P7	FSTH

License Issue Date: 6/2/1994
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 9000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

20 **6 of 18** **WSW/46.1** **182.9 / -0.53** **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE
NORTH YORK ON M6A 1P7 **GEN**

Generator No: ON0132013
SIC Code: 811199
SIC Description: All Other Automotive Repair and Maintenance
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

20 **7 of 18** **WSW/46.1** **182.9 / -0.53** **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE
NORTH YORK ON M6A 1P7 **GEN**

Generator No: ON0132013
SIC Code: 811199
SIC Description: All Other Automotive Repair and Maintenance
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

20 **8 of 18** **WSW/46.1** **182.9 / -0.53** **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE
NORTH YORK ON M6A 1P7 **GEN**

Generator No: ON0132013
SIC Code: 811199
SIC Description: All Other Automotive Repair and Maintenance
Approval Years: 2011
PO Box No:

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

20 | ***9 of 18*** | ***WSW/46.1*** | ***182.9 / -0.53*** | ***CITY OF TORONTO 140 BENTWORTH AVE NORTH YORK M6A 1P7 ON CA ON*** | ***FST***

Instance No: 11008884
Status:
Cont Name:
Instance Type: FS Liquid Fuel Tank
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Single Wall UST
Install Date: 12/27/1990
Install Year: 1984
Years in Service:
Model: NULL
Description:
Capacity: 9000
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protect:
Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type: Fuels Safety Private Fuel Outlet - Self Serve
Facility Location:
Device Installed Location: 140 BENTWORTH AVE NORTH YORK M6A 1P7 ON CA

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: CITY OF TORONTO
Item: FS LIQUID FUEL TANK

---

20 | ***10 of 18*** | ***WSW/46.1*** | ***182.9 / -0.53*** | ***CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7*** | ***GEN***

Generator No: ON0132013
SIC Code: 811199
SIC Description: All Other Automotive Repair and Maintenance
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

20 | ***11 of 18*** | ***WSW/46.1*** | ***182.9 / -0.53*** | ***CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON*** | ***GEN***

Generator No: ON0132013
SIC Code: 811199
SIC Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

20 | ***12 of 18*** | ***WSW/46.1*** | ***182.9 / -0.53*** | ***CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7*** | ***GEN***

Generator No: ON0132013
SIC Code: 811199
SIC Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

20 | **13 of 18** | **WSW/46.1** | **182.9 / -0.53** | **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE
NORTH YORK ON M6A 1P7 | **GEN**

Generator No: ON0132013
SIC Code: 811199
SIC Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

20 | **14 of 18** | **WSW/46.1** | **182.9 / -0.53** | **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE
NORTH YORK ON M6A 1P7 | **GEN**

Generator No: ON0132013
SIC Code: 811199
SIC Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

20 | **15 of 18** | **WSW/46.1** | **182.9 / -0.53** | **CITY OF TORONTO**
BENTWORTH YARD 140 BENTWORTH AVENUE | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				NORTH YORK ON M6A 1P7	

Generator No: ON0132013
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

20	16 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	GEN

Generator No: ON0132013
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

20	17 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				NORTH YORK ON M6A 1P7	

Generator No: ON0132013
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 I
Waste Class Name: Light fuels

20	18 of 18	WSW/46.1	182.9 / -0.53	CITY OF TORONTO BENTWORTH YARD 140 BENTWORTH AVENUE NORTH YORK ON M6A 1P7	GEN

Generator No: ON0132013
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

21	1 of 1	N/49.6	182.9 / -0.53	102 CARTRIGHT AVE Toronto ON	WWIS

Well ID:	7281891	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	24-Feb-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z253376	**Contractor:**	7241
Tag:	A185470	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2017/02/01
Year Completed:	2017
Depth (m):	6.096
Latitude:	43.722617641361
Longitude:	-79.4644642562738
Path:	

Bore Hole Information

Bore Hole ID:	1006358744	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623683.00
Code OB Desc:		**North83:**	4842211.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01-Feb-2017 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006603923
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL

Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006603924
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 3.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006603925
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 10.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006603935
Layer: 3
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006603934
Layer: 2
Plug From: 9.0
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006603933

Layer:	1
Plug From:	20.0
Plug To:	9.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006603932
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006603922
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006603928
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006603929
Layer:	1
Slot:	.10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Water Details

Water ID:	1006603927
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006603926
Diameter:	2.25
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Links

Bore Hole ID:	1006358744	***Tag No:***	A185470
Depth M:	6.096	***Contractor:***	7241
Year Completed:	2017	***Path:***	
Well Completed Dt:	2017/02/01	***Latitude:***	43.722617641361
Audit No:	Z253376	***Longitude:***	-79.4644642562738

22	***1 of 18***	***SE/67.1***	***184.4 / 0.96***	***Georgia-Pacific Canada Inc.*** ***123 Bentworth Ave*** ***North York ON M6A 1P6***	***SCT***

Established:	1963
Plant Size (ft²):	100000
Employment:	400

--Details--

Description:	Corrugated and Solid Fibre Box Manufacturing
SIC/NAICS Code:	322211
Description:	Other Paperboard Container Manufacturing
SIC/NAICS Code:	322219
Description:	All Other Converted Paper Product Manufacturing
SIC/NAICS Code:	322299
Description:	Polystyrene Foam Product Manufacturing
SIC/NAICS Code:	326140
Description:	Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code:	326150
Description:	All Other Plastic Product Manufacturing
SIC/NAICS Code:	326198

22	***2 of 18***	***SE/67.1***	***184.4 / 0.96***	***GEORGIA PACIFIC CANADA, CONSUMER PRODUCTS INC.*** ***123 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P6***	***GEN***

Generator No:	ON1947701
SIC Code:	326198
SIC Description:	All Other Plastic Product Manufacturing
Approval Years:	05,06
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	3 of 18	SE/67.1	184.4 / 0.96	Georgia-Pacific Canada Inc. 123 Bentworth Ave North York ON M6A 1P6	SCT

Established: 9/1/1963
Plant Size (ft²):
Employment:

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	4 of 18	SE/67.1	184.4 / 0.96	GEORGIA-PACIFIC CANADA, CONSUMER PRODUCTS, ULC 123 BENTWORTH AVENUE TORONTO ON M6A 1P6	GEN

Generator No: ON1947701
SIC Code: 326198
SIC Description: All Other Plastic Product Manufacturing
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

22 **5 of 18** **SE/67.1** **184.4 / 0.96** **Georgia-Pacific Canada, Consumer Products, Inc.**
123 Bentworth Avenue
Toronto ON M6A 1P6
CA

Certificate #: 6317-6LKH3F
Application Year: 2006
Issue Date: 5/19/2006
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

22 **6 of 18** **SE/67.1** **184.4 / 0.96** **Georgia-Pacific Canada Consumer Products LP**
123 Bentworth Avenue
Toronto ON M6A 1P6
NPRI

NPRI ID: 8800000096
Other ID: *
No Other ID:
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2009
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: Bentworth
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts: No
URL: WWW.GP.COM
No of Empl.: 0
Parent Co.: *
No Parent Co.:
Pollut Prev Cmnts: No
Stacks: No
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit):

Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type:
Contact Title:
Cont First Name:
Cont Last Name:
Contact Position:
Contact Fax:
Contact Ph.:
Cont Area Code:
Contact Tel.:
Contact Ext.:
Cont Fax Area Cde:
Contact Fax:
Contact Email:
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: No
No Streams:
Waste Off Sites: No
No Off Sites:
Shutdown: No
No of Shutdown:

NAICS 2 Description:
NAICS Code (4 digit):
NAICS 4 Description:
NAICS Code (6 digit):
NAICS 6 Description:

---

22 | ***7 of 18*** | ***SE/67.1*** | ***184.4 / 0.96*** | ***GEORGIA-PACIFIC CANADA LP*** ***123 Bentworth Avenue*** ***Toronto ON M6A1P6*** | ***NPRI***

NPRI ID:	7100009406	***Org ID:***	
Other ID:	*	***Submit Date:***	
No Other ID:		***Last Modified:***	
Track ID:		***Contact ID:***	
Report ID:		***Cont Type:***	MED
Report Type:		***Contact Title:***	
Rpt Type ID:		***Cont First Name:***	
Report Year:	2010	***Cont Last Name:***	
Not-Current Rpt?:		***Contact Position:***	
Yr of Last Filed Rpt:		***Contact Fax:***	
Fac ID:		***Contact Ph.:***	
Fac Name:	BENTWORTH	***Cont Area Code:***	
Fac Address1:		***Contact Tel.:***	
Fac Address2:		***Contact Ext.:***	
Fac Postal Zip:		***Cont Fax Area Cde:***	
Facility Lat:		***Contact Fax:***	
Facility Long:		***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	
Facility DLS:		***Longitude:***	
Datum:		***UTM Zone:***	
Facility Cmnts:	No	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	0	***Waste Streams:***	No
Parent Co.:	*	***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	No
Pollut Prev Cmnts:	No	***No Off Sites:***	
Stacks:	No	***Shutdown:***	No
No of Stacks:		***No of Shutdown:***	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit):
NAICS 2 Description:
NAICS Code (4 digit):
NAICS 4 Description:
NAICS Code (6 digit):
NAICS 6 Description:

---

22 | ***8 of 18*** | ***SE/67.1*** | ***184.4 / 0.96*** | ***GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP*** ***123 BENTWORTH AVENUE*** ***TORONTO ON M6A 1P6*** | ***GEN***

Generator No:	ON1947701
SIC Code:	326198
SIC Description:	All Other Plastic Product Manufacturing
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 243
Waste Class Name: PCBS

22	9 of 18	SE/67.1	184.4 / 0.96	GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP 123 BENTWORTH AVENUE TORONTO ON M6A 1P6	GEN

Generator No: ON1947701
SIC Code: 326198
SIC Description: All Other Plastic Product Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

22 | **10 of 18** | **SE/67.1** | **184.4 / 0.96** | **Kevric Ontario Real Estate Corp.**
123 Bentworth Ave.
Toronto ON M6A 1P6 | **GEN**

Generator No: ON5176532
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

22 | **11 of 18** | **SE/67.1** | **184.4 / 0.96** | **Kevric Ontario Real Estate Corp.**
123 Bentworth Ave.
Toronto ON M6A 1P6 | **GEN**

Generator No: ON5176532
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

22 | **12 of 18** | **SE/67.1** | **184.4 / 0.96** | **GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP** | **NPRI**

123 Bentworth Avenue
Toronto ON M6A1P6

NPRI ID:	8800000670	***Org ID:***	
Other ID:		***Submit Date:***	
No Other ID:		***Last Modified:***	
Track ID:		***Contact ID:***	
Report ID:		***Cont Type:***	MED
Report Type:		***Contact Title:***	Mr.
Rpt Type ID:		***Cont First Name:***	RAFAEL
Report Year:	2004	***Cont Last Name:***	INDACOCHEA
Not-Current Rpt?:		***Contact Position:***	PLANT ENGINEER
Yr of Last Filed Rpt:		***Contact Fax:***	
Fac ID:		***Contact Ph.:***	
Fac Name:	BENTWORTH	***Cont Area Code:***	905
Fac Address1:		***Contact Tel.:***	4566058
Fac Address2:		***Contact Ext.:***	0
Fac Postal Zip:		***Cont Fax Area Cde:***	
Facility Lat:		***Contact Fax:***	
Facility Long:		***Contact Email:***	Rafael.Indacochea@gapac.com
DLS (Last Filed Rpt):		***Latitude:***	
Facility DLS:		***Longitude:***	
Datum:		***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:	WWW.GP.COM	***UTM Easting:***	
No of Empl.:	133	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	31-33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3261		
NAICS 4 Description:	Plastic Product Manufacturing		
NAICS Code (6 digit):	326198		
NAICS 6 Description:	All Other Plastic Product Manufacturing		

Substance Release Report

CAS No:	124-38-9
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon dioxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M09
Report ID:	
Rpt Period:	2004
Subst Released:	PM10 - Particulate Matter <= 10 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	7446-09-5

Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 11104-93-1
Report ID:
Rpt Period: 2004
Subst Released: Nitrogen oxides (expressed as NO2)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2004
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:

Total Releases:	
Units:	tonnes
CAS No:	630-08-0
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon monoxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M08
Report ID:	
Rpt Period:	2004
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

22	13 of 18	SE/67.1	184.4 / 0.96	**GEORGIA-PACIFIC CANADA CONSUMER PRODUCTS LP** **123 Bentworth Avenue** **Toronto ON M6A1P6**	NPRI

NPRI ID:	7100000116	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	
Rpt Type ID:		**Cont First Name:**	
Report Year:	2009	**Cont Last Name:**	
Not-Current Rpt?:		**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	BENTWORTH	**Cont Area Code:**	
Fac Address1:		**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:	WWW.GP.COM	**UTM Easting:**	
No of Empl.:	0	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):			
NAICS 2 Description:			
NAICS Code (4 digit):			
NAICS 4 Description:			
NAICS Code (6 digit):			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

NAICS 6 Description:

---

22 | **14 of 18** | **SE/67.1** | **184.4 / 0.96** | **Georgia-Pacific Canada, Consumer Products, Inc.**
123 Bentworth Avenue
Toronto ON L6X 1A9 | **ECA**

Approval No:	6317-6LKH3F	**MOE District:**	Metro Toronto
Approval Date:	2006-05-19	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.465904
Record Type:	ECA	**Latitude:**	43.720222
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Georgia-Pacific Canada, Consumer Products, Inc.
Address: 123 Bentworth Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6688-5ZXL5S-14.pdf
PDF Site Location:

---

22 | **15 of 18** | **SE/67.1** | **184.4 / 0.96** | **GEORGIA-PACIFIC CANADA LP**
123 BENTWORTH AVENUE NOT AVAILABLE
TORONTO ON M6A1P6 | **NPRI**

NPRI ID:	9406	**Org ID:**	101754
Other ID:		**Submit Date:**	6/10/2011
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	88409	**Contact ID:**	
Report ID:	142475	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2010	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:	148472	**Contact Ph.:**	
Fac Name:	BENTWORTH	**Cont Area Code:**	
Fac Address1:	123 BENTWORTH AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M6A1P6	**Cont Fax Area Cde:**	
Facility Lat:	0	**Contact Fax:**	
Facility Long:	0	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	0	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit):
NAICS 2 Description:
NAICS Code (4 digit):
NAICS 4 Description:
NAICS Code (6 digit):
NAICS 6 Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	16 of 18	SE/67.1	184.4 / 0.96	GEORGIA-PACIFIC CANADA LP 123 BENTWORTH AVENUE NOT AVAILABLE TORONTO ON M6A1P6	NPRI

NPRI ID:	9406	**Org ID:**	101754
Other ID:		**Submit Date:**	6/10/2011
No Other ID:		**Last Modified:**	9/4/2015 9:56:49 AM
Track ID:	134544	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	Sale/Purchase/Closure	**Contact Title:**	
Rpt Type ID:	3	**Cont First Name:**	
Report Year:	2010	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:	148472	**Contact Ph.:**	
Fac Name:	BENTWORTH	**Cont Area Code:**	
Fac Address1:	123 BENTWORTH AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M6A1P6	**Cont Fax Area Cde:**	
Facility Lat:	0	**Contact Fax:**	
Facility Long:	0	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):			
NAICS 2 Description:			
NAICS Code (4 digit):			
NAICS 4 Description:			
NAICS Code (6 digit):			
NAICS 6 Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	17 of 18	SE/67.1	184.4 / 0.96	Shaw Dental Laboratory, Inc. 105 -123 Bentworth Avenue, Unit 1 North York ON M6A1P6	GEN

Generator No:	ON2580694
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

---

22 | **18 of 18** | **SE/67.1** | **184.4 / 0.96** | **Shaw Dental Laboratory, Inc.**
105 -123 Bentworth Avenue, Unit 1
North York ON M6A1P6 | **GEN**

Generator No: ON2580694
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232 L
Waste Class Name: POLYMERIC RESINS

---

23 | **1 of 1** | **W/67.3** | **181.9 / -1.55** | **TORONTO HYDRO**
117 CARTWRIGHT AVE. TRANSFORMER
TORONTO CITY ON M6A 1V4 | **SPL**

Ref No: 223492
Site No:
Incident Dt: 3/27/2002
Year:
Incident Cause: UNKNOWN
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND / WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/27/2002
Dt Document Closed:
Incident Reason: UNKNOWN
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: TORONTO HYDRO: NON PCB TRANSFORMER TO GRND 60 GAL, CONTAINED, CLEANED
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 01106
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 1	SSW/67.9	183.1 / -0.27	Ontario Acoustic Supply Inc. 139 Bentworth Ave North York ON M6A 1P6	SCT

Established: 01-SEP-30
Plant Size (ft²): 12000
Employment:

--Details--
Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: General-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416310

Description: Other Home Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414390

Description: Construction and Forestry Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417210

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: General-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416310

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	1 of 6	NW/70.0	180.9 / -2.55	ITALDOOR & WOODWORKING LTD. 120 CARTWRIGHT AVE TORONTO ON M6A 1V2	SCT

Established: 1969
Plant Size (ft²): 18000
Employment: 15

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: METAL DOORS, SASH, FRAMES, MOLDING, AND TRIM
SIC/NAICS Code: 3442

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	2 of 6	NW/70.0	180.9 / -2.55	Italdoor & Woodworking Ltd. 120 Cartwright Ave North York ON M6A 1V2	SCT

Established: 8/1/1969
Plant Size (ft²): 18000
Employment:

--Details--
Description: Wood Window and Door Manufacturing
SIC/NAICS Code: 321911

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Wood Window and Door Manufacturing
SIC/NAICS Code: 321911

Description: Hardware Manufacturing
SIC/NAICS Code: 332510

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Other Millwork
SIC/NAICS Code: 321919

---

25 | 3 of 6 | NW/70.0 | 180.9 / -2.55 | **120 Cartwright Avenue**
Toronto ON M6A 1V2 | EHS

Order No: 20111220007
Status: C
Report Type: Custom Report
Report Date: 12/29/2011 10:50:36 AM
Date Received: 12/20/2011 10:50:36 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.46581
Y: 43.722662

---

25 | 4 of 6 | NW/70.0 | 180.9 / -2.55 | **120 Cartwright Avenue**
Toronto ON | EHS

Order No: 20140919067
Status: C
Report Type: Custom Report
Report Date: 23-SEP-14
Date Received: 19-SEP-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.465834
Y: 43.722636

---

25 | 5 of 6 | NW/70.0 | 180.9 / -2.55 | **120 Cartwright Ave**
Toronto ON | EHS

Order No: 20190704068
Status: C
Report Type: RSC Report (Urban)
Report Date: 28-AUG-19
Date Received: 04-JUL-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.465878
Y: 43.722642

---

25 | 6 of 6 | NW/70.0 | 180.9 / -2.55 | **Toronto Transit Commission**
120 Cartwright Ave
Toronto ON M6A 1V2 | GEN

Generator No: ON5661427
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

26 ***1 of 1*** ***WNW/73.5*** ***181.3 / -2.11*** ***185 BRIDGELAND AVE Toronto ON*** ***WWIS***

Well ID: 7159338
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z127927
Tag: A112791
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info: WKQ003443

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 17-Feb-2011 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7159338.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/01/18
Year Completed: 2011
Depth (m): 6.096
Latitude: 43.7215927272301
Longitude: -79.4659181347263
Path: 715\7159338.pdf

Bore Hole Information

Bore Hole ID: 1003476744
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 18-Jan-2011 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:

Elevation:
Elevrc:
Zone: 17
East83: 623568.00
North83: 4842095.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1003778488
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778491
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 14.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778489
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778490
Layer: 3

Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.5
Formation End Depth:	14.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778500
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778502
Layer:	3
Plug From:	9.0
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778501
Layer:	2
Plug From:	0.5
Plug To:	9.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003778498
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1003778487
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003778494
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0

Depth To:	10.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003778495
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.7799999713897705

Water Details

Water ID:	1003778493
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003778492
Diameter:	4.5
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003476744	**Tag No:**	A112791
Depth M:	6.096	**Contractor:**	7241
Year Completed:	2011	**Path:**	715\7159338.pdf
Well Completed Dt:	2011/01/18	**Latitude:**	43.7215927272301
Audit No:	Z127927	**Longitude:**	-79.4659181347263

27 ***1 of 1*** ***NNW/74.8*** ***181.9 / -1.52*** ***SELECTED MODE INC.***
106 CARTWRIGHT AVE
NORTH YORK ON M6A 1V2 ***SCT***

Established:	0000
Plant Size (ft²):	0
Employment:	2

--Details--

Description:	WOMEN'S, MISSES', AND JUNIORS' BLOUSES, AND SHIRTS
SIC/NAICS Code:	2331
Description:	WOMEN'S, MISSES', AND JUNIORS' DRESSES
SIC/NAICS Code:	2335
Description:	WOMEN'S, MISSES', AND JUNIORS' SUITS, SKIRTS, AND COATS
SIC/NAICS Code:	2337

Description: WOMEN'S, MISSES', AND JUNIORS' OUTERWEAR, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2339

Description: GIRLS', CHILDREN'S, AND INFANTS' DRESSES, BLOUSES, AND SHIRTS
SIC/NAICS Code: 2361

Description: GIRLS', CHILDREN'S, AND INFANTS' OUTERWEAR, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2369

---

28 | 1 of 1 | W/74.9 | 181.6 / -1.77 | 185 BRIDGELAND AVE Toronto ON | WWIS

Well ID:	7159339	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	17-Feb-2011 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z127930	**Contractor:**	7241
Tag:	A112792	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info: WKQ-003443

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7159339.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/01/18
Year Completed: 2011
Depth (m): 6.096
Latitude: 43.7214318805022
Longitude: -79.4660091428312
Path: 715\7159339.pdf

Bore Hole Information

Bore Hole ID:	1003476746	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623561.00
Code OB Desc:		**North83:**	4842077.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	18-Jan-2011 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003778517
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778518
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.5
Formation End Depth:	1.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778519
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.5
Formation End Depth:	14.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778520
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05

Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	14.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778540
Layer:	2
Plug From:	0.5
Plug To:	9.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778541
Layer:	3
Plug From:	9.0
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778527
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003778525
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1003778516
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003778523
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003778524
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.7799999713897705

Water Details

Water ID:	1003778522
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003778521
Diameter:	4.5
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003476746	***Tag No:***	A112792
Depth M:	6.096	***Contractor:***	7241
Year Completed:	2011	***Path:***	715\7159339.pdf
Well Completed Dt:	2011/01/18	***Latitude:***	43.7214318805022
Audit No:	Z127930	***Longitude:***	-79.4660091428312

---

29 ***1 of 1*** ***NE/79.8*** ***184.8 / 1.44*** ***99 Cartwright Avenue Toronto ON*** ***EHS***

Order No:	20141127015	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	02-DEC-14	***Search Radius (km):***	.25
Date Received:	27-NOV-14	***X:***	-79.463725
Previous Site Name:		***Y:***	43.721972
Lot/Building Size:			
Additional Info Ordered:			

---

30 ***1 of 1*** ***SSE/82.9*** ***183.9 / 0.46*** ***ON*** ***WWIS***

Well ID:	7161397	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	05-Apr-2011 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No:	M10100	**Contractor:**	6988
Tag:	A098136	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7161397.pdf

Additional Detail(s) (Map)

Well Completed Date:	2010/11/19
Year Completed:	2010
Depth (m):	
Latitude:	43.7198829207221
Longitude:	-79.4639754685079
Path:	716\7161397.pdf

Bore Hole Information

Bore Hole ID:	1003493688	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623728.00
Code OB Desc:		**North83:**	4841908.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	19-Nov-2010 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1003493688	**Tag No:**	A098136
Depth M:		**Contractor:**	6988
Year Completed:	2010	**Path:**	716\7161397.pdf
Well Completed Dt:	2010/11/19	**Latitude:**	43.7198829207221
Audit No:	M10100	**Longitude:**	-79.4639754685079

---

31 | ***1 of 12*** | ***N/83.8*** | ***182.1 / -1.31*** | ***MEGA UNIFORMS LTD***
104 CARTWRIGHT AVE
NORTH YORK ON M6A 1V2 | ***SCT***

Established:	1979
Plant Size (ft²):	7000
Employment:	5

--Details--
Description: WOMEN'S, MISSES', AND JUNIORS' OUTERWEAR, NOT ELSEWHERE CLASSIFIED

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 2339

Description: MEN'S AND BOYS' CLOTHING AND FURNISHINGS
SIC/NAICS Code: 5136

Description: WOMEN'S, CHILDREN'S, AND INFANTS' CLOTHING AND ACCESSORIES
SIC/NAICS Code: 5137

Description: MEN'S AND BOYS' SUITS, COATS, AND OVERCOATS
SIC/NAICS Code: 2311

Description: MEN'S AND BOYS' SHIRTS, EXCEPT WORK SHIRTS
SIC/NAICS Code: 2321

Description: MEN'S AND BOYS' CLOTHING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2329

Description: WOMEN'S, MISSES', AND JUNIORS' DRESSES
SIC/NAICS Code: 2335

Description: WOMEN'S, MISSES', AND JUNIORS' SUITS, SKIRTS, AND COATS
SIC/NAICS Code: 2337

31	2 of 12	N/83.8	182.1 / -1.31	**Crisstar Cabinets Inc** **104 Cartwright Ave.** **North York ON M6A 1V2**	GEN

Generator No: ON2771587
SIC Code: 337110
SIC Description: Wood Kitchen Cabinet and Counter Top Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

31	3 of 12	N/83.8	182.1 / -1.31	**crisstar cabinets inc** **104 Carwright Ave.** **North York ON**	GEN

Generator No: ON5981666
SIC Code: 337110
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

31 ***4 of 12*** ***N/83.8*** ***182.1 / -1.31*** ***Crisstar Cabinets Inc*** ***GEN***
104 Cartwright Ave.
North York ON M6A 1V2

Generator No: ON2771587
SIC Code: 337110
SIC Description: Wood Kitchen Cabinet and Counter Top Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

31 ***5 of 12*** ***N/83.8*** ***182.1 / -1.31*** ***Crisstar Cabinets Inc*** ***GEN***
104 Cartwright Ave.
North York ON M6A 1V2

Generator No: ON2771587
SIC Code: 337110
SIC Description: Wood Kitchen Cabinet and Counter Top Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	6 of 12	N/83.8	182.1 / -1.31	Crisstar Cabinets Inc 104 Cartwright Ave. North York ON	GEN

Generator No: ON2771587
SIC Code: 337110
SIC Description: WOOD KITCHEN CABINET AND COUNTER TOP MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	7 of 12	N/83.8	182.1 / -1.31	Crisstar Cabinets Inc 104 Cartwright Ave. North York ON M6A 1V2	GEN

Generator No: ON2771587
SIC Code: 337110
SIC Description: WOOD KITCHEN CABINET AND COUNTER TOP MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	8 of 12	N/83.8	182.1 / -1.31	Crisstar Cabinets Inc 104 Cartwright Ave. North York ON M6A 1V2	GEN

Generator No: ON2771587
SIC Code: 337110
SIC Description: WOOD KITCHEN CABINET AND COUNTER TOP MANUFACTURING

Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

31 | ***9 of 12*** | ***N/83.8*** | ***182.1 / -1.31*** | ***Crisstar Cabinets Inc***
104 Cartwright Ave.
North York ON M6A 1V2 | ***GEN***

Generator No: ON2771587
SIC Code: 337110
SIC Description: WOOD KITCHEN CABINET AND COUNTER TOP MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

31 | ***10 of 12*** | ***N/83.8*** | ***182.1 / -1.31*** | ***Crisstar Cabinets Inc***
104 Cartwright Ave.
North York ON M6A 1V2 | ***GEN***

Generator No: ON2771587
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	11 of 12	N/83.8	182.1 / -1.31	Crisstar Cabinets Inc 104 Cartwright Ave. North York ON M6A 1V2	GEN

Generator No: ON2771587
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	12 of 12	N/83.8	182.1 / -1.31	Crisstar Cabinets Inc 104 Cartwright Ave. North York ON M6A 1V2	GEN

Generator No: ON2771587
SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
32	1 of 1	SSE/86.8	183.9 / 0.49	123 BENTWORTH AVE TORONTO ON	WWIS

Well ID: 7191977
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 22-Nov-2012 00:00:00
Selected Flag: TRUE

Casing Material:		**Abandonment Rec:**	
Audit No:	Z157887	**Contractor:**	7320
Tag:	A137926	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191977.pdf

Additional Detail(s) (Map)

Well Completed Date: 2012/09/18
Year Completed: 2012
Depth (m): 6.1
Latitude: 43.7198214169618
Longitude: -79.4640887694937
Path: 719\7191977.pdf

Bore Hole Information

Bore Hole ID:	1004209220	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623719.00
Code OB Desc:		**North83:**	4841901.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-Sep-2012 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004536729
Layer: 1
Color: 8
General Color: BLACK
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1004536730
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.30000001192092896
Formation End Depth:	1.2000000476837158
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536731
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Mat2 Desc:	
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	1.2000000476837158
Formation End Depth:	4.300000190734863
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536733
Layer:	5
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Mat2 Desc:	
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	4.599999904632568
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536732
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	

Mat3 Desc:
Formation Top Depth: 4.300000190734863
Formation End Depth: 4.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004536741
Layer: 2
Plug From: 2.4000000953674316
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004536740
Layer: 1
Plug From: 0.0
Plug To: 2.4000000953674316
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004536739
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004536728
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004536736
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004536737
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID:	1004536735
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004536734
Diameter:	16.0
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1004209220	***Tag No:***	A137926
Depth M:	6.1	***Contractor:***	7320
Year Completed:	2012	***Path:***	719\7191977.pdf
Well Completed Dt:	2012/09/18	***Latitude:***	43.7198214169618
Audit No:	Z157887	***Longitude:***	-79.4640887694937

---

33 ***1 of 1*** ***SSE/87.8*** ***183.7 / 0.28*** ***123 BENTWORTH AVE TORONTO ON*** ***WWIS***

Well ID:	7191975	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	22-Nov-2012 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z157886	***Contractor:***	7320
Tag:	A137924	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191975.pdf

Additional Detail(s) (Map)

Well Completed Date:	2012/09/18
Year Completed:	2012
Depth (m):	6.1
Latitude:	43.7197784148559
Longitude:	-79.4642388406472
Path:	719\7191975.pdf

Bore Hole Information

Bore Hole ID:	1004209214	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623707.00
Code OB Desc:		***North83:***	4841896.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	18-Sep-2012 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004536701
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	4.300000190734863
Formation End Depth:	4.599999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536699
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.30000001192092896
Formation End Depth:	1.2000000476837158
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536700
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT

Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 1.2000000476837158
Formation End Depth: 4.300000190734863
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004536698
Layer: 1
Color: 8
General Color: BLACK
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004536702
Layer: 5
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 4.599999904632568
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004536710
Layer: 2
Plug From: 2.4000000953674316
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004536709
Layer: 1
Plug From: 0.0
Plug To: 2.4000000953674316
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004536708
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004536697
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004536705
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004536706
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID: 1004536704
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004536703
Diameter: 16.0
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1004209214
Depth M: 6.1
Year Completed: 2012
Well Completed Dt: 2012/09/18
Tag No: A137924
Contractor: 7320
Path: 719\7191975.pdf
Latitude: 43.7197784148559

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No: Z157886 **Longitude:** -79.4642388406472

---

34 **1 of 3** **ESE/89.6** **184.8 / 1.44** **105 Bentworth Inc** **GEN**
105 Bentworth Ave
North York ON M6A 1P6

Generator No: ON8623539
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

34 **2 of 3** **ESE/89.6** **184.8 / 1.44** **105 Bentworth Avenue** **EHS**
North York ON M6A 1P6

Order No: 20200708027
Status: C
Report Type: Standard Report
Report Date: 13-JUL-20
Date Received: 08-JUL-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.4630782
Y: 43.7205067

---

34 **3 of 3** **ESE/89.6** **184.8 / 1.44** **105 Bentworth Avenue** **EHS**
North York ON M6A 1P6

Order No: 20200708027
Status: C
Report Type: Standard Report
Report Date: 13-JUL-20
Date Received: 08-JUL-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.4630782
Y: 43.7205067

---

35 **1 of 3** **W/90.0** **180.9 / -2.55** **UNIVERSAL CHINA LAMP & GLASS** **SCT**
121 CARTWRIGHT AVE
TORONTO ON M6A 1V4

Established: 1950
Plant Size (ft²): 25000
Employment: 25

--Details--
Description: WOOD OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS
SIC/NAICS Code: 2541

Description:	OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS, EXCEPT WOOD
SIC/NAICS Code:	2542
Description:	PRESSED AND BLOWN GLASS AND GLASSWARE, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code:	3229
Description:	GLASS PRODUCTS, MADE OF PURCHASED GLASS
SIC/NAICS Code:	3231
Description:	RESIDENTIAL ELECTRIC LIGHTING FIXTURES
SIC/NAICS Code:	3645
Description:	MANUFACTURING INDUSTRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code:	3999
Description:	HOMEFURNISHINGS
SIC/NAICS Code:	5023
Description:	ELECTRICAL APPARATUS AND EQUIPMENT, WIRING SUPPLIES, AND CONSTRUCTION MATERIALS
SIC/NAICS Code:	5063
Description:	NONDURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code:	5199
Description:	MISCELLANEOUS HOME FURNISHING STORES
SIC/NAICS Code:	5719
Description:	Glass Manufacturing
SIC/NAICS Code:	327214
Description:	Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code:	327215
Description:	Lighting Fixture Manufacturing
SIC/NAICS Code:	335120
Description:	Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code:	337215
Description:	Sign Manufacturing
SIC/NAICS Code:	339950
Description:	All Other Miscellaneous Manufacturing
SIC/NAICS Code:	339990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	*2 of 3*	*W/90.0*	*180.9 / -2.55*	***Universal China Lamp & Glass Co. Ltd. - Universal Lamp Manufacturing Division 121 Cartwright Ave Toronto ON M6A 1V4***	*SCT*

Established:	1950
Plant Size (ft²):	25000
Employment:	30

--Details--

Description:	Other Home Furnishings Wholesaler-Distributors
SIC/NAICS Code:	414390
Description:	Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code:	416110
Description:	Other Specialty-Line Building Supplies Wholesaler-Distributors

SIC/NAICS Code: 416390

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Description: All Other Home Furnishings Stores
SIC/NAICS Code: 442298

---

35 | ***3 of 3*** | ***W/90.0*** | ***180.9 / -2.55*** | ***Universal Lamp***
121 Cartwright Ave
Toronto ON M6A 1V4 | ***SCT***

Established: 01-JAN-50
Plant Size (ft²): 25000
Employment:

--Details--
Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Description: All Other Electrical Equipment and Component Manufacturing
SIC/NAICS Code: 335990

Description: Other Home Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414390

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: All Other Converted Paper Product Manufacturing
SIC/NAICS Code: 322299

Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: All Other Home Furnishings Stores
SIC/NAICS Code: 442298

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Small Electrical Appliance Manufacturing
SIC/NAICS Code: 335210

Description: Glass Manufacturing
SIC/NAICS Code: 327214

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Sign Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 339950

Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

Description: Electrical Contractors and Other Wiring Installation Contractors
SIC/NAICS Code: 238210

---

36 | **1 of 5** | **ESE/91.3** | **184.8 / 1.44** | **Superb Fashions Ltd.**
89 Bentworth Ave Unit 4
Toronto ON M6A 1P6 | **SCT**

Established: 01-SEP-80
Plant Size (ft²):
Employment:

--Details--
Description: Clothing and Clothing Accessories Wholesaler-Distributors
SIC/NAICS Code: 414110

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

---

36 | **2 of 5** | **ESE/91.3** | **184.8 / 1.44** | **Russo Apparel Mfg. Inc.**
89 Bentworth Ave Unit 3
North York ON M6A 1P6 | **SCT**

Established: 1995
Plant Size (ft²): 17000
Employment: 8

--Details--
Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Other Men's and Boys' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315229

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

---

36 | **3 of 5** | **ESE/91.3** | **184.8 / 1.44** | **XS: Clothing Co. Inc.**
89 Bentworth Ave Unit 2
North York ON M6A 1P6 | **SCT**

Established: 9/1/1991
Plant Size (ft²): 2700
Employment:

--Details--
Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	4 of 5	ESE/91.3	184.8 / 1.44	Empire Uniforms 89 Bentworth Ave Unit 3 Toronto ON M6A 1P6	SCT

Established:
Plant Size (ft²):
Employment:

--Details--

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Other Men's and Boys' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315229

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

Description: All Other Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315299

Description: Clothing Accessories and Other Clothing Manufacturing
SIC/NAICS Code: 315990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	5 of 5	ESE/91.3	184.8 / 1.44	Adele Wechsler Designs Limited 89 Bentworth Ave Unit 3 North York ON M6A 1P6	SCT

Established: 01-JUL-83
Plant Size (ft²): 4500
Employment:

--Details--

Description: Clothing and Clothing Accessories Wholesaler-Distributors
SIC/NAICS Code: 414110

Description: Clothing and Clothing Accessories Wholesaler-Distributors
SIC/NAICS Code: 414110

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Women's and Girls' Cut and Sew Dress Manufacturing
SIC/NAICS Code: 315233

Description: All Other Clothing Stores
SIC/NAICS Code: 448199

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	1 of 1	SSE/94.0	183.8 / 0.39	123 BENTWORTH AVE TORONTO ON	WWIS

Well ID:	7191976	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	22-Nov-2012 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z157885	**Contractor:**	7320
Tag:	A137925	**Form Version:**	7
Constructn Method:		**Owner:**	

Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191976.pdf

Additional Detail(s) (Map)

Well Completed Date:	2012/09/18
Year Completed:	2012
Depth (m):	6.1
Latitude:	43.7197920795481
Longitude:	-79.4639157179138
Path:	719\7191976.pdf

Bore Hole Information

Bore Hole ID:	1004209217	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623733.00
Code OB Desc:		**North83:**	4841898.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-Sep-2012 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004536716
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.30000001192092896
Formation End Depth:	1.2000000476837158
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004536717

Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 1.2000000476837158
Formation End Depth: 4.300000190734863
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004536719
Layer: 5
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 4.599999904632568
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004536715
Layer: 1
Color: 8
General Color: BLACK
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004536718
Layer: 4
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 4.300000190734863
Formation End Depth: 4.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1004536726
Layer:	1
Plug From:	0.0
Plug To:	2.4000000953674316
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004536727
Layer:	2
Plug From:	2.4000000953674316
Plug To:	6.099999904632568
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004536725
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1004536714
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004536722
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0999999046325684
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004536723
Layer:	1
Slot:	10
Screen Top Depth:	3.0999999046325684
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.099999904632568

Water Details

Water ID: 1004536721
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004536720
Diameter: 16.0
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1004209217
Depth M: 6.1
Year Completed: 2012
Well Completed Dt: 2012/09/18
Audit No: Z157885
Tag No: A137925
Contractor: 7320
Path: 719\7191976.pdf
Latitude: 43.7197920795481
Longitude: -79.4639157179138

---

38 | 1 of 10 | NW/98.1 | 179.8 / -3.56 | **PICTURE PICTURE**
122 CARTWRIGHT AVE
NORTH YORK ON M6A 1V2 | SCT

Established: 0000
Plant Size (ft²): 0
Employment: 0

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: WOOD PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2499

Description: HOMEFURNISHINGS
SIC/NAICS Code: 5023

---

38 | 2 of 10 | NW/98.1 | 179.8 / -3.56 | **Picture Picture Co.**
122 Cartwright Ave
North York ON M6A 1V2 | SCT

Established: 1990
Plant Size (ft²):
Employment: 15

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Other Home Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414390

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		Other Publishers			
SIC/NAICS Code:		511190			

38	3 of 10	NW/98.1	179.8 / -3.56	**Lamintech Corp. Ltd** **122 Cartwright Ave** **North York ON M6A 1V2**	SCT

Established: 01-MAY-90
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

38	4 of 10	NW/98.1	179.8 / -3.56	**MR. T-SHIRT INC.** **122 CARTWRIGHT AVE.** **TORONTO ON M6A 1V2**	GEN

Generator No: ON0626700
SIC Code: 2499
SIC Description: OTHER CLOTHING ETC.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

38	5 of 10	NW/98.1	179.8 / -3.56	**MR. T-SHIRT INC.** **122 CARTWRIGHT AVE.** **TORONTO ON M6A 1V2**	GEN

Generator No: ON0626700
SIC Code: 2499
SIC Description: OTHER CLOTHING ETC.
Approval Years: 88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	6 of 10	NW/98.1	179.8 / -3.56	MR. T-SHIRT INC. (OUT OF BUSINESS) 122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	GEN

Generator No:	ON0626700
SIC Code:	2499
SIC Description:	OTHER CLOTHING ETC.
Approval Years:	90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	7 of 10	NW/98.1	179.8 / -3.56	MR. T-SHIRT INC. (OUT OF BUSINESS)27-183 122 CARTWRIGHT AVE. TORONTO ON M6A 1V2	GEN

Generator No:	ON0626700
SIC Code:	2499
SIC Description:	OTHER CLOTHING ETC.
Approval Years:	92,93,94,95,96,97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	8 of 10	NW/98.1	179.8 / -3.56	Picture Picture Co. Ltd. 122 Cartwright Ave Toronto ON M6A 1V2	SCT

Established:	01-JUL-90
Plant Size (ft²):	21000
Employment:	

--Details--

Description:	Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code:	327215
Description:	All Other Miscellaneous Manufacturing
SIC/NAICS Code:	339990
Description:	Other Printing
SIC/NAICS Code:	323119
Description:	Support Activities for Printing
SIC/NAICS Code:	323120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	9 of 10	NW/98.1	179.8 / -3.56	Lamintech Corp. Ltd. 122 Cartwright Ave North York ON M6A 1V2	SCT

Established:	1990
Plant Size (ft²):	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 25

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

38 ***10 of 10*** ***NW/98.1*** ***179.8 / -3.56*** ***Lamin Tech*** ***SCT***
122A Cartwright Ave
Toronto ON M6A 1V2

Established:
Plant Size (ft²): 21000
Employment:

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

39 ***1 of 1*** ***SE/99.4*** ***184.1 / 0.65*** ***WWIS***
ON

Well ID:	7161057	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	29-Mar-2011 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	M06726	***Contractor:***	7241
Tag:	A111546	***Form Version:***	5
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7161057.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/03/08
Year Completed: 2011
Depth (m):
Latitude: 43.7200085879487
Longitude: -79.4632770501065
Path: 716\7161057.pdf

Bore Hole Information

Bore Hole ID: 1003492018 ***Elevation:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623784.00
Code OB Desc:		**North83:**	4841923.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	08-Mar-2011 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1003492018	**Tag No:**	A111546
Depth M:		**Contractor:**	7241
Year Completed:	2011	**Path:**	716\7161057.pdf
Well Completed Dt:	2011/03/08	**Latitude:**	43.7200085879487
Audit No:	M06726	**Longitude:**	-79.4632770501065

---

40 | ***1 of 3*** | ***WSW/100.7*** | ***181.9 / -1.51*** | ***I&D AUTOBODY & COLLISION CENTRE LTD.***
142 BENTWORTH AVENUE
TORONTO CITY ON M6A 1P7 | ***CA***

Certificate #:	8-3370-99-
Application Year:	99
Issue Date:	12/1/1999
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	PAINT SPRAY BOOTH FOR AUTOBODY SHOP
Contaminants:	
Emission Control:	

---

40 | ***2 of 3*** | ***WSW/100.7*** | ***181.9 / -1.51*** | ***CANADIAN IRON METAL INC***
142 BENTWORTH AVE
NORTH YORK ON M6A 1P7 | ***AUWR***

Headcode:	1169400
Headcode Desc:	Scrap Metals
Phone:	4162567861
List Name:	
Description:	

---

40 | ***3 of 3*** | ***WSW/100.7*** | ***181.9 / -1.51*** | ***I & D Autobody and Collision Centre Limited***
142 Bentworth Avenue Toronto
ON | ***EBR***

EBR Registry No:	IA9E1666	**Decision Posted:**	
Ministry Ref No:	8337099	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	August 30, 2001	**Act 2:**	

Proposal Date: October 27, 1999
Site Location Map:
Year: 1999
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: I & D Autobody and Collision Centre Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 142 Bentworth Avenue, Toronto Ontario, M6A 1P7
Comment Period:
URL:

Site Location Details:

142 Bentworth Avenue Toronto

---

41 | **1 of 1** | **N/108.0** | **182.8 / -0.59** | **102 CARTRIGHT AVE Toronto ON** | **WWIS**

Well ID: 7281890
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z253374
Tag: A185463
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 24-Feb-2017 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/02/01
Year Completed: 2017
Depth (m): 6.096
Latitude: 43.7232808625813
Longitude: -79.464906670858
Path:

Bore Hole Information

Bore Hole ID: 1006358741
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:

Elevation:
Elevrc:
Zone: 17
East83: 623646.00
North83: 4842284.00
Org CS: UTM83
UTMRC: 4

Date Completed: 01-Feb-2017 00:00:00
UTMRC Desc: margin of error : 30 m - 100 m
Remarks:
Location Method: wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006603911
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 11.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006603910
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 3.0
Formation End Depth: 11.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006603909
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1006603921
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603919
Layer:	1
Plug From:	20.0
Plug To:	9.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603920
Layer:	2
Plug From:	9.0
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006603918
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006603908
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006603914
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006603915
Layer:	1
Slot:	.10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5

Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.5

Water Details

Water ID: 1006603913
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006603912
Diameter: 2.25
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006358741
Depth M: 6.096
Year Completed: 2017
Well Completed Dt: 2017/02/01
Audit No: Z253374
Tag No: A185463
Contractor: 7241
Path: 728\7281890.pdf
Latitude: 43.7232808625813
Longitude: -79.464906670858

---

42 | **1 of 14** | **NNE/108.8** | **184.0 / 0.63** | **CAPPOLA FOOD INC.**
92 CARTWRIGHT AVE
TORONTO ON M6A 1V2 | **SCT**

Established: 1966
Plant Size (ft²): 0
Employment: 35

--Details--
Description: SAUSAGES & OTHER PREPARED MEAT PRODUCTS
SIC/NAICS Code: 2013

Description: MEATS & MEAT PRODUCTS
SIC/NAICS Code: 5147

---

42 | **2 of 14** | **NNE/108.8** | **184.0 / 0.63** | **Cappola Food Inc.**
92 Cartwright Ave.
Toronto ON M6A 1V2 | **GEN**

Generator No: ON7231378
SIC Code: 311990
SIC Description: All Other Food Manufacturing
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | ***3 of 14*** | ***NNE/108.8*** | ***184.0 / 0.63*** | ***Maple Leaf Food Inc.***
92 Cartwright Ave.
Toronto ON M6A 1V2 | ***GEN***

Generator No: ON7231378
SIC Code: 311990
SIC Description: All Other Food Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | ***4 of 14*** | ***NNE/108.8*** | ***184.0 / 0.63*** | ***Maple Leaf Food Inc.***
92 Cartwright Ave.
Toronto ON M6A 1V2 | ***GEN***

Generator No: ON7231378
SIC Code: 311990
SIC Description: All Other Food Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | ***5 of 14*** | ***NNE/108.8*** | ***184.0 / 0.63*** | ***Maple Leaf Food Inc.***
92 Cartwright Ave.
Toronto ON M6A 1V2 | ***GEN***

Generator No: ON7231378
SIC Code: 311990
SIC Description: All Other Food Manufacturing
Approval Years: 2011
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	6 of 14	NNE/108.8	184.0 / 0.63	Maple Leaf Food Inc. 92 Cartwright Ave. Toronto ON M6A 1V2	GEN

Generator No: ON7231378
SIC Code: 311990
SIC Description: All Other Food Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	7 of 14	NNE/108.8	184.0 / 0.63	Maple Leaf Food Inc. 92 Cartwright Ave. Toronto ON	GEN

Generator No: ON7231378
SIC Code: 311990
SIC Description: ALL OTHER FOOD MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	8 of 14	NNE/108.8	184.0 / 0.63	Maple Leaf Food Inc. 92 Cartwright Ave.	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Toronto ON M6A 1V2	

Generator No: ON7231378
SIC Code: 311990
SIC Description: ALL OTHER FOOD MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Andre Kraeuter
Choice of Contact: CO_OFFICIAL
Phone No Admin: 416-633-0389 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

42	9 of 14	NNE/108.8	184.0 / 0.63	**Maple Leaf Food Inc.** **92 Cartwright Ave.** **Toronto ON M6A 1V2**	GEN

Generator No: ON7231378
SIC Code: 311990
SIC Description: ALL OTHER FOOD MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Patrick Armstrong
Choice of Contact: CO_OFFICIAL
Phone No Admin: 416-633-0389 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

42	10 of 14	NNE/108.8	184.0 / 0.63	**Maple Leaf Food Inc.** **92 Cartwright Ave.** **Toronto ON M6A 1V2**	GEN

Generator No: ON7231378
SIC Code: 311990
SIC Description: ALL OTHER FOOD MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Patrick A Armstrong
Choice of Contact: CO_OFFICIAL
Phone No Admin: 416-633-0389 Ext.

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

42 | **11 of 14** | **NNE/108.8** | **184.0 / 0.63** | **Maple Leaf Food Inc.**
92 Cartwright Ave.
Toronto ON M6A 1V2 | **GEN**

Generator No: ON7231378
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

42 | **12 of 14** | **NNE/108.8** | **184.0 / 0.63** | **Maple Leaf Food Inc.**
92 Cartwright Ave.
Toronto ON M6A 1V2 | **GEN**

Generator No: ON7231378
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 L

Waste Class Name: Wastes from the use of pigments, coatings and paints

---

42 | **13 of 14** | **NNE/108.8** | **184.0 / 0.63** | **Maple Leaf Food Inc.**
92 Cartwright Ave.
Toronto ON M6A 1V2 | **GEN**

Generator No: ON7231378
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

---

42 | **14 of 14** | **NNE/108.8** | **184.0 / 0.63** | **Maple Leaf Food Inc.**
92 Cartwright Ave.
Toronto ON M6A 1V2 | **GEN**

Generator No: ON7231378
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

43 | **1 of 1** | **N/109.2** | **182.9 / -0.50** | **102 CARTRIGHT AVE**
Toronto ON | **WWIS**

Well ID: 7281889 **Flowing (Y/N):**

Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	24-Feb-2017 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z253375	**Contractor:**	7241
Tag:	A211211	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2017/02/01
Year Completed:	2017
Depth (m):	6.096
Latitude:	43.7232883627755
Longitude:	-79.4647947434645
Path:	

Bore Hole Information

Bore Hole ID:	1006358738	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623655.00
Code OB Desc:		**North83:**	4842285.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01-Feb-2017 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006603891
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	

Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006603892
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	34
Mat3 Desc:	TILL
Formation Top Depth:	3.0
Formation End Depth:	11.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006603893
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	34
Mat3 Desc:	TILL
Formation Top Depth:	11.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603902
Layer:	2
Plug From:	9.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603903
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006603901
Layer:	1
Plug From:	20.0

Plug To:	9.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006603900
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006603890
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006603896
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006603897
Layer:	1
Slot:	.10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Water Details

Water ID:	1006603895
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006603894
Diameter:	2.25
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Links

Bore Hole ID:	1006358738	***Tag No:***	A211211
Depth M:	6.096	***Contractor:***	7241
Year Completed:	2017	***Path:***	
Well Completed Dt:	2017/02/01	***Latitude:***	43.7232883627755
Audit No:	Z253375	***Longitude:***	-79.4647947434645

---

44 ***1 of 1*** ***ENE/121.3*** ***185.8 / 2.44*** ***99 CARTWRIGHT AVE Toronto ON*** ***WWIS***

Well ID:	7222994	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	30-Jun-2014 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z179648	***Contractor:***	7247
Tag:	A156007	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7222994.pdf

Additional Detail(s) (Map)

Well Completed Date:	2014/05/03
Year Completed:	2014
Depth (m):	4.572
Latitude:	43.7220335800552
Longitude:	-79.4632128642432
Path:	722\7222994.pdf

Bore Hole Information

Bore Hole ID:	1004896946	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623785.00
Code OB Desc:		***North83:***	4842148.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	03-May-2014 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005132576
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.5400000214576721
Formation End Depth:	4.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005132577
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	4.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005132575
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.2919999957084656
Formation End Depth:	0.5400000214576721
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005132574
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	

Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.2919999957084656
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005132585
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005132584
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005132573
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005132580
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 0.75
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005132581
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.0

Water Details

Water ID: 1005132579
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID:	1005132578
Diameter:	6.0
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1004896946	***Tag No:***	A156007
Depth M:	4.572	***Contractor:***	7247
Year Completed:	2014	***Path:***	722\7222994.pdf
Well Completed Dt:	2014/05/03	***Latitude:***	43.7220335800552
Audit No:	Z179648	***Longitude:***	-79.4632128642432

---

45 ***1 of 1*** ***ESE/121.6*** ***184.8 / 1.44*** ***85 Bentworth Avenue North York ON M6A 1P6*** ***EHS***

Order No:	22042800038	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	03-MAY-22	***Search Radius (km):***	.25
Date Received:	28-APR-22	***X:***	-79.46269
Previous Site Name:		***Y:***	43.72044
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

46 ***1 of 2*** ***SW/123.9*** ***182.7 / -0.68*** ***PRESTON METAL & ROOFING PRODUCTS 147 BENTWORTH AVENUE TORONTO ON M6A 1P6*** ***GEN***

Generator No:	ON0423401
SIC Code:	3039
SIC Description:	OTHER ARCH. METAL
Approval Years:	86,87,88,89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

---

46 ***2 of 2*** ***SW/123.9*** ***182.7 / -0.68*** ***PRESTON METAL (OUT OF BUSINESS) 31-244 147 BENTWORTH AVENUE TORONTO ON M6A 1P6*** ***GEN***

Generator No:	ON0423401
SIC Code:	3039
SIC Description:	OTHER ARCH. METAL
Approval Years:	92,93,94,95,96,97,98

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					

47	1 of 3	SW/124.0	182.7 / -0.68	**Aden Earthworks Inc.** **147A Bentworth Ave** **Toronto ON M6A 1P6**	GEN

Generator No:	ON6765162
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

47	2 of 3	SW/124.0	182.7 / -0.68	**Brea Water Technologies** **147 Bentworth Ave** **Toronto ON M6A 1P6**	GEN

Generator No:	ON8757805
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues
Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

47	3 of 3	SW/124.0	182.7 / -0.68	**Aden Earthworks Inc.** **147A Bentworth Ave** **Toronto ON M6A 1P6**	GEN

Generator No:	ON6765162
SIC Code:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

48	*1 of 6*	*SW/125.2*	*182.7 / -0.72*	***1014177 Ontario Ltd.*** ***147 Bentworth Avenue Toronto CITY OF TORONTO*** ***ON***	***EBR***

EBR Registry No: 010-2499
Ministry Ref No: 2592-79NTH2
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 17, 2008
Proposal Date: January 10, 2008
Year: 2008
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: 1014177 Ontario Ltd.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 147 Bentworth Avenue, Toronto Ontario, Canada M6A 1P6
Comment Period:
URL:

Site Location Details:

147 Bentworth Avenue Toronto CITY OF TORONTO

48	*2 of 6*	*SW/125.2*	*182.7 / -0.72*	***1014177 Ontario Ltd.*** ***147 Bentworth Ave*** ***Toronto ON***	***CA***

Certificate #: 6299-7JBQP8
Application Year: 2008
Issue Date: 9/11/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	3 of 6	SW/125.2	182.7 / -0.72	147 Bentworth Ave Toronto ON	EHS

Order No:	20130321002	**Nearest Intersection:**	
Status:	C	**Municipality:**	North York
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	01-APR-13	**Search Radius (km):**	.25
Date Received:	21-MAR-13	**X:**	0
Previous Site Name:		**Y:**	0
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	4 of 6	SW/125.2	182.7 / -0.72	1014177 Ontario Ltd. 147 Bentworth Ave Toronto ON M6A 1P6	ECA

Approval No:	6299-7JBQP8	**MOE District:**	Metro Toronto
Approval Date:	2008-09-11	**City:**	
Status:	Approved	**Longitude:**	-79.4659
Record Type:	ECA	**Latitude:**	43.71968
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	1014177 Ontario Ltd.		
Address:	147 Bentworth Ave		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2592-79NTH2-13.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	5 of 6	SW/125.2	182.7 / -0.72	147 Bentworth Avenue North York ON M6A 1P6	EHS

Order No:	21060900335	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	14-JUN-21	**Search Radius (km):**	.2
Date Received:	09-JUN-21	**X:**	-79.465906
Previous Site Name:		**Y:**	43.719735
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	6 of 6	SW/125.2	182.7 / -0.72	147 Bentworth Avenue North York ON M6A 1P6	EHS

Order No:	21060900335	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	14-JUN-21	**Search Radius (km):**	.2
Date Received:	09-JUN-21	**X:**	-79.465906
Previous Site Name:		**Y:**	43.719735
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	1 of 1	NW/128.5	179.8 / -3.56	185 BRIDGELAND AVE Toronto ON	WWIS

Well ID:	7159337	**Flowing (Y/N):**	

Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	17-Feb-2011 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z127928	**Contractor:**	7241
Tag:	A112813	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info: WKQ-003443

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7159337.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/01/18
Year Completed: 2011
Depth (m): 7.62
Latitude: 43.7226298021263
Longitude: -79.4667110527875
Path: 715\7159337.pdf

Bore Hole Information

Bore Hole ID:	1003476742	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623502.00
Code OB Desc:		**North83:**	4842209.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	18-Jan-2011 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1003778461
Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 77
Mat3 Desc: LOOSE

Formation Top Depth: 1.5
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778459
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778462
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 14.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003778460
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003778473
Layer: 3
Plug From: 14.0
Plug To: 25.0

Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778472
Layer:	2
Plug From:	0.5
Plug To:	14.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003778471
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003778469
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1003778458
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003778465
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003778466
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	25.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.7799999713897705

Water Details

Water ID: 1003778464
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003778463
Diameter: 4.5
Depth From: 0.0
Depth To: 25.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003476742
Depth M: 7.62
Year Completed: 2011
Well Completed Dt: 2011/01/18
Audit No: Z127928
Tag No: A112813
Contractor: 7241
Path: 715\7159337.pdf
Latitude: 43.7226298021263
Longitude: -79.4667110527875

---

50 **1 of 2** **W/129.2** **180.8 / -2.56** **TRANSPORT TRUCK**
127 CARTWRIGHT AVE. MOTOR VEHICLE
(OPERATING FLUID)
TORONTO CITY ON M6A 1V4 **SPL**

Ref No: 79292
Site No:
Incident Dt: 11/26/1992
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Multi Media Pollution
Receiving Medium: LAND / WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/26/1992
Dt Document Closed:
Incident Reason: UNKNOWN
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: REIDER'S FREIGHT LINER- 350L DIESEL FUEL TO ROAD & SEWER,FD & WORKS.
Contaminant Qty:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 01106
Site Lot:
Site Conc:
Northing:
Easting: FD,WORKS.
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

50 **2 of 2** **W/129.2** **180.8 / -2.56** **BENIX & CO**
127 CARTWRIGHT AVE
TORONTO ON M6A 1V4 **SCT**

Established: 1983
Plant Size (ft²):

Employment: 10

--Details--
Description: MISCELLANEOUS HOME FURNISHING STORES
SIC/NAICS Code: 5719

---

51 ***1 of 1*** ***NW/134.6*** ***179.8 / -3.56*** ***185 BRIDGELAND AVE Toronto ON*** ***WWIS***

Well ID:	7159336	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	17-Feb-2011 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z127929	***Contractor:***	7241
Tag:	A112814	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:	WKQ-003443		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7159336.pdf

Additional Detail(s) (Map)

Well Completed Date:	2011/01/18
Year Completed:	2011
Depth (m):	8.2296
Latitude:	43.7227559787072
Longitude:	-79.4667202490093
Path:	715\7159336.pdf

Bore Hole Information

Bore Hole ID:	1003476740	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623501.00
Code OB Desc:		***North83:***	4842223.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	18-Jan-2011 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1003778429
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778432
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	14.0
Formation End Depth:	27.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778431
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.5
Formation End Depth:	14.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003778430
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE

Formation Top Depth: 0.5
Formation End Depth: 1.5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003778441
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003778442
Layer: 2
Plug From: 0.5
Plug To: 16.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003778443
Layer: 3
Plug From: 16.0
Plug To: 27.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003778439
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1003778428
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003778435
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 17.0
Casing Diameter: 1.5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1003778436
Layer:	1
Slot:	10
Screen Top Depth:	17.0
Screen End Depth:	27.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.7300000190734863

Water Details

Water ID:	1003778434
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003778433
Diameter:	4.5
Depth From:	0.0
Depth To:	27.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003476740	**Tag No:**	A112814
Depth M:	8.2296	**Contractor:**	7241
Year Completed:	2011	**Path:**	715\7159336.pdf
Well Completed Dt:	2011/01/18	**Latitude:**	43.7227559787072
Audit No:	Z127929	**Longitude:**	-79.4667202490093

---

52 **1 of 4** **WSW/134.7** **182.0 / -1.36** **EXPRESS ROADSIDE RECOVERY INC** **GEN**
144 Bentworth Ave
Toronto ON M6A 1P7

Generator No:	ON8718347
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

---

52 **2 of 4** **WSW/134.7** **182.0 / -1.36** **EXPRESS ROADSIDE RECOVERY INC** **GEN**
144 Bentworth Ave
Toronto ON M6A 1P7

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8718347
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

52	*3 of 4*	*WSW/134.7*	*182.0 / -1.36*	***EXPRESS ROADSIDE RECOVERY INC*** ***144 Bentworth Ave*** ***Toronto ON M6A 1P7***	*GEN*

Generator No: ON8718347
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

52	*4 of 4*	*WSW/134.7*	*182.0 / -1.36*	***EXPRESS ROADSIDE RECOVERY INC*** ***144 Bentworth Ave*** ***Toronto ON M6A 1P7***	*GEN*

Generator No: ON8718347
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	1 of 1	E/141.2	185.8 / 2.44	ON	WWIS

Well ID: 7232232
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C24804
Tag: A161856
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 21-Nov-2014 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 6988
Form Version: 8
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2014/09/11
Year Completed: 2014
Depth (m):
Latitude: 43.7212693413827
Longitude: -79.4626240845204
Path:

Bore Hole Information

Bore Hole ID: 1005234579
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Sep-2014 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623834.00
North83: 4842064.00
Org CS: UTM83
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: wwr

Links

Bore Hole ID: 1005234579
Depth M:
Year Completed: 2014
Well Completed Dt: 2014/09/11
Audit No: C24804

Tag No: A161856
Contractor: 6988
Path:
Latitude: 43.7212693413827
Longitude: -79.4626240845204

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	1 of 1	E/142.3	185.8 / 2.44	NORTH YORK CITY MCADAM AVE./PAUL DAVID ST. NORTH YORK CITY ON	CA

Certificate #: 7-0205-94-
Application Year: 94
Issue Date: 4/11/1994
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
55	1 of 1	E/142.8	185.8 / 2.44	ON	WWIS

Well ID: 7218673
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C25359
Tag: A161856
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 28-Mar-2014 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7230
Form Version: 8
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2013/07/04
Year Completed: 2013
Depth (m):
Latitude: 43.7212871758295
Longitude: -79.4626112136953
Path:

Bore Hole Information

Bore Hole ID: 1004727782
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:

Elevation:
Elevrc:
Zone: 17
East83: 623835.00
North83: 4842066.00
Org CS: UTM83

Cluster Kind:		**UTMRC:**	4
Date Completed:	04-Jul-2013 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1004727782	**Tag No:**	A161856
Depth M:		**Contractor:**	7230
Year Completed:	2013	**Path:**	
Well Completed Dt:	2013/07/04	**Latitude:**	43.7212871758295
Audit No:	C25359	**Longitude:**	-79.4626112136953

56 | ***1 of 1*** | ***N/153.2*** | ***182.8 / -0.60*** | ***161 BRIDGELAND TORONTO ON*** | ***WWIS***

Well ID:	7154036	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04-Nov-2010 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z122690	**Contractor:**	7241
Tag:	A108616	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7154036.pdf

Additional Detail(s) (Map)

Well Completed Date:	2010/09/27
Year Completed:	2010
Depth (m):	3.6576
Latitude:	43.7236840605164
Longitude:	-79.4647598059506
Path:	715\7154036.pdf

Bore Hole Information

Bore Hole ID:	1003362168	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623657.00
Code OB Desc:		**North83:**	4842329.00
Open Hole:		**Org CS:**	UTM83

Cluster Kind:
Date Completed: 27-Sep-2010 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003478814
Layer: 1
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 0.0
Formation End Depth: 12.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003478816
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003478818
Layer: 3
Plug From: 5.0
Plug To: 12.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003478817
Layer: 2
Plug From: 1.0
Plug To: 5.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003478824
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID:	1003478813
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003478820
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	7.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003478821
Layer:	1
Slot:	10
Screen Top Depth:	7.0
Screen End Depth:	12.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.75

Water Details

Water ID:	1003478819
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003478815
Diameter:	3.25
Depth From:	0.0
Depth To:	12.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003362168	***Tag No:***	A108616
Depth M:	3.6576	***Contractor:***	7241
Year Completed:	2010	***Path:***	715\7154036.pdf
Well Completed Dt:	2010/09/27	***Latitude:***	43.7236840605164
Audit No:	Z122690	***Longitude:***	-79.4647598059506

57	***1 of 3***	***SSE/153.8***	***182.8 / -0.62***	***SWENSON CANADA INC.*** ***80 ORFUS RD***	***SCT***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				NORTH YORK ON M6A 1M1	

Established: 1922
Plant Size (ft²): 0
Employment: 30

--Details--
Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

Description: Small Electrical Appliance Manufacturing
SIC/NAICS Code: 335210

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
57	2 of 3	SSE/153.8	182.8 / -0.62	SWENSON CANADA LIMITED INC. 80 ORFUS RD NORTH YORK ON M6A 1M1	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 30

--Details--
Description: PERFUMES, COSMETICS, AND OTHER TOILET PREPARATIONS
SIC/NAICS Code: 2844

Description: ELECTRIC HOUSEWARES AND FANS
SIC/NAICS Code: 3634

Description: MANUFACTURING INDUSTRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
57	3 of 3	SSE/153.8	182.8 / -0.62	Wahl Canada Inc. 80 Orfus Rd North York ON M6A 1M1	SCT

Established: 01-AUG-22
Plant Size (ft²): 25000
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Description: Small Electrical Appliance Manufacturing
SIC/NAICS Code: 335210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	1 of 1	WSW/157.5	181.8 / -1.62	COLLEZIONI DONNA 150 BENTWORTH AVE TORONTO ON M6A 1P7	SCT

Established: 1981
Plant Size (ft²): 10000
Employment: 6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: WOMEN'S, MISSES', & JUNIORS' DRESSES
SIC/NAICS Code: 2335

Description: WOMEN'S, MISSES', & JUNIORS' OUTERWEAR, N.E.C.
SIC/NAICS Code: 2339

Description: MEN'S & BOYS' CLOTHING & FURNISHINGS
SIC/NAICS Code: 5136

Description: WOMEN'S, CHILDREN'S, & INFANTS' CLOTHING & ACCESSORIES
SIC/NAICS Code: 5137

59	*1 of 3*	*W/157.9*	*180.8 / -2.56*	***ZALDIAM & CO*** ***129 CARTWRIGHT AVE*** ***NORTH YORK ON M6A 1V4***	***SCT***

Established: 1978
Plant Size (ft²): 1300
Employment: 2

--Details--
Description: JEWELLERY, PRECIOUS METAL
SIC/NAICS Code: 3911

Description: JEWELLERY, WATCHES, PRECIOUS STONES, AND PRECIOUS METALS
SIC/NAICS Code: 5094

59	*2 of 3*	*W/157.9*	*180.8 / -2.56*	***ZALDIAM & CO*** ***129 Cartwright Ave*** ***Toronto ON M6A 1V4***	***SCT***

Established: 1978
Plant Size (ft²): 1300
Employment: 2

--Details--
Description: Jewellery and Silverware Manufacturing
SIC/NAICS Code: 339910

59	*3 of 3*	*W/157.9*	*180.8 / -2.56*	***Trippers Inc.*** ***129 Cartwright Ave*** ***North York ON M6A 1V4***	***SCT***

Established: 1983
Plant Size (ft²): 1000
Employment: 2

--Details--
Description: Commercial Screen Printing
SIC/NAICS Code: 323113

60	*1 of 3*	*SW/158.5*	*181.9 / -1.55*	***GRANT AUTO REPAIR LIMITED*** ***151-153 BENTWORTH AVE.,LOT 66*** ***NORTH YORK CITY ON M6A 1P6***	***CA***

Certificate #: 8-3575-94-
Application Year: 94
Issue Date: 11/4/1994
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INSTALL PAINT SPRAY BOOTH (8-3578-94)
Contaminants:
Emission Control:

---

60 | ***2 of 3*** | ***SW/158.5*** | ***181.9 / -1.55*** | ***GRAF AUTO REPAIR LIMITED*** ***151-153 BENTWORTH AVE., LOT 66*** ***NORTH YORK CITY ON M6A 1P6*** | ***CA***

Certificate #: 8-3578-94-
Application Year: 94
Issue Date: 12/19/1994
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INSTALL PAINT SPRAY BOOTH
Contaminants: Nitrogen Oxides, Xylene, N-Butyl Acetate, Methyl Isobutyl Ketone, Isopropyl Alcohol, Toluene(Pentyl Methane) (Methyl Benzene), Ethyl-3-Ethoxy Propionate, Mineral Spirits Med., Suspended Particulate Matter
Emission Control: Absorp. By Dry Collectors

---

60 | ***3 of 3*** | ***SW/158.5*** | ***181.9 / -1.55*** | ***GRAF AUTO REPAIR LIMITED*** ***151 BENTWORTH AVE*** ***NORTH YORK ON M6A 1P6*** | ***EASR***

Approval No: R-001-4282215080
Status: REGISTERED
Date: 2012-11-17
Record Type: EASR
Link Source: MOFA
Project Type: Automotive Refinishing Facility
Full Address:
Approval Type: EASR-Automotive Refinishing Facility
SWP Area Name:
PDF URL:
PDF Site Location:

MOE District:
Municipality: NORTH YORK
Latitude:
Longitude:
Geometry X:
Geometry Y:

---

61 | ***1 of 2*** | ***SSW/160.5*** | ***181.8 / -1.58*** | ***SM FOOTWEAR LTD.*** ***130 ORFUS RD*** ***NORTH YORK ON M6A 1L9*** | ***SCT***

Established: 1980
Plant Size (ft²): 0
Employment: 16

--Details--
Description: Footwear Manufacturing

SIC/NAICS Code: 316210

---

61 *2 of 2* **SSW/160.5** **181.8 / -1.58** **130 Orfus Road Toronto ON M6A 1L9** **EHS**

Order No:	20090819032	**Nearest Intersection:**	Duffern Street and Lawrence Ave. West
Status:	C	**Municipality:**	Toronto
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	8/28/2009	**Search Radius (km):**	0.25
Date Received:	8/19/2009	**X:**	-79.467588
Previous Site Name:		**Y:**	43.718321
Lot/Building Size:			
Additional Info Ordered:			

---

62 *1 of 1* **SSW/165.3** **181.9 / -1.49** **106-110 ORFUS RD NORTH YORK ON** **WWIS**

Well ID:	6929661	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	06-Dec-2005 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z40263	**Contractor:**	6607
Tag:	A034576	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/692\6929661.pdf

Additional Detail(s) (Map)

Well Completed Date:	2005/11/04
Year Completed:	2005
Depth (m):	4.5
Latitude:	43.7191957037526
Longitude:	-79.4657682659525
Path:	692\6929661.pdf

Bore Hole Information

Bore Hole ID:	11328630	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623585.00
Code OB Desc:		**North83:**	4841829.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04-Nov-2005 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	933039904
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933039905
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.30000001192092896
Formation End Depth:	4.5
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933282717
Layer:	1
Plug From:	0.0
Plug To:	1.2000000476837158
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	966929661
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11343485
Casing No:	1

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	930873643
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933415889
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.5
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	934068632
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	3.9000000953674316
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11549746
Diameter:	15.0
Depth From:	0.0
Depth To:	4.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	11328630	***Tag No:***	A034576
Depth M:	4.5	***Contractor:***	6607
Year Completed:	2005	***Path:***	692\6929661.pdf
Well Completed Dt:	2005/11/04	***Latitude:***	43.7191957037526
Audit No:	Z40263	***Longitude:***	-79.4657682659525

63	***1 of 1***	***N/168.7***	***183.9 / 0.49***	***161 BRIDGELAND RD. TORONTO ON***	***WWIS***

Well ID:	7154035	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	04-Nov-2010 00:00:00

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z122693	**Contractor:**	7241
Tag:	A108615	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7154035.pdf

Additional Detail(s) (Map)

Well Completed Date:	2010/09/27
Year Completed:	2010
Depth (m):	6.096
Latitude:	43.7237587299738
Longitude:	-79.4642861214266
Path:	715\7154035.pdf

Bore Hole Information

Bore Hole ID:	1003362166	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623695.00
Code OB Desc:		**North83:**	4842338.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	27-Sep-2010 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003478800
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003478801
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	5.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478803
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478804
Layer:	2
Plug From:	1.0
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478805
Layer:	3
Plug From:	8.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003478811
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1003478799
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID: 1003478807
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 1.5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003478808
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.75

Water Details

Water ID: 1003478806
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003478802
Diameter: 4.25
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003362166
Depth M: 6.096
Year Completed: 2010
Well Completed Dt: 2010/09/27
Audit No: Z122693
Tag No: A108615
Contractor: 7241
Path: 715\7154035.pdf
Latitude: 43.7237587299738
Longitude: -79.4642861214266

---

64 | ***1 of 1*** | ***S/174.0*** | ***181.7 / -1.73*** | ***100 Orfus Rd Toronto ON M6A1L9*** | ***EHS***

Order No: 20151110023
Status: C
Report Type: Standard Select Report
Report Date: 16-NOV-15
Date Received: 10-NOV-15
Previous Site Name:
Lot/Building Size: 2.04 Acres
Additional Info Ordered:
Nearest Intersection:
Municipality: TORONTO
Client Prov/State: ON
Search Radius (km): .25
X: -79.465032
Y: 43.718934

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
65	1 of 1	N/179.3	182.8 / -0.61	161 BRIDGELAND RD. TORONTO ON	WWIS

Well ID: 7154054
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z122672
Tag: A108617
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04-Nov-2010 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7154054.pdf

Additional Detail(s) (Map)

Well Completed Date: 2010/09/27
Year Completed: 2010
Depth (m): 5.4864
Latitude: 43.7239177454657
Longitude: -79.4647290063807
Path: 715\7154054.pdf

Bore Hole Information

Bore Hole ID: 1003362204
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 27-Sep-2010 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623659.00
North83: 4842355.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003481631
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28

Most Common Material:	SAND
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003481632
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	
Mat3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	18.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003481634
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003481636
Layer:	3
Plug From:	6.0
Plug To:	18.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003481635
Layer:	2
Plug From:	1.0
Plug To:	6.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003481642
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1003481630
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003481638
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	8.0
Casing Diameter:	1.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003481639
Layer:	1
Slot:	10
Screen Top Depth:	8.0
Screen End Depth:	18.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Water Details

Water ID:	1003481637
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1003481633
Diameter:	2.25
Depth From:	0.0
Depth To:	18.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003362204	***Tag No:***	A108617
Depth M:	5.4864	***Contractor:***	7241
Year Completed:	2010	***Path:***	715\7154054.pdf
Well Completed Dt:	2010/09/27	***Latitude:***	43.7239177454657
Audit No:	Z122672	***Longitude:***	-79.4647290063807

66	***1 of 4***	***SSE/187.0***	***182.8 / -0.59***	***SWENSON CANADA INC 80 ORFUS ROAD TORONTO ON M6A 1M1***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0639100
SIC Code: 3771
SIC Description: TOILET PREP. IND.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

---

66 ***2 of 4*** ***SSE/187.0*** ***182.8 / -0.59*** ***SWENSON CANADA INC 36-270***
80 ORFUS ROAD
TORONTO ON M6A 1M1 ***GEN***

Generator No: ON0639100
SIC Code: 3771
SIC Description: TOILET PREP. IND.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

---

66 ***3 of 4*** ***SSE/187.0*** ***182.8 / -0.59*** ***SWENSON CANADA INC.***
80 ORFUS ROAD
TORONTO ON M6A 1M1 ***GEN***

Generator No: ON0639100

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 3771
SIC Description: TOILET PREP. IND.
Approval Years: 01,03
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

66	*4 of 4*	*SSE/187.0*	*182.8 / -0.59*	***SWENSON CANADA INC.*** ***80 ORFUS ROAD*** ***TORONTO ON M6A 1M1***	***GEN***

Generator No: ON0639100
SIC Code:
SIC Description:
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

67	*1 of 1*	*SSE/187.0*	*182.7 / -0.67*	***EMERSON SUMMERS CO. LTD.*** ***88 ORFUS RD UNIT 2*** ***NORTH YORK ON M6A 1L9***	***SCT***

Established: 1917
Plant Size (ft²): 10000
Employment: 12

--Details--
Description: MEN'S AND BOYS' CLOTHING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2329

Description: WOMEN'S, MISSES', AND JUNIORS' OUTERWEAR, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2339

Description: PERFUMES, COSMETICS, AND OTHER TOILET PREPARATIONS
SIC/NAICS Code: 2844

Description: MANUFACTURING INDUSTRIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3999

Description: DRUGS, DRUG PROPRIETARIES, AND DRUGGISTS' SUNDRIES
SIC/NAICS Code: 5122

Description: MEN'S AND BOYS' CLOTHING AND FURNISHINGS
SIC/NAICS Code: 5136

Description: WOMEN'S, CHILDREN'S, AND INFANTS' CLOTHING AND ACCESSORIES
SIC/NAICS Code: 5137

Description: NONDURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5199

---

68 | **1 of 1** | **SW/194.0** | **181.9 / -1.50** | **157 Bentworth Ave, York Toronto ON** | **WWIS**

Well ID:	7048137	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10-Aug-2007 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z74042	**Contractor:**	7241
Tag:	A061562	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	TORONTO CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7048137.pdf

Additional Detail(s) (Map)

Well Completed Date: 2007/07/10
Year Completed: 2007
Depth (m): 6.1
Latitude: 43.7195332209763
Longitude: -79.4667652112784
Path: 704\7048137.pdf

Bore Hole Information

Bore Hole ID:	23048137	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623504.00
Code OB Desc:		**North83:**	4841865.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10-Jul-2007 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 30148137
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 30248137
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 0.6100000143051147
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 30348137
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 4.570000171661377
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44003556
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.440000057220459
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44003554
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 44003555
Layer: 3
Plug From: 2.440000057220459
Plug To: 6.099999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 25948137
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 29048137
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 42148137
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 3.809999942779541
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 43148137
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 3.6700000762939453

Hole Diameter

Hole ID: 46002457
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 23048137
Depth M: 6.1
Year Completed: 2007
Well Completed Dt: 2007/07/10
Audit No: Z74042
Tag No: A061562
Contractor: 7241
Path: 704\7048137.pdf
Latitude: 43.7195332209763
Longitude: -79.4667652112784

---

69 | ***1 of 1*** | ***WSW/194.5*** | ***181.8 / -1.58*** | ***155-157 Bentworth Ave. Toronto ON M6A 1P6*** | ***EHS***

Order No: 20060111012
Status: C
Report Type: Basic Report
Report Date: 1/20/2006
Date Received: 1/11/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.466913
Y: 43.719801

---

70 | ***1 of 2*** | ***SSE/195.6*** | ***181.8 / -1.58*** | ***HARVEY'S BUILDING SUPPLIES (1987) LTD. 96 ORFUS ROAD TORONTO ON M6A 1L9*** | ***PES***

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:
PDF Site Location:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

70 | ***2 of 2*** | ***SSE/195.6*** | ***181.8 / -1.58*** | ***HARVEY'S BUILDING SUPPLIES (1987) LTD. 96 ORFUS ROAD TORONTO ON M6A 1L9*** | ***PES***

Detail Licence No: 23-01-09867-0
Operator Box:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence No:	09867	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	1
Lot:		**Operator County:**	62
Concession:		**Op Municipality:**	
Region:	3	**Post Office Box:**	
District:	1	**MOE District:**	
County:	62	**SWP Area Name:**	
Trade Name:			
PDF URL:			
PDF Site Location:			

---

71 **1 of 4** **WSW/195.8** **181.9 / -1.53**

ERIC KINGSTON SALES LTD.
162 BENTWORTH AVE.
TORONTO ON M6A 1P7

GEN

Generator No:	ON0674600
SIC Code:	5731
SIC Description:	IND. MACHINERY, WH.
Approval Years:	86,87,88
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

---

71 **2 of 4** **WSW/195.8** **181.9 / -1.53**

ERIC KINGSTON SALES LTD.
162 BENTWORTH AVE.
TORONTO ON M6A 1P7

GEN

Generator No:	ON0674600
SIC Code:	5731
SIC Description:	IND. MACHINERY, WH.
Approval Years:	89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
71	3 of 4	WSW/195.8	181.9 / -1.53	ERIC KINGSTON (OUT OF BUSINESS) 14-247 162 BENTWORTH AVE. TORONTO ON M6A 1P7	GEN
Generator No:		ON0674600			
SIC Code:		5731			
SIC Description:		IND. MACHINERY, WH.			
Approval Years:		92,93,95,96,97,98			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
71	4 of 4	WSW/195.8	181.9 / -1.53	ERIC KINGSTON SALES LTD. 14-247 162 BENTWORTH AVE. TORONTO ON M6A 1P7	GEN
Generator No:		ON0674600			
SIC Code:		5731			
SIC Description:		IND. MACHINERY, WH.			
Approval Years:		94			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
72	1 of 2	SE/197.7	183.1 / -0.31	BAZAAR & NOVELTY CO. 76 ORFUS RD NORTH YORK ON M6A 1L9	SCT
Established:		1936			
Plant Size (ft²):		0			
Employment:		26			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: TOYS AND HOBBY GOODS AND SUPPLIES
SIC/NAICS Code: 5092

Description: STATIONERY AND OFFICE SUPPLIES
SIC/NAICS Code: 5112

Description: INDUSTRIAL AND PERSONAL SERVICE PAPER
SIC/NAICS Code: 5113

Description: NONDURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5199

---

72 | ***2 of 2*** | ***SE/197.7*** | ***183.1 / -0.31*** | ***BAZAAR NOVELTY***
76 ORFUS RD
NORTH YORK ON M6A 1L9 | ***SCT***

Established:
Plant Size (ft²): 0
Employment: 27

--Details--
Description: NONDURABLE GOODS, N.E.C.
SIC/NAICS Code: 5199

---

73 | ***1 of 1*** | ***N/197.7*** | ***183.9 / 0.46*** | ***161 BRIDGELAND RD.***
TORONTO ON | ***WWIS***

Well ID:	7154034	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	04-Nov-2010 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z122692	***Contractor:***	7241
Tag:	A108614	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/715\7154034.pdf

Additional Detail(s) (Map)

Well Completed Date: 2010/09/27
Year Completed: 2010
Depth (m): 5.7912
Latitude: 43.7240384190174
Longitude: -79.464328635956
Path: 715\7154034.pdf

Bore Hole Information

Bore Hole ID:	1003362164	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623691.00
Code OB Desc:		***North83:***	4842369.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	27-Sep-2010 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003478787
Layer:	2
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	8.0
Formation End Depth:	19.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003478786
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478791
Layer:	3
Plug From:	7.0
Plug To:	19.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478789
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003478790
Layer:	2
Plug From:	1.0
Plug To:	7.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1003478797
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1003478785
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003478793
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	9.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003478794
Layer:	1
Slot:	10
Screen Top Depth:	9.0
Screen End Depth:	19.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.75

Water Details

Water ID:	1003478792
Layer:	

Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003478788
Diameter: 4.25
Depth From: 0.0
Depth To: 19.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003362164
Depth M: 5.7912
Year Completed: 2010
Well Completed Dt: 2010/09/27
Audit No: Z122692
Tag No: A108614
Contractor: 7241
Path: 715\7154034.pdf
Latitude: 43.7240384190174
Longitude: -79.464328635956

---

74 ***1 of 2*** ***SW/200.2*** ***181.9 / -1.52*** ***BRITSTONE TEXTILE IMPORT***
155 BENTWORTH AVE
TORONTO ON M6A 1P6 ***SCT***

Established: 1959
Plant Size (ft²):
Employment: 4

--Details--
Description: HOMEFURNISHINGS
SIC/NAICS Code: 5023

---

74 ***2 of 2*** ***SW/200.2*** ***181.9 / -1.52*** ***Canada Glass & Mirror Co.***
155 Bentworth Ave
Toronto ON M6A 1P6 ***SCT***

Established: 01-AUG-70
Plant Size (ft²): 10000
Employment:

--Details--
Description: Other Home Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414390

Description: China, Glassware, Crockery and Pottery Wholesaler-Distributors
SIC/NAICS Code: 414310

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Description: Paint, Glass and Wallpaper Wholesaler-Distributors
SIC/NAICS Code: 416340

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

---

75 **1 of 7** **W/211.8** **179.8 / -3.56** **NORTH YORK HYDRO**
133 CARTWRIGHT
TORONTO CITY ON M6A 1V4 **SPL**

Ref No: 100107
Site No:
Incident Dt: //
Year:
Incident Cause: COOLING SYSTEM LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: CONFIRMED
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/20/1994
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: NORTH YORK HYDRO-240 L OFTRANSFORMER OIL TO GROUNDFROM TRANSFORMERS
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 1106
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

75 **2 of 7** **W/211.8** **179.8 / -3.56** **ICI CONVERTERS INK 21-545**
133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE
BRAMPTON ON M6A 1V4 **GEN**

Generator No: ON0003970
SIC Code: 3791
SIC Description: PRINTING INK IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	3 of 7	W/211.8	179.8 / -3.56	ICI CONVERTERS INK(OUT OF BUS) 133 CARTWRIGHT AVE. NORTH YORK C/O 10 WEST DRIVE BRAMPTON ON M6A 1V4	GEN

Generator No: ON0003970
SIC Code: 3791
SIC Description: PRINTING INK IND.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	4 of 7	W/211.8	179.8 / -3.56	CONVERTERS INK 133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	GEN

Generator No: ON0061500
SIC Code: 3791
SIC Description: PRINTING INK IND.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	5 of 7	W/211.8	179.8 / -3.56	CONVERTERS INC.(OUT OF BUS) 11-026 133 CARTWRIGHT AVE. TORONTO ON M6A 1V4	GEN

Generator No: ON0061500
SIC Code: 3791
SIC Description: PRINTING INK IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

75 | ***6 of 7*** | ***W/211.8*** | ***179.8 / -3.56*** | ***CONVERTERS INK LTD. (OUT OF BUSINESS)***
133 CARTWRIGHT AVENUE
TORONTO ON M6A 1V4 | ***GEN***

Generator No: ON0061500
SIC Code: 3791
SIC Description: PRINTING INK IND.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

75 | ***7 of 7*** | ***W/211.8*** | ***179.8 / -3.56*** | ***CHAMPION INVESTMENTS LTD. 07-538***
133 CARTWRIGHT AVE., NORTH YORK C/O BOX
47 SUITE 2600, 20 QUEEN ST. W.
TORONTO ON M6A 1V4 | ***GEN***

Generator No: ON1625800
SIC Code: 4021
SIC Description: MANU. & IND. BLDG.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

76 | ***1 of 1*** | ***SSE/212.7*** | ***182.1 / -1.27*** | ***UNKNOWN***
ORFUS RD/DUFFLAW RD & OUTFALL H275 IN
RUSTIC PARK.
TORONTO CITY ON | ***SPL***

Ref No: 135396
Site No:
Incident Dt: 12/17/1996
Year:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:

Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	01106
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	WORKS & POLICE.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	12/17/1996	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SOURCE UNKNOWN-UNK QUANT OF DIESEL IN SEWER & OUT-FALL, BOOMED BY WORKS.		
Contaminant Qty:			

---

77 ***1 of 7*** ***SW/214.3*** ***181.9 / -1.55*** ***GREEN JAY SALES INC.*** ***157 BENTWORTH AVE*** ***TORONTO ON M6A 1P6*** ***SCT***

Established:	1983
Plant Size (ft²):	15000
Employment:	6

--Details--

Description:	MEN'S & BOYS' CLOTHING & FURNISHINGS
SIC/NAICS Code:	5136
Description:	WOMEN'S, CHILDREN'S, & INFANTS' CLOTHING & ACCESSORIES
SIC/NAICS Code:	5137

---

77 ***2 of 7*** ***SW/214.3*** ***181.9 / -1.55*** ***MANTEX JOBBERS LTD.*** ***157 Bentworth Ave Unit 1*** ***North York ON M6A 1P6*** ***SCT***

Established:	0000
Plant Size (ft²):	0
Employment:	0

--Details--

Description:	Cut and Sew Clothing Contracting
SIC/NAICS Code:	315210
Description:	Women's and Girls' Cut and Sew Lingerie, Loungewear and Nightwear Manufacturing
SIC/NAICS Code:	315231
Description:	Women's and Girls' Cut and Sew Blouse and Shirt Manufacturing
SIC/NAICS Code:	315232
Description:	Women's and Girls' Cut and Sew Dress Manufacturing
SIC/NAICS Code:	315233
Description:	Women's and Girls' Cut and Sew Suit, Coat, Tailored Jacket and Skirt Manufacturing
SIC/NAICS Code:	315234

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

---

77 **3 of 7** **SW/214.3** **181.9 / -1.55** **Minuteman Press**
157 Bentworth Ave
Toronto ON M6A 1P6
SCT

Established: 1986
Plant Size (ft²): 2000
Employment: 5

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

---

77 **4 of 7** **SW/214.3** **181.9 / -1.55** **Dunmet Products (1998) Ltd.**
157 Bentworth Ave
North York ON M6A 1P6
SCT

Established: 01-AUG-60
Plant Size (ft²): 5000
Employment:

--Details--
Description: Power Boiler and Heat Exchanger Manufacturing
SIC/NAICS Code: 332410

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

---

77 **5 of 7** **SW/214.3** **181.9 / -1.55** **The Promise Holdings Inc.**
157 Bentworth Avenue
Toronto ON M6A 1P6
GEN

Generator No: ON5697837
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

77 **6 of 7** **SW/214.3** **181.9 / -1.55** **Dunmet Products Ltd**
157 Bentworth Ave
GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				North York ON M6A 1P6	

Generator No: ON7426496
SIC Code: 331410
SIC Description: NON-FERROUS METAL (EXCEPT ALUMINUM) SMELTING AND REFINING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
77	7 of 7	SW/214.3	181.9 / -1.55	Dunmet Products (2014) Limited 157 Bentworth avenue Toronto ON M6A1P6	GEN

Generator No: ON9208400
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	1 of 1	NNE/219.9	184.8 / 1.37	130 BRIDGELAND ROAD Toronto ON	WWIS

Well ID: 7179517
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z145453
Tag: A108652
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 17-Apr-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info: WKQ-004608 A0-A00

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2012/01/26
Year Completed: 2012
Depth (m): 9.144
Latitude: 43.724159257966
Longitude: -79.4639406749647
Path:

Bore Hole Information

Bore Hole ID: 1003711337
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 26-Jan-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623722.00
North83: 4842383.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004248771
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0.0
Formation End Depth: 2.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004248773
Layer: 3
Color: 2
General Color: GREY
Mat1: 05

Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 12.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004248772
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 2.5
Formation End Depth: 12.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004248781
Layer: 1
Plug From: 30.0
Plug To: 19.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004248782
Layer: 2
Plug From: 19.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004248780
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004248770
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1004248776
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	20.0
Depth To:	0.0
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004248777
Layer:	1
Slot:	
Screen Top Depth:	30.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Water Details

Water ID:	1004248775
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004248774
Diameter:	2.25
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003711337	**Tag No:**	A108652
Depth M:	9.144	**Contractor:**	7241
Year Completed:	2012	**Path:**	
Well Completed Dt:	2012/01/26	**Latitude:**	43.724159257966
Audit No:	Z145453	**Longitude:**	-79.4639406749647

---

79 | ***1 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***G.A. FOSS TRANSPORT LTD.***
161 BRIDGELAND AVE. TANK TRUCK (CARGO)
TORONTO CITY ON | ***SPL***

Ref No:	102420	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/7/1994	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	

Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	1106
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/7/1994	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	G. A. FOSS TANK TRUCK- 100 L DIESEL TO GROUND, CONTAINED.		
Contaminant Qty:			

---

79 **2 of 27** **N/221.6** **184.0 / 0.55** **BROWNING-FERRIS INDUSTRIES LTD.**
161 BRIDGELAND AVENUE
TORONTO ON M6A 1Z1 **GEN**

Generator No:	ON0040001
SIC Code:	4569
SIC Description:	OTHER TRUCK./TRANS.
Approval Years:	86,87,88,89
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

79 **3 of 27** **N/221.6** **184.0 / 0.55** **BROWNING-FERRIS INDUSTRIES LTD.**
161 BRIDGELAND AVENUE
TORONTO ON M6A 1Z1 **GEN**

Generator No:	ON0040001
SIC Code:	4569
SIC Description:	OTHER TRUCK./TRANS.
Approval Years:	90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

79 | ***4 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***BROWNING-FERRIS INDUSTRIES LTD. 06-111***
161 BRIDGELAND AVENUE
TORONTO ON M6A 1Z1 | ***GEN***

Generator No: ON0040001
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

79 | ***5 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***BROWNING-FERRIS INDUSTRIES LIMITED***
161 BRIDGELAND AVENUE
TORONTO ON M6A 1Z1 | ***GEN***

Generator No: ON0040001
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
79	6 of 27	N/221.6	184.0 / 0.55	**WASTECO** **161 BRIDGELAND AVENUE** **NORTH YORK ON M6A 1Z1**	GEN
Generator No:		ON0765501			
SIC Code:		4999			
SIC Description:		OTHER UTILITY IND.			
Approval Years:		93,94,95,96,97,98			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
79	7 of 27	N/221.6	184.0 / 0.55	**WASTECO, A DIVISION OF** **161 BRIDGELAND AVENUE** **NORTH YORK ON M6A 1Z1**	GEN
Generator No:		ON0765501			
SIC Code:		4999			
SIC Description:		OTHER UTILITY IND.			
Approval Years:		99,00,01			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
79	8 of 27	N/221.6	184.0 / 0.55	**SOUTHERN SANITATION** **161 BRIDGELAND AVENUE** **NORTH YORK ON**	GEN
Generator No:		ON0765501			
SIC Code:		562110			

SIC Description: Waste Collection
Approval Years: 03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

79 | ***9 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***161 Bridgeland Avenue Toronto ON*** | ***EHS***

Order No: 20100816011
Status: C
Report Type: No Charge
Report Date: 8/23/2010
Date Received: 8/16/2010
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.4648
Y: 43.724683

---

79 | ***10 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1*** | ***GEN***

Generator No: ON0765501
SIC Code: 562110
SIC Description: Waste Collection
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	11 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code: 562110
SIC Description: Waste Collection
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	12 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code: 562110
SIC Description: Waste Collection
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	13 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code: 562110

SIC Description:	Waste Collection
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	14 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON	GEN

Generator No:	ON0765501
SIC Code:	562110
SIC Description:	WASTE COLLECTION
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	15 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No:	ON0765501
SIC Code:	562110
SIC Description:	WASTE COLLECTION
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Serge Gomes
Choice of Contact:	CO_ADMIN

Phone No Admin: 416 787 5000 Ext.242
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

79	16 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code: 562110
SIC Description: WASTE COLLECTION
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Serge Gomes
Choice of Contact: CO_ADMIN
Phone No Admin: 416 787 5000 Ext.242
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

79	17 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code: 562110
SIC Description: WASTE COLLECTION
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Serge Gomes
Choice of Contact: CO_ADMIN
Phone No Admin: 416 787 5000 Ext.242
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

79	18 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION WASTECO - TORONTO 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON0765501
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

79	19 of 27	N/221.6	184.0 / 0.55	WASTECO 161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON9188696
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

79	20 of 27	N/221.6	184.0 / 0.55	SOUTHERN SANITATION WASTECO - TORONTO 161 BRIDGELAND AVENUE NORTH YORK ON M6A 1Z1	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0765501
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	21 of 27	N/221.6	184.0 / 0.55	WASTECO 161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON9188696
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	22 of 27	N/221.6	184.0 / 0.55	WASTECO 161 BRIDGELAND AVE NORTH YORK ON M6A 1Z1	GEN

Generator No: ON9188696
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

---

79 ***23 of 27*** ***N/221.6*** ***184.0 / 0.55*** ***SOUTHERN SANITATION WASTECO - TORONTO***
161 BRIDGELAND AVENUE
NORTH YORK ON M6A 1Z1 ***GEN***

Generator No: ON0765501
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

79 ***24 of 27*** ***N/221.6*** ***184.0 / 0.55*** ***161 Bridgeland Avenue***
North York ON M6A 1Z1 ***EHS***

Order No: 21043000097
Status: C
Report Type: Standard Report
Report Date: 05-MAY-21
Date Received: 30-APR-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.4645891
Y: 43.7242903

---

79 ***25 of 27*** ***N/221.6*** ***184.0 / 0.55*** ***SOUTHERN SANITATION WASTECO - TORONTO***
161 BRIDGELAND AVENUE
NORTH YORK ON M6A 1Z1 ***GEN***

Generator No: ON0765501
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

---

79 | ***26 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***WASTECO***
161 BRIDGELAND AVE
NORTH YORK ON M6A 1Z1 | ***GEN***

Generator No: ON9188696
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

---

79 | ***27 of 27*** | ***N/221.6*** | ***184.0 / 0.55*** | ***161 Bridgeland Avenue***
North York ON M6A 1Z1 | ***EHS***

Order No: 21043000097
Status: C
Report Type: Standard Report
Report Date: 05-MAY-21
Date Received: 30-APR-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.4645891
Y: 43.7242903

---

80 | ***1 of 1*** | ***SE/222.0*** | ***183.5 / 0.10*** | ***Drummer's East Agency Ltd.***
66 Orfus Rd
North York ON M6A 1L9 | ***SCT***

Established: 01-SEP-80
Plant Size (ft²):
Employment:

--Details--
Description: Stationery and Office Supplies Wholesaler-Distributors
SIC/NAICS Code: 418210

Description: All Other Wholesaler-Distributors

SIC/NAICS Code: 418990

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

---

81 *1 of 5* *NNW/224.4* *181.9 / -1.50* **GENERAL TRANSFORMERS LTD.** **SCT**
185 BRIDGELAND AVE
TORONTO ON M6A 1Y7

Established: 1977
Plant Size (ft²): 0
Employment: 0

--Details--
Description: ELECTRICAL APPARATUS & CONSTRUCTION MATERIALS
SIC/NAICS Code: 5063

---

81 *2 of 5* *NNW/224.4* *181.9 / -1.50* **185 Bridgeland Ave<UNOFFICIAL>** **SPL**
Toronto ON M6A 1Y7

Ref No:	2602-69HQ7N	**Discharger Report:**	0
Site No:		**Material Group:**	Waste
Incident Dt:	2/11/2005	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Intent - Intentional or planned occurrence	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Toronto
Nature of Impact:	Air Pollution; Human Health/Safety; Surface Water Pollution; Vegetation Damage	**Site Lot:**	
Receiving Medium:	Water & Air	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/11/2005	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spill to Land; Spills
Incident Reason:	Negligence (Apparent) - Caused by lack of diligence	**Source Type:**	
Site Name:	185 Bridgeland Ave<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Raw Sewage / waste to ditch		
Contaminant Qty:			

---

81 *3 of 5* *NNW/224.4* *181.9 / -1.50* **Faylaura Investments Inc.** **SPL**
185 Bridgeland Ave
Toronto ON M6A 1Y7

Ref No:	8624-69NP55	**Discharger Report:**	0
Site No:		**Material Group:**	Waste
Incident Dt:	7/1/2004	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	

Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Multi-Media Pollution	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/16/2005	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spill to Land
Incident Reason:	Negligence (Apparent) - Caused by lack of diligence	**Source Type:**	
Site Name:	185 Bridgeland		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Sewage to property from illegal toilets.		
Contaminant Qty:	unknown		

---

81 | ***4 of 5*** | ***NNW/224.4*** | ***181.9 / -1.50*** | ***185 Bridgeland Avenue Toronto ON M6A 1Y7*** | ***EHS***

Order No:	20101206017	**Nearest Intersection:**	Dufferin & Caledonia
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	12/10/2010	**Search Radius (km):**	0.25
Date Received:	12/6/2010 11:59:00 AM	**X:**	-79.466141
Previous Site Name:		**Y:**	43.724743
Lot/Building Size:			
Additional Info Ordered:			

---

81 | ***5 of 5*** | ***NNW/224.4*** | ***181.9 / -1.50*** | ***Property west of 185 Bridgeland Avenue Toronto ON*** | ***SPL***

Ref No:	3401-BADSDN	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	3/18/2019	**Health/Env Conseq:**	0 - No Impact
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	Property west of 185 Bridgeland Avenue
Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/18/2019	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:		**Source Type:**	
Site Name:	Commercial Property<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Commercial property collecting junk cars and trailers		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 2	NNW/224.7	181.9 / -1.50	AMERICAN LOUVER OF CANADA LTD. 185 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	SCT

Established: 1963
Plant Size (ft²): 0
Employment: 35

--Details--
Description: RESIDENTIAL ELECTRIC LIGHTING FIXTURES
SIC/NAICS Code: 3645

Description: COMMERCIAL, INDUSTRIAL, AND INSTITUTIONAL ELECTRICAL LIGHTING FIXTURES
SIC/NAICS Code: 3646

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	2 of 2	NNW/224.7	181.9 / -1.50	Silkscape Designs Inc. 185 Bridgeland Ave Unit 1 North York ON M6A 1Y7	SCT

Established:
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	1 of 1	WSW/231.1	180.8 / -2.56	Lorellana Couture Inc. 164A Bentworth Ave Toronto ON M6A 1P7	SCT

Established: 01-JAN-81
Plant Size (ft²): 3500
Employment:

--Details--
Description: Women's and Girls' Cut and Sew Dress Manufacturing
SIC/NAICS Code: 315233

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	1 of 1	WSW/231.2	180.8 / -2.56	164 Bentworth Ave Toronto ON M6A1P7	EHS

Order No: 20180312116
Status: C
Report Type: Standard Express Report
Report Date: 12-MAR-18
Date Received: 12-MAR-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.467646
Y: 43.72024

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	1 of 1	N/231.4	184.5 / 1.13	278 BRIDGELAND AVE TORONTO ON	WWIS

Well ID: 6930320
Construction Date:

Flowing (Y/N):
Flow Rate:

Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	15-Jun-2006 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z49533	**Contractor:**	7147
Tag:	A041538	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/693\6930320.pdf

Additional Detail(s) (Map)

Well Completed Date: 2006/05/23
Year Completed: 2006
Depth (m): 5.2
Latitude: 43.7243149389909
Longitude: -79.4641353410253
Path: 693\6930320.pdf

Bore Hole Information

Bore Hole ID:	11559120	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623706.00
Code OB Desc:		**North83:**	4842400.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	23-May-2006 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 933054581
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0

Formation End Depth: 0.20000000298023224
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933054583
Layer: 3
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 5.199999809265137
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933054582
Layer: 2
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.20000000298023224
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933293428
Layer: 1
Plug From: 0.0
Plug To: 0.20000000298023224
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933293431
Layer: 4
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933293429
Layer: 2
Plug From: 0.20000000298023224
Plug To: 1.7999999523162842

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933293430
Layer: 3
Plug From: 1.7999999523162842
Plug To: 5.199999809265137
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 966930320
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11568727
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930878970
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0999999046325684
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933418461
Layer: 1
Slot: 10
Screen Top Depth: 2.0999999046325684
Screen End Depth: 5.199999809265137
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Hole Diameter

Hole ID: 11691237
Diameter: 10.0
Depth From: 0.0
Depth To: 5.199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	11559120	**Tag No:**	A041538
Depth M:	5.2	**Contractor:**	7147
Year Completed:	2006	**Path:**	693\6930320.pdf
Well Completed Dt:	2006/05/23	**Latitude:**	43.7243149389909
Audit No:	Z49533	**Longitude:**	-79.4641353410253

86 **1 of 1** **NW/232.9** **180.8 / -2.56** **223 Bridgeland Avenue, North York Toronto ON** **SPL**

Ref No:	8550-5LGPAW	**Discharger Report:**	
Site No:		**Material Group:**	Oil
Incident Dt:	4/10/2003	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Intent - Intentional or planned occurrence	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Central
Environment Impact:	Possible	**Site Municipality:**	Toronto
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/10/2003	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spills
Incident Reason:	Spill	**Source Type:**	

Site Name: GREEN WALL FORMING COMPANY<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Green Wall - Spill of water/oil/silt
Contaminant Qty:

87 **1 of 2** **WSW/239.5** **180.8 / -2.56** **ON** **WWIS**

Well ID:	7192516	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	04-Dec-2012 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C19391	**Contractor:**	7215
Tag:	A139572	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Detail(s) (Map)

Well Completed Date: 2012/10/26
Year Completed: 2012
Depth (m):
Latitude: 43.7206201194731
Longitude: -79.4679168693174
Path:

Bore Hole Information

Bore Hole ID:	1004213196	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623409.00
Code OB Desc:		***North83:***	4841984.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	26-Oct-2012 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1004213196	***Tag No:***	A139572
Depth M:		***Contractor:***	7215
Year Completed:	2012	***Path:***	
Well Completed Dt:	2012/10/26	***Latitude:***	43.7206201194731
Audit No:	C19391	***Longitude:***	-79.4679168693174

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	2 of 2	WSW/239.5	180.8 / -2.56	ON	WWIS

Well ID:	7231719	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	22-Nov-2012 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C12956	***Contractor:***	7147
Tag:	A139592	***Form Version:***	5
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Detail(s) (Map)

Well Completed Date: 2012/11/14
Year Completed: 2012
Depth (m):
Latitude: 43.7206201194731
Longitude: -79.4679168693174
Path:

Bore Hole Information

Bore Hole ID: 1005284576
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 14-Nov-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623409.00
North83: 4841984.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1005284576
Depth M:
Year Completed: 2012
Well Completed Dt: 2012/11/14
Audit No: C12956

Tag No: A139592
Contractor: 7147
Path:
Latitude: 43.7206201194731
Longitude: -79.4679168693174

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	1 of 1	WNW/242.4	180.1 / -3.35	245 BRIDGELAND AVE Toronto ON	WWIS

Well ID: 7286369
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z258067
Tag: A208902
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map):

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11-May-2017 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Well Completed Date: 2017/04/27
Year Completed: 2017
Depth (m): 6.096
Latitude: 43.722783787521
Longitude: -79.4681224333844
Path:

Bore Hole Information

Bore Hole ID: 1006442363
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 27-Apr-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623388.00
North83: 4842224.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006673637
Layer: 1
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006673638
Layer: 2
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 2.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1006673640
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	14.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006673639
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	14.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006673650
Layer:	3
Plug From:	9.0
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006673649
Layer:	2
Plug From:	0.5
Plug To:	9.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006673648
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well

Use

Method Construction ID: 1006673647
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1006673636
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006673643
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006673644
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1006673642
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006673641
Diameter: 6.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006442363
Depth M: 6.096
Year Completed: 2017
Tag No: A208902
Contractor: 7241
Path: 728\7286369.pdf

Well Completed Dt:	2017/04/27			**Latitude:**	43.722783787521
Audit No:	Z258067			**Longitude:**	-79.4681224333844

89	1 of 3	SE/242.6	182.8 / -0.59	**1056934 Ontario Limited** **65 Orfus Rd.** **Toronto ON M6A 1L7**	GEN

Generator No: ON7976047
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

89	2 of 3	SE/242.6	182.8 / -0.59	**1056934 Ontario Limited** **65 Orfus Rd.** **Toronto ON M6A 1L7**	GEN

Generator No: ON7976047
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

89	3 of 3	SE/242.6	182.8 / -0.59	**1056934 Ontario Limited** **65 Orfus Rd.** **Toronto ON M6A 1L7**	GEN

Generator No: ON7976047
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

---

90 | ***1 of 1*** | ***S/244.2*** | ***180.8 / -2.56*** | ***HUGHES CONTAINERS LIMITED***
95 ORFUS RD
TORONTO ON M6A 1M4 | ***SCT***

Established: 1962
Plant Size (ft²):
Employment: 42

--Details--
Description: CORRUGATED & SOLID FIBER BOXES
SIC/NAICS Code: 2653

---

91 | ***1 of 1*** | ***W/244.7*** | ***179.8 / -3.56*** | ***1277 Caledonia rd***
Toronto ON | ***WWIS***

Well ID:	7365139	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	14-Aug-2020 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z339604	***Contractor:***	7241
Tag:	A294678	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008436543	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623382.00
Code OB Desc:		***North83:***	4842130.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11-Jun-2020 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008742473
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	05
Mat3 Desc:	CLAY
Formation Top Depth:	5.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008742472
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.25
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008742471
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.25
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008742597
Layer:	1
Plug From:	0.0
Plug To:	14.0
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1008742598
Layer:	2
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008742714
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	direct push

Pipe Information

Pipe ID:	1008742337
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008742756
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008742799
Layer:	1
Slot:	.10
Screen Top Depth:	15.0
Screen End Depth:	25.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008742849
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	

Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008742668
Diameter: 6.0
Depth From: 0.0
Depth To: 25.0
Hole Depth UOM: ft
Hole Diameter UOM: Inch

Links

Bore Hole ID: 1008436543
Depth M: 7.62
Year Completed: 2020
Well Completed Dt: 2020/06/11
Audit No: Z339604
Tag No: A294678
Contractor: 7241
Path:
Latitude: 43.721938717507
Longitude: -79.4682184597095

---

92 ***1 of 1*** ***W/246.2*** ***179.8 / -3.56*** ***135 Cartwright Avenue North York ON M6A 1V4*** ***EHS***

Order No: 20190612043
Status: C
Report Type: Standard Express Report
Report Date: 12-JUN-19
Date Received: 12-JUN-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.468147
Y: 43.721165

---

93 ***1 of 9*** ***WNW/246.7*** ***179.8 / -3.56*** ***Alternator Exchange Co. Ltd. 124A Cartwright Ave North York ON M6A 1V2*** ***SCT***

Established: 1978
Plant Size (ft²): 8500
Employment: 12

--Details--
Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: Motor Vehicle Electrical and Electronic Equipment Manufacturing
SIC/NAICS Code: 336320

Description: Motor and Generator Manufacturing
SIC/NAICS Code: 335312

---

93 ***2 of 9*** ***WNW/246.7*** ***179.8 / -3.56*** ***ALTERNATOR EXCHANGE CO. LTD. 124 A CARTWRIGHT AVE TORONTO ON M6A 1V2*** ***SCT***

Established: 1978
Plant Size (ft²): 8500
Employment: 12

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: RELAYS & INDUSTRIAL CONTROLS
SIC/NAICS Code: 3625

Description: ELECTRICAL EQUIPMENT FOR INTERNAL COMBUSTION ENGINES
SIC/NAICS Code: 3694

Description: MOTOR VEHICLE PARTS & ACCESSORIES
SIC/NAICS Code: 3714

Description: MOTOR VEHICLE SUPPLIES & NEW PARTS
SIC/NAICS Code: 5013

Description: MOTORS & GENERATORS
SIC/NAICS Code: 3621

93	*3 of 9*	*WNW/246.7*	*179.8 / -3.56*	***Arte Unico Inc.*** ***124 Cartwright Ave*** ***Toronto ON M6A 1V2***	***SCT***

Established:
Plant Size (ft²):
Employment: 4

--Details--
Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: Wood Office Furniture, including Custom Architectural Woodwork, Manufacturing
SIC/NAICS Code: 337213

93	*4 of 9*	*WNW/246.7*	*179.8 / -3.56*	***ALTERNATOR EXCHANGE LTD.*** ***124 A CARTWRIGHT AVE.*** ***TORONTO ON M6A 1V2***	***GEN***

Generator No: ON0272900
SIC Code: 6342
SIC Description: TIRE, ETC. STORES
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	5 of 9	WNW/246.7	179.8 / -3.56	ALTERNATOR EXCHANGE COMPANY LTD. 124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	GEN

Generator No: ON0272900
SIC Code: 6342
SIC Description: TIRE, ETC. STORES
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	6 of 9	WNW/246.7	179.8 / -3.56	ALTERNATOR EXCHANGE COMPANY LTD. 02-029 124 A CARTWRIGHT AVE. TORONTO ON M6A 1V2	GEN

Generator No: ON0272900
SIC Code: 6342
SIC Description: TIRE, ETC. STORES
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	7 of 9	WNW/246.7	179.8 / -3.56	ALTERNATOR EXCHANGE COMPANY LIMITED 124A CARTWRIGHT AVENUE TORONTO ON M6A 1V2	GEN

Generator No: ON0272900

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 6342
SIC Description: TIRE, ETC. STORES
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

93	8 of 9	WNW/246.7	179.8 / -3.56	ALTERNATOR EXCHANGE COMPANY LIMITED 124 A Cartwright Ave., Toronto ON M6A 1V2	GEN

Generator No: ON0272900
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

93	9 of 9	WNW/246.7	179.8 / -3.56	Arte Unico Inc. 124 Cartwright Ave North York ON M6A 1V2	SCT

Established: 1995
Plant Size (ft²): 10000
Employment:

--Details--
Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: Wood Office Furniture, including Custom Architectural Woodwork, Manufacturing
SIC/NAICS Code: 337213

---

94 | **1 of 3** | **ESE/254.6** | **182.8 / -0.58** | **ARBOR STORE INTERIORS INC.**
52 ORFUS RD
NORTH YORK ON M6A 1L6 | **SCT**

Established: 1971
Plant Size (ft²): 16500
Employment: 40

--Details--
Description: WOOD KITCHEN CABINETS
SIC/NAICS Code: 2434

Description: WOOD OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS
SIC/NAICS Code: 2541

Description: OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS, EXCEPT WOOD
SIC/NAICS Code: 2542

---

94 | **2 of 3** | **ESE/254.6** | **182.8 / -0.58** | **UNIVERSAL SHOWCASE LTD.**
52 Orfus Rd
North York ON M6A 1L6 | **SCT**

Established: 1971
Plant Size (ft²): 16500
Employment: 40

--Details--
Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

---

94 | **3 of 3** | **ESE/254.6** | **182.8 / -0.58** | **52 Orfus Road**
Toronto ON | **EHS**

Order No: 20170207031
Status: C
Report Type: Standard Report
Report Date: 10-FEB-17
Date Received: 07-FEB-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.461584
Y: 43.719696

---

95 | **1 of 1** | **NW/254.9** | **181.9 / -1.54** | **ON** | **WWIS**

Well ID: 7374604
Construction Date:

Flowing (Y/N):
Flow Rate:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	14-Dec-2020 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C50403	**Contractor:**	7472
Tag:	A303308	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008561269	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623484.00
Code OB Desc:		**North83:**	4842381.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08-Sep-2020 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008561269	**Tag No:**	A303308
Depth M:		**Contractor:**	7472
Year Completed:	2020	**Path:**	
Well Completed Dt:	2020/09/08	**Latitude:**	43.7241809228264
Audit No:	C50403	**Longitude:**	-79.4668949572793

96	*1 of 5*	*WSW/255.0*	*180.8 / -2.56*	***SCM Special Construction Machines*** ***166 Bentworth Avenue*** ***Toronto ON M6A 1P7***	***GEN***

Generator No:	ON2851722
SIC Code:	238990
SIC Description:	All Other Specialty Trade Contractors
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

96 | ***2 of 5*** | ***WSW/255.0*** | ***180.8 / -2.56*** | ***166 Bentworth Avenue Toronto ON M6A 1P7*** | ***EHS***

Order No: 20120918011
Status: C
Report Type: Standard Report
Report Date: 26-SEP-12
Date Received: 18-SEP-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.467876
Y: 43.720156

---

96 | ***3 of 5*** | ***WSW/255.0*** | ***180.8 / -2.56*** | ***SCM Special Construction Machines 166 Bentworth Avenue Toronto ON M6A 1P7*** | ***GEN***

Generator No: ON2851722
SIC Code: 238990
SIC Description: All Other Specialty Trade Contractors
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

96 | ***4 of 5*** | ***WSW/255.0*** | ***180.8 / -2.56*** | ***SCM Special Construction Machines 166 Bentworth Avenue Toronto ON M6A 1P7*** | ***GEN***

Generator No: ON2851722
SIC Code: 238990
SIC Description: All Other Specialty Trade Contractors
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	5 of 5	WSW/255.0	180.8 / -2.56	SCM Special Construction Machines 166 Bentworth Avenue Toronto ON M6A 1P7	GEN

Generator No: ON2851722
SIC Code: 238990
SIC Description: All Other Specialty Trade Contractors
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	1 of 1	SW/257.7	180.8 / -2.56	167 Bentworth Avenue North York ON M6A 1P6	EHS

Order No: 20180523078
Status: C
Report Type: Standard Report
Report Date: 30-MAY-18
Date Received: 23-MAY-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.467488
Y: 43.71929

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
98	1 of 1	W/261.4	179.8 / -3.56	ON	BORE

Borehole ID: 642871
OGF ID: 215543264
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: MAY-1959
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 6.7
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 178
Elev Reliabil Note:
DEM Ground Elev m: 179
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.721968
Longitude DD: -79.468433
UTM Zone: 17
Easting: 623365
Northing: 4842133
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID:	218501309	**Mat Consistency:**	Hard
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	3.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. BROWN,HARD,AGE GLACIAL.		

Geology Stratum ID:	218501306	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,ORGANIC,SAND, STONES. BLACK,AGE POST-GLACIAL.		

Geology Stratum ID:	218501307	**Mat Consistency:**	Hard
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	2.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. BROWN,HARD,AGE GLACIAL.		

Geology Stratum ID:	218501310	**Mat Consistency:**	Hard
Top Depth:	3.6	**Material Moisture:**	
Bottom Depth:	6.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY, STONES. GREY,HARD,AGE GLACIAL. 012 011 00007032000980580011 70 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218501308	**Mat Consistency:**	
Top Depth:	2.8	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	Fine
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE. BROWN,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 108910 NTS_Sheet: 30M11E		

Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

99 **1 of 1** **WSW/261.6** **180.8 / -2.56** **1245 CALEDONIA RD Toronto ON** **WWIS**

Well ID: 7181106
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z148235
Tag: A125731
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 18-May-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7181106.pdf

Additional Detail(s) (Map)

Well Completed Date: 2012/04/13
Year Completed: 2012
Depth (m): 7.3152
Latitude: 43.7203704283215
Longitude: -79.4680970362788
Path: 718\7181106.pdf

Bore Hole Information

Bore Hole ID: 1003788553
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 13-Apr-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Elevation:
Elevrc:
Zone: 17
East83: 623395.00
North83: 4841956.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1004312199
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.5
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004312198
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	60
Mat2 Desc:	CEMENTED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004312201
Layer:	4
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	15.0
Formation End Depth:	24.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004312200
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28

Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312209
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312210
Layer:	2
Plug From:	0.5
Plug To:	13.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312211
Layer:	3
Plug From:	13.0
Plug To:	24.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004312208
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004312197
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004312204
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	14.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004312205
Layer: 1
Slot: 10
Screen Top Depth: 14.0
Screen End Depth: 24.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.2799999713897705

Water Details

Water ID: 1004312203
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004312202
Diameter: 4.5
Depth From: 0.0
Depth To: 24.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003788553
Depth M: 7.3152
Year Completed: 2012
Well Completed Dt: 2012/04/13
Audit No: Z148235
Tag No: A125731
Contractor: 7241
Path: 718\7181106.pdf
Latitude: 43.7203704283215
Longitude: -79.4680970362788

---

100 ***1 of 3*** ***SW/264.2*** ***180.8 / -2.56*** ***CALEDONIA MARBLE COMPANY LTD.***
167 BENTWORTH AVE
NORTH YORK ON M6A 1P6 ***SCT***

Established: 1963
Plant Size (ft²): 21000
Employment: 27

--Details--
Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

---

100 ***2 of 3*** ***SW/264.2*** ***180.8 / -2.56*** ***CALEDONIA MARBLE COMPANY LTD***
167 BENTWORTH AVE
NORTH YORK ON M6A 1P6 ***SCT***

Established: 1963
Plant Size (ft²): 21000
Employment: 15

--Details--
Description: CUT STONE AND STONE PRODUCTS
SIC/NAICS Code: 3281

---

100 ***3 of 3*** ***SW/264.2*** ***180.8 / -2.56*** ***Caledonia Marble Company Ltd.***
167 Bentworth Ave
Toronto ON M6A 1P6 ***SCT***

Established: 01-AUG-63
Plant Size (ft²): 21000
Employment:

--Details--
Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

---

101 ***1 of 1*** ***ENE/265.5*** ***187.3 / 3.92*** ***102 -123 BENTOWORTH AVE.***
NORTH YORK ON ***WWIS***

Well ID:	7149492	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	05-Aug-2010 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z118953	***Contractor:***	7241
Tag:	A102955	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7149492.pdf

Additional Detail(s) (Map)

Well Completed Date: 2010/07/19
Year Completed: 2010
Depth (m): 1.85928
Latitude: 43.722307057056
Longitude: -79.4614553726597
Path: 714\7149492.pdf

Bore Hole Information

Bore Hole ID:	1003269403	***Elevation:***	
DP2BR:		***Elevrc:***	

Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623926.00
Code OB Desc:		**North83:**	4842181.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	19-Jul-2010 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003313040
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	4.900000095367432
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003313039
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	1.8200000524520874
Formation End Depth:	4.900000095367432
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003313038
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0

Formation End Depth: 1.8200000524520874
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003313042
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003313044
Layer: 3
Plug From: 3.0999999046325684
Plug To: 6.099999904632568
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003313043
Layer: 2
Plug From: 0.3100000023841858
Plug To: 3.0999999046325684
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003313050
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1003313037
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003313046
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.199999809265137
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003313047

Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1003313045
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003313041
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003269403
Depth M: 1.85928
Year Completed: 2010
Well Completed Dt: 2010/07/19
Audit No: Z118953
Tag No: A102955
Contractor: 7241
Path: 714\7149492.pdf
Latitude: 43.722307057056
Longitude: -79.4614553726597

---

102 | ***1 of 10*** | ***NNW/266.2*** | ***181.8 / -1.59*** | ***SUPERIOR CRANE LIMITED 195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7*** | ***GEN***

Generator No: ON0496100
SIC Code: 3699
SIC Description: OTHER PETRO. & COAL
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

102 | ***2 of 10*** | ***NNW/266.2*** | ***181.8 / -1.59*** | ***SUPERIOR OUT OF BUSINESS 195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7*** | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0496100
SIC Code: 3699
SIC Description: OTHER PETRO. & COAL
Approval Years: 88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

102	3 of 10	NNW/266.2	181.8 / -1.59	SUPERIOR OUT OF BUSINESS 34-130 195 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	GEN

Generator No: ON0496100
SIC Code: 3699
SIC Description: OTHER PETRO. & COAL
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

102	4 of 10	NNW/266.2	181.8 / -1.59	FER-PAL CONSTRUCTION LTD. 195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	GEN

Generator No: ON2178000
SIC Code: 4931
SIC Description: WATER SYSTEMS IND.
Approval Years: 96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

102	5 of 10	NNW/266.2	181.8 / -1.59	FER-(OUT OF BUS) 195 BRIDGELAND AVENUE BEHIND BUILDING NORTH YORK ON M6A 1Y7	GEN

Generator No: ON2178000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 4931
SIC Description: WATER SYSTEMS IND.
Approval Years: 97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

102 | **6 of 10** | **NNW/266.2** | **181.8 / -1.59** | **H & E Copy Services Inc.**
195 Bridgeland Ave.
Toronto ON M6A 1Y7 | **GEN**

Generator No: ON9513160
SIC Code: 323114
SIC Description: Quick Printing
Approval Years: 03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

102 | **7 of 10** | **NNW/266.2** | **181.8 / -1.59** | **Curtis Properties (195 Bridgeland) Inc.**
195 Bridgeland Ave
Toronto ON M6A 1Y7 | **GEN**

Generator No: ON7279760
SIC Code:
SIC Description:
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

102 | ***8 of 10*** | ***NNW/266.2*** | ***181.8 / -1.59*** | ***Shefa<UNOFFICIAL>*** | ***SPL***

195 Bridgeland Avenue
Toronto ON

Ref No:	0443-9N64SE	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	2014/08/19	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Overflow/Surcharge	***Sector Type:***	Sewer (Private or Municipal)
Incident Event:		***Agency Involved:***	
Contaminant Code:	44	***Nearest Watercourse:***	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	***Site Address:***	195 Bridgeland Avenue
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Toronto
Nature of Impact:	Soil Contamination	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	No Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2014/08/19	***Site Map Datum:***	
Dt Document Closed:	2014/09/09	***SAC Action Class:***	Sewage Bypasses / Overflows
Incident Reason:	Blockage	***Source Type:***	
Site Name:	Shefa<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Shefa: sanitary overflow to pkg lot/cb		
Contaminant Qty:	1 other - see incident description		

---

102 | ***9 of 10*** | ***NNW/266.2*** | ***181.8 / -1.59*** | ***195 Bridgeland Avenue*** | ***EHS***

North York ON M6A 1Z4

Order No:	20190514176	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	22-MAY-19	***Search Radius (km):***	.2
Date Received:	14-MAY-19	***X:***	-79.466693
Previous Site Name:		***Y:***	43.724355
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

102 | ***10 of 10*** | ***NNW/266.2*** | ***181.8 / -1.59*** | ***Gus Kastanis*** | ***WDS***

195 Bridgeland
toronto ON M6A 1Y7

Approval No:	R-007-5112084649	***Total Area (ha):***	
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	REGISTERED	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	EASR	***Inciner. Area (ha):***	
Link Source:	MOFA	***Inciner. Cap (t):***	
Project Type:	End-of-Life Vehicle Waste Disposal Sites	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2020-02-28	***Process Vol (m³):***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.72388889
Prop Postal:		**Longitude:**	-79.46666667
Prop Phone:		**Geometry X:**	
Serial Link:		**Geometry Y:**	
Approval Type:	EASR-End-of-Life Vehicle Waste Disposal Sites		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	195 Bridgeland		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2222435		
PDF Site Location:			

---

103 | ***1 of 4*** | ***W/267.2*** | ***179.9 / -3.53*** | ***ATTARDO CO. LTD.***
1259 CALEDONIA RD
TORONTO ON M6A 2X6 | ***SCT***

Established:	1973
Plant Size (ft²):	10000
Employment:	12

--Details--

Description:	HOMEFURNISHINGS
SIC/NAICS Code:	5023

---

103 | ***2 of 4*** | ***W/267.2*** | ***179.9 / -3.53*** | ***ON*** | ***BORE***

Borehole ID:	644552	**Inclin FLG:**	No
OGF ID:	215544935	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	DEC-1959	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.720796
Total Depth m:	7.6	**Longitude DD:**	-79.468338
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	623375
Drill Method:	Diamond Drill	**Northing:**	4842003
Orig Ground Elev m:	29.7	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable

DEM Ground Elev m: 180
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218507996
Top Depth: 0
Bottom Depth: 2.1
Material Color: Dark
Material 1: Fill
Material 2: Silt
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL,SILT. DARK,DENSE.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218507997
Top Depth: 2.1
Bottom Depth: 4.3
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: SILT,SAND,CLAY. GREY,BROWN,GLACIAL,VERY DENSE,AGE GLACIAL.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218507998
Top Depth: 4.3
Bottom Depth: 7.6
Material Color: Grey
Material 1: Till
Material 2: Sand
Material 3: Gravel
Material 4:
Gsc Material Description:
Stratum Description: TILL,SAND,GRAVEL. GREY,GLACIAL,VERY DENSE, AGE GLACIAL. 00000020000700550014005O **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 125740 NTS_Sheet: 30M11E
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
103	3 of 4	W/267.2	179.9 / -3.53	Yongetex Limited 1259 Caledonia Rd North York ON M6A 2X6	SCT

Established: 01-SEP-82
Plant Size (ft²): 30000
Employment:

--Details--
Description: Linen, Drapery and Other Textile Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414330

Description: Floor Covering Wholesaler-Distributors
SIC/NAICS Code: 414320

Description: Linen, Drapery and Other Textile Furnishings Wholesaler-Distributors
SIC/NAICS Code: 414330

Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
103	4 of 4	W/267.2	179.9 / -3.53	1259 Caledonia Road Toronto ON M6A 2X6	EHS

Order No: 20120730012
Status: C
Report Type: Standard Report
Report Date: 08-AUG-12
Date Received: 30-JUL-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.468463
Y: 43.720749

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	1 of 1	W/267.4	180.5 / -2.87	1245 CALEDONIA RD Toronto ON	WWIS

Well ID: 7180722
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z147207
Tag: A132372
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 10-May-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7180722.pdf

Additional Detail(s) (Map)

Well Completed Date:	2012/03/08
Year Completed:	2012
Depth (m):	7.62
Latitude:	43.720588774756
Longitude:	-79.4682652752323
Path:	718\7180722.pdf

Bore Hole Information

Bore Hole ID:	1003761093	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623381.00
Code OB Desc:		**North83:**	4841980.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08-Mar-2012 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004304344
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.5
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304346
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	8.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304343
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	60
Mat3 Desc:	CEMENTED
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304345
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304355
Layer:	2
Plug From:	0.5
Plug To:	14.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304356
Layer:	3
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304354
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID: 1004304353
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004304342
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004304349
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004304350
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.2799999713897705

Water Details

Water ID: 1004304348
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004304347
Diameter: 4.5
Depth From: 0.0
Depth To: 25.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003761093
Depth M: 7.62
Year Completed: 2012
Well Completed Dt: 2012/03/08
Audit No: Z147207
Tag No: A132372
Contractor: 7241
Path: 718\7180722.pdf
Latitude: 43.720588774756
Longitude: -79.4682652752323

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
105	1 of 1	SW/267.8	180.8 / -2.56	112-120 ORFUS RD NORTH YORK ON	WWIS

Well ID: 6929662
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z40264
Tag: A034570
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06-Dec-2005 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/692\6929662.pdf

Additional Detail(s) (Map)

Well Completed Date: 2005/11/03
Year Completed: 2005
Depth (m): 5.9
Latitude: 43.7188821612576
Longitude: -79.4672287276531
Path: 692\6929662.pdf

Bore Hole Information

Bore Hole ID: 11328631
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03-Nov-2005 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623468.00
North83: 4841792.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933039908
Layer: 3
Color: 2
General Color: GREY

Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 3.9000000953674316
Formation End Depth: 5.900000095367432
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933039907
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 0.20000000298023224
Formation End Depth: 3.9000000953674316
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933039906
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.20000000298023224
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933282718
Layer: 1
Plug From: 0.0
Plug To: 2.5999999046325684
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 966929662
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11343486
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930873644
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.9000000953674316
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933415890
Layer: 1
Slot: 10
Screen Top Depth: 2.9000000953674316
Screen End Depth: 5.900000095367432
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID: 934068633
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 5.599999904632568
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11549747
Diameter: 15.0
Depth From: 0.0
Depth To: 5.900000095367432
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 11328631
Depth M: 5.9
Year Completed: 2005
Well Completed Dt: 2005/11/03
Audit No: Z40264
Tag No: A034570
Contractor: 6607
Path: 692\6929662.pdf
Latitude: 43.7188821612576
Longitude: -79.4672287276531

106 ***1 of 1*** ***WSW/268.9*** ***180.7 / -2.67*** ***1245 CALEDONIA RD Toronto ON*** ***WWIS***

Well ID: 7181269
Construction Date:
Flowing (Y/N):
Flow Rate:

Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	18-May-2012 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z148236	**Contractor:**	7241
Tag:	A125728	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: NORTH YORK BOROUGH
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7181269.pdf

Additional Detail(s) (Map)

Well Completed Date: 2012/04/13
Year Completed: 2012
Depth (m): 11.7348
Latitude: 43.7205166025821
Longitude: -79.4682546998136
Path: 718\7181269.pdf

Bore Hole Information

Bore Hole ID:	1003791343	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623382.00
Code OB Desc:		**North83:**	4841972.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	13-Apr-2012 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004316061
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2: 60
Mat2 Desc: CEMENTED
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0

Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004316063
Layer: 3
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 1.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004316064
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 15.0
Formation End Depth: 38.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004316062
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004316072
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004316073
Layer:	2
Plug From:	0.5
Plug To:	27.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004316074
Layer:	3
Plug From:	27.5
Plug To:	38.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004316071
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004316060
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004316067
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	28.5
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004316068
Layer:	1
Slot:	10
Screen Top Depth:	28.5
Screen End Depth:	38.5
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.2799999713897705

Water Details

Water ID:	1004316066
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004316065
Diameter:	4.5
Depth From:	0.0
Depth To:	38.5
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003791343	**Tag No:**	A125728
Depth M:	11.7348	**Contractor:**	7241
Year Completed:	2012	**Path:**	718\7181269.pdf
Well Completed Dt:	2012/04/13	**Latitude:**	43.7205166025821
Audit No:	Z148236	**Longitude:**	-79.4682546998136

---

107 ***1 of 1*** ***WNW/269.3*** ***179.8 / -3.56*** ***ON*** ***BORE***

Borehole ID:	642872	**Inclin FLG:**	No
OGF ID:	215543265	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1959	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.722374
Total Depth m:	4.9	**Longitude DD:**	-79.468547
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	623355
Drill Method:	Diamond Drill	**Northing:**	4842178
Orig Ground Elev m:	179	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	181		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218501314	**Mat Consistency:**	Hard
Top Depth:	2.2	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Stones	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,STONES. BROWN,HARD,AGE GLACIAL. 021 012 0000701000040004000720600 0 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218501311	**Mat Consistency:**	Firm
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Organic	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SILT,SAND, ORGANIC. BROWN,FIRM,AGE POST-GLACIAL.		

Geology Stratum ID:	218501312	**Mat Consistency:**	Stiff
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. BROWN,STIFF,AGE GLACIAL.		

Geology Stratum ID:	218501313	**Mat Consistency:**	Soft
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. BROWN,SOFT,AGE GLACIAL, WATER STABLE AT 587.5 FEET.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 108920 NTS_Sheet: 30M11E		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

108 | ***1 of 1*** | ***WNW/270.1*** | ***180.9 / -2.55*** | ***1289 CALEDONIA RD NORTH YORK ON*** | ***WWIS***

Well ID:	7167693	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	23-Aug-2011 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	

Audit No:	Z136669	**Contractor:**	7241
Tag:	A116717	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:	WKQ-004095		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7167693.pdf

Additional Detail(s) (Map)

Well Completed Date:	2011/08/10
Year Completed:	2011
Depth (m):	7.93
Latitude:	43.7233073267901
Longitude:	-79.4682208258793
Path:	716\7167693.pdf

Bore Hole Information

Bore Hole ID:	1003554441	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623379.00
Code OB Desc:		**North83:**	4842282.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10-Aug-2011 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003956289
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	0.6100000143051147
Formation End Depth:	5.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock

Materials Interval

Formation ID:	1003956290
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	5.570000171661377
Formation End Depth:	7.929999828338623
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1003956288
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.6100000143051147
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003956299
Layer:	2
Plug From:	0.30000001192092896
Plug To:	4.570000171661377
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003956300
Layer:	3
Plug From:	4.570000171661377
Plug To:	7.929999828338623
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003956298
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID: 1003956297
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1003956287
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003956293
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.880000114440918
Casing Diameter: 3.450000047683716
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1003956294
Layer: 1
Slot: 10
Screen Top Depth: 4.880000114440918
Screen End Depth: 7.929999828338623
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.210000038146973

Water Details

Water ID: 1003956292
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1003956291
Diameter: 8.25
Depth From: 0.0
Depth To: 7.929999828338623
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1003554441
Depth M: 7.93
Year Completed: 2011
Well Completed Dt: 2011/08/10
Tag No: A116717
Contractor: 7241
Path: 716\7167693.pdf
Latitude: 43.7233073267901

Audit No:	Z136669			**Longitude:**	-79.4682208258793

109 **1 of 1** **WSW/270.4** **180.8 / -2.56** **1245 CALEDONIA RD Toronto ON** **WWIS**

Well ID:	7180725	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	10-May-2012 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z147204	**Contractor:**	7241
Tag:	A132371	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7180725.pdf

Additional Detail(s) (Map)

Well Completed Date:	2012/03/08
Year Completed:	2012
Depth (m):	7.62
Latitude:	43.7201727450192
Longitude:	-79.4681269030725
Path:	718\7180725.pdf

Bore Hole Information

Bore Hole ID:	1003761155	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623393.00
Code OB Desc:		**North83:**	4841934.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08-Mar-2012 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004304388
Layer:	1
Color:	8

General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	60
Mat3 Desc:	CEMENTED
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304390
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	1.0
Formation End Depth:	9.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304389
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.5
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004304391
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	9.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304401
Layer:	3
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304399
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004304400
Layer:	2
Plug From:	0.5
Plug To:	14.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004304398
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004304387
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004304394
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004304395
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	25.0

Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.2799999713897705

Water Details

Water ID:	1004304393
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004304392
Diameter:	4.5
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003761155	**Tag No:**	A132371
Depth M:	7.62	**Contractor:**	7241
Year Completed:	2012	**Path:**	718\7180725.pdf
Well Completed Dt:	2012/03/08	**Latitude:**	43.7201727450192
Audit No:	Z147204	**Longitude:**	-79.4681269030725

110 **1 of 1** **WSW/271.2** **180.7 / -2.67** ***1245 CALEDONIA RD Toronto ON*** ***WWIS***

Well ID:	7181104	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	18-May-2012 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z148233	**Contractor:**	7241
Tag:	A125730	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7181104.pdf

Additional Detail(s) (Map)

Well Completed Date:	2012/04/13
Year Completed:	2012
Depth (m):	7.62

Latitude:	43.7205351030716
Longitude:	-79.4682914719523
Path:	718\7181104.pdf

Bore Hole Information

Bore Hole ID:	1003788536	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623379.00
Code OB Desc:		**North83:**	4841974.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	13-Apr-2012 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004312171
Layer:	2
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Mat2 Desc:	SILT
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	10.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004312170
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	77
Mat3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312181
Layer:	3

Plug From: 14.0
Plug To: 25.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004312180
Layer: 2
Plug From: 0.5
Plug To: 14.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004312179
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004312178
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004312169
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004312174
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004312175
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.2799999713897705

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID:	1004312173
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004312172
Diameter:	8.5
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003788536	***Tag No:***	A125730
Depth M:	7.62	***Contractor:***	7241
Year Completed:	2012	***Path:***	718\7181104.pdf
Well Completed Dt:	2012/04/13	***Latitude:***	43.7205351030716
Audit No:	Z148233	***Longitude:***	-79.4682914719523

111	***1 of 7***	***W/271.3***	***179.8 / -3.56***	***BASF CANADA INC.*** ***AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD*** ***NORTH YORK ON M6A 2X7***	***GEN***

Generator No:	ON0102119
SIC Code:	6341
SIC Description:	HOME/AUTO. SUPPLY
Approval Years:	93,94,95,96
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

111	***2 of 7***	***W/271.3***	***179.8 / -3.56***	***BASF (OUT OF BUS)*** ***AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD*** ***NORTH YORK ON M6A 2X7***	***GEN***

Generator No:	ON0102119
SIC Code:	6341
SIC Description:	HOME/AUTO. SUPPLY
Approval Years:	97
PO Box No:	
Country:	
Status:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

111 **3 of 7** **W/271.3** **179.8 / -3.56** **BASF CANADA INC. (OUT OF BUSINESS) AUTOMOTIVE REFINISH TECHNOLOGIES 1277 CALEDONIA ROAD NORTH YORK ON M6A 2X7** **GEN**

Generator No: ON0102119
SIC Code: 6341
SIC Description: HOME/AUTO. SUPPLY
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

111 **4 of 7** **W/271.3** **179.8 / -3.56** **1277 Caledonia Rd Toronto ON** **SPL**

Ref No: 8076-B8G3VA
Site No: NA
Incident Dt: 2019/01/15
Year:
Incident Cause:
Incident Event: Dumping
Contaminant Code: 27
Contaminant Name: FIRE SUPPRESSANT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Surface Water
MOE Response: Yes
Dt MOE Arvl on Scn: 2019/01/16
MOE Reported Dt: 2019/01/15
Dt Document Closed:
Incident Reason: Unknown / N/A
Site Name: Catchbasin<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Fire Foam Dumped to Catchbasin
Contaminant Qty: 0 other - see incident description

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address: 1277 Caledonia Rd
Site District Office: Toronto - District
Site Postal Code:
Site Region: Central
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing: 4842078.3
Easting: 623316.73
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Primary Assessment of Spills
Source Type: Other

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
111	5 of 7	W/271.3	179.8 / -3.56	732090 Ontario LTD 1277 Caledonia Road Toronto ON M6A2X7	GEN

Generator No: ON8041541
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
111	6 of 7	W/271.3	179.8 / -3.56	1277 Caledonia Rd North York ON M6A 1V2	EHS

Order No: 20191120059
Status: C
Report Type: Standard Report
Report Date: 25-NOV-19
Date Received: 20-NOV-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.46852
Y: 43.721792

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
111	7 of 7	W/271.3	179.8 / -3.56	1277 Caledonia Rd North York ON M6A 1V2	EHS

Order No: 20191120059
Status: C
Report Type: Standard Report
Report Date: 25-NOV-19
Date Received: 20-NOV-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.46852
Y: 43.721792

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
112	1 of 1	WSW/272.6	180.8 / -2.56	167 BENTWORTH AVE NORTH YORK ON	WWIS

Well ID: 7316357
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z285993
Tag: A247819
Constructn Method:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 13-Aug-2018 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7320
Form Version: 7
Owner:

Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2018/06/21
Year Completed:	2018
Depth (m):	25
Latitude:	43.7195208659978
Longitude:	-79.4678579861153
Path:	

Bore Hole Information

Bore Hole ID:	1007245409	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623416.00
Code OB Desc:		**North83:**	4841862.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	21-Jun-2018 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007510587
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	34
Mat2 Desc:	TILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	17.0
Formation End Depth:	25.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007510586

Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	34
Mat2 Desc:	TILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	5.0
Formation End Depth:	17.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007510585
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007510595
Layer:	1
Plug From:	0.0
Plug To:	14.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007510596
Layer:	2
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007510594
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1007510584
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007510590
Layer:	1
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007510591
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	25.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	2.0

Water Details

Water ID:	1007510589
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007510588
Diameter:	6.0
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007245409	***Tag No:***	A247819
Depth M:	25	***Contractor:***	7320
Year Completed:	2018	***Path:***	
Well Completed Dt:	2018/06/21	***Latitude:***	43.7195208659978
Audit No:	Z285993	***Longitude:***	-79.4678579861153

113 ***1 of 1*** ***ENE/274.3*** ***186.8 / 3.36*** ***102 -123 BENTWORTH AVE. NORTH YORK ON*** ***WWIS***

Well ID:	7149493	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	05-Aug-2010 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	

Audit No:	Z118940	**Contractor:**	7241
Tag:	A102880	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7149493.pdf

Additional Detail(s) (Map)

Well Completed Date:	2010/07/19
Year Completed:	2010
Depth (m):	2.04216
Latitude:	43.7219885235078
Longitude:	-79.461202814836
Path:	714\7149493.pdf

Bore Hole Information

Bore Hole ID:	1003269405	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623947.00
Code OB Desc:		**North83:**	4842146.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	19-Jul-2010 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003313055
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	4.900000095367432
Formation End Depth:	6.699999809265137
Formation End Depth UOM:	ft

Overburden and Bedrock

Materials Interval

Formation ID:	1003313054
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	1.8200000524520874
Formation End Depth:	4.900000095367432
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003313053
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	1.8200000524520874
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003313058
Layer:	2
Plug From:	0.3100000023841858
Plug To:	3.700000047683716
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003313059
Layer:	3
Plug From:	3.700000047683716
Plug To:	6.699999809265137
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003313057
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID: 1003313063
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1003313052
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003313061
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.700000047683716
Casing Diameter: 5.199999809265137
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003313062
Layer: 1
Slot: 10
Screen Top Depth: 3.700000047683716
Screen End Depth: 6.699999809265137
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1003313060
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003313056
Diameter: 10.920000076293945
Depth From: 0.0
Depth To: 6.699999809265137
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003269405
Depth M: 2.04216
Year Completed: 2010
Well Completed Dt: 2010/07/19
Tag No: A102880
Contractor: 7241
Path: 714\7149493.pdf
Latitude: 43.7219885235078

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No: Z118940 **Longitude:** -79.461202814836

114 **1 of 3** **S/274.4** **180.2 / -3.25** **FANCY DIAMOND JEWELLERY LTD.** **SCT**
103 ORFUS RD
NORTH YORK ON M6A 1M4

Established: 1986
Plant Size (ft²): 5000
Employment: 3

--Details--
Description: Jewellery and Watch Wholesaler-Distributors
SIC/NAICS Code: 414410

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Description: JEWELLERY, PRECIOUS METAL
SIC/NAICS Code: 3911

Description: JEWELLERY, WATCHES, PRECIOUS STONES, AND PRECIOUS METALS
SIC/NAICS Code: 5094

Description: NONDURABLE GOODS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5199

Description: Jewellery and Silverware Manufacturing
SIC/NAICS Code: 339910

---

114 **2 of 3** **S/274.4** **180.2 / -3.25** **EDWARD DWORKIN DISTRIBUTORS** **SCT**
103 ORFUS RD
TORONTO ON M6A 1M4

Established: 1904
Plant Size (ft²): 15000
Employment: 16

--Details--
Description: HARDWARE
SIC/NAICS Code: 5072

Description: JEWELLERY, WATCHES, PRECIOUS STONES & PRECIOUS METALS
SIC/NAICS Code: 5094

Description: STATIONERY & OFFICE SUPPLIES
SIC/NAICS Code: 5112

---

114 **3 of 3** **S/274.4** **180.2 / -3.25** **Beebed Realty** **GEN**
103 Orphus Rd.
Toronto ON

Generator No: ON1315922
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

115 **1 of 1** **SSW/275.2** **180.0 / -3.45** **TORONTO BARBER & BEAUTY SUPPLY** **SCT**
112 ORFUS RD
TORONTO ON M6A 1L9

Established: 1937
Plant Size (ft²): 15000
Employment: 50

--Details--
Description: SERVICE ESTABLISHMENT EQUIPMENT & SUPPLIES
SIC/NAICS Code: 5087

---

116 **1 of 1** **SW/275.4** **180.8 / -2.56** **167 BENTWORTH AVE** **WWIS**
NORTH YORK ON

Well ID: 7316356
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z285991
Tag: A247741
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 13-Aug-2018 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7320
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2018/06/21
Year Completed: 2018
Depth (m): 15
Latitude: 43.7190026659251
Longitude: -79.4674863533886
Path:

Bore Hole Information

Bore Hole ID: 1007245392
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 21-Jun-2018 00:00:00

Elevation:
Elevrc:
Zone: 17
East83: 623447.00
North83: 4841805.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m

Remarks: ***Location Method:*** wwr
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007510562
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 14.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007510563
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 14.0
Formation End Depth: 15.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007510561
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007510571
Layer: 1
Plug From: 0.0
Plug To: 4.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007510572
Layer: 2
Plug From: 4.0
Plug To: 15.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007510570
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1007510560
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007510566
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: -3.0
Depth To: 5.0
Casing Diameter: 2.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007510567
Layer: 1
Slot: 10
Screen Top Depth: 5.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 2.0

Water Details

Water ID: 1007510565
Layer: 1
Kind Code: 8
Kind: Untested

Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007510564
Diameter: 6.0
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1007245392
Depth M: 15
Year Completed: 2018
Well Completed Dt: 2018/06/21
Audit No: Z285991
Tag No: A247741
Contractor: 7320
Path:
Latitude: 43.7190026659251
Longitude: -79.4674863533886

---

117 ***1 of 1*** ***WSW/276.2*** ***180.5 / -2.87*** ***1245 CALEDONIA RD Toronto ON*** ***WWIS***

Well ID: 7181105
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z148234
Tag: A125729
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 18-May-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/718\7181105.pdf

Additional Detail(s) (Map)

Well Completed Date: 2012/04/13
Year Completed: 2012
Depth (m): 7.62
Latitude: 43.7204997655135
Longitude: -79.4683420304826
Path: 718\7181105.pdf

Bore Hole Information

Bore Hole ID: 1003788550
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Elevation:
Elevrc:
Zone: 17
East83: 623375.00
North83: 4841970.00

Open Hole:
Cluster Kind:
Date Completed: 13-Apr-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004312184
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004312186
Layer: 4
Color: 2
General Color: GREY
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 15.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004312185
Layer: 3
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 1.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1004312183
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	60
Mat2 Desc:	CEMENTED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312196
Layer:	3
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312194
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004312195
Layer:	2
Plug From:	0.5
Plug To:	14.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004312193
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004312182
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004312189
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004312190
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	25.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.2799999713897705

Water Details

Water ID:	1004312188
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004312187
Diameter:	4.5
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1003788550	***Tag No:***	A125729
Depth M:	7.62	***Contractor:***	7241
Year Completed:	2012	***Path:***	718\7181105.pdf
Well Completed Dt:	2012/04/13	***Latitude:***	43.7204997655135
Audit No:	Z148234	***Longitude:***	-79.4683420304826

118 ***1 of 2*** ***W/276.4*** ***179.8 / -3.56*** ***1277 Caledonia Road North York ON M6A 1V2*** ***EHS***

Order No:	20200521073	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	26-MAY-20	***Search Radius (km):***	.2
Date Received:	21-MAY-20	***X:***	-79.46858267
Previous Site Name:		***Y:***	43.72178399
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	2 of 2	W/276.4	179.8 / -3.56	1277 Caledonia Road North York ON M6A 1V2	EHS

Order No: 20200521073
Status: C
Report Type: Custom Report
Report Date: 26-MAY-20
Date Received: 21-MAY-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .2
X: -79.46858267
Y: 43.72178399

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
119	1 of 4	WSW/277.4	180.8 / -2.56	CALEDONIA MARBLE COMPANY LTD. 176 BENTWORTH AVENUE TORONTO ON M6A 1P7	GEN

Generator No: ON0043100
SIC Code: 0813
SIC Description: MARBLE QUARRIES
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
119	2 of 4	WSW/277.4	180.8 / -2.56	CALEDONIA (OUT OF BUS) 07-054 176 BENTWORTH AVENUE TORONTO ON M6A 1P7	GEN

Generator No: ON0043100
SIC Code: 0813
SIC Description: MARBLE QUARRIES
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
119	3 of 4	WSW/277.4	180.8 / -2.56	CALEDONIA MARBLE CO. (OUT OF BUSINESS) 176 BENTWORTH AVENUE TORONTO ON M6A 1P7	GEN

Generator No: ON0043100
SIC Code: 0813
SIC Description: MARBLE QUARRIES
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

---

119 | **4 of 4** | **WSW/277.4** | **180.8 / -2.56** | **176 Bentworth Avenue North York ON M6A 1P7** | **EHS**

Order No: 20190610065
Status: C
Report Type: Standard Report
Report Date: 13-JUN-19
Date Received: 10-JUN-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.468169
Y: 43.720057

---

120 | **1 of 1** | **S/278.0** | **180.8 / -2.56** | **80 DUFFLAW Toronto ON** | **WWIS**

Well ID: 7173825
Construction Date:
Use 1st: Test Hole
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z133618
Tag: A113927
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 27-Dec-2011 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7173825.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/10/13
Year Completed: 2011
Depth (m): 4.8768
Latitude: 43.7179842748145

Longitude: -79.4647315799656
Path: 717\7173825.pdf

Bore Hole Information

Bore Hole ID: 1003625082
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 13-Oct-2011 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623671.00
North83: 4841696.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004084664
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 6.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004084666
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 12.0
Formation End Depth: 16.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004084665
Layer: 2
Color: 6

General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Mat2 Desc:	
Mat3:	68
Mat3 Desc:	DRY
Formation Top Depth:	6.0
Formation End Depth:	12.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004084675
Layer:	2
Plug From:	5.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004084676
Layer:	3
Plug From:	1.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004084674
Layer:	1
Plug From:	16.0
Plug To:	5.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004084673
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1004084663
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004084670
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	6.0
Depth To:	1.0

Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004084671
Layer: 1
Slot: 10
Screen Top Depth: 16.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1004084669
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004084668
Diameter: 8.0
Depth From: 0.0
Depth To: 1.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1004084667
Diameter: 4.0
Depth From: 1.0
Depth To: 16.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1003625082
Depth M: 4.8768
Year Completed: 2011
Well Completed Dt: 2011/10/13
Audit No: Z133618
Tag No: A113927
Contractor: 7215
Path: 717\7173825.pdf
Latitude: 43.7179842748145
Longitude: -79.4647315799656

---

121 ***1 of 3*** ***SW/278.8*** ***180.8 / -2.56*** ***CALEDONIA MARBLE COMPANY LTD.***
167 BENTWORTH AVENUE
TORONTO ON M6A 1P6 ***GEN***

Generator No: ON0043101
SIC Code: 3599
SIC Description: OTHER NON-METAL PROD
Approval Years: 93,94,95,96,97,98,99,00,01
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

---

121 ***2 of 3*** ***SW/278.8*** ***180.8 / -2.56*** ***Caledonia Marble Co Ltd*** ***GEN***
167 Bentworth Ave.
Toronto ON M6A 1P7

Generator No: ON4530869
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 221 L
Waste Class Name: Light fuels

---

121 ***3 of 3*** ***SW/278.8*** ***180.8 / -2.56*** ***Caledonia Marble Co Ltd*** ***GEN***
167 Bentworth Ave.
Toronto ON M6A 1P7

Generator No: ON4530869
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 150 L
Waste Class Name: Inert organic wastes

---

122 **1 of 1** **ESE/280.0** **182.9 / -0.53** **ON** **BORE**

Borehole ID: 646981
OGF ID: 215547363
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: FEB-1965
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 5
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 182
Elev Reliabil Note:
DEM Ground Elev m: 181
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.719751
Longitude DD: -79.460916
UTM Zone: 17
Easting: 623975
Northing: 4841898
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218517151
Top Depth: 0
Bottom Depth: .1
Material Color:
Material 1: Asphalt
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: ASPHALT.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218517153
Top Depth: 1.5
Bottom Depth: 5
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4:
Gsc Material Description:
Stratum Description: TILL,SILT,SAND. GREY,BROWN,GLACIAL,DENSE, AGE GLACIAL. 013 010 00003026000500 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218517152
Top Depth: .1
Bottom Depth: 1.5
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Clay
Material 4:
Gsc Material Description:

Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Stratum Description: TILL,SILT,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 150070 NTS_Sheet: 30M11E
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

123 ***1 of 2*** ***E/280.4*** ***186.7 / 3.28*** ***Simcoe Fluid Power Inc.***
61 McAdam Ave
Toronto ON M6A 1S6 ***SCT***

Established: 01-AUG-84
Plant Size (ft²): 2500
Employment:

--Details--
Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

Description: All Other Building Equipment Contractors
SIC/NAICS Code: 238299

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Metal Valve Manufacturing
SIC/NAICS Code: 332910

Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
SIC/NAICS Code: 811310

Description: Industrial Design Services
SIC/NAICS Code: 541420

---

123 ***2 of 2*** ***E/280.4*** ***186.7 / 3.28*** ***ALESSANDRO GERALDO, DEBORA CANTANHEDE***
61 McAdam AV
Toronto ON M6A 1S6 ***EASR***

Approval No:	R-004-6110362180	***MOE District:***	Metro Toronto
Status:	REGISTERED	***Municipality:***	Toronto
Date:	2018-02-11	***Latitude:***	43.72138889
Record Type:	EASR	***Longitude:***	-79.46083333
Link Source:	MOFA	***Geometry X:***	
Project Type:	Waste Management System	***Geometry Y:***	
Full Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Approval Type:		EASR-Waste Management System			
SWP Area Name:		Toronto			
PDF URL:					
PDF Site Location:					
124	1 of 3	NW/282.9	181.8 / -1.58	CURTIS PROPERTIES SUITE 101; 201 BRIDEGLAND AVE. SUITE 101; 201 BRIDGELAND AVE. TORONTO ON M6A 1Y7	NPCB
Company Code:		O1032			
Industry:		Other			
Site Status:					
Transaction Date:		10/18/1993			
Inspection Date:					
124	2 of 3	NW/282.9	181.8 / -1.58	ANGEL DANCE WEAR INC 201 BRIDGELAND AVE UNIT 3 TORONTO ON M6A 1Y7	SCT
Established:		1959			
Plant Size (ft²):					
Employment:		5			
--Details--					
Description:		WOMEN'S FULL-LENGTH & KNEE-LENGTH HOSIERY			
SIC/NAICS Code:		2251			
124	3 of 3	NW/282.9	181.8 / -1.58	Zeifmans LLP 201 Bridgeland Ave Toronto ON M6A 1Y7	GEN
Generator No:		ON9057533			
SIC Code:		541212			
SIC Description:		Offices of Accountants			
Approval Years:		2010			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
125	1 of 1	SW/285.2	180.0 / -3.37	LOUIS INTERIORS INC 120 ORFUS RD TORONTO ON M6A 1L9	SCT
Established:		1961			
Plant Size (ft²):					
Employment:		30			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: FURNITURE
SIC/NAICS Code: 5021

---

126 | ***1 of 6*** | ***WSW/285.8*** | ***180.8 / -2.56*** | ***Galaxy Silk Screening Design*** ***1245 Caledonia Rd*** ***Toronto ON M6A 2X6*** | ***SCT***

Established: 01-AUG-94
Plant Size (ft²): 7500
Employment:

--Details--
Description: Textile and Fabric Finishing
SIC/NAICS Code: 313310

---

126 | ***2 of 6*** | ***WSW/285.8*** | ***180.8 / -2.56*** | ***GALAXY SILK SCREENING INC.*** ***1245 CALEDONIA ROAD*** ***TORONTO ON M6A 2X6*** | ***GEN***

Generator No: ON2873737
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

126 | ***3 of 6*** | ***WSW/285.8*** | ***180.8 / -2.56*** | ***Finer Fabrics Ltd*** ***1245 Caledonia Rd*** ***Toronto ON M6A 2X6*** | ***GEN***

Generator No: ON9520098
SIC Code: 562990
SIC Description: All Other Waste Management Services
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
126	4 of 6	WSW/285.8	180.8 / -2.56	GREEN GALAXY COMPANIES 1245 CALEDONIA ROAD TORONTO ON M6A 2X6	GEN

Generator No: ON2873737
SIC Code: 323113
SIC Description: Commercial Screen Printing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
126	5 of 6	WSW/285.8	180.8 / -2.56	GREEN GALAXY COMPANIES 1245 CALEDONIA ROAD TORONTO ON M6A 2X6	GEN

Generator No: ON2873737
SIC Code: 323113
SIC Description: Commercial Screen Printing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
126	6 of 6	WSW/285.8	180.8 / -2.56	GREEN GALAXY COMPANIES 1245 CALEDONIA ROAD TORONTO ON M6A 2X6	GEN

Generator No: ON2873737
SIC Code: 323113
SIC Description: Commercial Screen Printing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

127 | ***1 of 1*** | ***W/286.3*** | ***179.8 / -3.56*** | ***1277 Caledonia rd Toronto ON*** | ***WWIS***

Well ID: 7365301
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z339602
Tag: A294680
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 14-Aug-2020 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008444231
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Jun-2020 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623344.00
North83: 4842107.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008747157
Layer: 1
Color: 2
General Color: GREY

Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.4000000059604645
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008747158
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0.4000000059604645
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008747159
Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 05
Mat3 Desc: CLAY
Formation Top Depth: 5.0
Formation End Depth: 23.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747211
Layer: 2
Plug From: 12.0
Plug To: 23.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747210
Layer: 1
Plug From: 0.0
Plug To: 12.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:	1008747270
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	direct push

Pipe Information

Pipe ID:	1008747098
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008747290
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	13.0
Casing Diameter:	1.5
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008747311
Layer:	1
Slot:	.10
Screen Top Depth:	13.0
Screen End Depth:	23.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	1.75

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008747331
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008747250

Diameter:	3.25
Depth From:	0.0
Depth To:	23.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1008444231	**Tag No:**	A294680
Depth M:	7.0104	**Contractor:**	7241
Year Completed:	2020	**Path:**	
Well Completed Dt:	2020/06/11	**Latitude:**	43.7217380212444
Audit No:	Z339602	**Longitude:**	-79.4686953356493

---

128 ***1 of 1*** ***NNW/286.3*** ***182.9 / -0.49*** ***185 Bridgeland Avenue North York ON M6A 2V1*** ***EHS***

Order No:	20190128020	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	31-JAN-19	**Search Radius (km):**	.25
Date Received:	28-JAN-19	**X:**	-79.466293
Previous Site Name:		**Y:**	43.724694
Lot/Building Size:			
Additional Info Ordered:			

---

129 ***1 of 1*** ***WSW/286.7*** ***180.8 / -2.56*** ***ON*** ***WWIS***

Well ID:	7343059	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	30-Sep-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C46017	**Contractor:**	7215
Tag:	A269278	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	YORK
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2019/08/06
Year Completed:	2019
Depth (m):	
Latitude:	43.7198948868939
Longitude:	-79.4682208847406
Path:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole Information

Bore Hole ID:	1007658565	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	623386.00
Code OB Desc:		***North83:***	4841903.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06-Aug-2019 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1007658565	***Tag No:***	A269278
Depth M:		***Contractor:***	7215
Year Completed:	2019	***Path:***	
Well Completed Dt:	2019/08/06	***Latitude:***	43.7198948868939
Audit No:	C46017	***Longitude:***	-79.4682208847406

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	1 of 1	SSE/286.7	180.8 / -2.56	Dufflaw Rd Orfus Rd Toronto ON	EHS

Order No:	20160926193	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	BC
Report Date:	03-OCT-16	***Search Radius (km):***	.25
Date Received:	26-SEP-16	***X:***	-79.46395
Previous Site Name:		***Y:***	43.717971
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	1 of 3	WSW/287.1	180.8 / -2.56	ULTRAMAR CANADA LTD. 171 BENTWORTH AVENUE CARDLOCK SITE 00235 TORONTO ON M6A 1P6	GEN

Generator No:	ON0177958
SIC Code:	3611
SIC Description:	REFINED PETRO. PROD.
Approval Years:	95,96,97
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	2 of 3	WSW/287.1	180.8 / -2.56	ULTRAMAR CANADA LTD. ULTRAMAR CARDLOCK - SITE 00235 171 BENTWORTH AVENUE TORONTO ON M6A 1P6	GEN

Generator No: ON0177958
SIC Code: 3611
SIC Description: REFINED PETRO. PROD.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	3 of 3	WSW/287.1	180.8 / -2.56	ULTRAMAR CANADA INC 171 BENTWORTH AV TORONTO ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10139742
Status: EXPIRED
Instance ID: 12616
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Gasoline Station - Card/Keylock
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
132	1 of 1	WNW/288.5	180.9 / -2.53	245 BROADLAND AVE Toronto ON	WWIS

Well ID: 7191352
Construction Date:
Use 1st: Test Hole
Use 2nd:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z157932
Tag: A137936
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 14-Nov-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7320
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2012/10/11
Year Completed: 2012
Depth (m): 6.1
Latitude: 43.7228812799487
Longitude: -79.4686786240642
Path:

Bore Hole Information

Bore Hole ID: 1004202373
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Oct-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623343.00
North83: 4842234.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004502843
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT

Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 3.299999952316284
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004502841
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.6000000238418579
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004502842
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 34
Mat3 Desc: TILL
Formation Top Depth: 0.6000000238418579
Formation End Depth: 3.299999952316284
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004502851
Layer: 2
Plug From: 0.15000000596046448
Plug To: 2.700000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004502852
Layer: 3
Plug From: 2.700000047683716
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004502850
Layer: 1
Plug From: 0.0
Plug To: 0.15000000596046448
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004502849
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004502840
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004502846
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004502847
Layer: 1
Slot: 010
Screen Top Depth: 3.0
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID: 1004502845
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.299999952316284
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004502844
Diameter: 16.0
Depth From: 0.0
Depth To: 6.099999904632568

Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID:	1004202373	**Tag No:**	A137936
Depth M:	6.1	**Contractor:**	7320
Year Completed:	2012	**Path:**	719\7191352.pdf
Well Completed Dt:	2012/10/11	**Latitude:**	43.7228812799487
Audit No:	Z157932	**Longitude:**	-79.4686786240642

---

133 ***1 of 4*** ***WNW/289.2*** ***179.8 / -3.56*** ***PREMIER KNITWEAR INC.*** ***SCT***
1283 CALEDONIA RD
TORONTO ON M6A 2X7

Established: 1985
Plant Size (ft²): 5000
Employment: 32

--Details--
Description: KNIT OUTERWEAR MILLS
SIC/NAICS Code: 2253

---

133 ***2 of 4*** ***WNW/289.2*** ***179.8 / -3.56*** ***Louis Interiors Inc.*** ***SCT***
1283 Caledonia Rd
Toronto ON M6A 2X7

Established: 01-AUG-61
Plant Size (ft²):
Employment:

--Details--
Description: Wood Office Furniture, including Custom Architectural Woodwork, Manufacturing
SIC/NAICS Code: 337213

Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: Upholstered Household Furniture Manufacturing
SIC/NAICS Code: 337121

---

133 ***3 of 4*** ***WNW/289.2*** ***179.8 / -3.56*** ***MERIT AUTOMOTIVE PRODUCTS LTD.*** ***GEN***
1283 CALEDONIA ROAD
NORTH YORK ON M6A 2X7

Generator No: ON0589300
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

133 | ***4 of 4*** | ***WNW/289.2*** | ***179.8 / -3.56*** | ***MERIT AUTOMOTIVE PRODUCTS LTD. 26-162 1283 CALEDONIA ROAD NORTH YORK ON M6A 2X7*** | ***GEN***

Generator No: ON0589300
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

134 | ***1 of 2*** | ***NNE/290.2*** | ***185.0 / 1.59*** | ***658457 Ontario Inc. 153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6*** | ***GEN***

Generator No: ON7228449
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Irene Hamilton
Choice of Contact: CO_OFFICIAL
Phone No Admin: 4162472157 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

134 | ***2 of 2*** | ***NNE/290.2*** | ***185.0 / 1.59*** | ***658457 Ontario Inc. 153 Bridgeland Avenue Unit 14 Toronto ON M6A2Y6*** | ***GEN***

Generator No: ON7228449
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Irene Hamilton
Choice of Contact: CO_OFFICIAL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin: 4162472157 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

135 *1 of 10* *NNE/290.3* *185.0 / 1.59* ***GALAXY BAKERY*** ***153 BRIDGELAND AVE UNIT 5*** ***TORONTO ON M6A 2Y6*** *SCT*

Established: 0
Plant Size (ft²):
Employment: 10

--Details--
Description: GROCERIES & RELATED PRODUCTS, N.E.C.
SIC/NAICS Code: 5149

---

135 *2 of 10* *NNE/290.3* *185.0 / 1.59* ***HOGARTH PRINTING COMPANY LIMIT*** ***153 BRIDGELAND AVE UNIT 14*** ***TORONTO ON M6A 2Y6*** *SCT*

Established: 1954
Plant Size (ft²):
Employment: 8

--Details--
Description: COMMERCIAL PRINTING, N.E.C.
SIC/NAICS Code: 2759

---

135 *3 of 10* *NNE/290.3* *185.0 / 1.59* ***STEAM SAUNA*** ***153 Bridgeland Ave Unit 13*** ***Toronto ON M6A 2Y6*** *SCT*

Established: 1980
Plant Size (ft²): 5000
Employment: 8

--Details--
Description: Plastic Plumbing Fixture Manufacturing
SIC/NAICS Code: 326191

Description: Prefabricated Wood Building Manufacturing
SIC/NAICS Code: 321992

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

---

135 *4 of 10* *NNE/290.3* *185.0 / 1.59* ***UNITOOL Inc.*** ***153 Bridgeland Ave Unit 12*** ***North York ON M6A 2Y6*** *SCT*

Established: 1970

Plant Size (ft²):
Employment:

--Details--
Description: Hardware Wholesaler-Distributors
SIC/NAICS Code: 416330

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: All Other Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	5 of 10	NNE/290.3	185.0 / 1.59	D.S. FRASER EQUIPMENT INC. 153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	GEN

Generator No: ONC000606
SIC Code: 5622
SIC Description: PLUMBING, ETC., WH.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	6 of 10	NNE/290.3	185.0 / 1.59	D.S. FRASER EQUIPMENT INC. 48-039 153 BRIDGELAND AVE. TORONTO ON M6A 2Y6	GEN

Generator No: ONC000606
SIC Code: 5622
SIC Description: PLUMBING, ETC., WH.
Approval Years: 92,93,94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 331

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		WASTE COMPRESSED GASES			

135	7 of 10	NNE/290.3	185.0 / 1.59	**D.S. (OUT OF BUS)** **153 BRIDGELAND AVE.** **TORONTO ON M6A 2Y6**	GEN

Generator No: ONC000606
SIC Code: 5622
SIC Description: PLUMBING, ETC., WH.
Approval Years: 97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

135	8 of 10	NNE/290.3	185.0 / 1.59	**BEAUTIFUL SOUTH INC.** **153 BRIDGELAND AVENUE, UNIT 4** **TORONTO ON M6A 2Y6**	GEN

Generator No: ON2568300
SIC Code: 2499
SIC Description: OTHER CLOTHING ETC.
Approval Years: 00,01,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

135	9 of 10	NNE/290.3	185.0 / 1.59	**Steam Sauna Inc.** **153 Bridgeland Ave Unit 13** **Toronto ON M6A 2Y6**	SCT

Established: 01-AUG-74
Plant Size (ft²): 4500
Employment:

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Prefabricated Wood Building Manufacturing
SIC/NAICS Code: 321992

Description: Prefabricated Wood Building Manufacturing
SIC/NAICS Code: 321992

---

135 | **10 of 10** | **NNE/290.3** | **185.0 / 1.59** | **Rainbow Aluminum/Vinyl Prods**
153 Bridgeland Ave Unit 15
North York ON M6A 2Y6 | **SCT**

Established: 01-AUG-63
Plant Size (ft²): 11000
Employment:

--Details--
Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

---

136 | **1 of 1** | **NW/291.0** | **181.3 / -2.14** | **227 Bridgeland Avenue**
North York ON M6A 1Z4 | **EHS**

Order No: 20180620058
Status: C
Report Type: Standard Report
Report Date: 21-JUN-18
Date Received: 20-JUN-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.467605
Y: 43.724199

---

137 | **1 of 1** | **WSW/291.4** | **180.8 / -2.56** | **1215 Caledonia Road**
Toronto ON M6A 2X3 | **RSC**

RSC ID:
RA No:
RSC Type:
Curr Property Use:
Ministry District: Toronto
Filing Date: 03/09/01
Date Ack: 04/09/01
Date Returned:
Restoration Type: Generic
Soil Type: Medium/Fine
Criteria: Ind/Comm + Nonpotable
CPU Issued Sect 1686:
Asmt Roll No:
Prop ID No (PIN):
Property Municipal Address:
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant: Jacques Whitford Environment Ltd
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF:

Cert Date:
Cert Prop Use No:
Intended Prop Use:
Qual Person Name:
Stratified (Y/N): N
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
138	1 of 1	WNW/291.6	180.8 / -2.59	1289 CALEDONIA RD NORTH YORK ON	WWIS

Well ID: 7167692
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z136668
Tag: A116718
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info: WKQ-004095

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 23-Aug-2011 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7167692.pdf

Additional Detail(s) (Map)

Well Completed Date: 2011/08/10
Year Completed: 2011
Depth (m): 8.53
Latitude: 43.723257647293
Longitude: -79.4685448842487
Path: 716\7167692.pdf

Bore Hole Information

Bore Hole ID: 1003554439
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10-Aug-2011 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623353.00
North83: 4842276.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003956259
Layer: 1
Color: 6
General Color: BROWN

Mat1: 01
Most Common Material: FILL
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003956260
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 0.6100000143051147
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003956261
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Mat2 Desc: CLAY
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 4.570000171661377
Formation End Depth: 8.529999732971191
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003956271
Layer: 3
Plug From: 5.179999828338623
Plug To: 8.529999732971191
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003956269
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1003956270
Layer:	2
Plug From:	0.30000001192092896
Plug To:	5.179999828338623
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1003956268
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1003956258
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003956264
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	5.489999771118164
Casing Diameter:	3.450000047683716
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003956265
Layer:	1
Slot:	10
Screen Top Depth:	5.489999771118164
Screen End Depth:	8.529999732971191
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.210000038146973

Water Details

Water ID:	1003956263
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1003956262
Diameter:	8.25

Depth From:	0.0
Depth To:	8.529999732971191
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1003554439	**Tag No:**	A116718
Depth M:	8.53	**Contractor:**	7241
Year Completed:	2011	**Path:**	716\7167692.pdf
Well Completed Dt:	2011/08/10	**Latitude:**	43.723257647293
Audit No:	Z136668	**Longitude:**	-79.4685448842487

139 **1 of 2** **WNW/291.8** **180.9 / -2.50** **1285 Caledonia Rd Toronto ON** **SPL**

Ref No:	7566-9CTNVN	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2013/10/25	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Overflow/Surcharge	**Sector Type:**	Sewer (Private or Municipal)
Incident Event:		**Agency Involved:**	
Contaminant Code:	44	**Nearest Watercourse:**	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	1285 Caledonia Rd
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Human Health/Safety; Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/10/25	**Site Map Datum:**	
Dt Document Closed:	2013/11/13	**SAC Action Class:**	Sewage Bypasses / Overflows
Incident Reason:	Blockage	**Source Type:**	
Site Name:	sewage overflow<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Toronto - CSO due to blockage of sewer		
Contaminant Qty:	0 other - see incident description		

139 **2 of 2** **WNW/291.8** **180.9 / -2.50** **City of Toronto 1285 Caledonia Rd. Toronto ON** **SPL**

Ref No:	3722-BMDMQJ	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2020/03/04	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Municipal Government
Incident Cause:		**Sector Type:**	Municipal Sewage
Incident Event:	Overflow/Surcharge	**Agency Involved:**	
Contaminant Code:	44	**Nearest Watercourse:**	
Contaminant Name:	GREY WATER	**Site Address:**	1285 Caledonia Rd.
Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	n/a	**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land; Surface Water	**Northing:**	4842204.67
MOE Response:	No	**Easting:**	623289.78

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2020/03/04	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Watercourse Spills
Incident Reason:	Blockage	**Source Type:**	Sewer (Private or Municipal)
Site Name:	Sanitary Main Break, Impacted CB's<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Toronto Water: Sanitary Main Back-up, CB's Impacted		
Contaminant Qty:	0 other - see incident description		

---

140 | ***1 of 1*** | ***W/291.8*** | ***179.3 / -4.08*** | ***FRANK & WILLIES SERVICE CENTRE LTD***
141 CARTWRIGHT AV
TORONTO ON M6A1V4 | ***PRT***

Location ID:	15212
Type:	retail
Expiry Date:	1993-03-31
Capacity (L):	0
Licence #:	0015475001

---

141 | ***1 of 3*** | ***W/291.8*** | ***179.3 / -4.08*** | ***S & F DEMELIS CONSTRUCTION LTD.***
141 CARTWRIGHT AVENUE
TORONTO ON M6A 1V4 | ***GEN***

Generator No:	ON1593306
SIC Code:	3611
SIC Description:	REFINED PETRO. PROD.
Approval Years:	93,94,95,96,97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

---

141 | ***2 of 3*** | ***W/291.8*** | ***179.3 / -4.08*** | ***City of Toronto***
141 Cartwright Ave<UNOFFICIAL>
Toronto ON M6A 1V4 | ***SPL***

Ref No:	3543-8982MD	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Sewer
Incident Event:		**Agency Involved:**	
Contaminant Code:	44	**Nearest Watercourse:**	
Contaminant Name:	SEWAGE,RAW UNCHLORINATED	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/11/2010	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Sewage Bypasses / Overflows
Incident Reason:		**Source Type:**	
Site Name:	141 Cartwright Ave<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	City of Toronto: sewage to CB, cntd clnd		
Contaminant Qty:	0 other - see incident description		

---

141 | ***3 of 3*** | ***W/291.8*** | ***179.3 / -4.08*** | ***FRANK & WILLIES SERVICE CENTRE LTD***
141 CARTWRIGHT AV
TORONTO ON M6A 1V4 | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9494010	**Expired Date:**	3/20/1992
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

---

142 | ***1 of 1*** | ***ESE/292.3*** | ***183.5 / 0.06*** | ***ON*** | ***BORE***

Borehole ID:	642869	**Inclin FLG:**	No
OGF ID:	215543262	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.719972
Total Depth m:	6.6	**Longitude DD:**	-79.460662

Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	623995
Drill Method:	Diamond Drill	***Northing:***	4841923
Orig Ground Elev m:	182	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	181		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218501302	***Mat Consistency:***	Dense
Top Depth:	3.9	***Material Moisture:***	
Bottom Depth:	6.6	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND. GREY,GLACIAL,DENSE, AGE GLACIAL. 014 011 009 000080 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218501299	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Organic	***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL,SILT,SAND, ORGANIC. BROWN,AGE POST-GLACIAL.		

Geology Stratum ID:	218501300	***Mat Consistency:***	Compact
Top Depth:	.2	***Material Moisture:***	
Bottom Depth:	1.3	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,GRAVEL. GREY,BROWN,COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218501301	***Mat Consistency:***	Dense
Top Depth:	1.3	***Material Moisture:***	
Bottom Depth:	3.9	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND. GREY,BROWN,GLACIAL,DENSE, AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27

Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 108890 NTS_Sheet: 30M11E
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

143 **1 of 1** **W/294.1** **179.8 / -3.56** **1277 Caledonia rd Toronto ON** **WWIS**

Well ID: 7365303
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z339603
Tag: A294677
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 14-Aug-2020 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008444237
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11-Jun-2020 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 623333.00
North83: 4842124.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008747163
Layer: 1

Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.25
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008747164
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0.25
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008747165
Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 05
Mat3 Desc: CLAY
Formation Top Depth: 5.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747215
Layer: 2
Plug From: 14.0
Plug To: 25.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747214
Layer: 1
Plug From: 0.0
Plug To: 14.0

Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008747272
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: direct push

Pipe Information

Pipe ID: 1008747100
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008747292
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008747313
Layer: 1
Slot: .10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: Inch
Screen Diameter: 2.25

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008747333
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1008747252
Diameter:	6.0
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1008444237	***Tag No:***	A294677
Depth M:	7.62	***Contractor:***	7241
Year Completed:	2020	***Path:***	
Well Completed Dt:	2020/06/11	***Latitude:***	43.7218928628754
Audit No:	Z339603	***Longitude:***	-79.4688279537373

---

144 ***1 of 1*** ***W/294.6*** ***180.0 / -3.40*** ***ON*** ***BORE***

Borehole ID:	644553	***Inclin FLG:***	No
OGF ID:	215544936	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	DEC-1959	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.720529
Total Depth m:	9.4	***Longitude DD:***	-79.468593
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	623355
Drill Method:	Diamond Drill	***Northing:***	4841973
Orig Ground Elev m:	29.7	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	180		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218508001	***Mat Consistency:***	Dense
Top Depth:	4.3	***Material Moisture:***	
Bottom Depth:	9.4	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. GREY,GLACIAL,DENSE, AGE GLACIAL. 00000020000650600014004O **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218507999	***Mat Consistency:***	Dense
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SILT,SAND,CLAY. BROWN,FLUVIO-GLACIAL,DENSE.

Geology Stratum ID: 218508000
Top Depth: 2
Bottom Depth: 4.3
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3: Gravel
Material 4: Clay
Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Gsc Material Description:
Stratum Description: SILT,SAND,GRAVEL, CLAY. GREY,BROWN,GLACIAL,DENSE, AGE GLACIAL.

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 125750 NTS_Sheet: 30M11E
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

145 | ***1 of 1*** | ***W/294.9*** | ***179.7 / -3.71*** | ***1277 Caledonia rd Toronto ON*** | ***WWIS***

Well ID: 7365302
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z339601
Tag: A294679
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NORTH YORK BOROUGH
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 14-Aug-2020 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: YORK
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008444234
DP2BR:
Elevation:
Elevrc:

Spatial Status:		**Zone:**	17
Code OB:		**East83:**	623338.00
Code OB Desc:		**North83:**	4842095.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11-Jun-2020 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008747160
Layer:	1
Color:	2
General Color:	GREY
Mat1:	
Most Common Material:	
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.4000000059604645
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008747161
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.4000000059604645
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008747162
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	05
Mat3 Desc:	CLAY
Formation Top Depth:	5.0

Formation End Depth: 23.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747212
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008747213
Layer: 2
Plug From: 9.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008747271
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: direct push

Pipe Information

Pipe ID: 1008747099
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008747291
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008747312
Layer: 1
Slot: .10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: Inch
Screen Diameter: 2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008747332
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008747251
Diameter:	6.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Links

Bore Hole ID:	1008444234	***Tag No:***	A294679
Depth M:	7.0104	***Contractor:***	7241
Year Completed:	2020	***Path:***	
Well Completed Dt:	2020/06/11	***Latitude:***	43.7216310102846
Audit No:	Z339601	***Longitude:***	-79.4687725503677

---

146 ***1 of 4*** ***WSW/295.0*** ***180.8 / -2.56*** ***DUNMET PRODUCTS (1988) LTD.***
178 BENTWORTH AVE
NORTH YORK ON M6A 1P7 ***SCT***

Established:	1960
Plant Size (ft²):	5000
Employment:	6

--Details--

Description:	SHEET METAL WORK
SIC/NAICS Code:	3444
Description:	WARM AIR HEATING & AIR-CONDITIONING EQUIPMENT AND SUPPLIES
SIC/NAICS Code:	5075

---

146 ***2 of 4*** ***WSW/295.0*** ***180.8 / -2.56*** ***Dunmet Products (1998) Ltd.***
178 Bentworth Ave
North York ON M6A 1P7 ***SCT***

Established:	1960
Plant Size (ft²):	5000
Employment:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Plumbing, Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 416120

Description: Power Boiler and Heat Exchanger Manufacturing
SIC/NAICS Code: 332410

---

146 ***3 of 4*** ***WSW/295.0*** ***180.8 / -2.56*** ***178-180 Bentworth Avenue Toronto ON M6A 1P7*** ***EHS***

Order No: 20050525030
Status: C
Report Type:
Report Date: 5/27/2005
Date Received: 5/25/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: Caledonia Road
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.468348
Y: 43.719829

---

146 ***4 of 4*** ***WSW/295.0*** ***180.8 / -2.56*** ***178-180 Bentworth Avenue Toronto ON M6A 1P7*** ***EHS***

Order No: 20081104062
Status: C
Report Type: Standard Report
Report Date: 11/13/2008
Date Received: 11/4/2008
Previous Site Name:
Lot/Building Size: 5000 sq ft building, 83-150 ft lot
Additional Info Ordered: City Directory

Nearest Intersection: Bentworth Ave and Caledonia
Municipality: Toronto
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.468407
Y: 43.719928

---

147 ***1 of 5*** ***SE/295.0*** ***181.8 / -1.59*** ***ROTHMANS OF PALL MALL CANADA LTD BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4*** ***GEN***

Generator No: ON0151900
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		WASTE OILS & LUBRICANTS			
147	2 of 5	SE/295.0	181.8 / -1.59	ROTHMANS BENSON & HEDGES INC. BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	GEN

Generator No: ON0151900
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 88
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
147	3 of 5	SE/295.0	181.8 / -1.59	ROTHMANS (OUT OF BUSINESS) BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	GEN

Generator No: ON0151900
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
147	4 of 5	SE/295.0	181.8 / -1.59	ROTHMANS (OUT OF BUSINESS) 33-040 BENSON & HEDGES 67-75 DUFFLAW ROAD TORONTO ON M6A 2W4	GEN

Generator No: ON0151900
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

147 | **5 of 5** | **SE/295.0** | **181.8 / -1.59** | **ROTHMANS BENSON & HEDGES(OUT OF BUS.)**
67-75 DUFFLAW ROAD
TORONTO ON M6A 2W4 | **GEN**

Generator No: ON0151900
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

148 | **1 of 1** | **NW/295.6** | **181.5 / -1.95** | **225 Bridgeland Ave**
Toronto ON M6A 1Y7 | **EHS**

Order No: 20081204010
Status: C
Report Type: Standard Report
Report Date: 12/8/2008
Date Received: 12/4/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Supplementary Anderson Report
Nearest Intersection: Bridgeland Ave and Caledonia Rd
Municipality: Municipality of York
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.467413
Y: 43.724443

---

149 | **1 of 2** | **ESE/296.0** | **183.2 / -0.24** | **TORONTO DISTRICT SCHOOL BOARD**
YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD
TORONTO ON M6A 1L6 | **GEN**

Generator No: ON0195005
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

149	2 of 2	ESE/296.0	183.2 / -0.24	TORONTO DISTRICT SCHOOL BOARD YORKDALE SECONDARY SCHOOL 38 ORFUS ROAD TORONTO ON M6A 1L6	GEN

Generator No: ON0195005
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243 D
Waste Class Name: PCBS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

150 **1 of 1** **W/296.3** **179.8 / -3.56** **ON** **BORE**

Borehole ID:	642870	**Inclin FLG:**	No
OGF ID:	215543263	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1959	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.721703
Total Depth m:	6.4	**Longitude DD:**	-79.468812
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	623335
Drill Method:	Diamond Drill	**Northing:**	4842103
Orig Ground Elev m:	178	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	178		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218501304	**Mat Consistency:**	Hard
Top Depth:	.2	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Stones	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,STONES, CLAY. BROWN,HARD,AGE GLACIAL.		

Geology Stratum ID:	218501305	**Mat Consistency:**	Soft
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,GRAVEL. GREY,VERY SOFT,AGE GLACIAL. 012 011 0000504700142027 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218501303	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SILT,SAND, STONES. BROWN,LOOSE,AGE POST-GLACIAL.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 108900 NTS_Sheet: 30M11E		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

151 | ***1 of 1*** | ***SE/297.3*** | ***181.8 / -1.59*** | ***67 & 75 Dufflaw Rd & 65 Orfus Rd_Toronto (ERIS)*** ***North York ON M6A 1L7*** | ***EHS***

Order No:	20190503200	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	10-MAY-19	***Search Radius (km):***	.25
Date Received:	03-MAY-19	***X:***	-79.462267
Previous Site Name:		***Y:***	43.718329
Lot/Building Size:			
Additional Info Ordered:			

---

152 | ***1 of 1*** | ***WNW/298.4*** | ***180.8 / -2.63*** | ***245 BRIDGELAND AVE Toronto ON*** | ***WWIS***

Well ID:	7286370	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Test Hole	***Data Entry Status:***	
Use 2nd:	Monitoring	***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	11-May-2017 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z258064	***Contractor:***	7241
Tag:	A208905	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	YORK
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NORTH YORK BOROUGH		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2017/04/27
Year Completed: 2017
Depth (m): 6.4008
Latitude: 43.7233928244961
Longitude: -79.4685538550466
Path:

Bore Hole Information

Bore Hole ID: 1006442366
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 27-Apr-2017 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 623352.00
North83: 4842291.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006673703
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 15.0
Formation End Depth: 21.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006673702
Layer: 3
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006673700
Layer: 1
Color: 8
General Color: BLACK
Mat1: 27
Most Common Material: OTHER
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006673701
Layer: 2
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 2.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006673711
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006673712
Layer: 2
Plug From: 0.5
Plug To: 10.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006673713
Layer: 3
Plug From: 10.0
Plug To: 21.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006673710
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1006673699
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006673706
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 11.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006673707
Layer: 1
Slot: 10
Screen Top Depth: 11.0
Screen End Depth: 21.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1006673705
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006673704
Diameter: 6.0
Depth From: 0.0
Depth To: 21.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1006442366
Depth M: 6.4008
Year Completed: 2017
Well Completed Dt: 2017/04/27
Audit No: Z258064
Tag No: A208905
Contractor: 7241
Path: 728\7286370.pdf
Latitude: 43.7233928244961
Longitude: -79.4685538550466

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	1 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave North York ON M6A 1Y7	SCT

Established: 01-AUG-95
Plant Size (ft²): 40000
Employment:

--Details--
Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	2 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Avenue Toronto M6A 1Y7 CITY OF TORONTO ON	EBR

EBR Registry No: 011-1127
Ministry Ref No: 2853-88XRM9
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 24, 2011
Proposal Date: September 08, 2010
Year: 2010
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Geovin Furniture Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 245 Bridgeland avenue, Toronto Ontario, Canada M6A 1Y7
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

245 Bridgeland Avenue Toronto M6A 1Y7 CITY OF TORONTO

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	3 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	CA

Certificate #: 9912-8GZL4H
Application Year: 2011
Issue Date: 5/19/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	4 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	GEN

Generator No: ON4531698
SIC Code: 337123
SIC Description: Other Wood Household Furniture Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	5 of 10	WNW/298.9	180.8 / -2.65	245 Bridgeland Ave Toronto ON M6A 1Y7	EHS

Order No: 20121207012
Status: C
Report Type: Standard Report
Report Date: 17-DEC-12
Date Received: 07-DEC-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.468369
Y: 43.723651

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	6 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	GEN

Generator No: ON4531698
SIC Code: 337123
SIC Description: Other Wood Household Furniture Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	7 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	GEN

Generator No: ON4531698
SIC Code: 337123
SIC Description: Other Wood Household Furniture Manufacturing
Approval Years: 2011

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	8 of 10	WNW/298.9	180.8 / -2.65	245 Bridgeland Avenue Ltd 245 Bridgeland Avenue Toronto ON	GEN

Generator No: ON2579910
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	9 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	GEN

Generator No: ON4531698
SIC Code: 337123
SIC Description: Other Wood Household Furniture Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	10 of 10	WNW/298.9	180.8 / -2.65	Geovin Furniture Inc. 245 Bridgeland Ave Toronto ON M6A 1Y7	ECA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No: 9912-8GZL4H
Approval Date: 2011-05-19
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Geovin Furniture Inc.
Address: 245 Bridgeland Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2853-88XRM9-14.pdf
PDF Site Location:
MOE District: Metro Toronto
City:
Longitude: -79.46829
Latitude: 43.72346
Geometry X:
Geometry Y:

---

154 | **1 of 1** | **WNW/299.0** | **180.8 / -2.65** | **245 Bridgeland Avenue Toronto ON** | **EHS**

Order No: 20170310104
Status: C
Report Type: Standard Report
Report Date: 17-MAR-17
Date Received: 10-MAR-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: BC
Search Radius (km): .25
X: -79.468369
Y: 43.723651

---

155 | **1 of 4** | **WNW/299.5** | **180.9 / -2.53** | **DOLDAN FASHIONS MFG CO LTD 1287 CALEDONIA RD NORTH YORK ON M6A 2X7** | **SCT**

Established: 1978
Plant Size (ft²): 5400
Employment: 15

--Details--
Description: LEATHER AND SHEEP-LINED CLOTHING
SIC/NAICS Code: 2386

---

155 | **2 of 4** | **WNW/299.5** | **180.9 / -2.53** | **DOLDAN FASHIONS 1287 CALEDONIA RD NORTH YORK ON M6A 2X7** | **SCT**

Established: 1979
Plant Size (ft²): 2500
Employment: 25

--Details--
Description: LEATHER & SHEEP-LINED CLOTHING
SIC/NAICS Code: 2386

---

155 | **3 of 4** | **WNW/299.5** | **180.9 / -2.53** | **DOLDAN FASHIONS MFG. CO. LTD. 1287 Caledonia Rd North York ON M6A 2X7** | **SCT**

Established: 1978
Plant Size (ft²): 5400

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 15

--Details--
Description: Fur and Leather Clothing Manufacturing
SIC/NAICS Code: 315292

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
155	4 of 4	WNW/299.5	180.9 / -2.53	Doldan Fashions Manufacturing Co. Ltd. 1287 Caledonia Rd North York ON M6A 2X7	SCT

Established: 1978
Plant Size (ft²): 5400
Employment: 15

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
156	1 of 4	NW/299.9	181.3 / -2.14	SCARBOROUGH METALS 241 BRIDGELAND AVE NORTH YORK ON M6A 1Y7	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
156	2 of 4	NW/299.9	181.3 / -2.14	SCARBOROUGH METALS 241 BRIDGELAND AVE NORTH YORK ON M6A1Y7	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone: 4162566041
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
156	3 of 4	NW/299.9	181.3 / -2.14	Dax Automotive and Collision 241 Bridgeland Ave 241 Bridgeland Ave North York ON M6A 1Y7	GEN

Generator No: ON4778478
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I

Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

156 | **4 of 4** | **NW/299.9** | **181.3 / -2.14** | **SCARBOROUGH METALS**
241 BRIDGELAND AVE
NORTH YORK ON M6A1Y7 | **AUWR**

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone: 4162566041
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

157 | **1 of 20** | **NNE/299.9** | **186.4 / 2.97** | **Giffin Sheet Metals Limited**
133 Bridgeland Ave
North York ON M6A 1Y7 | **SCT**

Established: 01-JAN-49
Plant Size (ft²): 65000
Employment:

--Details--
Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Description: Power Boiler and Heat Exchanger Manufacturing
SIC/NAICS Code: 332410

Description: Heating Equipment and Commercial Refrigeration Equipment Manufacturing
SIC/NAICS Code: 333416

Description: Automotive Body, Paint and Interior Repair and Maintenance
SIC/NAICS Code: 811121

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Pump and Compressor Manufacturing
SIC/NAICS Code: 333910

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Commercial and Service Industry Machinery Manufacturing
SIC/NAICS Code: 333310

---

157 | **2 of 20** | **NNE/299.9** | **186.4 / 2.97** | **GIFFIN SHEET METALS LIMITED**
LOT 1, CONC. 5, VAUGHAN TWP. 133
BRIDGELAND AVENUE
TORONTO ON M6A 1Y7 | **GEN**

Generator No: ON0913300
SIC Code: 0000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: *** NOT DEFINED ***
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

157	3 of 20	NNE/299.9	186.4 / 2.97	GIFFIN SHEET METALS LIMITED 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	GEN

Generator No: ON0913300
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND
Approval Years: 92,93,97,98,99,00,01,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

157	4 of 20	NNE/299.9	186.4 / 2.97	GIFFIN SHEET METALS LIMITED 18-256 LOT 1, CONC. 5, VAUGHAN TWP. 133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	GEN

Generator No: ON0913300
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

157 ***5 of 20*** ***NNE/299.9*** ***186.4 / 2.97*** ***GIFFIN SHEET METALS LIMITED*** ***GEN***
133 Bridgeland Avenue
Toronto ON M6A 1Y7

Generator No: ON0913300
SIC Code: 332329
SIC Description: Other Ornamental and Architectural Metal Products Manufacturing
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

157 ***6 of 20*** ***NNE/299.9*** ***186.4 / 2.97*** ***GIFFIN SHEET METALS LIMITED*** ***GEN***
133 Bridgeland Avenue
Toronto ON M6A 1Y7

Generator No: ON0913300
SIC Code: 332329
SIC Description: Other Ornamental and Architectural Metal Products Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

157 **7 of 20** **NNE/299.9** **186.4 / 2.97** **GIFFIN SHEET METALS LIMITED** **GEN**
133 Bridgeland Avenue
Toronto ON M6A 1Y7

Generator No: ON0913300
SIC Code: 332329
SIC Description: Other Ornamental and Architectural Metal Products Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

157 **8 of 20** **NNE/299.9** **186.4 / 2.97** **GIFFIN SHEET METALS LIMITED** **GEN**
133 Bridgeland Avenue
Toronto ON M6A 1Y7

Generator No: ON0913300
SIC Code: 332329
SIC Description: Other Ornamental and Architectural Metal Products Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

157 **9 of 20** **NNE/299.9** **186.4 / 2.97** **GIFFIN SHEET METALS LIMITED** **GEN**
133 Bridgeland Avenue

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Toronto ON M6A 1Y7	

Generator No: ON0913300
SIC Code: 332329
SIC Description: Other Ornamental and Architectural Metal Products Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

157	10 of 20	NNE/299.9	186.4 / 2.97	**GIFFIN SHEET METALS LIMITED** **133 Bridgeland Avenue** **Toronto ON**	GEN

Generator No: ON0913300
SIC Code: 332329
SIC Description: OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCT MANUFACTURING, OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCTS MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

157	11 of 20	NNE/299.9	186.4 / 2.97	**GIFFIN SHEET METALS LTD.** **133 BRIDGELAND AVENUE NOT AVAILABLE** **TORONTO ON M6A 1Y7**	NPRI

NPRI ID: 28587
Other ID:
No Other ID:
Org ID: 103469
Submit Date: 6/1/2015
Last Modified: 6/10/2015 10:59:04 AM

Track ID:	131063	**Contact ID:**	235207
Report ID:	57351	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2014	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	227581	**Contact Ph.:**	
Fac Name:	GIFFIN CANADA	**Cont Area Code:**	
Fac Address1:	133 BRIDGELAND AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M6A 1Y7	**Cont Fax Area Cde:**	
Facility Lat:	43.7251	**Contact Fax:**	
Facility Long:	-79.46332	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.7251
Facility DLS:		**Longitude:**	-79.46332
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	55	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3323		
NAICS 4 Description:	Architectural and structural metals manufacturing		
NAICS Code (6 digit):	332329		
NAICS 6 Description:	Other ornamental and architectural metal product manufacturing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Selenium (and its compounds)
Chem (fr):	Sélénium (et ses composés)
Quantity:	.004
Unit:	kg
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Chromium (and its compounds)
Chem (fr):	Chrome (et ses composés)
Quantity:	.0005
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias

Grouping:	Total All Media<1t
Trans Code:	
Chem:	Nickel (and its compounds)
Chem (fr):	Nickel (et ses composés)
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Lead (and its compounds)
Chem (fr):	Plomb (et ses composés)
Quantity:	.0012
Unit:	kg
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

---

157 **12 of 20** **NNE/299.9** **186.4 / 2.97** **GIFFIN SHEET METALS LIMITED** **GEN**
133 Bridgeland Avenue
Toronto ON M6A-1Y7

Generator No:	ON0913300
SIC Code:	332329
SIC Description:	OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCT MANUFACTURING, OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCTS MANUFACTURING
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

---

157 **13 of 20** **NNE/299.9** **186.4 / 2.97** **GIFFIN SHEET METALS LIMITED** **GEN**
133 Bridgeland Avenue
Toronto ON M6A-1Y7

Generator No:	ON0913300
SIC Code:	332329
SIC Description:	OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCT MANUFACTURING, OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCTS MANUFACTURING
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	

Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

157 | ***14 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***GIFFIN SHEET METALS LIMITED*** ***133 Bridgeland Avenue*** ***Toronto ON M6A-1Y7*** | ***GEN***

Generator No: ON0913300
SIC Code: 332329
SIC Description: OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCT MANUFACTURING, OTHER ORNAMENTAL AND ARCHITECTURAL METAL PRODUCTS MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

157 | ***15 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***GIFFIN SHEET METALS LIMITED*** ***133 Bridgeland Avenue*** ***Toronto ON M6A-1Y7*** | ***GEN***

Generator No: ON0913300
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	253 L
Waste Class Name:	Emulsified oils

157 | ***16 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***Giffin Sheet Metals Ltd.*** ***133 BRIDGELAND AVENUE NOT AVAILABLE*** ***TORONTO ON M6A 1Y7*** | ***NPRI***

NPRI ID:	28587	***Org ID:***	107763
Other ID:		***Submit Date:***	5/31/2016
No Other ID:		***Last Modified:***	11/18/2016 8:28:05 AM
Track ID:	140785	***Contact ID:***	243880
Report ID:	75806	***Cont Type:***	MEM
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	William P.
Report Year:	2015	***Cont Last Name:***	Giffin
Not-Current Rpt?:	No	***Contact Position:***	Vice President
Yr of Last Filed Rpt:	2014	***Contact Fax:***	4167819977
Fac ID:	227581	***Contact Ph.:***	4167816166
Fac Name:	GIFFIN CANADA	***Cont Area Code:***	416
Fac Address1:	133 BRIDGELAND AVENUE	***Contact Tel.:***	67816166
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	M6A 1Y7	***Cont Fax Area Cde:***	416
Facility Lat:	43.7251	***Contact Fax:***	67819977
Facility Long:	-79.46332	***Contact Email:***	bgiffin@giffincanada.com
DLS (Last Filed Rpt):		***Latitude:***	43.7251
Facility DLS:		***Longitude:***	-79.46332
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	55	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3323		
NAICS 4 Description:	Architectural and structural metals manufacturing		
NAICS Code (6 digit):	332329		
NAICS 6 Description:	Other ornamental and architectural metal product manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	
Chem (fr):	
Quantity:	.0005

Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	
Chem (fr):	
Quantity:	.0012
Unit:	kg
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	
Chem (fr):	
Quantity:	.004
Unit:	kg
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	
Chem (fr):	
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

---

157 | ***17 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***133 Bridgeland Avenue North York ON M6A 1Z4*** | ***EHS***

Order No:	20180514123	**Nearest Intersection:**	
Status:	C	**Municipality:**	North York
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	22-MAY-18	**Search Radius (km):**	.25
Date Received:	14-MAY-18	**X:**	-79.463194
Previous Site Name:		**Y:**	43.724926
Lot/Building Size:	3 acres		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

157 | ***18 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***GIFFIN SHEET METALS LIMITED 133 Bridgeland Avenue Toronto ON M6A-1Y7*** | ***GEN***

Generator No:	ON0913300
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 211 I
Waste Class Name: Aromatic solvents and residues

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

157 | ***19 of 20*** | ***NNE/299.9*** | ***186.4 / 2.97*** | ***GIFFIN SHEET METALS LIMITED***
133 Bridgeland Avenue
Toronto ON M6A-1Y7 | ***GEN***

Generator No: ON0913300
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 211 I
Waste Class Name: Aromatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
157	20 of 20	NNE/299.9	186.4 / 2.97	OXFORD PROPERTIES GROUP 115-133 BRIDGELAND AVENUE TORONTO ON M6A 1Y7	GEN

Generator No: ON2927181
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Unplottable Summary

Total: 13 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	City of Toronto	Caledonia Rd	Toronto ON	
CONV	BROWNING-FERRIS INDUSTRIES LTD		ON	
CONV	UNIVERSAL SHOWCASE LTD.		ON	
DTNK	A1 TOOLS	BRIDGELAND AV DOWNSVIEW	NORTH YORK ON	
DTNK	A1 TOOLS	BRIDGELAND AV DOWNSVIEW	NORTH YORK ON	
ECA	City of Toronto	Caledonia Rd	Toronto ON	M9C 2Y2
ECA	City of Toronto	Caledonia Rd	Toronto ON	M9C 2Y2
EHS		Bentworth Ave, Samor Rd, Dufflaw Rd, Orfus Rd	North York ON	
INC		Astral Gate, Lot #26, Toronto	ON	
PRT	A1 TOOLS	BRIDGELAND AV DOWNSVIEW	NORTH YORK ON	
SPL	Toronto Transit Commission	Northbound lanes of Caledonia Rd., just South of Kitchener Ave. CALEDONIA ROAD<UNOFFICIAL>	Toronto ON	
SPL	NORTH YORK HYDRO	POLE 69, BRIDGELAND AVENUE	TORONTO CITY ON	
SPL	UNKNOWN	BENTWOOD AVE, TO CALEDONIA RD, TO LAWRENCE AVE.	TORONTO CITY ON	

Unplottable Report

Site: ***City of Toronto***
Caledonia Rd Toronto ON

Database: ***CA***

Certificate #: 2808-6ZJLGT
Application Year: 2007
Issue Date: 3/25/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROWNING-FERRIS INDUSTRIES LTD***
ON

Database: ***CONV***

File No:
Crown Brief No: 99-0096-0151
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: OPERATE A HEAVY DIESEL-FUELLED MOTOR VEHICLE THAT CONTRAVENES THE EMISSION STANDARDS.
Background:
URL:

Location:
Region: CENTRAL REGION
Ministry District: METRO

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation: 361/98
Section: 12(5)
Act/Regulation/Section: EPA-361/98-12(5)
Date of Offence:
Date of Conviction:
Date Charged: 10/12/99
Charge Disposition: SUSPENDED SENTENCE
Fine: $400.00
Synopsis:

Site: ***UNIVERSAL SHOWCASE LTD.***
ON

Database: ***CONV***

File No:

Location:

Crown Brief No:	98-0000-9003	***Region:***	CENTRAL REGION
Court Location:		***Ministry District:***	
Publication City:			
Publication Title:			
Act:			
Act(s):			
First Matter:			
Second Matter:			
Investigation 1:			
Investigation 2:			
Penalty Imposed:			
Description:	THIS IS THE CENTRAL BRIEF FOR ALL P.O.A. TICKETS		
Background:			
URL:			

Additional Details

Publication Date:	
Count:	1
Act:	EPA
Regulation:	
Section:	9(7)
Act/Regulation/Section:	EPA- -9(7)
Date of Offence:	
Date of Conviction:	
Date Charged:	8/10/01
Charge Disposition:	SUSPENDED SENTENCE
Fine:	$305.00
Synopsis:	

Site: ***A1 TOOLS***
BRIDGELAND AV DOWNSVIEW NORTH YORK ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11281843	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	76990	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***A1 TOOLS***
BRIDGELAND AV DOWNSVIEW NORTH YORK ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10099429	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	11999	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***City of Toronto***
Caledonia Rd Toronto ON M9C 2Y2

Database: ***ECA***

Approval No:	1438-6ZJLQC	***MOE District:***	
Approval Date:	2007-03-25	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	City of Toronto		
Address:	Caledonia Rd		
Full Address:			
Full PDF Link:			
PDF Site Location:			

Site: ***City of Toronto***
Caledonia Rd Toronto ON M9C 2Y2

Database: ***ECA***

Approval No:	2808-6ZJLGT	***MOE District:***	
Approval Date:	2007-03-25	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		

Business Name:	City of Toronto
Address:	Caledonia Rd
Full Address:	
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6426-6Z9RVU-14.pdf
PDF Site Location:	

Site: **Database:** EHS

Bentworth Ave, Samor Rd, Dufflaw Rd, Orfus Rd North York ON

Order No:	20050602008	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:		**Client Prov/State:**	ON
Report Date:	6/13/2005	**Search Radius (km):**	0.25
Date Received:	6/2/2005	**X:**	-79.464181
Previous Site Name:		**Y:**	43.720436
Lot/Building Size:			
Additional Info Ordered:			

Site: **Database:** INC

Astral Gate, Lot #26, Toronto ON

Incident No:	414268	**Any Health Impact:**	No
Incident ID:	2565964	**Any Enviro Impact:**	No
Instance No:		**Service Interrupted:**	No
Status Code:	Causal Analysis Complete	**Was Prop Damaged:**	Yes
Attribute Category:	FS-Perform L1 Incident Insp	**Reside App. Type:**	
Context:		**Commer App. Type:**	
Date of Occurrence:	2010/06/17 00:00:00	**Indus App. Type:**	
Time of Occurrence:	14:00:00	**Institut App. Type:**	
Incident Created On:		**Venting Type:**	
Instance Creation Dt:		**Vent Conn Mater:**	
Instance Install Dt:		**Vent Chimney Mater:**	
Occur Insp Start Date:	2010/06/28 00:00:00	**Pipeline Type:**	Main Distribution Pipeline
Approx Quant Rel:		**Pipeline Involved:**	
Tank Capacity:		**Pipe Material:**	Plastic
Fuels Occur Type:	Vapour Release	**Depth Ground Cover:**	
Fuel Type Involved:	Natural Gas	**Regulator Location:**	
Enforcement Policy:	NULL	**Regulator Type:**	
Prc Escalation Req:	NULL	**Operation Pressure:**	
Tank Material Type:		**Liquid Prop Make:**	
Tank Storage Type:		**Liquid Prop Model:**	
Tank Location Type:		**Liquid Prop Serial No:**	
Pump Flow Rate Cap:		**Liquid Prop Notes:**	
Task No:	2950994	**Equipment Type:**	
Notes:		**Equipment Model:**	
Drainage System:		**Serial No:**	
Sub Surface Contam.:		**Cylinder Capacity:**	
Aff Prop Use Water:		**Cylinder Cap Units:**	
Contam. Migrated:		**Cylinder Mat Type:**	
Contact Natural Env:		**Near Body of Water:**	

Incident Location:	Astral Gate, Lot #26, Toronto - 2" Pipeline Hit
Occurence Narrative:	MUD CRUST GAVE WAY UNDER BULLDOZER
Operation Type Involved:	Construction Site (pipeline strike)
Item:	
Item Description:	
Device Installed Location:	

Site: ***A1 TOOLS***
BRIDGELAND AV DOWNSVIEW NORTH YORK ON

Database: PRT

Location ID:	28766
Type:	retail
Expiry Date:	1995-08-31
Capacity (L):	1000

Licence #: 0076427442

Site: ***Toronto Transit Commission*** **Database:** SPL
Northbound lanes of Caledonia Rd., just South of Kitchener Ave. CALEDONIA ROAD<UNOFFICIAL> Toronto ON

Ref No:	4460-6R2GD4	***Discharger Report:***	
Site No:		***Material Group:***	Oils
Incident Dt:	6/23/2006	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Other Transport Accident	***Sector Type:***	Unknown
Incident Event:		***Agency Involved:***	
Contaminant Code:	15	***Nearest Watercourse:***	
Contaminant Name:	HYDRAULIC OIL	***Site Address:***	NORTHBOUND LANES OF CALEDONIA RD., JUST SOUTH OF KITCHENER AVE.
Contaminant Limit 1:		***Site District Office:***	Toronto - District
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Not Anticipated	***Site Municipality:***	Toronto
Nature of Impact:	Soil Contamination; Surface Water Pollution	***Site Lot:***	
Receiving Medium:	Land & Water	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	6/23/2006	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	Equipment/Vehicles	***Source Type:***	
Site Name:	NORTHBOUND LANES OF CALEDONIA RD., JUST SOUTH OF KITCHENER AVE.		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Spill of Hydraulic Fluid - 25L to gnrd. 1L to c/b- Toronto		
Contaminant Qty:	25 L		

Site: ***NORTH YORK HYDRO*** **Database:** SPL
POLE 69, BRIDGELAND AVENUE TORONTO CITY ON

Ref No:	96985	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/3/1994	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	1106
Nature of Impact:	Other	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	3/3/1994	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	DAMAGE BY MOVING EQUIPMENT	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	NORTH YORK HYDRO - 14L NON-PCB TRANSFORMER OIL TO LAND & CARS		
Contaminant Qty:			

Site: ***UNKNOWN*** **Database:** SPL
BENTWOOD AVE, TO CALEDONIA RD, TO LAWRENCE AVE. TORONTO CITY ON

Ref No:	114158	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/7/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	WORKS
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	6/7/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SOURCE UNKNOWN: 180 L OF HYDRAULIC OIL TO ASPHALT,WORKS CLEANING UP.		
Contaminant Qty:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Nov 2021

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-May 31, 2022

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2020

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-May 31, 2022

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Sep 2022

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Sep 2022

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Oct 31, 2022

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2022

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Feb 28, 2022

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011- Sep 30, 2022

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Oct 31, 2022

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Sep 30, 2022

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Jul 31, 2022

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2021

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Sep 2022

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2019

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 21, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2022

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2020

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Aug 31, 2022

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2021

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Oct 31, 2022

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Sep 30, 2022

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Oct 31, 2022

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2019

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Oct 2022

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-May 31, 2022

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Sep 2020; Dec 2020-Mar 2021

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Dec 2020

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011- Sep 30, 2022

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Jun 30 2022

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.


Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX G

TERRAPROBE INC.



Ontario

Ministry of the Environment, Conservation and Parks

Freedom of Information Request for Property Information

Instructions

Use this form to:

- submit and pay for a new FOI request for access to records/information about a property
- pay for a deposit or a final fee on an existing FOI request

Fields marked with an asterisk (*) are mandatory.

Are you: *

☑ Submitting a new FOI Request for Property Information

☐ Paying a deposit or final fee for an existing FOI Request for Property Information

Section 1 – Description of Records Requested

Time Period for Records Requested

From (yyyy/mm/dd) * 1962/01/01

To (yyyy/mm/dd) * 2023/01/12

Type of Record(s) *

☐ All environmental records relating to the identified property/site exclusive of Environmental Approvals and Registrations

☑ Environmental Approvals and Registrations (e.g. Environmental Compliance Approvals; Certificate of Approval; Renewable Energy Approvals; Environmental Activity and Sector Registry Registrations)

Select only if you are seeking access to an Approval or Registration that is not publicly available or if you are also seeking supporting documents relating to the Approval or Registration.

Operator and vendor Pesticide Licenses from September 4, 2018, final Approvals and Registrations are publicly available on the Access Environment website at:
https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/GoSearch.action?search=basic&lang=en.

Records of Site Condition (RSC) records are publicly available on the Brownfields Environmental Site Registry (BSER).

- RSC records between 2004 to June 30, 2011 are available at: https://www.lrcsde.lrc.gov.on.ca/besrWebPublic/generalSearch
- RSC records filed after July 2011 are available at: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/earchFiledRsc_search?request_locale=en

☐ Other Specific Document(s)

Type of Approval/Registration *

☑ Drinking Water Licenses

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Pesticide Licenses

 © King's Printer for Ontario, 2022

Only pesticide licenses post September 2018 are available. Prior to September 2018, only Pesticide license applications and supporting documentation is available

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Permits to Take Water

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

Water Source *

☑ Groundwater ☑ Surface Water

☑ Noise Vibrations Approvals/Registrations

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Air Emissions Approvals/Registrations

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Water Approvals/Registrations - Ontario Water Resources Commission, treatment, ground level, standpipes & elevated storage, pumping stations (local & booster), mains

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Sewage – Treatment, Stormwater, Storm, Leachate & Lieachate Treatment & Sewage pump stations, Sanitary

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Water - Industrial discharge

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Sites - Disposal, Landfill sites, Transfer stations, Processing sites, Incinerator sites

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Management Systems - haulers: sewage, non-hazardous & hazardous waste, mobile waste processing units, Polychlorinated Biphenyls (PCBs) storage, transfer or destruction, Waste Generator Systems)

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

Company Name

☑ Waste Generator Registration - number/class

List any record(s) that should be excluded from the scope of your request (e.g. email correspondences; records originating from your organization/business; records already in your possession, prior year(s) annual reports for approvals)

Please provide any additional relevant information relating to your request. For example, does your request relate to any other ministry business? Please note that this information is being requested only in order to provide contextual information to the Access and Privacy Office and will not in any way affect or expedite the status of any related ministry business identified.

Section 2 – Requester Information

Last Name * Elgergawy

First Name * Omar

Middle Initial

Business/Organization Name (if applicable or indicate "N/A") * Terraprobe

Project/Reference Number (if applicable) 02210387

Are you submitting this request on behalf of a client? *

☐ Yes ☑ No

Mailing Address

Unit Number

Street Number * 11

Street Name * Indell Lane

PO Box

City/Town * Brampton

Province * ON

Postal Code * L6T 3Y3

Telephone Number * 905-796-2650

ext.

Email Address * omar.elgergawy@englobecorp.com

Is there an alternate contact (e.g. office admin)? *

☐ Yes ☑ No

Section 3 – Current Property Address Information

Is the property a:

☐ Park ☐ Lake ☐ First Nation Band ☐ Wind Farm ☐ Federal Land ☐ Island ☐ Unsurveyed Land

Are you requesting information about multiple addresses? *

☐ Yes ☑ No

Property Address

Unit Number

Street Number 109

Street Name Cartwright Avenue

Full Lot Number

Concession

Geographic Township

City/Town/Village * Toronto

Closest Intersection

Section 4 – Previous Property Address Information

Do you want the ministry to search all prior historical addresses for this property/site for the time period of the records requested? *

☐ Yes ☑ No

Section 5 – Owner Information

Please provide all present and previous property owner and/or tenant names for the search years requested.

Current Property Owner/Tenant

109 Cartwright Avenue
Toronto

Owner/Tenant * 1

Owner Name: Dufferin-Ranee Investments Limited

Date of Ownership (yyyy/mm/dd): 1962/07/31

Tenant Name:

Owner/Tenant * 2

Owner Name: Gordon Saltzman & Samuel Silverstein

Date of Ownership (yyyy/mm/dd): 1969/12/18

Tenant Name:

Owner/Tenant * 3

Owner Name: Dufferin-Ranee Investments Limited

Date of Ownership (yyyy/mm/dd): 1976/12/11

Tenant Name:

Owner/Tenant * 4

Owner Name: 109 Cartwright Limited

Date of Ownership (yyyy/mm/dd): 2007/08/17

Tenant Name:

Section 6 – Supporting Documents

Please upload any documents (e.g. Maps) that are relevant to your FOI request.

The total size of all attachments must not be more than 8 MB.

1. File Name

Total File Size

Payment confirmation number: 25115212

Ontario

Ministry of the Environment, Conservation and Parks

Freedom of Information Request for Property Information

Instructions

Use this form to:

- submit and pay for a new FOI request for access to records/information about a property
- pay for a deposit or a final fee on an existing FOI request

Fields marked with an asterisk (*) are mandatory.

Are you: *

☑ Submitting a new FOI Request for Property Information

☐ Paying a deposit or final fee for an existing FOI Request for Property Information

Section 1 – Description of Records Requested

Time Period for Records Requested

From (yyyy/mm/dd) * 1957/01/01

To (yyyy/mm/dd) * 2023/01/12

Type of Record(s) *

☑ All environmental records relating to the identified property/site exclusive of Environmental Approvals and Registrations

☑ Environmental Approvals and Registrations (e.g. Environmental Compliance Approvals; Certificate of Approval; Renewable Energy Approvals; Environmental Activity and Sector Registry Registrations)

Select only if you are seeking access to an Approval or Registration that is not publicly available or if you are also seeking supporting documents relating to the Approval or Registration.

Operator and vendor Pesticide Licenses from September 4, 2018, final Approvals and Registrations are publicly available on the Access Environment website at:
https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/GoSearch.action?search=basic&lang=en.

Records of Site Condition (RSC) records are publicly available on the Brownfields Environmental Site Registry (BSER).

- RSC records between 2004 to June 30, 2011 are available at:
  https://www.lrcsde.lrc.gov.on.ca/besrWebPublic/generalSearch
- RSC records filed after July 2011 are available at:
  https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/earchFiledRsc_search?request_locale=en

☐ Other Specific Document(s)

Type of Approval/Registration *

☑ Drinking Water Licenses

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Pesticide Licenses

 © King's Printer for Ontario, 2022

Only pesticide licenses post September 2018 are available. Prior to September 2018, only Pesticide license applications and supporting documentation is available

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Permits to Take Water

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

Water Source *

☑ Groundwater ☑ Surface Water

☑ Noise Vibrations Approvals/Registrations

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Air Emissions Approvals/Registrations

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Water Approvals/Registrations - Ontario Water Resources Commission, treatment, ground level, standpipes & elevated storage, pumping stations (local & booster), mains

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Sewage – Treatment, Stormwater, Storm, Leachate & Lieachate Treatment & Sewage pump stations, Sanitary

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Water - Industrial discharge

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Sites - Disposal, Landfill sites, Transfer stations, Processing sites, Incinerator sites

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

☑ Waste Management Systems - haulers: sewage, non-hazardous & hazardous waste, mobile waste processing units, Polychlorinated Biphenyls (PCBs) storage, transfer or destruction, Waste Generator Systems)

☐ No Supporting Documents ☑ All Supporting Documents ☐ Some Supporting Documents

Company Name

☑ Waste Generator Registration - number/class

List any record(s) that should be excluded from the scope of your request (e.g. email correspondences; records originating from your organization/business; records already in your possession, prior year(s) annual reports for approvals)

Please provide any additional relevant information relating to your request. For example, does your request relate to any other ministry business? Please note that this information is being requested only in order to provide contextual information to the Access and Privacy Office and will not in any way affect or expedite the status of any related ministry business identified.

Section 2 – Requester Information

Last Name * Elgergawy

First Name * Omar

Middle Initial

Business/Organization Name (if applicable or indicate "N/A") * Terraprobe

Project/Reference Number (if applicable) 012210387

Are you submitting this request on behalf of a client? *

☐ Yes ☑ No

Mailing Address

Unit Number

Street Number * 11

Street Name * Indell Lane

PO Box

City/Town * Brampton

Province * ON

Postal Code * L6T 3Y3

Telephone Number * 905-796-2650

ext.

Email Address * omar.elgergawy@englobecorp.com

Is there an alternate contact (e.g. office admin)? *

☐ Yes ☑ No

Section 3 – Current Property Address Information

Is the property a:

☐ Park ☐ Lake ☐ First Nation Band ☐ Wind Farm ☐ Federal Land ☐ Island ☐ Unsurveyed Land

Are you requesting information about multiple addresses? *

☐ Yes ☑ No

Property Address

Unit Number

Street Number 130

Street Name Bentworth Avenue

Full Lot Number

Concession

Geographic Township

City/Town/Village * Toronto

Closest Intersection

Section 4 – Previous Property Address Information

Do you want the ministry to search all prior historical addresses for this property/site for the time period of the records requested? *

☐ Yes ☑ No

Section 5 – Owner Information

Please provide all present and previous property owner and/or tenant names for the search years requested.

Current Property Owner/Tenant

130 Bentworth Avenue
Toronto

Owner/Tenant * 1

Owner Name: Isac Wagner, Yechezkel Wagner & Gertrude Wagner

Date of Ownership (yyyy/mm/dd): 1957/11/14

Tenant Name:

Owner/Tenant * 2

Owner Name: Israel Wagner

Date of Ownership (yyyy/mm/dd): 2005/08/08

Tenant Name:

Owner/Tenant * 3

Owner Name: 130 Bentworth Avenue Limited

Date of Ownership (yyyy/mm/dd): 2006/06/12

Tenant Name:

Owner/Tenant * 4

Owner Name: The Sterling Hall School

Date of Ownership (yyyy/mm/dd): 2019/05/30

Tenant Name:

Section 6 – Supporting Documents

Please upload any documents (e.g. Maps) that are relevant to your FOI request.

The total size of all attachments must not be more than 8 MB.

1. File Name

Total File Size

Payment confirmation number: 25115529

TSSA - Request

PS

Public Information Services <publicinformationservices@tssa.org>

To: Omar Elgergawy

Mon 2022-12-05 7:50 AM

ATTENTION: Assurez-vous que le contenu soit de confiance avant d'ouvrir une pièce jointe ou un hyperlien.
CAUTION: Do not click on links or open attachments you do not trust.

Please refrain from sending documents to head office. The Public Information (PI) team works remotely, mailing in applications will lengthen the overall processing time.

NO RECORD FOUND IN CURRENT DATABASE

Hello,

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are no records in our current database of any fuel storage tanks at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please submit an application for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site.
Please follow the steps below to access the new application(s) and Service Prepayment Portal:

1. Click Release of Public Information - TSSA and click "need a copy of a document";
2. Select the appropriate application, download it and complete it in full; and
3. Proceed to page 3 of the application and click the link TSSA Service Prepayment Portal under payment options (the link will take you the secure site to pay for the release via credit card).


Accessing the Service Prepayment Portal:


1. Select new or existing customer (*if you are an existing customer, you will need your account # & postal code to access your account);
2. Select the program area: AD (Amusement Devices), BPV (Boilers and Pressure Vessels), ED (Elevating Devices), FS (Fuels Services), OE (Operating Engineers) or SKI (Ski Lifts) and click continue;
3. Enter the application form number (obtained from bottom left corner of application form) and click continue;
   a. When selecting the application form number from the drop-down menu, please make sure you select the application that begins with "PI" (i.e. PI-FS, PI-BPV etc.);
4. Complete the primary contact information section;
5. Complete the fees section;
6. Upload your completed application; and
7. Upload supporting documents (if required) and click continue.

Once all steps have been successfully completed, you will receive your receipt via email.

APPENDIX H

TERRAPROBE INC.





SCALE 0 50 100m

Terraprobe


11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph

File No. 02210387.000.300

YEAR : 1946

Y:\Shared\CAI\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A_Dwgs, Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, _DWG To PDF.pc3



SCALE 0 50 100m


Terraprobe
11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph

File No. 02210387.000.300

YEAR : 1950

Y:\Shared\CAI\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESAIA, Dwgs, Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, _DWG To PDF.pc3



SCALE 0 50 100m

Terraprobe

11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph

File No. 02210387.000.300

YEAR : 1965

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESAA, Dwgs, Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, , DWG To PDF.pc3



SCALE 0 50 100m

Terraprobe


11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph

File No. 02210387.000.300

YEAR : 1970

Y:\Shared\CAITerraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESAA, Dwgs, Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, _DWG To PDF.pc3



SCALE 0 50 100m

Terraprobe

11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph

File No. 02210387.000.300

YEAR : 1982

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESAIA, Dwgs, Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, _DWG To PDF.pc3



SCALE 0 50 100m

Terraprobe

11 Indell Lane, Brampton, Ontario, L6T 3Y3
Tel: (905) 796-2650 Fax: (905) 796-2250

Title: Aerial Photograph


File No. 02210387.000.300


YEAR : 2019

Y:\Shared\CA\Terraprobe\Brampton\1-Project Files\2022-Englobe\02210387.000 - 99 Cartwright Avenue, North York\0300 - Phase One ESA\A_Dwgs_Logs\AutoCAD\02210387.000.300 Aerials.dwg, aalashaab, _DWG To PDF.pc3

APPENDIX I

TERRAPROBE INC.





Halton Till
predominantly silt to silty clay matrix, high in matrix carbonate content and clast poor
Pleistocene
Directions: To here - From here
130 Bentworth Ave
Beaverton
LINDSAY
Ennismore
Lakefield
Norwood
Peterborough
Little Britain
Sunderland
Innisfil
Georgina
East Gwillimbury
Newmarket
Aurora
Uxbridge
Port Perry
Millbrook
Rice Lake
Roseneath
Grafton
Colborne
Cobourg
Bowmanville
Oshawa
Ajax
Vaughan
Bolton
Toronto
Image NOAA
Image Landsat / Copernicus


Ontario
Ontario Geological Survey
5b Till
Stone-poor, sandy silt to silty sand-textured till on Paleozoic terrain
THORNHILL
CONCORD
L'AMOREAUX
AGINCOURT
WOODBRIDGE
WILLOWDALE
NORTH YORK
Ontario 401 Express
JANE AND FINCH
DON MILLS
DOWNSVIEW
REXDALE
GOLDEN MILE
YORKDALE
Allen Rd
YORK
shorecliff
Image © 2023 TerraMetrics
THE BEACHES
Google Earth
Imagery Date: 6/27/2019 43°43'57.50" N 79°26'41.67" W elev 187 m eye alt 25.21 km

APPENDIX J

TERRAPROBE INC.



Water Well Records

Wednesday, December 21, 2022

3:40:12 AM

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623395 4841956 W	2012/04 7241	2			MT	0014 10	7181106 (Z148235) A125731	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SAND SILT LOOS 0015 GREY SAND SILT DNSE 0024
NORTH YORK BOROUGH	17 623379 4842282 W	2011/08 7241	1.36			MT	0016 10	7167693 (Z136669) A116717	BRWN FILL GRVL LOOS 0002 BRWN SILT CLAY DNSE 0018 GREY SILT CLAY DNSE 0026
NORTH YORK BOROUGH	17 623722 4842383 W	2012/01 7241	1.25			MT	0030 10	7179517 (Z145453) A108652	BRWN SAND FILL 0002 BRWN CLAY SILT DNSE 0012 GREY CLAY SILT DNSE 0030
NORTH YORK BOROUGH	17 623381 4841980 W	2012/03 7241	2			MT	0015 10	7180722 (Z147207) A132372	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SILT CLAY LOOS 0008 GREY SILT CLAY LOOS 0025
NORTH YORK BOROUGH	17 623347 4841975 W	2012/03 7241	2			MT	0010 10	7180723 (Z147205) A132374	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SILT CLAY LOOS 0008 GREY SILT CLAY LOOS 0020
NORTH YORK BOROUGH	17 623361 4841926 W	2012/03 7241	2			MT	0010 10	7180724 (Z147206) A132373	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SILT CLAY LOOS 0008 GREY SILT CLAY LOOS 0020
NORTH YORK BOROUGH	17 623393 4841934 W	2012/03 7241	2			MT	0015 10	7180725 (Z147204) A132371	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SILT CLAY LOOS 0009 GREY SILT CLAY LOOS 0025
NORTH YORK BOROUGH	17 623733 4841898 W	2012/09 7320	2.00			MO	0010 10	7191976 (Z157885) A137925	BLCK GRVL 0001 BRWN SAND SILT 0004 BRWN SILT HARD 0014 BRWN SAND SILT 0015 BRWN SILT HARD 0020
NORTH YORK BOROUGH	17 623375 4841970 W	2012/04 7241	2			MT	0015 10	7181105 (Z148234) A125729	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SAND SILT LOOS 0015 GREY SAND SILT DNSE 0025
NORTH YORK BOROUGH	17 623784 4841923 W	2011/03 7241						7161057 (M06726) A111546 P	
NORTH YORK BOROUGH	17 623382 4841972 W	2012/04 7241	2			MT	0028 10	7181269 (Z148236) A125728	BLCK CMTD 0000 BRWN SAND GRVL LOOS 0001 BRWN SAND SILT LOOS 0015 GREY SILT SAND DNSE 0038
NORTH YORK BOROUGH	17 623381 4842382 W	2012/10 7320	2.00	UT 0005		TH	0005 10	7191350 (Z157931) A137938	BRWN SAND GRVL 0001 GREY MUCK 0005 BRWN SAND WBRG 0005 BRWN SAND SILT CLAY 0013 GREY CLAY 0015
NORTH YORK BOROUGH	17 623351 4842303 W	2012/10 7320	2.00	UT 0012		TH	0010 10	7191351 (Z157933) A137909	BRWN SAND GRVL 0002 BRWN SILT CLAY TILL 0012 GREY SILT CLAY 0020

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623343 4842234 W	2012/10 7320	2.00	UT 0011		TH	0010 10	7191352 (Z157932) A137936	BRWN SAND GRVL 0002 BRWN SILT CLAY TILL 0011 GREY SILT CLAY 0020
NORTH YORK BOROUGH	17 623342 4842339 W	2012/10 7320	2.00	UT 0012		TH	0010 10	7191353 (Z157934) A137910	BRWN SAND GRVL 0002 BRWN SILT CLAY TILL 0012 GREY SILT CLAY 0020
NORTH YORK BOROUGH	17 623641 4842088 W	2007/07 7241					0009 10	7048099 (Z74086) A056663	BRWN CLAY SILT 0014 GREY SAND SILT CLAY 0019
NORTH YORK BOROUGH	17 623379 4841974 W	2012/04 7241	2			MT	0015 10	7181104 (Z148233) A125730	BRWN SAND GRVL LOOS 0010 GREY SAND SILT DNSE 0025
NORTH YORK BOROUGH	17 623695 4842338 W	2010/09 7241	1.5			MT	0010 10	7154035 (Z122693) A108615	BRWN SILT SAND 0005 GREY SILT CLAY WBRG 0020
NORTH YORK BOROUGH	17 623402 4841776 W	2005/11 6607	2.00	FR 0010			0005 10	6929657 (Z40262) A034574	BRWN SAND GRVL 0001 BRWN SILT GRVL 0015
NORTH YORK BOROUGH	17 623686 4841967 W	2005/11 6607	2.00				0010 10	6929659 (Z40260) A036870	BRWN SAND GRVL 0001 BRWN CLAY SILT 0016 GREY CLAY SILT 0020
NORTH YORK BOROUGH	17 623585 4841829 W	2005/11 6607	2.00	FR 0013			0005 10	6929661 (Z40263) A034576	BRWN SAND GRVL 0001 GREY SILT CLAY 0015
NORTH YORK BOROUGH	17 623468 4841792 W	2005/11 6607	2.00	FR 0018			0010 10	6929662 (Z40264) A034570	BRWN SAND GRVL 0001 BRWN CLAY SILT 0013 GREY CLAY SILT 0019
NORTH YORK BOROUGH	17 623706 4842400 W	2006/05 7147	1.97			NU	0007 10	6930320 (Z49533) A041538	BLCK 0001 BRWN FILL 0001 BRWN CLAY 0017
NORTH YORK BOROUGH	17 623926 4842181 W	2010/07 7241	5.19			MT	0003 3	7149492 (Z118953) A102955	BRWN SAND GRVL FILL 0002 BRWN SILT CLAY DNSE 0005 GREY CLAY SILT DNSE 0006
NORTH YORK BOROUGH	17 623353 4842276 W	2011/08 7241	1.36			MT	0018 10	7167692 (Z136668) A116718	BRWN FILL GRVL LOOS 0002 BRWN SILT CLAY DNSE 0015 GREY SILT CLAY DNSE 0028
NORTH YORK BOROUGH	17 623691 4842369 W	2010/09 7241	1.5			MT	0009 10	7154034 (Z122692) A108614	BRWN SILT SAND 0008 GREY CLAY SILT 0019
NORTH YORK BOROUGH	17 623728 4841908 W	2010/11 6988						7161397 (M10100) A098136 P	

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623657 4842329 W	2010/09 7241	1.5			MT	0007 5	7154036 (Z122690) A108616	GREY SILT CLAY WBRG 0012
NORTH YORK BOROUGH	17 623659 4842355 W	2010/09 7241	1			MT	0008 10	7154054 (Z122672) A108617	BRWN SAND 0010 BRWN SILT CLAY 0018
NORTH YORK BOROUGH	17 623501 4842223 W	2011/01 7241	1.5			MT	0017 10	7159336 (Z127929) A112814	BLCK 0000 BRWN SAND GRVL LOOS 0002 BRWN SAND SILT LOOS 0014 GREY SILT CLAY DNSE 0027
NORTH YORK BOROUGH	17 623502 4842209 W	2011/01 7241	1.5			MT	0015 10	7159337 (Z127928) A112813	BLCK 0000 BRWN SAND GRVL LOOS 0002 BRWN SILT SAND LOOS 0014 GREY SILT CLAY DNSE 0025
NORTH YORK BOROUGH	17 623568 4842095 W	2011/01 7241	1.5			MT	0010 10	7159338 (Z127927) A112791	BLCK 0000 BRWN SAND GRVL LOOS 0002 BRWN SAND SILT LOOS 0014 GREY SILT CLAY DNSE 0020
NORTH YORK BOROUGH	17 623561 4842077 W	2011/01 7241	1.5			MT	0010 10	7159339 (Z127930) A112792	BLCK 0000 BRWN SAND GRVL LOOS 0002 BRWN SILT SAND LOOS 0014 GREY SILT CLAY DNSE 0020
NORTH YORK BOROUGH	17 623719 4841901 W	2012/09 7320	2.00			MO	0010 10	7191977 (Z157887) A137926	BLCK GRVL 0001 BRWN SAND SILT 0004 BRWN SILT HARD 0014 BRWN SAND SILT 0015 BRWN SILT HARD 0020
NORTH YORK BOROUGH	17 623947 4842146 W	2010/07 7241	5.19				0004 3	7149493 (Z118940) A102880	BRWN SAND GRVL FILL 0002 BRWN SILT CLAY DNSE 0005 GREY CLAY SILT DNSE 0007
NORTH YORK BOROUGH	17 623347 4842331 W	2019/10 6988						7356340 (C45815) A276612 P	
NORTH YORK BOROUGH	17 623707 4841896 W	2012/09 7320	2.00			MO	0010 10	7191975 (Z157886) A137924	BLCK GRVL 0001 BRWN SAND SILT 0004 BRWN SILT HARD 0014 BRWN SAND SILT 0015 BRWN SILT HARD 0020
NORTH YORK BOROUGH	17 623388 4842224 W	2017/04 7241	2			TH MO	0010 10	7286369 (Z258067) A208902	GREY GRVL 0000 BRWN FILL 0002 BRWN SILT SAND 0014 GREY SILT SAND 0020
NORTH YORK BOROUGH	17 623352 4842291 W	2017/04 7241	2			TH MO	0011 10	7286370 (Z258064) A208905	BLCK ---- 0000 BRWN FILL 0002 BRWN SILT SAND 0015 GREY SILT SAND 0021
NORTH YORK BOROUGH	17 623447 4841805 W	2018/06 7320	0.79	UT		TH MO	0016 33	7316356 (Z285991) A247741	BRWN FILL 0016 BRWN SILT 0046 GREY SILT 0049
NORTH YORK BOROUGH	17 623416 4841862 W	2018/06 7320	0.79	UT		TH MO	0049 33	7316357 (Z285993) A247819	BRWN FILL 0016 BRWN SILT TILL 0056 GREY SILT TILL 0082

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623980 4842395 W	2018/10 6988						7331247 (C40760) A242856 P	
NORTH YORK BOROUGH	17 623339 4842351 W	2017/04 7241	2			TH MO	0012 10	7286367 (Z258065) A208904	BLCK ---- 0000 BRWN FILL 0002 BRWN SILT SAND 0015 GREY SILT SAND 0022
NORTH YORK BOROUGH	17 623942 4842380 W	2019/06 6988						7343116 (C40788) A256466 P	
NORTH YORK BOROUGH	17 623673 4842204 W	2017/02 7241	1.25			TH MO	0005 10	7281892 (Z251094) A217290	BRWN SAND GRVL 0003 BRWN SILT SAND TILL 0010 GREY SILT CLAY TILL 0015
NORTH YORK BOROUGH	17 623624 4842100 W	2019/04 7644	2			TH MO	0010 10	7332344 (Z310707) A265263	BRWN TILL SAND 0015 GREY TILL SAND DNSE 0020
NORTH YORK BOROUGH	17 623613 4842150 W	2019/04 7644	2			TH MO	0010 10	7332345 (Z310709) A260396	BRWN TILL DNSE 0020
NORTH YORK BOROUGH	17 623642 4842094 W	2019/04 7644	2			TH MO	0010 10	7332346 (Z310708) A265262	BRWN TILL SAND 0015 GREY TILL DNSE 0020
NORTH YORK BOROUGH	17 623382 4842130 W	2020/06 7241						7365139 (Z339604) A294678 P	
NORTH YORK BOROUGH	17 623344 4842107 W	2020/06 7241						7365301 (Z339602) A294680 P	
NORTH YORK BOROUGH	17 623338 4842095 W	2020/06 7241						7365302 (Z339601) A294679 P	
NORTH YORK BOROUGH	17 623386 4841903 W	2019/08 7215						7343059 (C46017) A269278 P	
NORTH YORK BOROUGH	17 623835 4842066 W	2013/07 7230						7218673 (C25359) A161856 P	
NORTH YORK BOROUGH	17 623409 4841984 W	2012/10 7215						7192516 (C19391) A139572 P	
NORTH YORK BOROUGH	17 623377 4841855 W	2013/09 7241	2			MT	0022 10	7209000 (Z177877) A152756	BLCK SOFT 0000 BRWN TILL CLAY SOFT 0005 BRWN TILL FSND SOFT 0010 GREY TILL CLAY SOFT 0020 GREY CLAY TILL SOFT 0032

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623368 4841861 W	2013/09 7241	2.04			MT	0021 10	7209002 (Z177876) A152757	BLCK SOFT 0000 BRWN SAND SILT GRVL 0010 BRWN SILT FSND SOFT 0020 GREY SILT FSND SOFT 0031
NORTH YORK BOROUGH	17 623355 4841849 W	2013/09 7241	2			MT	0030 10	7209003 (Z177878) A152760	BLCK SOFT 0000 BRWN TILL CLAY SOFT 0005 BRWN TILL FSND SOFT 0010 GREY TILL CLAY SOFT 0025 GREY CLAY TILL SOFT 0040
NORTH YORK BOROUGH	17 623346 4841801 W	2013/11 7241	2			MT		7212013 (Z181154) A152757 A	
NORTH YORK BOROUGH	17 623324 4841799 W	2013/11 7241	2			MT		7212014 (Z181151) A154289 A	
NORTH YORK BOROUGH	17 623382 4842349 W	2017/04 7241	2			TH MO	0012 10	7286368 (Z258066) A208903	BLCK ---- 0000 BRWN FILL 0002 BRWN SILT SAND 0015 GREY SILT SAND 0022
NORTH YORK BOROUGH	17 623339 4841787 W	2013/11 7241	2			MT		7212016 (Z181153) A152750 A	
NORTH YORK BOROUGH	17 623333 4842124 W	2020/06 7241						7365303 (Z339603) A294677 P	
NORTH YORK BOROUGH	17 623785 4842148 W	2014/05 7247	0.75			MT	0010 5	7222994 (Z179648) A156007	BLCK 0000 BRWN 0001 BRWN CLAY SILT LOOS 0004 BRWN CLAY SAND 0015
NORTH YORK BOROUGH	17 623409 4841984 W	2012/11 7147						7231719 (C12956) A139592 P	
NORTH YORK BOROUGH	17 623834 4842064 W	2014/09 6988						7232232 (C24804) A161856 A P	
NORTH YORK BOROUGH	17 623664 4842218 W	2017/02 7241	1			TH MO	0004 10	7281833 (Z245481) A185472	BLCK CMTD 0002 BRWN SAND SILT GRVL 0014 GREY
NORTH YORK BOROUGH	17 623655 4842285 W	2017/02 7241	1.25			TH MO	0010 10	7281889 (Z253375) A211211	BRWN SAND GRVL 0003 BRWN SILT CLAY TILL 0011 GREY SILT CLAY TILL 0020
NORTH YORK BOROUGH	17 623646 4842284 W	2017/02 7241	1.25			TH MO	0010 10	7281890 (Z253374) A185463	BRWN SAND GRVL 0003 BRWN SILT CLAY TILL 0011 GREY SILT CLAY TILL 0020
NORTH YORK BOROUGH	17 623683 4842211 W	2017/02 7241	1.25			TH MO	0010 10	7281891 (Z253376) A185470	BRWN SAND GRVL 0003 BRWN SILT CLAY TILL 0010 GREY SILT CLAY TILL 0020

TOWNSHIP CON LOT	UTM	DATE CNTR	CASING DIA	WATER	PUMP TEST	WELL USE	SCREEN	WELL	FORMATION
NORTH YORK BOROUGH	17 623321 4841789 W	2013/11 7241	2			MT		7212015 (Z181152) A152760 A	
TORONTO CITY	17 623504 4841865 W	2007/07 7241	1.5				0010 10	7048137 (Z74042) A061562	BRWN FILL SAND LOOS 0002 BRWN CLAY SILT DNSE 0015 GREY CLAY SILT WBRG 0020

Notes:
UTM: UTM in Zone, Easting, Northing and Datum is NAD83; L: UTM estimated from Centroid of Lot; W: UTM not from Lot Centroid
DATE CNTR: Date Work Completedand Well Contractor Licence Number
CASING DIA: .Casing diameter in inches
WATER: Unit of Depth in Fee. See Table 4 for Meaning of Code

PUMP TEST: Static Water Level in Feet / Water Level After Pumping in Feet / Pump Test Rate in GPM / Pump Test Duration in Hour : Minutes
WELL USE: See Table 3 for Meaning of Code
SCREEN: Screen Depth and Length in feet
WELL: WEL (AUDIT #) Well Tag . A: Abandonment; P: Partial Data Entry Only
FORMATION: See Table 1 and 2 for Meaning of Code

1. Core Material and Descriptive terms

Code	Description	Code	Description	Code	Description	Code	Description	Code	Description
BLDR	BOULDERS	FCRD	FRACTURED	IRFM	IRON FORMATION	PORS	POROUS	SOFT	SOFT
BSLT	BASALT	FGRD	FINE-GRAINED	LIMY	LIMY	PRDG	PREVIOUSLY DUG	SPST	SOAPSTONE
CGRD	COARSE-GRAINED	FGVL	FINE GRAVEL	LMSN	LIMESTONE	PRDR	PREV. DRILLED	STKY	STICKY
CGVL	COARSE GRAVEL	FILL	FILL	LOAM	TOPSOIL	QRTZ	QUARTZITE	STNS	STONES
CHRT	CHERT	FLDS	FELDSPAR	LOOS	LOOSE	QSND	QUICKSAND	STNY	STONEY
CLAY	CLAY	FLNT	FLINT	LTCL	LIGHT-COLOURED	QTZ	QUARTZ	THIK	THICK
CLN	CLEAN	FOSS	FOSILIFEROUS	LYRD	LAYERED	ROCK	ROCK	THIN	THIN
CLYY	CLAYEY	FSND	FINE SAND	MARL	MARL	SAND	SAND	TILL	TILL
CMTD	CEMENTED	GNIS	GNEISS	MGRD	MEDIUM-GRAINED	SHLE	SHALE	UNKN	UNKNOWN TYPE
CONG	CONGLOMERATE	GRNT	GRANITE	MGVL	MEDIUM GRAVEL	SHLY	SHALY	VERY	VERY
CRYS	CRYSTALLINE	GRSN	GREENSTONE	MRBL	MARBLE	SHRP	SHARP	WBRG	WATER-BEARING
CSND	COARSE SAND	GRVL	GRAVEL	MSND	MEDIUM SAND	SHST	SCHIST	WDFR	WOOD FRAGMENTS
DKCL	DARK-COLOURED	GRWK	GREYWACKE	MUCK	MUCK	SILT	SILT	WTHD	WEATHERED
DLMT	DOLOMITE	GVLY	GRAVELLY	OBDN	OVERBURDEN	SLTE	SLATE		
DNSE	DENSE	GYPS	GYPSUM	PCKD	PACKED	SLTY	SILTY		
DRTY	DIRTY	HARD	HARD	PEAT	PEAT	SNDS	SANDSTONE		
DRY	DRY	HPAN	HARDPAN	PGVL	PEA GRAVEL	SNDY	SANDYOAPSTONE		

2. Core Color

Code	Description
WHIT	WHITE
GREY	GREY
BLUE	BLUE
GREN	GREEN
YLLW	YELLOW
BRWN	BROWN
RED	RED
BLCK	BLACK
BLGY	BLUE-GREY

3. Well Use


Code	Description	Code	Description
DO	Domestic	OT	Other
ST	Livestock	TH	Test Hole
IR	Irrigation	DE	Dewatering
IN	Industrial	MO	Monitoring
CO	Commercial	MT	Monitoring TestHole
MN	Municipal		
PS	Public		
AC	Cooling And A/C		
NU	Not Used		

4. Water Detail

Code	Description	Code	Description
FR	Fresh	GS	Gas
SA	Salty	IR	Iron
SU	Sulphur		
MN	Mineral		
UK	Unknown		

APPENDIX K

TERRAPROBE INC.





Photograph 1

Location:	Phase One Property
Viewing:	South
Description:	109 Cartwright Building.



Photograph 2

Location:	Phase One Property
Viewing:	North
Description:	109 Cartwright Building.




Photograph 3

Location:	Phase One Property
Viewing:	North
Description:	130 Bentworth Property.



Photograph 4

Location:	Phase One Property
Viewing:	South
Description:	130 Bentworth Property.



Photograph 5

Location:	Phase One Property
Viewing:	East side
Description:	Piping lines for suspect fuel oil UST at 109 Cartwright.



Photograph 6

Location:	Phase One Property
Viewing:	West side
Description:	Pad mounted transformer unit at 109 Cartwright.



Photograph 7

Location:	Phase One Property
Viewing:	West
Description:	Concrete pad and foundations for former building at 130 Bentworth.



Photograph 8

Location:	Phase One Property
Viewing:	Interior
Description:	Typical water staining in rear warehouse at 109 Cartwright.

APPENDIX L

TERRAPROBE INC.





Table of Area of Potential Environmental Concern

Area of Potential Environmental Concern	Location and Address of Potential Contaminating Activity	Potentially Contaminating Activity	Potential Contaminants of Concern	Media Potentially Impacted (Ground water, soil and/or sediment)
APEC 1	North side of 109 Cartwright Ave.	#NA1 – Waste Generator	Metals, HFM, PHCs, BTEX, VOCs	Ground Water
APEC 1A	North side of 109 Cartwright Ave.	#55 – Transformer, Manufacturing, Processing and Use	PHCs, BTEX	Soil and Ground Water
APEC 2	East side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 3	South side of 109 Cartwright Ave.	#12 – Concrete, Cement and Lime Manufacturing	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 4	West side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Metals, HFM, PHCs, BTEX	Ground Water
APEC 5	Northwest side of 130 Bentworth Ave.	#39 – Paints Manufacturing, Processing and Bulk Storage	Metals, HFM, VOCs, PHCs	Soil and Ground Water
APEC 6	North side of 130 Bentworth Ave.	#NA3 – De-icing Agents	EC, SAR	Soils
			Na, Cl	Ground Water
APEC 7	West central portion of 130 Bentworth Ave.	#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)	VOCs, PHCs	Soil and Ground Water
APEC 8	East central portion of 130 Bentworth Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 9	West side of 130 Bentworth Ave.	#NA1 – Waste Generator	Metals, HFM, PHCs, BTEX, VOCs	Ground Water
APEC 10	Entire Property	#30 – Importation of Fill Material of Unknown Quality	Metals, HFM, PHCs, BTEX, VOCs, PAHs	Soils

APPENDIX M

TERRAPROBE INC.



PHASE ONE CONCEPTUAL SITE MODEL

109 Cartwright Avenue and 130 Bentworth Avenue, Toronto, Ontario

Phase One CSM		Information Pertaining to Property
Figures of the Phase One Study Area are provided that:		
i.	Show any existing buildings and structures	The Property is currently occupied by a single-storey commercial building, driveway and parking lots. A concrete pad remains at 130 Bentworth Avenue, where a former building was located. The general land area is being used for staff parking by the adjacent Sterling Hall School, see Figures 1 and 2.
ii.	Identify and locate water bodies located in whole or in part on the Phase One Study Area	No water bodies were identified on the Property. The nearest water body Maple Leaf Creek located approximately 500 m west of the Property. All water bodies on the Phase One Property and in the Phase One Study Area are shown on Figure 3 (if any).
iii.	Identify and locate any Areas of Natural Significance (ANSI) located in whole or in part on the Phase One Study Area	Terraprobe reviewed the Ontario Ministry of Natural Resources and Forestry NHIC database and Toronto Conservation Authority. No ANSIs were found
iv.	Locate any drinking water wells at the Phase One Property	No drinking water wells were identified on the Property.
v.	Show roads, including names, within the Phase One Study Area	The Property is bounded by roads to the north and south of the Property. Other roads and properties within the Study Area are presented on Figure 3.
vi.	Show use of properties adjacent to the Phase One Property	The Land Uses of the adjacent properties are shown on Figure 4.
vii.	Identify and locate areas where any potentially contaminating activity has occurred, and show tanks in such areas	Potentially Contaminating Activities (PCAs) located on the Property and within the Study Area are shown on Figure 5.
viii.	Identify and locate any areas of potential environmental concern	Ten (10)) Areas of Potential Environmental Concern (APECs) and associated Contaminants of Potential Concern are described on the Table of APECs. The locations of the APECs on the Phase One Property are shown on Figure 6.
The following is a description and assessment of:		

Phase One CSM	Information Pertaining to Property
i. Any areas where potentially contaminating activity on or potentially affecting the Phase One Property has occurred	

Area of Potential Environmental Concern	Location of Area of Potential Environmental Concern on Phase One Property	Potentially Contaminating Activity	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Ground-water, soil and/or sediment)
APEC 1	North side of 109 Cartwright Ave.	#NA1 – Waste Generator	Off-Site	Metals, HFM, PHCs, BTEX, VOCs	Ground Water
APEC 1A	North side of 109 Cartwright Ave.	#55 – Transformer, Manufacturing, Processing and Use	On-Site	PHCs, BTEX	Soil and Ground Water
APEC 2	East side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	On-Site	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 3	South side of 109 Cartwright Ave.	#12 – Concrete, Cement and Lime Manufacturing	On-Site	Metals, HFM, PHCs, BTEX	Soil and Ground Water
APEC 4	West side of 109 Cartwright Ave.	#28 – Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	Metals, HFM, PHCs, BTEX	Ground Water
APEC 5	Northwest side of 130 Bentworth Ave.	#39 – Paints Manufacturing, Processing and Bulk Storage	On-Site	Metals, HFM, VOCs, PHCs	Soil and Ground Water
APEC 6	North side of 130 Bentworth Ave.	#NA[3] – De-icing Agents	On-Site	EC, SAR Na, Cl	Soils Ground Water

<table>
<tr><th colspan="2">Phase One CSM</th><th>Information Pertaining to Property</th></tr>
<tr><td></td><td></td><td>
<table>
<tr><td>APEC 7</td><td>West central portion of 130 Bentworth Ave.</td><td>#37 – Operation of Dry-Cleaning Equipment (where chemicals are used)</td><td>On-Site</td><td>VOCs, PHCs</td><td>Soil and Ground Water</td></tr>
<tr><td>APEC 8</td><td>East central portion of 130 Bentworth Ave.</td><td>#28 – Gasoline and Associated Products Storage in Fixed Tanks</td><td>On-Site</td><td>Metals, HFM, PHCs, BTEX</td><td>Soil and Ground Water</td></tr>
<tr><td>APEC 9</td><td>West side of 130 Bentworth Ave.</td><td>#NA1 – Waste Generator</td><td>Off-Site</td><td>Metals, HFM, PHCs, BTEX, VOCs</td><td>Ground Water</td></tr>
<tr><td>APEC 10</td><td>Entire Property</td><td>#30 – Importation of Fill Material of Unknown Quality</td><td>On-Site</td><td>Metals, HFM, PHCs, BTEX, VOCs, PAHs</td><td>Soils</td></tr>
</table>
</td></tr>
<tr><td>ii.</td><td>Any contaminants of potential concern</td><td>Potential Contaminants of Concern (PCoCs) identified at the Property include:
Metals in soil and groundwater
Hydride Forming Metals (As, Sb, Se) in soil and groundwater
VOCs in soil and groundwater
BTEX in soil and groundwater
PHCs in soil and groundwater
PAHs in soil
EC and SAR in soil
Sodium and Chloride in groundwater</td></tr>
<tr><td>iii.</td><td>The potential for underground utilities, if any present, to affect contaminant distribution and transport</td><td>Underground utilities are present on the Property. Given their location relative to the APECs, no affect is likely for contaminant distribution and transport.</td></tr>
</table>

Phase One CSM		Information Pertaining to Property
iv.	Available regional or site specific geological and hydrogeological information	Topography • The OBM, Toporama, MNR and Google Earth maps were reviewed, and it was identified that the approximate elevation of the Property is 183 masl and is sloping towards the southwest Hydrology and Hydrogeology • The nearest water body Maple Leaf Creek located approximately 500 m west of the Property. The approximate depth to ground water, based on wells located within the Study Area ranges from 6 to 7 metres below ground surface. Ground water is interpreted to flow towards the southwest based on topography and the nearest water body. Geology (overburden) • Based on published geological information, the near surface soil at and in the vicinity of the Property consists of stone poor, sandy silt to silt sand – textured till. Geology (bedrock) • The bedrock underlying the Property is the Georgian Bay Formation which is comprised of limestone. Geology (depth to bedrock) • Based upon a borehole drilled within the Study Area, the depth to bedrock is greater than 50 metres below ground surface.
v.	How could any uncertainty or absence of information obtained in each of the components of the Phase One ESA affect the validity of the model	Based upon the information obtained, as noted above, it is the belief of the QP that there are no significant uncertainties or absence of information that would affect the conclusion as to the presence of an APEC or the validity of the Phase One Conceptual Site Model.

Figures

Figure 1 – Phase One Property Location
Figure 2 – Phase One Property
Figure 3 – Phase One Study Area
Figure 4 – Adjacent Property Land Uses
Figure 5 – PCA Locations
Figure 6 – APEC Locations